

ASS. REC. BY:

REF: CS/CT18010416/TI 9039 Special Instruction:

Survivor:
Meulmen

ASSIGNMENT (Office)

From (Person): Irene Tay of CTI Date/Time: 7/6/18 @ 4.34pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 9756P Insured: SJW 4917P

at Workshop m/s Comfort Belgro Tel: 6338 8778

of 45 Pandan Rd

Policy No: DMPCSN3013441808 Claim No: SNM18D02788C02

Sum Insured: Excess:

Make of Veh: D.O.A. 03/06/2018
(Client's Record) 08/06/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5.00pm @ 7/6/18 Person Contacted: Mr. Wong Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJU 9756P - X
	SJW 4917P - X
20/8/18	Submit Prelim report

Tanph

REF: CTI

ASSIGNMENT

From Date 08/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJU 9756P

at Workshop m/s: Comfort Delgrp

at 45 Pandan Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Mr. Wong

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Wong

Date / Time

Action / Instruction

23/10/18

Wong say owner change to od claim.

RECEIVED 30 AUG 2018

Veh No:

SJU 9756P

Yr Regn:

2019

Type: M. Cap / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

chevrolet - Cruze

cc 1598

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading:

—

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL1JA6961AK 589243

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

8/6/18 05pm

Survey held at

CDGE

at 45 Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☒

Preli. Report

30/8 11:30

☐

Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

220

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.t: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018		07 Jun 2018 16:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	HAJI MUSHARAF IQBAL		
Vehicle Reg. No.:	SJU9756P	Date of Loss:	03/06/2018 16:00 - :59
Claim Type:	TP / SNM18D02788C02	Policy/Cover Note No.:	DMPCSN3013441808
Vehicle Reg. No. (Insured):	SJW4917P	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 7 June 2018 3:49 PM
To: CDGE Pandan Private Cars Crash Repair Counter; assignments@lkkauto.com; Admin A
Subject: CTP REF NO. SNM18D02788C02 CDGC REF NO. SJU9756P - ACCIDENT INVOLVING SJW4917P AND SJU9756P ON 03 JUNE 2018

Dear Mr Wong,

We refer to the above matter and your email below.

Liability will be 50/50

We will be appointing LKK to the PRS.

Aside to LKK:

Please liaise with CDGE.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: CDGE Pandan Private Cars Crash Repair Counter [mailto:pandan_cr@sparkcarcare.com]
Sent: Wednesday, 6 June, 2018 2:39 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Fw: Check liability accident involvong for our client vehicle noSJU9756P and your insured vehicle noSJW4917P doa203.06.2018
Importance: High

Hi Irence ,

As spoken earlier ,For you action and advice .

Best Regards,

Wong Chee Wei
Crash Repair Pandan
DID 68676919
HP 97239882

----- Forwarded by CDGE Pandan Private Cars Crash Repair Counter/sparkcarcare/cdge/delgronotes on 06/06/2018 02:37 PM -----

From: CDGE Pandan Private Cars Crash Repair Counter/sparkcarcare/cdge/delgronotes
To: claimsdept@sg.cntaiping.com
Date: 06/06/2018 02:15 PM
Subject: Check liability accident involong for our client vehicle noSJU9756P and your insured vehicle noSJW4917P doa203.06.2018

Dear Sir / Mdm ,

With reference attached for above mentioned mater ,Please arrange survey ASAP at 45 Pandan Road .

Best Regards,

Wong Chee Wei
Crash Repair Pandan
DID 68676919
HP 97239882

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 08:37
Date Of Accident	03/06/2018 16:10
Exact Location Of Accident	JOHOR BAHRU CHECKPOINT/IMIGRATION NEAR TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU9756P
Insured/Policyholder	
Name Of Registered Owner	HAJI MUSHARAF IQBAL
NRIC No	S2742072I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90095898
Alternative Phone No	OFFICE-90095898

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE-1.6 L (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA308983/1
Cover Note Number	

Driver

Name of Driver	MUHAMMAD OMER FAROOQ
NRIC No	S8874164A
Date Of Birth	02/12/1988
Occupation	INDOOR
Date Of Driving Pass	19/12/2014
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82336745
Fax Number	
Contact Number	
Email Address	OMER.ACCA@HOTMAIL.COM

Address	2 BOON LAY DRIVE
	#08-06
Postcode	649925
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


REFER ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW4917P
Vehicle Make/Model/Colour	HONDA / FREED / GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MASWATI BINTI MOHAMMAD
NRIC/Passport Number	S1814671A
Contact Number	87517537
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was coming back to Singapore from JB and waiting at Jam at Malaysia side of Immigration. I was slowly moving ahead when other car tried to enter my lane quickly from left side even though there was very little space in front of me. Other car's right rear wheel hit my car left head light and my bumper got stuck in the mud-guard area of the other car and it came off. Other car kept moving about 1 meter even though I stopped and the bumper came further off at that time I got off car and stopped other car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policypholder's Signature
Date & Time:

Driver's Signature
If driver is not the policypholder
Date & Time:

COMFORTCLAD ENGINEERING PTE LTD
EXTERNAL BUSINESS DIVISION BRANCH
NAME & SIGNATURE: *[Signature]*
DESIGNATION: DATE:

Following Centre Personnel's Signature
Name: Wong Chee Wei
AFIC/PHI No.: 672180994.

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 — (65) 6880 4740
 — customer.care@axa.com.sg
 — www.axa.com.sg

document number
04247

Policyholder name	MAH MUSHARAF IQBAL	Certificate
Cover	Comprehensive	Chassis no
Plan name	Essential	Engine num
NCD applicable	50%	
Vehicle registration number	SJU9756P	
Period of insurance	from 06/01/2018 to 05/01/2019 (both dates inclusive)	
Finance loan company	STANDARD CHARTERED BANK SINGAPORE LTD	

GA308943 / 1
 NL10462014K589243
 F1603E135501

1. MUHAMMAD OMAR FAROOQ

It should be noted that the carbon driving is presented in accordance with the licensing or other laws or regulations in force in the Administrative Region of the origin of the material and is not disqualifying in order of a Point on Law or by reason of the treatment of a regulation in that domain if it was during the above example.

USE ONLY FOR EXPORT, DOMESTIC AND AIRCRAFT PURPOSES AND FOR THE POLYMERIZATION OF MONOMERS

The polymerization of monomers is a complex process involving many factors, including the nature of the monomer, the nature of the catalyst, the nature of the solvent, the nature of the reaction conditions, and the nature of the reaction time. The polymerization of monomers is a complex process involving many factors, including the nature of the monomer, the nature of the catalyst, the nature of the solvent, the nature of the reaction conditions, and the nature of the reaction time.

USE ONLY FOR EXPORT, DOMESTIC AND AIRCRAFT PURPOSES AND FOR THE POLYMERIZATION OF MONOMERS

The polymerization of monomers is a complex process involving many factors, including the nature of the monomer, the nature of the catalyst, the nature of the solvent, the nature of the reaction conditions, and the nature of the reaction time. The polymerization of monomers is a complex process involving many factors, including the nature of the monomer, the nature of the catalyst, the nature of the solvent, the nature of the reaction conditions, and the nature of the reaction time.

EXCESS	Basic Don Dramlage Excess	SGD 300.00
	Windscreen Excess	SGD 100.00

An additional Excess is applicable as follows:

1. \$3,500 for unpaired Authorized Driver
2. \$5,500 for declared young and inexperienced driver
3. \$35,000 for undeclared young and inexperienced drivers. This additional excess is reduced to \$62,500 if you have chosen A+ Premium Workshops.

144

I declare that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, Chapter 152 and Part III of the Road Transport Act, 1987 (Malaysia).

1

1993-1994: 100% of the total

1. Patented

1992, 1993, 1994, 1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 26

ACA Insurance Pte Ltd, 199503512M,
21-moon Way, #2d-01, A/A Tower,
Singapore 268311
Customer Centre #81-01

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S27420721



Name: HAJI MUHAMMAD IQBAL
Date of Birth: 05-1956
Country of Birth: PAKISTAN
Sex: M

MFIRIDELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
TEL: 6338 8778 FAX: 6262 6950



MFIRIDELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
TEL: 6338 8778 FAX: 6262 6950

MFIRIDELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
TEL: 6338 8778 FAX: 6262 6950

4378524



NRIC NO. S27420721



MFIRIDELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
TEL: 6338 8778 FAX: 6262 6950

Date of issue: 26-03-2009

2 BOON LAY DRIVE #08-06
SINGAPORE 649325

NRIC NO. S27420721

Date: 14/04/2013

No: 7341038

MFIRIDELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
TEL: 6338 8778 FAX: 6262 6950

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8874164A



INDIAN
Date of birth: 02-12-1988
Country of birth: PAKISTAN

TEL: 6338 8778 FAX: 6252 6852

45 PANDAN ROAD
SINGAPORE 603286

OMER FAROOQ

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8874164A
Name: MUHAMMAD OMER FAROOQ

Birth Date: 02 Dec 1988
Issue Date: 19 Dec 2014

002377686F

INDIADELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 603286
TEL: 6338 8778 FAX: 6252 6852

4550303



NRIC No: S8874164A



DATE OF ISSUE: 25-03-2010

2 BOON LAY DRIVE #08-08
SINGAPORE 646925

NRIC No: S8874164A

INDIADELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 603286
TEL: 6338 8778 FAX: 6252 6852

No: 7341039

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

EFFECTIVE DATE: 19 Dec 2014



NP 428A

To whomsoever it may concern,

I HAJI MUSHARAF IQBAL (S2742072)

authorize Muhammad Omar Farooq

(S8874164A) to carry out insurance

claims procedure for vehicle

SJU 9746P with respect to accident

on 3 June 2018.

Haji Musharaf Iqbal

S2742072 I

3 June 2018

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☐ Own Damage
☒ 3rd Party
☐ Windscreen

Vehicle No. : **SJU9756P**
Make & Model : **CHEVROLET / CRUZE 16LA**
Year of Manufacture : **2009**
Chassis No. : **KL1JA6961AK589243**
Engine No. : **F16D35186591**
Policy No. :
Time of Accident : **16.10 p.m**

Ins Company : **China Taiping Ins**
Excess :
Date of Accident : **03.06.2018**
Suggested Days of Repair : **6 DAY**

In-house Vehicle Assessor

Repair Estimates

Name : **Wong Chee Wei**
Signature :
Contact No : **68676919**
HP : 97239882

Parts (a) Cost / List Price Items **\$2,761.50**
Plus/Less 10 % **\$276.15**
(b) Nett Price Items
Less %
(c) Special Nett Items **\$105.00**
Total Parts Cost (Appendix A) \$3,142.65
Labour (Appendix B) \$1,910.00
Total Repair Cost \$5,052.65 *4500.35*

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Name of Surveyor : *Tan Jiah*
Company :
Survey conducted on : at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : *4 days* day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : *[Signature]* Date: *6/6/18*

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : SJU9756P Submit By : Wong Chee Wei
 Make & Model : CHEVROLET CRUZE 16LA Year Manufacture : 2009
 Chassis No. : KL1JA6961AK589243 Engine No. : F16D35186591

TP

S/Order : _____

S/No	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price	Disposition By Surveyor
1	FR BUMPER	1			\$914.00		de ✓
2	FR BUMPER C'LIPS	10			\$50.00		de ✓
3	FR BUMPER SIDE RETAINER RH	1			\$45.00		X n ✓
4	FR BUMPER SIDE RETAINER LH	1			\$45.00		de ✓
5	FR BUMPER BRACKET RH	1			\$45.00		X n ✓
6	FR BUMPER BRACKET LH	1			\$45.00		de ✓
7	FENDER LHF	1			\$712.00		ht ✓
8	FENDER LINER LHF	1			\$99.00		X n ✓
9	FENDER LINER CLIPS LHF	1			\$19.50		X n ✓
10	HEAD LAMP LH	1			\$787.00		X n ✓
11	FR NUMBER PLATE	1				\$45.00	de ✓
12	FR NUMBER PLATE LTA SEAL PIN	1				\$60.00	de ✓
13		1					
14		1					
15		1					
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)
Tel: 68676919 Fax: 62626950, 68676903

Labour

Submit By : : Kent

Year of Manufacture : 2009

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018		07 Jun 2018 16:34 Edit Adj Rpt	S\$2,624.40 Edit Estimates	S\$2,624.40 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	0, Co. Reg. No.: 0		
Main Claimant:	HAJI MUSHARAF IQBAL		
Vehicle Reg. No.:	SJU9756P	Date of Loss:	03/06/2018 16:00 - :59 [100 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02788C02	Policy/Cover Note No.:	DMPCSN3013441808
Vehicle Reg. No. (Insured):	SJW4917P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/06/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJU9756P (SNM18D02788C02)**
[SJW4917P]

TP

HAJI MUSHARAF IQBAL

Jun 3 2018 4:00PM

[0]

ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/18 17:44	General View	 Load JPG	✓
2	29/08/18 17:44	General View	 Load JPG	✓
3	29/08/18 17:44	General View	 Load JPG	✓
4	29/08/18 17:44	General View	 Load JPG	✓
5	29/08/18 17:44	General View	 Load JPG	✓
6	29/08/18 17:44	General View	 Load JPG	✓
7	29/08/18 17:44	General View	 Load JPG	✓
8	29/08/18 17:44	General View	 Load JPG	✓
9	29/08/18 17:44	General View	 Load JPG	✓
10	29/08/18 17:44	General View	 Load JPG	✓
11	29/08/18 17:44	General View	 Load JPG	✓
12	29/08/18 17:44	General View	 Load JPG	✓
13	29/08/18 17:44	General View	 Load JPG	✓
14	29/08/18 17:44	General View	 Load JPG	✓
15	29/08/18 17:44	General View	 Load JPG	✓
16	29/08/18 17:44	General View	 Load JPG	✓
17	29/08/18 17:44	General View	 Load JPG	✓
18	29/08/18 17:44	General View	 Load JPG	✓
19	29/08/18 17:44	General View	 Load JPG	✓
20	29/08/18 17:44	General View	 Load JPG	✓
21	29/08/18 17:44	General View	 Load JPG	✓
22	29/08/18 17:44	General View	 Load JPG	✓
23	29/08/18 17:44	General View	 Load JPG	✓
24	29/08/18 17:44	General View	 Load JPG	✓
25	29/08/18 17:44	Chassis Number	 Load JPG	✓
26	29/08/18 17:44	General View	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18010416/T1QD3S2

Date: 05/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3013441808

Claimant Vehicle No: SJU9756P Insured Vehicle No: SJW4917P

Date of Loss: 03/06/2018 Nature of Claim: TP Claim No: SNM18D02788C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU9756P**

Make & Model: CHEVROLET CRUZE, 1.6 L (A) Engine No: F16D35186591

Reg. Date: 06/01/2010 (Man. Year: 2009) Chassis No: KL1JA6961AK589243

Colour: Blue Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50R17 Rear Tyre Size: 215/50R17

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,590.35	1,694.40	895.95	34.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	930.00	980.00	51.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,500.35	2,624.40	1,875.95	41.68
+ GST 7.00/7.00% (S\$)	315.02	183.71	131.31	41.68
Nett Amount (S\$)	4,815.37	2,808.11	2,007.26	41.68

INSPECTION

Date of Assignment: 07/06/2018

Date Inspected: 08/06/2018 Inspected At: ComfortDelGro Engineering Pte Ltd (Pandan)
45 Pandan Road
Singapore 609286

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

ACCORDING TO THE REPAIRER, THE OWNER CHANGE TO OD CLAIM.
(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2018)
Parts:	143	CHEVROLET CRUZE 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU9756P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR BUMPER	Deformed	914.00 FL	*914.00 FL
2	10		*FR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*FR BUMPER SIDE RETAINER RH	Not Necessary	45.00 FL	*- FL
4	1		*FR BUMPER SIDE RETAINER LH	Necessary	45.00 FL	*45.00 FL
5	1		*FENDER LHF	Bent	712.00 FL	*712.00 FL
6	1		*FENDER LINER LHF	Not Necessary	99.00 FL	*- FL
7	1		*FENDER LINER CLIPS LHF	Not Necessary	19.50 FL	*- FL
8	1		*HEAD LAMP LH	Not Necessary	787.00 FL	*- FL
9	1		*FR NUMBER PLATE	Necessary	45.00 FS	*45.00 FS
10	1		*FR NUMBER PLATE LTA SEAL PIN	Necessary	60.00 FS	*60.00 FS
11	1		*FR BUMPER BRACKET RH	Not Necessary	45.00 FL	*- FL
12	1		*FR BUMPER BRACKET LH	Necessary	45.00 FL	*45.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	2,866.50	1,871.00
- List Item Discount on L Items 10.00/10.00% (S\$)	276.15	176.60
Total Parts (S\$)	2,590.35	1,694.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE,STRAIGHTEN,PANEL BEAT;FR BUMPER FENDER LHF,DAMAGED AREA	New	900.00	400.00
2	TO PUTTY,RESPRAY FRONT BUMPER,FENDER LHF DAMAGED AREA	New	800.00	400.00
3	TO CHECK WIRE	New	60.00	30.00
4	TO ARRANGE EXPRESS SERVICE TO DO DOCUMENT AT LTA (FOR WEEKEND PLATE)	New	150.00	100.00
Gross Labour Cost (S\$)			1,910.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >