

ASS. REC. BY:

REF: CS3/ICS18010419/Nz4d302

Final Instruction:

Surveyor
minimh

Naz

ASSIGNMENT (Office)

From (Person): Janice Goh

of ECICS

Date/Time: 7/6/18 @ 4:20pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJE 3757K

Insured: SLD 9553Z

at Workshop m/s Ace Autolution

Tel: 6844 1184

of 13 Kaki Bkt Rd 4 #03-29

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/6/2018

CA / REV / REP. / REV 24 HRS (up)

08/06/2018

H.O.D. Endorsement:

Date/Time: 5:04pm @ 7/6/18

Person Contacted:

Jenny

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SJE 3757K - X
	SLD 9553Z - X
11/6/18	Disman filed

NAZ

REF: ECICS

ASSIGNMENT

From Date: 08/06/2018

Veh No: SJE 3757K Yr Regn: 23/Jun/2017

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SJE 3757K
at Workshop n/s Ace Autoolution
of 13 kaki Bkt Rd 4 # 03-29

Make: HONDA VEZEL 1.5X (A) c.c. 1496

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 24,645 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: RU1 - 1201448

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD A/Rim or BBS

(Policy Condition)

Tyre Size: F: 225 / 45 R18

R: 11

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Bal. or Market Value:

Front Rear

IDAC Accident Report: Consistent? : Yes or No

R/Bal. 7 mm R/Bal. 7 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 7 mm L/Bal. 7 mm

Est. Repairs: days Res: Yes or No

D.O.A. 7/6/18 D.O.I. 8/8/18 -> ?

Lum Sum: % 3 Val: Yes or No

Survey held at ACE AUTOOLUTION 08/06/2018

CA / REV / REP. / 24 HRS ^{hwp}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate 3 S\$ 2500 - 3500

* 2 days

13/6/18 Submit PRS Report.

RECEIVED 13 JUN 2018

Date/Time File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Date/Time File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$

Transportation

) S + RS SI

Report Format :

Interview (\$

Photos

Lump Sum / I.B.I: (\$

Tech. Invs (\$

Others

Weekend (\$

TOTAL

100
100
10
20

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Thursday, 7 June 2018 4:20 PM
To: Jerone; assignments@lkkauto.com
Cc: 'Weng Kit'; ECICS Claims
Subject: RE: Our Ref: SJE 3757K (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJE 3757K & SLD 9553Z ALONG LORONG 6 TOA PAYOH TOWARDS PIE ON 7 JUNE 2018
Attachments: 20180607131800718.pdf

Without Prejudice

Dear Jerone

Thank you for your email.

We are not agreeable with your surveyor list and we will appoint LKK for the TP PRI.
We would appreciate that you could provide us a copy of your client's accident report.

Aside to LKK

Please assist to arrange for the TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Jerone [mailto:jerone@chiaarul.com]
Sent: Thursday, 7 June, 2018 4:03 PM
To: ECICS Claims
Cc: 'Weng Kit'
Subject: RE: Our Ref: SJE 3757K (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJE 3757K & SLD 9553Z ALONG LORONG 6 TOA PAYOH TOWARDS PIE ON 7 JUNE 2018

O/Ref: SJE 3757K (Wk)
Y/Ref: TBA

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir / Madam,

We thank you for your email below.

Kindly be informed that our client is not agreeable to your list of surveyors and we hereby propose the following:

Name of Surveyor	Company
Andrew Aw	I-spex Services
S. Kumanan	SK Auto Consultants
Thanapaul	Quantum Risk Management
Samuel	Autoprobe

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

Mr. Jerone Lee

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: ECICS Claims [mailto:claims@ecics.com.sg]

Sent: Thursday, 7 June, 2018 3:57 PM

To: Weng Kit <wengkit@chiaarul.com>

Cc: 'Jerone' <jerone@chiaarul.com>; ECICS Claims <claims@ecics.com.sg>

Subject: RE: Our Ref: SJE 3757K (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJE 3757K & SLD 9553Z ALONG LORONG 6 TOA PAYOH TOWARDS PIE ON 7 JUNE 2018

Without prejudice

Dear Mr Weng Kit

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Weng Kit [mailto:wengkit@chiaarul.com]
Sent: Thursday, 7 June, 2018 1:22 PM
To: ECICS Claims
Cc: 'Jerone'
Subject: Our Ref: SJE 3757K (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJE 3757K & SLD 9553Z ALONG LORONG 6 TOA PAYOH TOWARDS PIE ON 7 JUNE 2018

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair inspection notice dated 7 June 2018 for your attention.

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJE 3757K (wk)

Your Ref : To be advised

7 June 2018

ECICS Limited

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : MOHAMED FERAZ S/O MUHAMED ISMAIL
ACCIDENT INVOLVING SJE 3757K & SLD 9553Z ALONG LORONG 6 TOA
PAYOH TOWARDS PIE ON 7 JUNE 2018
PRE-REPAIR SURVEY NOTICE

1. We act for Mohamed Feroz s/o Mohamed Ismail, the owner of motor vehicle no. SJE 3757K which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SLD 9553Z for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS3/ICS18010419/Nz4d3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 07-06-2018



Code : ICS

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLD 9553Z	Veh. Inspected	SJE 3757K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/06/2018	Inspection Date	
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2018 16:03
Date Of Accident	07/06/2018 10:55
Exact Location Of Accident	TOA PAYOH LOR 6 TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE3757K
Insured/Policyholder	
Name Of Registered Owner	MOHAMED FERUZ S/O MOHAMED ISMAIL
NRIC No	S7301987G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90029001
Alternative Phone No	OFFICE-90029001
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA231124/1
Cover Note Number	
Driver	
Name of Driver	MOHAMED FERUZ S/O MOHAMED ISMAIL
NRIC No	S7301987G
Date Of Birth	20/01/1973
Occupation	INDOOR
Date Of Driving Pass	26/04/1993
Driving Experience	25 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90029001
Fax Number	
Contact Number	OFFICE-90029001
E-Mail Address	NOEMAIL

Address	APT BLK 138A LORONG 1A TOA PAYOH #29-04 SINGAPORE
Postcode	311138
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **OBJECTS** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workmate and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing P & A; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's signature
Name:
NRIC/PS No:

Sketch Plan #2

SKETCH PLAN



Vehicle A: SJE 3757 K

Vehicle B: SLD 9563 Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/6/2018 at around 10:55 a.m, I was travelling along Loring to Tea Bayah Towards PIE. My vehicle slow down and stopped to check for on coming traffic. Suddenly, vehicle B (SLD 9563 Z) collided onto my vehicle rear portion.

DECLARATION

I hereby declare the foregoing particulars are true in every respect

Police Officer Signature
Date & Time:

Driver's Signature
(in driver's and the accompanying
Date & Time:

Reporting Officer/Person's Signature
Name:
NRP/IN No:

JOB SUMMARY REPORT

ACE AUTOLUTION PTE LTD
13 ,KAKI BUKIT ROAD 4
BARTLEY BIZ CENTRE #03-29,
SINGAPORE 417807.

BILLING

BILL to -

Vehicle NO :	SJK 6219 X
Repair Type :	LUMPSUM
Repair As Per Surveyor Report:	\$ 3,645.00
Material Cost :	
Less Repair Items/Adjustment	
Special Nett Items :	
Total Repair Cost :	\$ 3,645.00
Final Repair Cost :	\$ 3,645.00

Others

Search Fees (LTA)	-
Surveyor Fees	\$ 400.00
Loss of Rental	-
Loss Of Use	\$ 441.00

Total Amount Bill : \$ 4,486.00

Approved By : QUEK YONG PHENG

Signature:

Date : 8/6/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2018 15:10 Edit Reg		07 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	-, Co. Reg. No.: -, Email: EMAL@EMAIL.COM	
Main Claimant:	MOHAMED FEROS S/O MOHAMED ISMAIL, ID: S7301987G	
Vehicle Reg. No.:	SJE3757K	Date of Loss: 07/06/2018 10:00 - :59 [11 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:
Vehicle Reg. No. (Insured):	SLD9553Z	Policy No. (Claimant):
		Excess:
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:	
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 22/06/2018]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SJE3757K**
[SLD9553Z]
TP
MOHAMED FEROUZ S/O MOHAMED ISMAIL
Jun 7 2018 10:00AM
[-]
Ace Autolution

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/06/18 20:06	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
39	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
40	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
41	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
42	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
43	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
44	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
45	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
46	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
47	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
48	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
49	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
50	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
51	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
52	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
53	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
54	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
55	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
56	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
57	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
58	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
59	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
60	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
61	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
62	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
63	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
64	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
65	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>
66	12/06/18 20:06	Dismantled Parts		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18010419/NZ4D3E2

Date: 18/06/2018

REFERENCE

Handling Insurer: ECICS Limited	Policy No:			
Claimant Vehicle No : SJE3757K	Insured Vehicle No :	SLD9553Z		
Date of Loss: 07/06/2018	Nature of Claim:	TP	Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE3757K		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4401448
Reg. Date:	23/06/2017 (Man. Year: 2016)	Chassis No:	RU11201448
Colour:	White	Odometer:	24645 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/06/2018	
Date Inspected:	08/06/2018 Inspected At:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	2.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE3757K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >