

(INSUR)

INS. CASE OWNER:

CC 3/AIG1801 0420, TI job

LKK:

IDAC:

Surveyor:

Zhang Teh

DOI:

ASSIGNMENT

12/6/18

Date / Time:

21/6/18

Registered in Merimen:

21/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDX 19354

Name of Insured:

SU HONG ZEE

Insured Tel No.:

HP: 90765874

Excess Sec II :SS

D.O.A.:

6/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Of GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SDX 49450

INSRS:
WSP:
Tel:
Liability:
RMKS:

volkswagen

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

11/6/18

PM

SDX 49450 - X

SDX 19354 - X

14-6-18 REQ TP VIDEO.

14-6-18 @ 306 PM - NO ANSWER.

14-6-18 @ 323 CALLED - NO ANSWER

20-6-18 @ 1044 W/OI. HE DENIED
CHANGING LANE.
TOLD HIM TP CCTV SHOWED
TP STRAIGHT & OI
CHANGED LANE. HE
AGREED & AWARE NCD
ISIVE.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

days) Reduction: %

Email: Call:

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability:

S\$

(Agreed / Assessed) BOLA S/N No.:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

days)

Loss of Use (LOU):

S\$

days)

Loss of Income (LOI):

S\$

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

Name 1:

VOLKSWAGEN CENTRE SINGAPORE

Payee 2: (Strike if N.A.)

S\$

Name 2:

CHAY WEN YEE (XIE WENYI)

Payee 3: (Strike if N.A.)

S\$

Name 3:

Tamplin

REF:

Azh

ASSIGNMENT

From: Date 13062018

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SLX 4945D

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh

4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: 6 days Res Yes or No

Lump Sum: % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No

SLX 4945D

Vt Regn

2018 March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Volkswagen Golf

cc 999.

Colour

Silver

A/C

Insured / Std / NI / NA

Spl Reading

1168

T/Radio: Insured / Std / NI / NA

Eng/No

C/No

WVW ZZZ 447 JW 180226

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/B/m / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

2

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.A.

13/6/2018

Survey held at

ku Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$5,260.XV

R (\$ 2,060/28%)

Date/Time: File Pass to:

☐

Preli. Report

Days Of Repair:

to:

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return to:

to:

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Week-end \$

Survey Fee:

Transportation:

Y...S...R...\$

1. Photos

1. Others

Report Format:

Lump Sum / I.B. \$

70246



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18010430/jb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 07-06-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDX 1935Y	Veh. Inspected	SLX 4945D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/06/2018	Inspection Date
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	(Insd veh)	Model:	TOYOTA CAMRY 2.0 (A)
	(TP veh)		
Date of Accident:			

Global Sum Settlement	: [] Yes [] No
-----------------------	------------------

Repair Estimate	: \$
-----------------	------

Final Repair Cost	: \$
-------------------	------

Loss of Use	: \$	days at \$.. per day
-------------	------	-----------------------

Rental (if any)	: \$	0.00	days
-----------------	------	------	------

LTA / GIA Search Fee	: \$
----------------------	------

Others:	: \$	0.00
---------	------	------

	: \$
--	------

Final Settlement Sum	: \$
----------------------	------

Is Third Party Workshop GIA Registered?	[X] YES [] NO	(Kindly indicate below)
---	------------------	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
-------------------------------------	----------------------------

B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No	BOLA Scenario No: ____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks	
---------	--

Payment Instruction: Payee's Breakdown
--

1)	: \$
----	------

--	--

--	--

16 Apr
2013

Date

PAYMENT ADVICE

Your ref: AIG Insurance Vehicle No. SDX 1935Y

Claimant's Vehicle No. SLX 4945D

Accident on 6-6-78 involving vehicle/s No. _____

_____ along/at JALAN BINTU TIMAH

BREAKDOWN OF PAYMENT/S

1. Repair Cost S\$ 5628.20 Payable to Volkswagen Centre Singapore

8 days x 60

2. Loss-of-Use/
Car Rental S\$ 420 Payable to CAR RENTAL

3. ~~Medical~~ and
Search Fees S\$ 2 Payable to Volkswagen Centre Singapore

Remarks : _____

Service Adviser _____

Contact No./H/P. _____

PDI TUAS

PDI TUAS

CHAY WEN YEE (XIE WENYI)
121 SUNSET WAY
#02-02
Singapore, 597153
Singapore

Tanpin 97495749
WR
13/6/18 @ 1545
Resurvey after repair
SVC @ 1/18/18
6 days

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV030272
Quote No. SER/QUO/1800912
QuoteDate 06/06/18
Salesperson Delsie Ong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSi 81 kW Trendline	0	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLX4945D	WVWZZZAUZJW180226	29/03/18	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 664838	BQ12AZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT	2.5 x 800	2/00 3,360.00
P B&P ALEX PAINT	SPRAY PAINTING	4	UNIT		2400 3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				7,320.00

Sum Labor 7,320.00

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total	SGD	7,320.00	7,320.00
7% GST			512.40
Total SGD Incl. GST			7,832.40

Payments to: - BBN: - Acc.-No...

* > Back to OneMotoring

* Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5729G
Vehicle Details	
Vehicle No.:	SJL4825D
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1NZX818127
Chassis No.:	MR053HY9305085712
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,834.00
Original Registration Date:	28 Nov 2008
First Registration Date:	28 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$11,834.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2018
PARF Rebate Amount:	\$5,917.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$2.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$5,917.00

The information contained herein is correct as at 28 Jun 2018

OK

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 20 June 2018 10:54 AM
To: 'suhongzee@gmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SDX 1935Y AND SLX 4945D ON 06/06/2018 ALONG JALAN BUKIT MERAH TOWARDS SGH

Our ref: CC3/AIG18010430/T1jb3

SU HONG ZEE

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SDX 1935Y AND SLX 4945D ON 06/06/2018 ALONG JALAN BUKIT MERAH TOWARDS SGH

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario seen on video, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident

AUTHORIZATION TO ACT

(AIG Asia Pacific - Express Third Party Claim)

I, CHAY WEN YEE (the third party claimant) of 121 SUNSET WAY #02-02 (address), owner of SLX4945D (vehicle no.) hereby authorize VOLESWAGEN Centre Singapore ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SLX4945D that was damaged pursuant to the accident which occurred on 06/06/2018 (date) along JALAN BUKIT MERAH (location) involving vehicle no/s SDX 19394 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 05 (day) of JULY (month) 2018 (year)

Chay Wen Yee
Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"

(with chop)

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident

RELEASE VOUCHER

(AIG Asia Pacific - Express Third Party Claim)

"We/I, VOLKSWAGEN CENTRE SINGAPORE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS\$ 628.24 (Repair Cost), SS\$ 480.00 (Loss of Use/Rentall), SS - (Disbursement) for vehicle no. SLX 49450 that was damaged pursuant to the accident which occurred on 6.6.18 (date) along JALAN BUKIT MERAH (location) involving vehicle no/s 50X198. This is pursuant to the inspection conducted on 13.6.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHAY WEN YEE ("the third party claimant") of vehicle no. SLX 49450 make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLX 49450 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 (day) of Nov (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P28550

Sis Reg. No. 531030696
GST No. M20098505-2

SERVICE ORDER NO: 18IP1586

SERVICE CUSTOMER NO.: F01089R

SERVICE CUSTOMER NAME: AIG ASIA PACIFIC INSURANCE P/L

TELEPHONE NO.:

ADDRESS: 78 Shenton Way
#07-15 AIG Building
Singapore

Post Code: 079120

VEH NO.: SLX4945D

DATE: 28/08/18

Pickup:

VIN NO.: WVGZZZAUJZW180226

KM: 1,418

GEARBOX CODE:

Engine No.:

MODEL: Golf 1.0 TSI 81 kW Trendline

SA: Cheong Pearlyn

Next Appointment Date:

Next Appointment Mileage: 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
	DIRECT SETTLEMENT				
	DOA: 06/06/2018				
	TP VEHICLE : SDX1935Y				
	SURVEY BY : TAUFIK (LKK)				

	Labor				
1	LABOUR	2.50	UNIT	840.00	2,100.00
2	SPRAY PAINTING	3.00	UNIT	800.00	2,400.00
3	Tow SVC- Quality Recovery Services	1.00	UNIT		
4	Tow SVC- Quality Recovery Services	1.00	UNIT		
5	PROGRAMMING & CALIBRATION- NETT	1.00	TU	480.00	480.00
6	CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1.00	TU	280.00	280.00

GST (7%) AMOUNT: 368.20
TOTAL AMOUNT: 5,628.20

For Volkswagen Group Singapore Pte Ltd



Customer

NOTICE

1. All fund transfer payments should be made payable to: Volkswagen Group Singapore Pte Ltd Bank Account: 2538214802 Swift Code: DEUT3333 Please indicate Customer Name and Invoice Number in the payment

Phone : Fax :

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2018 Edit Reg		13 Jun 2018 00:00 Edit Adj Rpt	S\$5,260.00 Edit Estimates	S\$5,260.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SU HONG ZEE, ID: S0083250B								
Main Claimant:	CHAY WEN YEE (XIE WENYI), ID: S8027173E								
Vehicle Reg. No.:	SLX4945D	Date of Loss:	06/06/2018 07:00 - :59 [2 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4329350425SG	Policy/Cover Note No.:	2100283916 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDX1935Y	Policy No. (Claimant):	A29077298AVW						
		Excess:							
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX4945D (4329350425SG)
[SDX1935Y]
TP
CHAY WEN YEE (XIE WENYI)
Jun 6 2018 7:00AM
[SU HONG ZEE]
Volkswagen Centre Singapore

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	20/06/18 10:58	Video - Other						1 Load MP4			
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1 Edit			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	20/06/18 10:57	LETTER TO INSURED						1 Load PDF			
2	21/11/18 11:20	Odometer Reading						1 Load JPG	<input checked="" type="checkbox"/>		
3	21/11/18 11:20	Chassis Number						1 Load JPG	<input checked="" type="checkbox"/>		
4	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
5	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
6	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
7	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
8	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
9	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
10	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
11	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
12	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
13	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
14	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
15	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
16	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
17	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
18	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
19	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
20	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
21	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
22	21/11/18 11:20	General View						1 Load JPG	<input checked="" type="checkbox"/>		
23	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
24	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
25	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
26	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
27	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
28	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
29	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		
30	21/11/18 11:20	Reinspection Photo						1 Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 18:46	TP GIA REPORT	Load PDF	
2	14/06/18 15:55	TP ESTIMATE- MARKED	Load PDF	
3	20/06/18 10:57	LETTER TO INSURED	Load PDF	
4	23/11/18 14:21	WORKSHOP INVOICE	Load PDF	
5	23/11/18 14:21	AUTHORISATION TO ACT FORM	Load PDF	
6	23/11/18 14:21	Release Voucher	Load PDF	
7	23/11/18 14:21	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/06/18 09:32	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDX1935Y (Insd veh)	Model:	VOLKSWAGEN GOLF 1.2
	SLX4945D (TP veh)		(A7) TSI (A)
Date of Accident:	06/06/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	7,832.40
Final Repair Cost	:	\$	5,628.20
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,108.20

8.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Volkswagen Centre Singapore	:	\$ 5,628.20
2)	Chay Wen Yee (Xie Wenyi)	:	\$ 480.00

JOANNE LEE KHANG MIN

23 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18010430/T1JB3Q2

Date: 23/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100283916
 Claimant Vehicle No: SLX4945D Insured Vehicle No: SDX1935Y
 Date of Loss: 06/06/2018 Nature of Claim: TP Claim No: 4329350425SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX4945D**
 Make & Model: VOLKSWAGEN GOLF, 1.2 (A7) TSI (A) Engine No: CHZ664838
 Reg. Date: 29/03/2018 (Man. Year: 2018) Chassis No: WWWZZAUZJW180226
 Colour: Silver Odometer: 1168 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	5,260.00	2,060.00	28.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,320.00	5,260.00	2,060.00	28.14
+ GST 7.00/7.00% (S\$)	512.40	368.20	144.20	28.14
Nett Amount (S\$)	7,832.40	5,628.20	2,204.20	28.14
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
Nett Liability (S\$)		6,108.20		

INSPECTION

Date of Assignment: 13/06/2018
 Date Inspected: 13/06/2018 Inspected At: Volkswagen Centre Singapore (HQ)
 247 Alexandra Road
 Singapore 159934
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,360.00	2,100.00
2	SPRAY PAINTING -RHR DOOR ,FENDER,BUMPER	New	3,200.00	2,400.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	CHECK WIRE HARNESS ,ECU ,S	New	280.00	280.00
Gross Labour Cost (S\$)			7,320.00	5,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >