

LXX
IDAC

PTE CASE OWNER:

SAUNA

CC 4, A19, 10438, Ah63 G

Surveyor:

AQUAN

DOI:

6/6/18

Date / Time:

6/6/18

Registered in Merimen:

7/6/18

Re-assign / CCU / FTE



Insured Vehicle No.:

SKZ 7931A

Name of Insured:

788 km AQUAN

Insured Tel No.:

HP: 9626338

Excess Sec II :SS

D.O.A: 6-6-18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

0083A96765G

Policy No.:

200450983

Make / Model:

CITROEN C4

Place of Accident:

BLK 7 PLE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L-YES / NO)

OI GIA REPORT: YES/NO : TP GIA REPORT: YES/NO

Insured Liability:

%

Final ? Yes / No

GZ 426 K

GIBS 2553 Z

SKZ 7931A

GV 9622 Y -> GX904



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP: Underly.

Tel:

Liability: 7P

RMKS:

Date/Time

13/6

W6

GV 9622 Y - NB (GZ 426 K) 13/6/18

SKZ 7931A - X

- ORIGINAL TP LOD IN

24/6/18 @ 4:45PM

SPOKE TO OI. HE CONFIRMED ACCIDENT DETAILS & WAS INVOLVED IN 5 VEH. C.C. & WAS THE 3RD CAR. INFORMED TP CLAIM & WCF, AGREED TO SETTLE & ACCEPTED LOSS. GROSS LOSSING & TOWING TO OI.

- MINUTED

- ORIGINAL TP LOD IN

14/06/19

TYPE REPORT FOR MANDATE APPROVAL

REPORT DONE

14/06/19

TP REPORT & ACCEPTED GIG 48K (C4 IN).

05/06/19

RECEIVED BY. AL. LOSS IN ORDER.

- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

24/6/18 - OK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others: GIGO FORM

PRELIMINARY ADVICE

Date/Time

Sent By:

FINALIZATION

Date/Time

Confirm with:

Confirm by:

Repair Cost:

L6

SS 6,800.00 (12 days) Reduction: 61 %

Email

Call

FINAL SETTLEMENT

Date/Time

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost: (w/est)

SS 6,958.00

(5 VEH. C.C.; OI 3RD)

Loss of Rental (LOR):

SS 1,000.00 (15 days) x \$100

Loss of Use (LOU):

SS - (5 x days)

Loss of Income (LOI):

SS - (5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost

SS -

Total:

SS 8,962.45

Global Sum SS:

8,000.00

FINAL PAYMENT

Date/Time

Confirm with:

Email

Call

Payee 1:

SS 8,000.00

Name 1:

UNITED SG AUTOMOBILE PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

-

Payee 3: (Strike if N.A.)

SS -

Name 3:

-

REF:

AGE REC BY: Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est Repairs:

12

days

Res:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GU 9622Y

Yr Regr: 2003, Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

c.c. 2986

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

450555

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LH1624008181

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 R14C

R:

185 R14C -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

06/06/18

Survey held at

United SG

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG

COE Expiry: 31/12/22

L/G \$6,500.00

MV: 33K

PV: 26.5K

Nett: 6.5K

CRAP: \$10,525.13 (41%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + TRC \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / LBJ: (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18010438/Aha3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-06-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 7931A	Veh. Inspected	GV 9622Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/06/2018	Inspection Date	06/06/2018	
Survey held at	United SG Automobile Pte Ltd			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4104K
Vehicle Details	
Vehicle No.:	GV9622Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DIESEL
Primary Colour:	White
Manufacturing Year:	2002
Engine No.:	5L5288574
Chassis No.:	LH1621008181
Maximum Power Output:	-
Open Market Value:	\$21,936.00
Original Registration Date:	14 Jan 2003
First Registration Date:	14 Jan 2003
Transfer Count:	3
Actual ARF Paid:	\$1,097.00
PARF Eligibility (COE Expiry > 31 Dec 2022)	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details (Vehicle > 3 years old)	
COE Expiry Date:	31 Dec 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$58,064.00
COE Rebate Amount:	\$26,503.00
Total Rebate Amount:	\$26,503.00

The information contained herein is correct as at 07 Jun 2018

OK

United SG Automobile Pte Ltd

"We are always in your journey"....

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

ESTIMATION QUOTE

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way

#08-16

Singapore 079120

ATTN: MOTOR CLAIMS DEPARTMENT

LH1621008181

Vic.

VEHICLE NO : GV9622Y

MAKE MODEL : TOYOTA HIACE

REFERENCE : USG-201806-10

DOA : 06-Jun-18

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT PANEL Distorted	1	\$ 1,335.20	✓ 1128
FRONT WINDSCREEN RUBBER New	1	\$ 307.50	✓
FRONT GRILLE Missing	1	\$ 396.15	✓
FRONT GRILLE LOGO	1	\$ 53.80	✓
FRONT BUMPER Deformed	1	\$ 482.44	✓
FRONT BUMPER BRACKET Bent	2	\$ 262.40	✓
FRONT BUMPER SIDE HOLDER New	1	\$ 138.60	✓
FRONT BUMPER INNER GARNISH	1	\$ 572.10	X
FRONT SIDE LAMP	2	\$ 262.90	X
FRONT HEADLAMP	2	\$ 534.70	X
FRONT HEADLAMP RIM cracked	2	\$ 62.30	✓
FRONT HEADLAMP INNER RIM New	2	\$ 127.10	X
HEADLAMP BASE PANEL	2	\$ 167.20	X
HORN	1	\$ 87.40	X
AIRCON BLOWER ASSY	1	\$ 985.60	X
AIRCON COOLING RESONATOR ASSY	1	\$ 1,817.10	X
DASHBOARD New	1	\$ 597.40	X
END PANEL Distorted	1	\$ 1,218.60	519
REAR BUMPER Deformed	1	\$ 508.10	✓
REAR BUMPER SIDE HOLDER New	2	\$ 133.80	✓
REAR BUMPER BEAM Bent	1	\$ 329.40	232
TAILLAMP R&L	2	\$ 616.40	248.30
TAILLAMP SEAL New	2	\$ 50.20	X
TAILLAMP PANEL Repair	2	\$ 281.68	X
TAILGATE Distorted	1	\$ 1,712.80	1248
TAILGATE GLASS RUBBER New	1	\$ 311.40	✓
TAILGATE EMBELM LOGO	1	\$ 61.00	✓
TAILGATE LOCK Damaged	1	\$ 313.70	230.10
TAILGATE LOCK CATCH Bent	1	\$ 146.00	48
TAILGATE HINGE New	2	\$ 178.00	X
TAILGATE RUBBER	1	\$ 381.00	✓

ESTIMATION QUOTE

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#08-16
Singapore 079120
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GV9622Y
MAKE MODEL : TOYOTA HIACE
REFERENCE : USG-201806-10
DOA : 06-Jun-18
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
TAILGATE DAMPER <i>3 New</i>	2	\$ 382.10	X
TAILGATE WEDGE CATCH <i>3 New</i>	2	\$ 86.10	X.

6749.84
less 25%: 5062.41

\$ 14,900.17
LESS 25% \$ 3,725.04
SUBTOTAL \$ 11,175.13
BALANCE C/F \$ 11,175.13

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
--------------------	-----	-----------------	---------

BALANCE B/F \$ 11,175.13

FRONT NUMBER PLATE <i>Bank</i>	1	\$ 60.00	30
FRONT BUMPER CLIP <i>new</i>	1 SET	\$ 50.00	30
FRONT GRILLE CLIP <i>new</i>	1 SET	\$ 50.00	20
REAR NUMBER PLATE <i>Bank</i>	1	\$ 60.00	30
REAR BUMPER CLIP <i>new</i>	1 SET	\$ 50.00	30
TAILGATE STICKER - 70KM/H <i>3 New</i>	1	\$ 30.00	15
TAILGATE STICKER - 7 PAX <i>3 New</i>	1	\$ 30.00	15
JOINT SEALANT <i>new</i>	1	\$ 150.00	60
WINDSCREEN SEALANT <i>new</i>	1	\$ 150.00	60

280.

SUBTOTAL \$ 630.00
BALANCE C/F \$ 11,805.13

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 11,805.13

CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM	1	\$ 80.00	60
REMOVE AND RENEW AIRCON BLOWER AND TOP UP GAS	2	\$ 200.00	120
REMOVE AND RENW COOLING COIL	3	\$ 200.00	80
REMOVE AND RENW FRONT DASHBOARD	4	\$ 500.00	220
REMOVE AND REFIT FRONT WINDSCREEN	5	\$ 150.00	120
REMOVE AND REFIT REAR WINDSCREEN	6	\$ 150.00	120
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	7	\$ 200.00	50
TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	8	\$ 200.00	80
PANEL BEATING ON AFFECTED AREAS	9	\$ 1,800.00	1600
SPRAY PAINTING ON AFFECTED AREAS	10	\$ 1,600.00	1000
APPLY ANTI RUST ON AFFECTED AREAS	11	\$ 150.00	60

3510

SUBTOTAL \$ 5,230.00

GRAND TOTAL \$ 17,035.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8862.41

L/S: 6.5K (Nett Value) ✓
12 Days

United SG Automobile Pte Ltd

"We are always in your journey"....

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934

Tel: 6747-4454 | Fax: 6747-7752 | Email: claims@unitedsg.com.sg

Register No: 201729521C | GST No: 201729521C

13th Sept 2018

Our reference: USG-201806-10

Your reference: SKZ7931A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 079120

Attn: Motor Claims Department

BY POST

Dear Sir/ Madam,

Claimant : KC PLUMBING ELECTRICAL & RENOVATION

Address : 30 KAKI BUKIT ROAD 3 #03-05 SINGAPORE 417819

We are instructed by the above named to claim damages against your insured/your insured's driver in connection with a road accident on 06 JUNE 2018 along BKE TOWARDS PIE BEFORE PIE CHANGU EXIT involving our client's vehicle registration number GV9622Y and vehicle registrations number SKZ7931A driven by you/your insured's driver at the material time.

The accident was caused by your insured negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Cost of Repair	:	\$6,955.00
Loss of Rental	:	\$1,800.00
LTA Search Fee	:	\$7.45
Total	:	<u>\$8,762.45</u>

A copy of each of the following supporting documents are enclosed:-

- | | |
|---|-----------------------------|
| a) Our client's Accident Report/Police Report | b) Certificate Of Insurance |
| c) Owner / Driver's IC & Driving License | d) LTA Search |
| e) Satisfaction | f) Letter Of Authorisation |
| g) Invoice | h) Rental Agreement |

The demand herein is in respect of our client's claim for damages pertaining to their motor vehicle and any settlement following or subsequent of this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to personal injuries.

Please send to us an acknowledgement of receipt of this letter with 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Yours faithfully



United SG Automobile Pte Ltd



S-26 Auto

Co. Reg No: 53343173E

Address: 31, Sunang Port Road,
404-27/28, Jurong Logistics
Hub, Singapore 619115
Tel: 6274 0030

TERMS AND CONDITIONS

S-26 AUTO

An agreement is made as per the day in the schedule between S-26 Auto (hereinafter called 'the owner') of the one part and the hirer named in the schedule hereto whose particulars and signature appear overleaf (hereinafter called 'the hirer') of the other part whereby it is agreed as follows :-

The owner will let and the hirer will take on hire, subject to terms and conditions hereinafter the motor vehicle described in the schedule here to (hereinafter call 'the vehicle'). Upon signing the agreement overleaf, the hirer shall agree to all terms and conditions stated on both sides of the agreement.

The hirer shall commence and expire on the date and time specified in the schedule.

The hirer acknowledges that the vehicle is the property of the owner and that the vehicle is without any visible defects and in perfect running condition. The hirer is under obligation to return the vehicle with all tyres, tools, accessories and equipment in as good order and condition as of what the vehicle was when collected by the hirer from the owner.

The hirer shall also pay rent in advance and the deposit specified in the agreement. The owner shall (without prejudice) be at liberty to retain out of such deposit :-

- a) The portion of any damage or loss which the hirer undertakes to be responsible regardless of the negligence as set out in this agreement.
- b) The amount of any loss or damage for which the hirer is responsible under the provisions of the clause of the front page hereof.
- c) Any other additional charges payable under clauses 7 and 8 hereof.
- d) All cost and expenses.

5. During the period of leasing, customer shall not drive vehicle into Malaysia, Thailand without prior notification and payment of additional charges to the company.

6. The use of the vehicle is strictly restricted to the Republic Of Singapore only, otherwise with the prior consent of the owner. Additional surcharge shall be paid before the hirer is allowed to drive the vehicle into West Malaysia. The hirer hereby indemnifies and keeps indemnifies the owner against all loss suffered by the owner including all loss from inability to use the vehicle in consequence of the vehicle passing out of the Republic of Singapore without prior consent of the owner.

7. During the hiring period, petrol is at the hirer's expense if the vehicle is delivered with a full tank of petrol, it must be returned likewise. In the event if the hirer is unable to fill up the vehicle, the owner will be authorised to do so in his name and at the hirer's account.

8. If there is any breach of terms and conditions herein by the hirer, including the payment of rental charges and others, the hirer shall pay for the full owner's legal cost, loss, damage, claims and expenses arising out of any damage to the said vehicle. In the event if the hirer fail to return the vehicle at the expiration of the period of rent then without prejudice to the other rights of the owner and the hirer shall pay to the owner to every hour elapsing between the time of such expiration and the time the vehicle is returned to the owner such further charge in accordance with the owner's current rate of rental charges or at such other rate as the owner may in its absolute discretion deem fit.

9. Should you decided to direct our bill charges to some other person, firm or organisation who fail to make any payment promptly when due, you will have to undertake the payment and pay accordingly to the company upon demand. All charges and amounts due hereunder which are not paid when due shall bear interest at 2% per month until they are paid.

10. As mentioned overleaf, hirer will have to pay for all fines, penalties, forfeitures and court costs imposed for any parking or traffic offences with respect to the vehicle during the period of leasing under this agreement. You will immediately report such violations to the company and will hold company harmless from all claims arising out of such violations.

11. If the vehicle is confiscated by the Government, the hirer shall compensate the company on all cost incurred including the value of the vehicle at the material time of confiscation.

12. The hirer shall agree to take proper care of the vehicle and drive the same in a careful and skilful manner observing the traffic regulations and laws. In the event of any breach thereof, the hirer shall pay all Police and Traffic Court Summonses, Notices and Inquires in connection therewith. Particular attention is to be accorded to the following factor :-



S-26 Auto

Co. Reg No: 53343173E

Address: 31, Jurong Port Road,
#04-27/28, Jurong Logistics
Hub, Singapore 619115
Tel: 6274 0030

TERMS AND CONDITIONS

- a) The hirer shall not carry load or passengers in excess of the motor vehicle's license carrying capacity of that particular make and model the hirer is leasing.
- b) The hirer shall not drive the vehicle whilst under the influence of intoxicating liquor or drugs.
- c) The hirer shall not leave the vehicle unattended while it is unlocked or while the keys are inside the vehicle.
- d) The hirer shall not deface the paintwork or bodywork of the vehicle nor add or erect any painting sign-writing.
- e) The hirer shall not use or permit the vehicle to be used for transportation of animals, creatures, plant or fruit which is or which contains properties which are unfit for carriage or which are improperly packed, inflammable, harmful, illegal, verminous, infested, contaminated, condemned or offensive smelling.
- f) The hirer must inform the owner of any serious faults, failures, mechanical issues or whatsoever so that the owner can rectify the problem. Otherwise should there be any losses, damaged and/or charges arise, the hirer will be liable.
- g) In case of any breakdowns, failures, accidents, or whatsoever occurs in Singapore or West Malaysia, the hirer must inform the owner immediately and/or its agent and the hirer is not allowed to engage any towing agents or motor workshops without the owner's written consent. Should the hirer engage any unauthorised workshop and/or agents, the hirer shall be liable to pay for the loss.

An authorised driver will immediately report any accident within 24 hours to the company at the location where the vehicle was rented and will also deliver to the company at that location, every summons, and complaint of paper of any kind received by authorised driver in any relating to any accident involving the vehicle while rented under this agreement. An authorised driver will not aid or encourage the filing of any claims as a result of any accident and cooperate fully with the company and its insurer in the investigation and defence of any claim or lawsuit. The hirer or driver must not admit to or compound any claim either partially or in full. It is important that they secure the names and address of all witnesses as well as the license number of any and all vehicles involved in the accident. In any case if the local police authorities have to be informed of any injuries with relates to the accident that happened in Malaysia, hirer are required to lodge a police report both in Malaysia and Singapore within 24 hours. All repairs must only be carried out by - Auto authorised workshop.

In the event that the vehicle or any part thereof is damaged or missing which includes all accessories and items, the hirer shall forthwith pay to the owner the excess amount payable in respect of each and every incident regardless of negligence. Arrangement may however be made at the request of the hirer to cover the vehicle with such a policy during the period of the hire, upon the hire having the current rate of premium as evidenced by his initials in 'accept' space provided on the overleaf.

- 15. The hirer and the registered additional driver are not insured under a policy of insurance against personal injury or death to themselves.
- 16. The owner is not obligated to provide any replacement vehicle if any accidents or breakdowns occur in Malaysia, whether or not the accident or breakdown is due to the negligence of the hirer, but however, if the owner chooses to provide any replacement vehicle for accident that occurred in Singapore, it will be at the hirer's expenses.
- 17. The person signing this agreement assumes the full personal responsibility along with the firm, person or organisation in whole name he/she might sign.
- 18. In the event of any disputes arising out of or in connection with this agreement, the parties here to, hereby and submit to the jurisdiction of the Courts of the Republic Of Singapore.

Employer
KC PLUMBING ELECTRICAL & RENOVATION

Sector: **CONSTRUCTION**



Name
CHINNAPPAN KUMAR
Occupation
CONSTRUCTION WORKER

Work Permit No.
0 34110018
Date of Application
30-04-2012
Date of Issue
26-04-2017
Date of Expiry
01-05-2019



L7873413

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **G8179685N**

CHINNAPPAN KUMAR

Birth Date: **15 Jun 1982**
Valid Date: **05 Aug 2015**
Valid Till: **07/09/2020**

0024583750

SG

VISI 1 PASS
Immigration Regulations

Name
CHINNAPPAN KUMAR



Date of Birth: 15-08-1982
Sex: M
Nationality: INDIAN
Date of Issue: 26-04-2017
Date of Expiry: 01-05-2019
FIR: G8179685N

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

EFFECTIVE DATE: 01-05-2019
Class 2B: Motorcycles up to 300 CC
Class 3: Motor cars up to 2000 kg with up to 7 passengers, exclusive of the driver, and motor tractors/vehicles up to 2500 kg

GR179685N

S / No. 9000253517



Licence No: GR179685N

NP 428A

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SI17V17764 /VCV /R02
Form	MZ300A
Date of Issue:	11-Dec-2017
1. Index Mark and Registration No. of Vehicle:	GV9622Y
2. Chassis number of Vehicle:	LH1621008181
3. Name of Policyholder:	KC PLUMBING ELECTRICAL & RENOVATION
4. Effective date of Commencement of Insurance for the purposes of the Act:	14-JAN-2018 00:00
5. Date of Expiry of Insurance:	13-JAN-2019 23:59
6. Persons or Classes of Persons entitled to drive*:	Any person who is driving on the Policyholder's order or with their permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.
7. Limitations as to use*:	A) Use in connection with the Policyholder's business. B) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. C) Use for social, domestic and pleasure purposes.
8. The Policy does not cover:	A) Use for hire or reward or for racing, pace-making, reliability trials or speed-testing. B) Use whilst drawing a trailer except the towing or any one disabled mechanically propelled vehicle.
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
<p>For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers</p>  <p>Authorised Signature</p>	

For information only:

COVERAGE:	Third Party Fire & Theft
SUM INSURED (\$\$):	MARKET VALUE AT THE TIME OF LOSS
EXCESS (\$\$):	Additional Excess - All Claims - Young, Elderly & Inexperienced Drivers \$3,000.00
FINANCE COMPANY:	HENLY ENTERPRISES CO PTE LTD
PRODUCER NAME:	NEW TIMES MOTOR & INSURANCE AGENCY P/L



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18010438/Aha3

24 OCTOBER 2018

**TEE KIM CHUAN
BLOCK 503 CHOA CHU KANG STREET 51
#11-157
SINGAPORE 680503**

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SKZ 7931A / GV 9622Y / OTHERS ON 06/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh
Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)
Jinquan14@yahoo.com.sg
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 24 October, 2018 4:26 PM
To: Jinqian14@yahoo.com.sg
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: SKZ 7931A_ACCIDENT INVOLVING SKZ 7931A / GV 9622Y / OTHERS ON 06/06/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18010438/Aha3

24 OCTOBER 2018

TEE KIM CHUAN
BLOCK 503 CHOA CHU KANG STREET 51
#11-157
SINGAPORE 680503

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SKZ 7931A / GV 9622Y / OTHERS ON 06/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Date 13 SEP 2018

Attn: Motor Claims Dept

ALG

Dear Sir/Mdm

ACCIDENT ON

INVOLVING VEHICLE NOS:

ALONG

06 June 2018

GV 96224

2

SLZ 7831A

BKE towards PIE before PIE Changi Expt

I/We the registered owner/driver of vehicle regn. no.
in the above accident with motor vehicle regn no.

GV 96224

SLZ 7831A

which was involved
insured by you.

I/We also hereby authorise that any payment due to me/us from the aforesaid claim be
paid to M/s UNITED SG AUTOMOBILE PTE LTD.

I/We hereby indemnify M/s United SG Automobile Pte Ltd against all claims and/or
damages which may arise from all action taken for and on my/our behalf.

I/We hereby affirmed that above-mentioned statement to be true and correct.

Yours faithfully





Owner Signature

(Company's stamp if applicable)

Name in Full : KC Plumbing Electrical & Renovation
NRIC No : S30441041
Address :

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **UNITED SG AUTOMOBILE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,000.00** (Global Sum – all in) for vehicle no. **GV 9622Y** that was damaged pursuant to the accident which occurred on **06/06/2018** (date) along **BKE TOWARDS PIE** (location) involving vehicle no/s **SKZ 7931A**. This is pursuant to the inspection conducted on **06/06/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **KC PLUMBING ELECTRICAL & RENOVATION** ("the third party claimant") of vehicle no. **GV 9622Y** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GV 9622Y** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of Mar (month) **2019** (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

my execution of this Discharge Voucher is solely
 for my claim for property damage and not for
 to any other claims arising from the same accident.

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934

Tel : 6747-4454 | Fax : 6747-7752 | Email: claims@unitedsg.com.sg

UEN No : 201729521C | GST No : 201729521C

TAX INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#08-16

SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPARTMENT

Invoice number

:

UI-1050

Date

:

13-Sep-18

Vehicle numner

:

GV9622Y

Make Model

:

TOYOTA HIACE

Accident date

:

06-Jun-18

Reference number

:

USG-201806-10

Description		Amount SGD\$
Inclusive of supplying parts, labour, panel beating and spray painting		
Lump Sum Repair		6500.00
GST @ 7%		455.00
	Total	6955.00

Singdollars: Six Thousand Nine Hundred and Fifty Five



UNITED SG AUTOMOBILE PTE LTD



S-26 Auto

Co. Reg No: 53343173E

Address: 21, Jurong Port Road,
#04-27/28, Jurong Logistics Hub,
Singapore 619115

Tel: 6274 0030

Vehicle No: Replacement No:

VEHICLE RENTAL AGREEMENT

GV96224 GBH 490C

HIRER'S PARTICULAR		<input type="radio"/> SAME AS HIRER DRIVER'S PARTICULAR	
Name: <i>LC Plumbing Electrical & Renovation</i>		Name: <i>Chinnappan Kumar</i>	
Address:		Address:	
I/C: <i>S304H10AL</i>		I/C: <i>G 817 9685N</i>	
D.O.B:		D.O.B: <i>15 June 1982</i>	
Contact:		Contact: <i>8348 7153</i>	
Pass Date:		Pass Date: <i>08 Sept 2010</i>	

	A - ACCIDENT	Hirer's acceptance
	C - CRACKED	
	D - DENTS	Driver's acceptance
	S - SCRATCHES	



RENTAL DETAILS					
Mileage Out		REMARKS	Mileage In		REMARKS
Date Out	<i>06/06/2018</i>		Date In	<i>21/06/2018</i>	
Time Out	<i>10:30am</i>		Time In	<i>1500</i>	
ASSIGNED BY			CHECKED BY		

RENTAL CHARGES				PETROL/ DIESEL LEVEL					
Daily	@ \$	<i>120</i>	<i>15</i> Days @ \$ <i>1800</i>	OUT	E	1/4	1/2	3/4	F
Weekly	@ \$		Wks @ \$						
Monthly	@ \$		Mth @ \$	IN	E	1/4	1/2	3/4	F
Hours	@ \$		Hrs @ \$						
*Inclusive of additional charges (if any)				Petrol Charges		YES	NO	AMT: _____	
Amt payable* \$ <i>1800</i>				CDW		YES	NO	AMT: _____	
Payment: <input type="radio"/> CASH <input type="radio"/> NETS <input type="radio"/> CHQ <input type="radio"/> VISA <input type="radio"/> MAST				Security Deposit		YES	NO	AMT: _____	
Bank/ Cheque No.:				Advance Payment		YES	NO	AMT: _____	

I/We have read and agree to the terms and conditions stated on this page and overleaf. I/We am/are also aware that should there be any parking and/or traffic offence committed during the leasing period when the vehicle is in my/our possession, we will be billed accordingly. Subsequently, our personal details may be tendered accordingly to the government parking and/or traffic offence department. With us undersigning below, I/We am/are sure that all information I/We have given to S-26 Auto in connection with this agreement are true and accurate.

IMPORTANT INFORMATION (To be go through by the personnel of S-26 Auto to the hirer and/or driver upon leasing of vehicle)

- > Only persons above 25 and below 60 years of age with 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
- > Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the company S-26 Auto.
- > Use of the vehicle for illegal purpose such as in connection with theft, drug peddling or trafficking, smuggling is strictly prohibited.
- > Additional drivers are required to register with us before they are allowed to drive the vehicle. Otherwise, he/she will not be protected by the insurance cover.
- > The hirer shall be liable for excess charges for any late return of the rate shown per hour or on a per day basis.
- > In case of any accident, the hirer MUST report to S-26 Auto immediately regardless of the seriousness of the impact occurred. If there are bodily injuries, a police report MUST be made within the next 24 hours.
- > In view of all accident, the hirer will bear the full responsibility for the SGD\$3,500/- excess payable to S-26 Auto and also the first SGD\$3,500/- excess for damaged to the third party vehicle.

ACKNOWLEDGEMENT	
 Signature of hirer / driver (company stamp if any)	 For and on behalf of S-26 AUTO (authorised signature only)

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 06 Jun 2018 / 12:41:19

Receipt Date/Time : 06 Jun 2018 / 12:41:18

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180606-001011

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKZ7931A				
As at 06 Jun 2018/08:40:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SKZ7931A			
	Enquiry Fee	7.00	0.49	7.49
	20180606124051621430			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx0343		Credit Card: Visa /MasterCard	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.


AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #08-16 Singapore 079120

Attention : Claims Department

AIG CLAIMS GIRO APPLICATION FORM**TYPE OF APPLICATION**

(Please tick one)



New Account



Amendment



Closed Account

Date of Submission

27 MAR 2019

Name of Vendor

UNITED SG AUTOMOBILE PTE LTD

Address of Vendor

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Name of Bank

DBS LIMITED

Bank A/c Number

003-955986-0

Bank Code

7171

Branch Code

003

Branch Address (Optional)

Company GST No.

201729521C

Name of Authoriser

LAURA LEE

Designation of Authoriser

DIRECTOR

Email Address

LAURA@TRADPROTRADING.COM

Contact Number

Office :

Mobile : 9119 1027

Company's Stamp /
Authoriser Signatory**FOR INTERNAL USE ONLY**

Vendor ID

Input Date

Prepared By

Prepared Date

Reviewed By

Reviewed Date

Approved By

Approved Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jun 2018 Edit Reg		06 Jun 2018 00:00 Edit Adj Rpt	S\$6,500.00 Edit Estimates	S\$6,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TEE KIM CHUAN , ID: S8109940E, Tel: +6596216338									
Main Claimant: KC PLUMBING ELECTRICAL & RENOVATION , Co. Reg. No.: 53044104K									
Vehicle Reg. No.: GV9622Y		Date of Loss: 06/06/2018 08:00 - :59 [184 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0118349675SG		Policy/Cover Note No.: 2100450983 (Comprehensive) Coverage: 03/02/2018 - 02/02/2019							
Vehicle Reg. No. (Insured): SKZ7931A		Policy No. (Claimant): SI17V17764/VCV/R02							
		Excess:							
Repairer: United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/06/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (11/06/2018): Non Coverage Policy AIG_SG (11/06/2018): No Policy Found 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GV9622Y (0118349675SG)
[SKZ7931A]

TP


















































KC PLUMBING ELECTRICAL & RENOVATION

Jun 6 2018 8:00AM

[TEE KIM CHUAN]

United SG Automobile Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1 Edit			
Photos/Images										3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
2	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
3	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
4	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
5	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
6	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
7	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
8	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
9	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
10	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
11	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
12	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
13	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
14	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
15	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
16	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
17	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
18	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
19	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
20	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
21	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
22	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
23	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
24	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
25	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
26	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
27	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
28	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
29	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
30	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
31	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
32	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
33	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	
34	07/03/19 17:18	General View						1 Load JPG		<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/03/19 17:18	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	07/03/19 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
84	07/03/19 17:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	07/03/19 17:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	07/03/19 17:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	07/03/19 17:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	07/03/19 17:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/06/18 19:50	ACKNOWLEDGEMENT EMAIL TO AIG DD 06.06.2018		Load PDF	
2	07/06/18 19:50	EMAIL FROM AIG DD 06.06.2018		Load PDF	
3	07/06/18 19:50	EMAIL FROM AIG DD 06.06.2018		Load PDF	
4	07/06/18 19:50	TP GIA REPORT		Load PDF	
5	24/10/18 16:30	EMAIL TO OI		Load PDF	
6	24/10/18 16:30	LETTER TO OI		Load PDF	
7	14/03/19 11:52	TP ESTIMATE - MARKED		Load PDF	
8	21/03/19 15:59	LTA SEARCH		Load PDF	
9	21/03/19 15:59	RENTAL RECEIPT		Load PDF	
10	09/04/19 14:04	WORKSHOP INVOICE		Load PDF	
11	09/04/19 14:04	AUTHORISATION TO ACT FORM		Load PDF	
12	09/04/19 14:04	Release Voucher		Load PDF	
13	09/04/19 14:04	GIRO FORM		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	12/06/18 09:04	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ7931A (Insd veh)	Model:	TOYOTA HIACE 3.0 (A)
	GV9622Y (TP veh)		
Date of Accident:	06/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	18,334.59
Final Repair Cost	:	\$	8,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	15 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	United SG Automobile Pte Ltd	:	\$ 8,000.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

09 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18010438/AHA3Q2

Date: 09/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100450983
 Claimant Vehicle No: GV9622Y Insured Vehicle No: SKZ7931A
 Date of Loss: 06/06/2018 Nature of Claim: TP Claim No: 0118349675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GV9622Y
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 5L5288574
 Reg. Date: 14/01/2003 (Man. Year: 2002) Chassis No: LH1621008181
 Colour: Blue Odometer: 450555 km
 Engine Capacity: 2986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14C Rear Tyre Size: 185 R14C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,805.13	5,352.42	6,452.71	54.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,330.00	3,510.00	1,820.00	34.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,135.13	8,862.42	8,272.71	48.28
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	17,135.13	6,500.00	10,635.13	62.07
+ GST 7.00/7.00% (S\$)	1,199.46	455.00	744.46	62.07
Nett Amount (S\$)	18,334.59	6,955.00	11,379.59	62.07
+ Car Rental (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,462.45		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 06/06/2018
 Date Inspected: 06/06/2018 Inspected At:

United SG Automobile Pte Ltd (HQ)
53 Ubi Avenue 1, #01-56 Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Distorted	1,335.20 FL	*1,128.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	307.50 FL	*307.50 FL
3	1		*FRONT GRILLE	Missing	396.15 FL	*396.15 FL
4	1		*FRONT GRILLE LOGO	Missing	53.80 FL	*53.80 FL
5	1		*FRONT BUMPER	Deformed	482.44 FL	*482.44 FL
6	2		*FRONT BUMPER BRACKET	Bent	262.40 FL	*262.40 FL
7	1		*FRONT BUMPER SIDE HOLDER	Necessary	138.60 FL	*138.60 FL
8	1		*FRONT BUMPER INNER GARNISH	Not Necessary	572.10 FL	*- FL
9	2		*FRONT SIDE LAMP	Not Necessary	262.90 FL	*- FL
10	2		*FRONT HEADLAMP	Not Necessary	534.70 FL	*- FL
11	1		*FRONT HEADLAMP RIM	Cracked	62.30 FL	*62.30 FL
12	2		*FRONT HEADLAMP INNER RIM	Not Necessary	127.10 FL	*- FL
13	2		*HEADLAMP BASE PANEL	Repair	167.20 FL	*- FL
14	1		*HORN	Not Necessary	87.40 FL	*- FL
15	1		*AIRCON BLOWE ASSY	Not Necessary	985.60 FL	*- FL
16	1		*AIRCON COOLING RESONATOR ASSY	Not Necessary	1,817.10 FL	*- FL
17	1		*DASHBOARD	Not Necessary	597.40 FL	*- FL
18	1		*END PANEL	Distorted	1,218.60 FL	*517.00 FL
19	1		*REAR BUMPER	Deformed	508.10 FL	*508.10 FL
20	2		*REAR BUMPER SIDE HOLDER	Necessary	133.80 FL	*133.80 FL
21	1		*REAR BUMPER BEAM	Bent	329.40 FL	*232.00 FL
22	1		*TAILLAMP	O/S Cut	616.40 FL	*248.30 FL
23	2		*TAILLAMP SEAL	Not Necessary	50.20 FL	*- FL
24	2		*TAILLAMP PANEL	Repair	281.68 FL	*- FL
25	1		*TAILGATE	Distorted	1,712.80 FL	*1,248.00 FL
26	1		*TAILGATE GLASS RUBBER	Necessary	311.40 FL	*311.40 FL
27	1		*TAILGATE EMBLEM LOGO	Necessary	61.00 FL	*61.00 FL
28	1		*TAILGATE LOCK	Damaged	313.70 FL	*230.10 FL
29	1		*TAILGATE LOCK CATCH	Bent	146.00 FL	*48.00 FL
30	2		*TAILGATE HINGE	Not Necessary	178.00 FL	*- FL
31	1		*TAILGATE RUBBER	Cut	381.00 FL	*381.00 FL
32	2		*TAILGATE DAMPER	Not Necessary	382.10 FL	*- FL
33	2		*TAILGATE WEDGE CATCH	Not Necessary	86.10 FL	*- FL
34	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*30.00 FS
35	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
36	1		*SET FRONT GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
37	1		*REAR NUMBER PLATE	Bent	60.00 FS	*30.00 FS
38	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
39	1		*TAILGATE STICKER -70KM/H	Necessary	30.00 FS	*15.00 FS
40	1		*TAILGATE STICKER -7PAX	Necessary	30.00 FS	*15.00 FS
41	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
42	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,530.17	7,039.89
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,725.04	1,687.47
Total Parts (\$\$)	11,805.13	5,352.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT ,REAR WIRING AND LIGHTING SYSTEM	New	80.00	60.00
2	REMOVE AND RENEW AIRCON BLOWER AND TOP UP GAS	New	200.00	120.00
3	REMOVE AND RENEW COOLING COIL	New	300.00	80.00
4	REMOVE AND RENEW FRONT DASHBOARD	New	500.00	220.00
5	REMOVE AND REFIT FRONT WINDSCREEN	New	150.00	120.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
7	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	50.00
8	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	80.00
9	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	1,600.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (S\$)			5,330.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >