

ASSIGNMENT

Veh No: SKC 2594 T Yr Regn: Jun / 2017

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Honda HRV c.c 1496

Colour	Red	A/C:	Insured / Std / NI / NA
--------	-----	------	-------------------------

Sp. Reading — T/Radio: Insured / Std / NI / NA

Eng/No: L15B4532266

C/No: JHMRU1810GX202266

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 215/60 R16

R: 215 / 60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/5/2018 D.O.I. 3/7/2018

Survey held at KAH MOTOR

Vehicle: IN / OUT

Date: Person Contacted:

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

☐: Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$) S + RS, S

Lump Sum / I.B.I: (\$)

☐ Interview (\$) Photos☐ : Tech. Invs (\$)) Others☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL