REF: CC3 /Ath 18010553/Atlon2

4 63433	CATALON A	B 77 PA T F B
1 2 2	6 - 1	DECEMBER 1
CM-2131	GNM	EAST VA

From: Date:	Veh No: SLX 7930B . Yr Regn: 2018 April
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: AdiQZ c.c 999
at Workshop m/s	Colour Red - A/C: Insured / Std / NI / NA
of	Sp.Reading 744 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WAUZZZGASJA068385
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: \$0 \[-	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 219/60R16
(Policy Condition)	R: 215 160 R16
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 130 K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. Ob mm R/Bal. Ob mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. do mm L/Bal. QU mm
Est Repairs: 05 1 days Res.: Yes or No	D.O.I. 08/06/18 ·
Lum Sum: % 3 Val.: Yes or No	Survey held at Polinium .
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	•
OP 416	
Part by Part \$6144.321,	(Red: 5576.68:47%)
/	
RECEIVED 2.7	SEP ZUID
V.N. 22-11	
	-
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5
1269 LYPST Final Report	Resurvey No. of Trip: Survey Fee: 200
Date/Time, File Return to?	
2) Add Fe	
(Ob)	: Interview (\$) Photos : Tech, Invs (\$) Others
Report Format:	: Tech Invs (\$) Others : Weekend (\$)
Lump Sum / LB) (3 6144-32	Total 210
	210

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Driving Experience

Mobile Number Fax Number Contact Number EMail Address

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	28/05/2018 14:27
Date Of Accident	27/05/2018 13:20
Exact Location Of Accident	ALONG GRANGE ROAD TO ORCHARD LINK
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLX7930B
Insured/Policyholder	
Name Of Registered Owner	ANG PENG KA
NRIC No	S1327269G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98426998
Alternative Phone No	OTHERS-98426998
Vehicle Particulars	
Manufacturer	AUDI
Model	Q2 1.0 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800037232
Cover Note Number	
Driver	
Name of Driver	ANG YI RUI TRICIA
NRIC No	S9006567Z
Date Of Birth	05/02/1990
Occupation	INDOOR
Date Of Driving Pass	05/06/2009

8 YEARS AND 11 MONTHS

(LOCAL) +65-97916882

TRICIAANG@GMAIL.COM

FEMALE

85 PASIR RIS GROVE

dress #08-08

Postcode 518212

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured C

Vehicle Registration Number of Driver's Own

Vehicle

...

Address

CHILDREN

Insurance Company of Driver's Own Vehicle

-

institution company of Different Comments

2

General Information of the Accident

Type Of Accident COLLIDED INTO MOTORCYCLIST

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO 2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: FLORENCE LEE

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

TEL NO: 65470000 - FAX NO:

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

Police Station Address SINGAPORE

Police Station Contact

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO:T/20180528/2021

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

Details of Witness 1

Name ZHENG XIN HUI
Phone Number 90250224

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM7971J

Vehicle Make/Model/Colour HONDA / CB190X MANUAL / WHITE

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

day.

Postcode

Insurance Company Name

AXA INSURANCE PTE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBM7971J

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1 ..

- Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance.
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

loob

Policyholder's Signature Date & Time Driver's Signature (if driver is not the policyholder) Date & Time: 23 MDJ 2018

12 - 40 pm

CALL TO SOLUTION OF THE PARTY O

Reporting Centre Personnel's Signature Name: Tony Foory

NRIC/FIN No.: Gr2048197K

Sketch Plan #2

SKETCH PLAN		
	Orchard Link	
	ntenord mun	
		1
		1
-3 - 7 -	-10-10	
	-	7
A	1	3
-		
2/	/	7
13th A.	/	
65/	7.71/	
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
DI	n / 1 h 1	h
1998	Refer to Pol	ice Keport
	The state of the s	Poll
Morto	0180528/2021	
100.12	010052012021	
	_/	
	/	
	/	
DECLARATION	COMPANIES CONTRACTOR CONTRACTOR	
I/We declare the foregoing partic	ulars are true in every respect.	(S) (\$ 1)
	and the	(m) (m)
Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time:	(If driver is not the policyholder)	Name Take Line
	Date & Time: 2% May 2018 (2.40)%1	NRIC/FIN NO GOODS

Page 5 of 19

Police Report

Vide Report No.:

E/20160527/0125





Police Station Of Origin: Traftic Police Division HQ 10 Ubi Averue 3.9 NGAPOHE 408885 1 of 4 Deport No. 1/20160586/9:21

Station Dinry No.:

10 Uti Averue 3 S NGAPOHE 408 Te No: 65470000

Date/Lime Report Marks:

28/05/2018 11:42

Name of Ir ANG YER		iai b	65 P	rses: MSIA PIS GI	HOVE #08-0	5 NV PESIL)E	NOES			
ID Type / II NRIC NO /		77	Can	SINGAPORE (18212 Contact No.: HomeyOffice: Mobile: 97916862							
Nationality SINGAPOI			Enri			manna, y	(9)	10002			
Sex. Female	Aga: 28	Date of Birth: 05/02/1990	Type	of Informan	1:						
Pape: Chinese		Wat 11 11 11 11 11 11 11 11 11 11 11 11 11		luage:	Institution / School Name						
Occupation BANK OFF			Crivi	ng Licence Ir s: 3/\	oformation:	Date of E	xpl:	y:			
General Inf	ormation	of the Accident									
Type of Acadent:	In	ury :nveyed By Amb		Drink Drive: No	Date/Tin Acciden			Type of Location			
Location: Along Roar ORCHARD											
Weather: Gear	111		Road	Surface:		R	bad	Speed Umit:			
fratfic Flow One Way	5		Traffi	ie Control: ie Light - War	king		affi sav	c Volume: v			
Type of Col Between M		ldes - Side Swip	s - San	ne Direction		2511	ryc nau es	ne conveyed by lance:			
Details of \	/ehicle in	volved		1.05	12014						
Vehicle No.	Type	Marte		Model	Color	Conde	lan	No of Passenger			
FBM7971J		role HONDA		CB190X MANUAL	White		D				
SLX7930B	Car	AUD		02 TFSLS TRONIC	Red			g			
Details of P Any Pedesh No. of Pade	rien involv	ed; No		Time	ol Padestria:	. Conseler 1					

PUBLIC OF SINGAPORE ENTITY CARD NO. \$9006567Z



ANG YI RUI TRICIA





Rece

CHINESE

Date of birth 05-02-1990

Country/Place of birth SINGAPORE

\$9006567Z

REPUBLIC OF SINGAPORE DRIVING LICENCE



S9006567Z

ANG YI RUI TRICIA

Ber Date: 05 Feb 1990

ue Date: 18 Nov 2017 002744797J

5790308





25-08-2017

85 PASIR RIS GROVE #08-08 SINGAPORE 518212

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A

Motor cars without clutch pedals (Auto) with unladen 05 Jun 2009 weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight =< 2500kg

NP 428A





COVER NOTE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Cover Note is hereby HELD COVERED on the terms and conditions of the policy, issued to the Policyholder.

Name of Polito Holder Period of Insurance

: ANG PENG KA V

: 11 Apr 2018 to 10 Apr 2019

Engine No. : CHZ 418334 V Chasis No.

: WAUZZZGA5JA065385

Vehicle No.

Cover Note No.

Endorsement No.

Issued Date

SLX 7930B

: 09 Apr 2018

ABOUT THE COVER

Make/Model

: AUDI Q2/ Q2 Sport 1.0 TFSI S tronic 1.

Engine Capacity/Tonnage: 999.00 CC V

Sum Insured : Market Value

First Year of Registration : 2018 V

Insuring with COE/PARF : Yes

Driver Restriction : NA Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

a) the Policyholser b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if ha/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young antifor Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Oriver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Off Peak Car : No V

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business,
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

ANG PENG KA - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubl Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

78 Shienion Way #07-16 AIG Building S078120 | T-+65 6418 3000 | F-+65 6415 3723 | www.sig.com.sg

If you do not receive your Certificate of insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.

If you do not receive your Certificate of insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.

If you do not receive your Certificate of insurance and policy documents within 30 days from the Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malassiya) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malassia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

SING

0504125261

PREMIUM LEASING -CYS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte, Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

AlG Asia Pacific Insurance Pte. Ltd.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop Contact No Ubi Road 1 6366 2323

Fax No

6841 1183

Reference

PA/TP/0635/2018/GW

Date

30-May-18

Vehicle not IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811 A16.

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name

: Mr. Ang Peng Ka

Address

85 Pasir Ris Grove

#08-08

Singapore 518212

Telephone

HP +65 98426998

Type of Claim

Own Damage Claims

Policy No.

1800037232

Vehicle No

SLX 7930 B

Model Code

Audi Q2 1.0 TFSI S- Tronic

Model / Year

: Apr-18

Engine No

CHZ 418334

Chassis No

: WAUZZZGA5JA065385

Mileage

:

Date In

**

Liability

.

Excess Cost

: -

Estimated By

Johnny Boo / Allan Wu

Accident Date

27-May-18

Place of Accident

Along Grange Road To Orchard Link

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7930 B.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlihght washer assy.	S/N	\$ 360.00	/ /
2	To dismantle and renew front bumper and lhs front fender. Re-organise front crash management components, reinstall all parts removed.		\$ 2,100.00	1000 .
3	To respray front bumper, lhs front fender , front lh door and front lh wind mirror cover.		\$ 3,000.00	1800.
4	To renew lhs front rim and carry out wheel alignment.	S/N	\$ 280.00	/ /
5	To remove and transfer lhs front door's multi- lock system and power window devices.	5/N	\$ 280.00	× ×
6	To carry out diagnostic check.	S/N	\$ 192.00	1.1
	TOTAL LABOUR CHARGES	:	\$ 6,212.00	•

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7930 B.

. 2:	2 7 70		Parts & Prices	
S/N	Parts Description	_	S/Nett	Remark
1	FRONT BUMPRER Payer	\$	1,620.00	X
2	FRONT BUMPER AIR GUIDE GRILLE-LH	S	145.00	¥
3	FRONT ADAPTER-LH	Ş	31.00	×
4	FRONT BUMPER SPOILER Lut	\$	259.00	207.20
5	FRONT WHEEL COVER-LH/RH ALL	2 5	558.00	
6	FRONT FENDER-LH Detect	5	1,011.00	V 808.80
7	FENDER ATTACHMENT PARTS Not Nec	5	34.00	7
7	FRONT FENDER BRACKET-LH 2	2 \$	52.00	K
9	FRONT FENDER BRACE-LH	5	28.00	<
10	FRONT WHEEL HOUSING LINER-LH	9	175.00	V
11	WHEEL HOUSING LINER ATTACHMENT PARTS	9	49.00	×
12	FRONT ALUMINIUM RIM-LH	9	633.00	V 506.40
13	RUBBER VALVE ALC	5 5	14.00	+
14	FRONT DOOR COVER - LH at	5	350.00	180.40
15	SUNDRIES Rec.	9	200.00	? 1392
	SPARE PARTS :		5,159.00	
	LABOUR CHARGES :	9	6,212.00	
	GRAND TOTAL :	-	\$ 11,371.00	
		_		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Anthrosed Repairs, ospays

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs Ubi Road 1

Workshop Contact No Fax No

6366 2323

6841 1183

Reference

PA/OD/0635/2018/GW

Date

30-May-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Hi Adrian

5 days - ok - jb - 13 Aug 18

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name

Mr. Ang Peng Ka

Address

85 Pasir Ris Grove

#08-08

Singapore 518212 HP +65 98426998

Telephone

Own Damage Claims

Type of Claim

Policy No.

1800037232

Vehicle No

SLX 7930 B

Model Code

Audi Q2 1.0 TFSI S- Tronic

Model / Year

Apr-18

Engine No

CHZ 418334

Chassis No

WAUZZZGA5JA065385

Mileage

Date In

Liability

Excess Cost

Estimated By

Johnny Boo / Allan Wu

Accident Date

27-May-18

Place of Accident

Along Grange Road To Orchard Link

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7930 B.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation			
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$	360.00
2	To dismantle and renew front bumper and lhs front fender. Re-organise front crash management components, reinstall all parts removed.		\$	2,100.00	s	1,000.00
3	To respray front bumper, lhs front fender , front lh door and front lh wind mirror cover.		\$	3,000.00	s	1,800.00
4	To renew lhs front rim and carry out wheel alignment.	S/N	\$	280.00	\$	280.00
5	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N	\$	280.00		
6	Supplementary		\$	350.00	\$	350.00
7	To carry out diagnostic check.	S/N	\$	192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$	6,562.00	\$	3,982.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7930 B.

			Damaged Pa	rts &	Prices
S/N	Parts Description		S/Nett	F	Remark
1	FRONT BUMPRER		\$ 1,620.00		
2	FRONT BUMPER AIR GUIDE GRILLE-LH		\$ 145.00		
3	FRONT ADAPTER-LH		\$ 31.00		
4	FRONT BUMPER SPOILER		\$ 259.00	\$	207.20
5	FRONT WHEEL COVER-LH/RH	2	\$ 558.00	\$	445.60
6	FRONT FENDER-LH		\$ 1,011.00	\$	808.80
7	FENDER ATTACHMENT PARTS		\$ 34.00		
7	FRONT FENDER BRACKET-LH	2	\$ 52.00		
9	FRONT FENDER BRACE-LH		\$ 28.00		
10	FRONT WHEEL HOUSING LINER-LH		\$ 175.00		
11	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 49.00		
12	FRONT ALUMINIUM RIM-LH		\$ 633.00	\$	506.40
13	RUBBER VALVE	5	\$ 14.00		
14	FRONT DOOR COVER - LH		\$ 350.00	\$	180.40
15	SUNDRIES		\$ 200.00	\$	13.92
	SPARE PARTS		\$ 5,159.00	\$	2,162.32
	LABOUR CHARGES		\$ 6,562.00	\$	3,982.00
	GRAND TOTAL		\$ 11,721.00	\$	6,144.32
	(2) (2) (3) (3) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4				

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Surveyed Date : Authorised Date :

Liability :

Remarks :

Please Note

Excess Cost

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date 2-Jul-18 Service Advisor Tony Foong

Pages Regn No

SLX 7930 B

PA/OD/0635/2018/GW

Model No Audi Q2 1.0 TFSI S- Tronic

Quantity	Description		it Price	A	mount
LABORS					
1	To remove and reinstall lhs front door panel trims, dismantle lhs wing mirror assy. (S/N)	\$	350.00	\$	350.00
	TOTAL	\$	350.00	\$	350.00

For Premium Automobiles Pte Ltd

Authorised Signature

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SLX 7930 B Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg

Body & Paint Dept PA/OD/0635/2018/MAS

22 Sept 2018

from

Telephone +65-

Telefax +65-

EMail

Our department

Our Ref

Your Ref

Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLX 7930 B, Audi Q2 1.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no SLX 7930 B, claimant, Mr. Ang Peng Ka, please find the related document per attached.

- A copy of the Original invoice no. 85012938 S\$6,574.42
- A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SLX 7930 B

total pages

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	02 Jun 2018		11 Jun 2018 10:57 Edit Adj Rpt	S\$6,144.32 Edit Estimates	S\$6,144.32 View Rpt		Report Cancel 6	For Survey	
	Main	Ref	erence	Claim Det	ails	Documents		Show All	
CLAIM S	UBFOLDER DE			SAME TO SAME T		[Create	d by insure	er]	
Insured:		ANG PE	NG KA, ID: S13	27269G		Lange			
Vehicle Re	eg. No.:	SLX79	30В	Date of L	oss:	[1 Month)18 13:00 - is and 16 Da ! (Man Yr)]	:59 iys From LTA	
Claim Typ	e:	OD / 0	OD / 0248029000SG		/Cover Note No.: 1800037232 (Comprehensive) /Cover Note No.: Coverage: 11/04/2018 - 10/04/2019				
				Excess:		S\$0.00)		
Repairer:		Premiu	m Automobiles F	te Ltd (UBI) 55 U	bi Road 1, 408699 I	Jbi - Tel: 676898	28/9827/99	11	
Handling	29:000 C/N (1/0)	AIG As Tinesh.	a Pacific Insura r@aig.com	nce Pte. Ltd. (SG)	- Tel: 65-6419-300	0 [Handled by	Tr, Tinesh	N-	
Adjuster:		due 21	/06/2018]	te Ltd (HQ) - Tel:			LING] [I	Final Rpt	
Driver/Cu	stodian:	ANG YI	RUI TRICIA (28 / I	Female), NRIC: S9	9006567Z, Tel: +	6597916882			
ASSOCI	ATED MAIL RE	CEIVED				View All	Compose	Case Mail	
AIG_S	G (12/06/2018):	SLX7930B / OD	/ 27/05/2018 /	Coverage & Exces	ss update				
ALL ASS	SOCIATED TAS	KS		View	All Search Tas	ks Create	New Task	Complete	
Due Da		Type Task G	roup Subject	Handler As	signed By Co	mpleted On	Created (On Done?	


Claim Documents

*SLX7930B (0248029000SG) OD May 27 2018 1:00PM [ANG PENG KA] Premium Automobiles Pte Ltd

Vide	90		1 per	page *	7
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	19/07/18 13:40	video- rear	0	Load MP4	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/05/18 14:45	Video - Accident [Linked Accident Report Documents]	0	Load MP4	
Pho	tos/Images		3 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/09/18 18:26	General View	0	Load JPG	7
2	11/09/18 18:26	General View	0	Load JPG	V
3	11/09/18 18:26	General View	0	Load JPG	V
4	11/09/18 18:26	General View	0	Load JPG	V
5	11/09/18 18:26	General View	0	Load JPG	V
6	11/09/18 18:26	General View	0	Load JPG	V
7	11/09/18 18:26	General View	0	Load JPG	V
8	11/09/18 18:26	General View	0	Load JPG	V
9	11/09/18 18:26	General View	0	Load JPG	V
10	11/09/18 18:26	General View	0	Load JPG	V
11	11/09/18 18:26	General View	0	Load JPG	V
12	11/09/18 18:26	General View	0	Load JPG	V
13	11/09/18 18:26	General View	0	Load JPG	V
	11/09/18 18:26	General View	0	Load JPG	V
14		General View	0	Load JPG	V
15	11/09/18 18:26		0	Load JPG	V
16	11/09/18 18:26	General View	0	Load JPG	(V)
17	11/09/18 18:26	General View	0	Load JPG	(V)
18	11/09/18 18:26	General View		0.0000000000000000000000000000000000000	-
19	11/09/18 18:26	General View	0	Load JPG	V
20	11/09/18 18:26	General View	0	Load JPG	
21	11/09/18 18:26	General View	0	Load JPG	V
22	11/09/18 18:26	General View	0	Load JPG	V
23	11/09/18 18:26	General View	0	Load JPG	[2]
24	11/09/18 18:26	General View	0	Load JPG	V
Do	cumentation		1 per	page •	Report.
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnai	
1	11/06/18 15:10	Singapore Accident Statement	0		-
2	11/06/18 15:10	CERTIFICATE OF INSURANCE & DRIVER'S DRIVING LICENSE	0		
3	11/06/18 15:10	ESTIMATE	0		-
4	02/10/18 10:22	WORKSHOP INVOICE	0		
5	02/10/18 10:22 02/10/18 10:23	DISCHARGE VOUCHER Suplementary	ő	The second second	-

Linked Accident Report Documents

			View	View Use Viewer	
Video			1 per pa	ge 🕶	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1	Thumbnail	Print
1	28/05/18 14:45	Video - Accident	0	Load MP4	



Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG18010553/ATBN2

Date:

02/10/2018

REFERENCE

Insured/Claimant: Date of Loss:

ANG PENG KA 27/05/2018

Policy No: Nature of Claim: 1800037232

OD

Claim No:

0248029000SG

WAUZZZGA5JA065385

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLX7930B

Make & Model:

AUDI Q2, 999cc TFSI S-TRONIC (A) 11/04/2018 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

CHZ418334

944 km

Reg. Date: Colour:

Red

999 cc

Engine Capacity: Market Value/New Car

Price:

S\$130,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 5,159.00 0.00	Adjuster's 2,162.32 0.00	Difference 2,996.68 0.00	Diff % 58.09
Labour Paintwork Labour	6,562.00 0.00	3,982.00 0.00	2,580.00 0.00	39.32
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,721.00	6,144.32	5,576.68	47.58
+ GST 7.00/7.00% (S\$)	820.47	430.10	390.37	47.58
Nett Amount (S\$)	12,541.47	6,574.42	5,967.05	47.58

INSPECTION

Date of Assignment:

11/06/2018

Date Inspected:

08/06/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

-			PROPERTY AND INCOME.	-
\Box	acam	man	hah	Parts
	CCOIL		ueu	allo

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*FRONT BUMPER	Repair	1,620.00 FS	*-FS
2	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	145.00 FS	*-FS
3	1		*FRONT ADAPTER-LH	Not Necessary	31.00 FS	*-FS
4	1		*FRONT BUMPER SPOILER	Cut	259.00 FS	*207.20 FS
5	2		*FRONT WHEEL COVER-LH/RH	Necessary	558.00 FS	*445.60 FS
6	1		*FRONT FENDER-LH	Dented	1,011.00 FS	*808.80FS
7	1		*FENDER ATTACHMENT PARTS	Not Necessary	34.00 FS	*- FS
8	2		*FRONT FENDER BRACKET-LH	Not Necessary	52.00 FS	*-FS
9	1		*FRONT FENDER BRACE-LH	Not Necessary	28.00 FS	*-FS
10	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	175.00 FS	*- FS
11	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	49.00 FS	*-FS
12	1		*FRONT ALUMINIUM RIM-LH	Cut	633.00 FS	*506.40 FS
13	5		*RUBBER VALVE	Not Necessary	14.00 FS	*-FS
14	1		*FRONT DOOR COVER-LH	Cut	350.00 FS	*180.40 FS
15	1		*SUNDRIES	Necessary	200.00 FS	*13.92 FS
F=Fr	anchise	part. S=Spcl	Nett.			- CHANGE STORY
				Total Parts (S\$)	5,159.00	2,162.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, FRONT LH DOOR AND FRONT LH WIND MIRROR COVER	New	3,000.00	1,800.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	13.5
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIMS, DISMANTLE LHS WING MIRROR ASSY	New	350.00	350.00
	Gross Labour	Cost (S\$)	6,562.00	3,982.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >