

ASS. REC. BY:

REF: CS/AGL18010556/Urb⁰²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Julie of AGI Date/Time: 11.06.2018 1059am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 9434S Insured: SKM 5383 M

at Workshop m/s Pegasus Tel: 6513 7748

of 74 Kiam Tek Rd

Policy No: Claim No: C10001649 / JM

Sum Insured: Excess:

Make of Veh: D.O.A. 04062018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI' H.O.D. Endorsement:

Date/Time: 11.06.2018 11:19am Person Contacted: Alvin Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 9434S - X
	SKM 5383M - (CG/Asm/7012955/Kpl332) DCA: 29062017

(08/1/13) waf

ASS. REC. BY: Mercus

REF:

Ala. 1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD: / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL9434S

at Workshop nms Perkasus

of _____

Insured: SKM 5383M

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

ID No. Accident Report: _____ Consistent?: Yes or No

QA / PR Seen: 4 Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLL9434S Yr Reg: 3.17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Private Motor /

Truck / Trailer or CA

Make: Toyota Vios cc 1496

Colour: Grey A/C: Insured / Std / Nil / No

Sp. Reading: 75499 T/Radio: Insured / Std / Nil / NA

Eng/No: 75499

C/No: MHF029F3802007411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R: _____

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/6/18 D.O.I. 3/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 49541

20/7/18 confirmed 1/5 \$1200 with willian.

Ref: 86991.63, 851.

RECEIVED 20 JUL 2018

Date/Time, File Pass to?

: Prelim. Report

Days Of Repair: 3

1) typist

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) _____

Add Fee: : Site Insp (\$ _____)) \$ < RS < SI

Transportation:

Report Format: TP

: Interview (\$ _____))

Photos

Lump Sum / t.B.: (\$ 1200)

: Tech. Invs (\$ _____))

Others

: Weekend (\$ _____))

TOTAL

250

Catherine Chong (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Monday, 11 June, 2018 10:59 AM
To: 'SUR'; 'assignments'
Subject: FW: Third party survey SLL9434S Your insured SKM5383M on 04.06.2018 | Our ref: C10001649/JM
Attachments: SLL9343S-TP.pdf

Hi Team

Please accept TPPD survey and survey on a without prejudice basis.
Workshop is asking for Mohamad Taufihk LKK Auto Consultants Pte Ltd

Thank you,
-Julie

From: Pegasus Engineering <claims@pegasusengrg.com.sg>
Sent: Monday, 11 June, 2018 9:35 AM
To: Claims <claims@budgetdirect.com.sg>
Subject: Re: Third party survey SLL9434S Your insured SKM5383M on 04.06.2018

Without Prejudice

Dear Sir/Mdm,

We would like to choose Mohamad Taufihk LKK Auto Consultants Pte Ltd to survey the vehicle.

Besides, we would like to attach video footage for your reference, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Thanks & Regards,

Alvin Low
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road
Singapore
628800

Tel
:
6513 7748

Fax :
6251 3161

Email : claims@pegasusengrg.com.sg

On Wed, Jun 6, 2018 at 3:21 PM, Claims <claims@budgetdirect.com.sg> wrote:

Our Ref: C10001649

Without Prejudice

Dear Alvin,

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, attached is the list of my 10 surveyors for your selection.


Please find the list of our surveyors to choose from.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Mohammed Rasul LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Simon Ho LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Chow Bo Xiong FormTeam Adjusters Pte Ltd

With regards to your confirmation of liability, we regret to inform you that we are of the opinion that the accident caused was not by the negligence of our insured.

Attached (evidence) from video of your client turning from another lane and cutting into our insured lane.

(Purely for your perusal & not to be circulated)



Warmest Regards,

Lincoln Yeo

Manager, Claims

T +65 6540 2180

F +65 6725 0853 (Claims)

M +65 8382 8999

E lincoln.yeo@budgetdirect.com.sg

Budget Direct insurance

Customer Care +65 6221 2111

Claims +65 6221 2199

Claims (Int.) +65 6540 2199

190 Clemenceau Avenue

#03-01, Singapore Shopping Centre

Singapore 239924

budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

From: Pegasus Engineering <claims@pegasusengrg.com.sg>

Sent: Wednesday, 6 June 2018 2:37 PM

To: Claims <claims@budgetdirect.com.sg>

Subject: Third party survey SLL9434S Your insured SKM5383M on 04.06.2018

Your Ref: SKM5383M

Our Ref: SLL9434S

DOA: 04.06.2018

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have **a list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

The vehicle currently not in our premise.

Thanks & Regards,

Alvin Low
Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road

Singapore

628800

Tel

:

6513 7748

Fax :

6251 3161

Email : claims@pegasusengrg.com.sg

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It

may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 7200G

Vehicle Details

Vehicle No.: SLL9434S
Vehicle to be Exported: Yes
Intended De-registration Date: 05 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5E CVT
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: 2NRX130038
Chassis No.: MHFB29F3802007411
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$12,946.00
Original Registration Date: 16 Mar 2017
First Registration Date: 16 Mar 2017
Transfer Count: 0
Actual ARF Paid: \$7,946.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Mar 2027
PARF Rebate Amount: \$5,959.00

Intended COE Rebate Details

COE Expiry Date: 15 Mar 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,101.00
COE Rebate Amount: \$40,080.00
Total Rebate Amount: \$46,039.00

The information contained herein is correct as at 05 Jun 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLL9434S
Vehicle to be Exported:	No
Intended De-registration Date:	03 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2NRX130038
Chassis No.:	MHFB29F3802007411
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,946.00
Original Registration Date:	16 Mar 2017
First Registration Date:	16 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$7,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2027
PARF Rebate Amount:	\$5,959.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$43,582.00
Total Rebate Amount:	\$49,541.00

The information contained herein is correct as at 03 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 14:35
Date Of Accident	04/06/2018 19:15
Exact Location Of Accident	ALONG GUILLEMARD RD IN FRONT OF CITY PLAZA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL9434S
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS 1.5E CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	
Driver	
Name of Driver	WOON SONG KHOON
NRIC No	S1604105Z
Date Of Birth	14/11/1963
Occupation	OUTDOOR
Date Of Driving Pass	21/09/1981
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98122888
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address NIL
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PASSENGER 1
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG GUILLEMARD RD TO CITY PLAZA AND I WAS DRIVING AT THE LEFT LANE. I SAW VEHICLE B COME DOWN FROM THE MSCP RAMP, SHE STOP STATIONARY SO I GO STRAIGHT. AUDDENLY I FELT AN IMPACT ON REAR. VEHICLE B COLLIDED ONTO MY CAR. THE DAMAGED WAS AT THE REAR LEFTMPORTION. WE MANAGED TO TOOK PHOTO AND EXCHANGED PARTICULARS. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: RETRIEVING
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKM5383M
 Vehicle Make/Model/Colour B.M.W./428i A/WHITE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver MAGGIE
 NRIC/Passport Number
 Contact Number 81285505
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Handwritten Signature]


VERIFIED BY AJAX MARS
 REPORTING OFFICER
 THOMAS NG CHIN CHUN

Policyholder's Signature / Date & Time

Driver's Signature (if Driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG GUILLEMARD RD TO CITY PLAZA AND I WAS DRIVING AT THE LEFT LANE. I SAW VEHICLE B COME DOWN FROM THE MSCP RAMP, SHE STOP STATIONARY SO I GO STRAIGHT. AUDDENLY I FELT AN IMPACT ON REAR. VEHICLE B COLLIDED ONTO MY CAR. THE DAMAGED WAS AT THE REAR LEFT PORTION. WE MANAGED TO TOOK PHOTO AND EXCHANGED PARTICULARS. NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
NG CHIN CHUN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

not allowed
inher
3/7/18
the photo attached
2/s #1200
3 day.

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

*Uk - Marcus,
03/07/2018 @ 10:00h*

Quotation No : QO18/06-1054	Quotation Date : 06/06/2018	Terms : 30 DAYS
Vehicle No : SLL9434S	Chassis No : MHFB29F3802007411	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SKM5383M, DOA: 04.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
1	REAR BUMPER <i>Deep cut</i>	1	504.9000	504.90	✓
2	N/S REAR BUMPER REFLECTOR <i>11</i>	1	130.5000	130.50	X
3	REAR BUMPER SIDE RETAINER <i>11</i>	2	116.3000	232.60	X
4	REAR BUMPER SIDE HOLDER <i>11</i>	2	22.3000	44.60	X
5	REAR BUMPER CLIP <i>12</i>	12	5.0000	60.00	✓
6	N/S REAR FENDER <i>2</i>	1	969.7000	969.70	X
7	N/S REAR FENDER AIR VENT <i>11</i>	1	45.1000	45.10	X
8	REAR FENDER TOP 1/4 GARNISH <i>11</i>	1	54.7000	54.70	X
9	N/S REAR LAMP <i>11</i>	1	375.8000	375.80	X
10	REAR LAMP CLIP HOLDER <i>11</i>	3	5.0000	15.00	X
11	N/S REAR SHOCK ABSORBER <i>11</i>	1	100.7000	100.70	X
12	REAR WHEEL BEARING WITH HUB <i>11</i>	2	714.2000	1,428.40	X
13	REAR AXLE BEAM ASSY <i>11</i>	1	2,413.5000	2,413.50	X
14	LESS 25% ITEM (1-13)	1	-1,593.8750	-1,593.87	
15	REAR WINDSHIELD GLASS SEALANT <i>11</i>	1	180.0000	180.00	X
16	REAR WINDSHIELD GLASS INNER SPONGE SEAL <i>11</i>	1	100.0000	100.00	X
17	N/S REAR WHEEL RIM <i>cut</i>	1	350.0000	350.00	✓
18	N/S REAR WHEEL TYRE <i>11</i>	1	280.0000	280.00	X
19	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00	20
20	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	280.0000	11 280.00	X
21	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	1	180.0000	11 180.00	X
22	TO REMOVE AND REFI INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	11 150.00	X

C/F 0.00


PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
--	--

Quotation No : QO18/06-1054	Quotation Date : 06/06/2018	Terms : 30 DAYS
Vehicle No : SLL9434S	Chassis No : MHFB29F3802007411	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SKM5383M, DOA: 04.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	TO DROP REAR AXLE AND REAR N/S SUSPENSION ASSY, REMOVE AND RENEWAL OF NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING	1	480.0000	480.00 <i>11</i>
24	TO TRANSFER OF REAR N/S TYRE, RIM AND ON WHEEL <i>BALANCING. align.</i>	1	50.0000	50.00 <i>1</i>
25	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	700.0000	700.00 <i>260</i>
26	PUTTY AND SPARY PAINTING OF THE AFFECTED PORTION.	1	600.0000	600.00 <i>400</i>

2. The Authorised Party shall notify the Repairer of the following:
 • To resurvey before spary painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

7- 564.9
252

423.68
1503.68

Sub Total	8,191.63
GST(7.00%)	573.41
Total (SGD)	8,765.04

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18010556/Urbn2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 24-07-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 5383M	Veh. Inspected	SLL 9434S
Policy No.		Coverage (\$)	0.00
Claim No.	C10001649/JM	Excess (\$)	0.00
Assign From	JULIE	Assign Date	11/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3802007411	Colour	GREY
Odometer	75499	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/06/2018	Inspection Date	03/07/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9434S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEEP CUT	504.90	504.90
1	N/S REAR BUMPER REFLECTOR	NOT NECESSARY	130.50	-
2	REAR BUMPER SIDE RETAINER @\$116.30	NOT NECESSARY	232.60	-
2	REAR BUMPER SIDE HOLDER @\$22.30	NOT NECESSARY	44.60	-
12	REAR BUMPER CLIP @\$5.00	NECESSARY	60.00	60.00
1	N/S REAR FENDER	TO REPAIR SEE LABOUR	969.70	-
1	N/S REAR FENDER AIR VENT	NOT NECESSARY	45.10	-
1	REAR FENDET TOP 1/4 GARNISH	NOT NECESSARY	54.70	-
1	N/S REAR LAMP	NOT NECESSARY	375.80	-
3	REAR LAMP CLIP HOLDER @\$5.00	NOT NECESSARY	15.00	-
1	N/S REAR SHOCK ABSORBER	NOT NECESSARY	100.70	-
2	REAR WHEEL BEARING WITH HUB @\$714.20	NOT NECESSARY	1,428.40	-
1	REAR AXLE BEAM ASSY	NOT NECESSARY	2,413.50	-
	LESS 25% DISCOUNT		-1,593.87	-141.22
			4,781.63	423.68
SPECIAL NETT ITEMS				
1	REAR WINDSHIELD GLASS SEALANT (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSHIELD GLASS INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	N/S REAR WHEEL RIM (SN)	CUT	350.00	350.00
1	N/S REAR WHEEL TYRE (SN)	NOT NECESSARY	280.00	-
			910.00	350.00
LABOUR				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	280.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	150.00	-
	TO DROP REAR AXLE AND REAR N/S SUSPENSION ASSY, REMOVE AND RENEWAL OF NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING.	NOT NECESSARY	480.00	-
	TO TRANSFER OF REAR N/S TYRE, RIM AND ON WHEEL ALIGNMENT.		50.00	50.00

Report Ref No. CS/AGI18010556/Urbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF N/S REAR FENDER.		700.00	260.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.00	400.00
			2,500.00	730.00
GRAND TOTAL			8,191.63	1,503.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/AGI18010556/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.