

ASS. REC. BY:

REF:

CS/FCI 18010565/Dgd3ⁿ²

Special Instruction:

Surveyor:

Bryen

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCI

Date/Time:

8/6/18 @ 5:40pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JSD 9476

Insured:

8HD3056D

at Workshop m/s

SG 98 Motor

Tel:

6452 4898

of BLK 4001, AMK Ind. Park | # 01-21

Policy No:

Claim No:

D18004458MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/06/2018

CA / REV / REP. / REV 24 HRS

'wp'

12/06/2018

H.O.D. Endorsement:

Date/Time:

9:24am @ 11/6/18

Person Contacted:

Leena

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

JSD 9476-X


8HD3056D-NA/TM/2004542/52

DOA: 2/3/2012

05/11/18 5:40pm Bryen said no need to do reverse to insurance, just submit report.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OO / TP / WS / TP RES / OD RES / EVA / HIV / MV
 To inspect Vehicle No. _____
 at Workshop no. _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Claim Insured _____ Excess: _____
 (Client's Record)
 Make of Veh. _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bat. or Market Value. _____
 IDAC Accident Report Consistent? Yes or No
 GIA / PR Soon. Consistent? Yes or No
 Est. Repairs. 2 days Res. Yes or No
 Loss Sum. 20 % 3 Val. Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. **JSD 9476** Yr Regd. **2017**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Kawasaki EX250** cc **249**
 Color: **Black** Acc. Insured / Std / NI / HA
 Cap. Branding: **24536** T/Radio: Insured / Std / NI / HA
 Fmt/Plt: **EX250LECD9193**
 CRAs: **PNK EX250LLMCB2102**
 Gen. Cond: **6** / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Mod: **NI** / STD / R/m or
 Tyre Size: F: **140/70 R17**
 R: **110/70 R17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PH / SUMI /
 TOYO / YOKO or **Dunlop**
 Front: _____ Rear: _____
 R/Bal. **3** mm R/Bal. **3** mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **01/06/2018** D.O.I. **12/06/2018**
 Survey held at **SG 98 AMK**
 Cos. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
First Capital SHD 3056D

7/10/18 finance 215 650/- with 2 days of rev (Red 18%, 74%)

RECEIVED 07 NOV 2018

Date/Time, 120 Pages for
10/11/18 ☐ : Prel. Report
☐ : Final Report

Days Of Repair: **2**

Recovery No. of Trip:

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Weekend (\$)

Survey Fee:	110
Transportation:	50
G + Rd, SI	18
Phone	
Other	
	178

Report Format: **TP**
 Lump Sum / B/L: **650**

MOTOR SURVEY ASSIGNMENT

Date	04-06-2018	Our Ref No. D18004458MFSH
Accident Date	01-06-2018	Claim Type. Third Party
Insured Vehicle	SHD3056D	Third Party Vehicle. JSD9476
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 0	Fax No. 64524868
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241091)



PRI Documents



Close



PRI Header Details

Claim No	D18004458MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SG 98 MC
Workshop Name	SG 98 MOTOR PTE LTD (Contact Person : LEENA)	Survey Location & Contact Details	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Mobile: 0 , Phone: 64524898 , Fax: 64524868 EmailId: SGMOTOR2000@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3056D	TP Vehicle No	JSD9476
PRI Recieved Date	08-06-2018 05:13:25 PM	Surveyor Appointed Date	08-06-2018 05:40:19 PM	Surveyor Accept Date	11-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-06-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Denise Tay (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 11 September 2018 12:31 PM
To: Sg Motor
Cc: Bryan Ang (LKKAUTO); CS A Team; SUR
Subject: RE: Please finalize bike JSD 9476
Attachments: JSD 9476 COR.pdf

Without Prejudice

Hi Linda,

Thank you for your email.

Hi Bryan/ Shiao Chan,

CS/FCI18010565/Dqd3

Log car and insurance cost.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Tuesday, 11 September 2018 12:25 PM
To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: Please finalize bike JSD 9476

Dear Bryan

Please finalize bike JSD 9476 as per attached.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

CWRVY67L

No. Pendaftaran : JSD9476
No. ID : 950520045261
Nama Pemunya Berdaftar : DENNIS MICHAEL DAS A/L MICHAEL DAS
Alamat : BATU 22 LIAN HEO ESTATE RANTA U PANJANG
78300 MASJID TANAH MELAKA

No. Chasis/No. Enjin : PNKEX250LLMCB2102 / EX250LECD9193
Buatan>Nama Model : KAWASAKI / EX250-L
Keupayaan Enjin : 249
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2017
Tarikh Pendaftaran : 04/06/2017
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

LESEN KENDERAAN MOTOR

ROAD TRANSPORT ACT 1967 MOTOR VEHICLES (REGISTRATION AND LICENSING) RULES 1969

MOTOSIKAL No. SIRE AG 428708
03 JUN 2018
JSD9476

001269 04062017 JSD9476 RM50.00
0101011 MEERA 03062018 249 SP AA
W4FLrB6
INS1 : AEBP0136583
INS2 :

VEL01001

LESEN INI TIDAK BAH KECUALI ADA CAP MESEK PENERIMAAN JABATAN PENGANGKUTAN JALAN

RTD CODE : 13

CERTIFICATE OF INSURANCE
SIJIL INSURANSORIGINAL COPY
SALINAN ASAL

M.Y.3

ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES 1959 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS & COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE)
MOTOR VEHICLES (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

CERTIFICATE NO.

AEBP0136583

NCD

0.00%

No. Sijil

Diskaun Tanpa Tuntutan

1. Index Mark and Registration Number of Vehicle : JSD9476 249.00 CC KAWASAKI EX250-L
Tanda Indeks Dan Nombor Pendaftaran Kenderaan
2. Name of Policyholder : DENNIS MICHAEL DAS A/L MICHAEL DAS
Nama Pemegang Polisi
3. Effective date of the Commencement of Insurance for the purposes for the Regulations, Ordinance or Enactment : 04-06-2017
Tarikh efektif permulaan insuran untuk kegunaan Ordinan
4. Date of Expiry of the Insurance : 03-06-2018
Tarikh Luput Insuran
5. Persons or Classes of Persons entitled to drive
Orang atau Kelas Pihak Yang Dibenarkan Memandu
a) THE POLICYHOLDER b) ANY OTHER PERSON WHO IS RIDING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OF REGULATIONS IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use* *Had Penggunaan*

Use only for social, domestic and pleasure purposes and by the Policyholder in person in connection with his business.

The Policy does not cover :

This Certificate is not transferable to a new owner of the Vehicle.

If for any reason the Insurance is terminated during its currency this Certificate must be returned to the Company or if this Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the compulsory Insurance Legislation.

This Certificate must be returned if the insurance is suspended during its currency.

IMPORTANT

If you are involved in an accident causing injury to any person or damage to any property or other vehicle you must :

- (a) Try to obtain names and address of any witness to the accident.
- (b) Report to the Company immediately.
- (c) Refer to the Company immediately all communications received from the Police Authorities.
- (d) Sent to the Company immediately all letters from Third Parties unanswered.
- (e) Not pay money to any Party involved in the accident without the Company's written permission.

* Limitations rendered inoperative by Section 95 of the Road Transport Act, 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.

Had yang tidak beroperasi oleh Seksyen 95 Akta Pengangkutan Jalan 1987 (Malaysia) atau Seksyen 8 Akta Kenderaan Bermotor (Gantugli dan Risiko Pihak Ketiga) (Cap 189) Republik Singapura atau Seksyen 7 Akta Singapura atau Seksyen 7 Akta Insurans Kenderaan Bermotor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam adalah tidak termasuk di bawah tajuk ini.

I/We certify that the Policy to which the Certificate is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Saya/kami berseluju bahawa Polisi di mana Sijil ini dikeluarkan tertakluk di bawah proviso Bahagian IV Akta Pengangkutan Jalan 1987, (Malaysia) Akta Kenderaan Bermotor (Risiko Pihak Ketiga & Gantugli) (Cap 189) Republik Singapura dan Akta Kenderaan Bermotor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam.

Agent Code
Kod Ejen

: BP03435

ALLIANZ GENERAL INSURANCE COMPANY (MALAYSIA) BERHAD (735426-V)


 Authorised Signature

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 20 June 2018

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : JSD 9476
ACCIDENT DATE: 1 June 2018

Kawasaki EX250-L

Description	Qty	Quotation \$
1 Rear Tail Tidy <i>defined</i>	1	450.00 ✓
2 Rear Signal RH <i>RT</i>	1 <i>640.00</i>	190.00 ✓
3 Swing Arm <i>HL</i>	1 <i>576.00</i>	1,500.00 X
Sub-Total		2,140.00
Less 10%		214.00
Sub-Total		1,926.00

Nett items

1 Number plate holder <i>broken</i>		180.00 <i>30/-</i>
2 Towing fee <i>HL</i>	<i>280.00</i>	60.00 X
3 Remove & replace new parts		300.00 <i>250.00</i>

Sub-Total 550.00

Nett Total 2,476.00

856.00

15650/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

12/06/2018 e Hoon

HLA Andrew

L/Sun

2 days

LKK Auto

[Signature]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010565/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3056D	Veh. Inspected	JSD 9476	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004458MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	08/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KAWASAKI EX250	c.c	249	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	PNKEX250LLMCB2102	Colour	BLACK	
Odometer	24536	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	140/70 R17	DUNLOP	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	110/70 R17	DUNLOP	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2018	Inspection Date	12/06/2018	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSD 9476

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL TIDY	DEFORMED	450.00	450.00
1	REAR SIGNAL RH	BENT	190.00	190.00
1	SWING ARM	NOT NECESSARY	1,500.00	-
	LESS 10% DISCOUNT		-214.00	-64.00
			1,926.00	576.00
SPECIAL NETT ITEMS				
1	NUMBER PLATE HOLDER (SN)	BROKEN	190.00	30.00
			190.00	30.00
LABOUR				
	TOWING FEE	NOT NECESSARY	60.00	-
	REMOVE & REPLACE NEW PARTS.		300.00	250.00
			360.00	250.00
GRAND TOTAL			2,476.00	856.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CS/FCI18010565/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.