

22/03/2003

ASS. REC. BY:

REF:

CS/CTI/8010597/Kad322

Special Instruction:

Surveyor
Menmen

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

11/6/18 @ 3:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 8322M

Insured:

XD 5527J

at Workshop m/s

Cheng Hae Motor

Tel:

6755 6142

of

Blk 1019 # 01-374/382

Policy No:

DMCVSN1444721703

Claim No:

SNM18D02882002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

4:07pm @ 11/6/18

Person Contacted:

Sharon

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

XD 8322M-NA / AIG 17010468/hq

D.O.A.: 26/5/2017

XD 5527J-X.

13/5

81256.00

Confirmed Effects (Red @ 210, 14%)

no lump sum

ASS. REC. BY:

REF: 0721

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lump Sum:

1.13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A/Rim or

Tyre Size:

F: 295/80R 22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / OKO or

Front

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

17 File pass to Catherine

RECEIVED 14 MAY 2019

Date/Time, File Pass to?

1) 14/5/2019

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

220

220

Report Format:

Lump Sum / I.B.I. (\$

MER-TP

1256

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		11 Jun 2018 15:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	800 SUPER WASTE MANAGEMENT PTE LTD, Co. Reg. No.: 198601155H		
Vehicle Reg. No.:	XD8322M	Date of Loss:	07/06/2018 00:00 - :59
Claim Type:	TP / SNM18D02882C02	Policy/Cover Note No.:	DMCVSN1444721703
Vehicle Reg. No. (Insured):	XD5527J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/06/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Monday, 25 June 2018 11:34 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June); CHENG HOE MOTOR PTE LTD (HQ); assignments; SUR
Cc: Irene Tay; Hwang Shiang Yi; Chee So Chow; xiaosi.tanss@ssgroup.sg; winnie.tangbl@ssgroup.sg; shirl@engbanhuat.com.sg; chew@engbanhuat.com.sg; Alfred Toh
Subject: RE: ENQUIRY OF LIABILITY - XD8322M (SNM18D02882C02/7)

Without Prejudice

Your Ref: XD8322M
Our Ref: SNM18D02882CC02/7 (XD5527J)

Dear June

We refer to our email of 12 June 2018 pertaining to the above matter.

Please be advised that liability is in favor of your client.

While waiting for our Insured's accident report, **we agree to go for Direct Settlement, subject to consistency of damages, based on M/s LKK Auto Consultants Pte Ltd's findings, with supporting documents.**

Aside to M/s LKK Auto Consultants Pte Ltd., please let us have your report and bill uploaded in Merimen at your earliest convenience.

Aside to Irene, please keep track on the matter.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: +65 6389 6183
FAX: +65 6224 7478/6224 7175
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1155H
Vehicle Details	
Vehicle No.:	XD8322M
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jun 2018
Vehicle Make:	MAN
Vehicle Model:	TGS 26.320 6X4 BB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	50535210973520
Chassis No.:	WMA26SZZ1DP045680
Maximum Power Output:	-
Open Market Value:	\$119,187.00
Original Registration Date:	24 Dec 2013
First Registration Date:	24 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$5,960.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,503.00
COE Rebate Amount:	\$30,750.00
Total Rebate Amount:	\$30,750.00

The information contained herein is correct as at 08 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/06/2018 16:47
Date Of Accident	07/06/2018 14:25
Exact Location Of Accident	SLE TOWARDS WOODLANDS AVE 12
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XD8322M
Insured/Policyholder	
Name Of Registered Owner	800 SUPER WASTE MANAGEMENT PTE LTD
Co Reg No	198601155H
Email Address	SUPER800@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63663800
Vehicle Particulars	
Manufacturer	MAN
Model	TGS 26.320 6X4 BB
Exact Purpose for which vehicle was being used at time of accident	GOING TO DISPOSE RUBBISH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5075785219-02
Cover Note Number	1/12/17-30/11/18
Driver	
Name of Driver	RONG BAOGUO
NRIC No	S8379320A
Date Of Birth	02/02/1983
Occupation	OUTDOOR
Date Of Driving Pass	17/10/2016
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97603357
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 657 YISHUN AVE 4 #07-363
Postcode	760657
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : COLLEAGUE
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20180607/2181

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD5527J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? XD5527J

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLAN

VEHICLE NO.: XD 8322 M
INSURER : NTUC
DATE & TIME: 07/6/18 14:25


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 06/18 5:40 PM


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20180607/2181

1 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20180607/2181

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/06/2018 21:33		Vide Report No.: J/20180607/0114		Station Diary No.: 117	
Informant's Particulars					
Name of Informant: RONG BAOGUO			Address: APT BLK 657 YISHUN AVENUE 4 #07-363 SINGAPORE 760657		
ID Type / ID No.: NRIC NO / S8379320A			Contact No.: Home/Office: Mobile: 97603357		
Nationality: CHINESE			Email:		
Age: 35	Date of Birth: 02/02/1983	Type of Informant: Driver			
Race: Chinese		Language: Chinese		Institution / School Name:	
Occupation: DRIVER		Driving Licence Information: Class: 3,4		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 07/06/2018 14:25	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SELETAR EXPRESSWAY WOODLANDS AVENUE 12				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Plate No.	Type	Make	Model	Color	Condition	No of Passenger
XD5527J	Lorry	ISUZU	CYZ52K	White	Seriously Damaged	0
XD8322M	Lorry	MAN	TGS 26.320 6X4 BB	White	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #2

SKETCH PLAN

Sketch Plan

SLE → Wohlstand Ave 12

A: XD8322M
B: XD5529J


The sketch plan shows a street layout with Wohlstand Ave 12 running vertically. Two vehicles are parked on the street: a white sedan (A) and a white sedan (B). A dashed line indicates the curb. A north arrow points towards the top right of the page.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report N^o: T/20180607/2181

DECLARATION

I/We declare the foregoing particulars are true in every respect.



 Policyholder's Signature _____

 Date 5/11/18, 5:40 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

() Claim Own Policy () Claim Third Party () Reporting Only
 () Claim OD/TP at other workshop (_____)

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20180607/2181

2 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20180607/2181

CONTINUATION OF REPORT

Driver			
Name	Unknown Driver		ID No. NIL
Related Vehicle	XD5527J (Lorry)		Contact No. NIL
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	RONG BAOGUO		ID No. S8379320A
Related Vehicle	XD8322M (Lorry)		Contact No. 97603357
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	NG TIAN SHUI DESMOND		ID No. S8534864G
Related Vehicle	XD8322M (Lorry)		Contact No. 91595252
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 07/06/2018 at about 1425hrs, I was driving my waste truck (Man, XD8322M) from SLE towards Woodlands Avenue 12. The lorry in front of me suddenly brake, hence I stepped on the brakes to stop. However, the tipper truck (Isuzu, XD5527J) behind my truck was not able to brake in time and collided into my rear of the truck.

As a result, the tipper truck (XD5527J) was seriously damaged and had to be towed away and the driver was conveyed to the Khoo Teck Puat Hospital via ambulance.

The rear of my truck suffered scratches and dents.

I was given a case card Ref no. J/20180607/0114 by Traffic Police to lodge a Traffic accident report.

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20180607/2181

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 4

Report No. T/20180607/2181

CONTINUATION OF REPORT

Sketch Plan #6



SINGAPORE
POLICE FORCE



T/20180607/2181

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

4 of 4

Report No. T/20180607/2181

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 JACQUELINE TOH XIN YI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMAD ABDILLAH BIN PALIL

Contact No.: 65476246

Signature Of Informant:

Date/Time:

07/06/2018 21:33

Classification Of Case:

S9035

Authentication Stamp

NP188

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111

FAX: 62221033

ATTN: Motor Claim Department

WS Ref: TP CHINA

Claim Type: Third Party

Accident Date: 07/06/2018

TP Veh Reg No: XD5527J

Claim No: ES1891497

Estimate No: ES1891497/WS

Date: 05 Jul 2018

Policy No: -

Veh Reg No: XD8322M

Make/Model: MAN TGS 26.320 6X4

Chassis No: WMA26SZZ1DP045680

Engine No: 50535210973520

Reg. Date: 24/12/2013

Not Authorized

Q 1256.00

3 days

Estimate Repair Cost to Vehicle No : XD8322M

Pages: 1/1

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 LH TAILLAMP	158.00	1 PC <i>CMT</i>	158.00	<i>✓</i>
2 LH TAILLAMP BRACKET	185.00	1 PCS <i>Ry</i>	185.00	<i>✓</i>
3 LH TAILLAMP SOCKET	38.00	1 PC <i>CMT</i>	38.00	<i>✓</i>
4 LH TAILLAMP PROTECTOR	120.00	1 PC <i>Ry</i>	120.00	<i>✓</i>
5 REAR NUMBER PLATE	0.00	1 PC <i>nd</i>	15.00	<i>✓</i>
				516.00
Labour				
6 TO REMOVE AND REFIX REAR NO. PLATE BRACKET, TAILLAMP & BRACKET; KNOCK AND REPAIR REAR CROSS MEMBER, LH PANLE AND RE-ALIGN TO SAME	0.00	1 LA	600.00	<i>500</i>
7 TO RESPRAY PAINTING	0.00	1 LA	300.00	<i>200</i>
8 TO REMOVE AND REFIX TAILLAMP WIRE HARNESS,REPAIR AND REWIRING	0.00	1 LA	50.00	<i>40</i>
				950.00

Total S\$ 1,466.00

Add GST @ 7% 102.62

Total Amount payable S\$ 1,568.62

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2018		11 Jun 2018 15:51 Edit Adj Rpt	S\$1,256.00 Edit Estimates	S\$1,256.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference	Claim Details	Documents	Show All
-------------	--	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	0, Co. Reg. No.: 0				
Main Claimant:	800 SUPER WASTE MANAGEMENT PTE LTD, Co. Reg. No.: 198601155H				
Vehicle Reg. No.:	XD8322M	Date of Loss:	07/06/2018 00:00 - :59 [53 Months and 14 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / SNM18D02882C02	Policy/Cover Note No.:	DMCVSN1444721703		
Vehicle Reg. No. (Insured):	XD5527J	Policy No. (Claimant):			
		Excess:	S\$0.00		
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/06/2018]				
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.				

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- CHINA_TAIPING (24/07/2018): Alert - Adj Mandate Approved (S\$0.00) - XD8322M - Claim Handler: Irene Tay Hui P...

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD8322M (SNM18D02882C02)**
[XD5527J]
TP
800 SUPER WASTE MANAGEMENT PTE LTD
Jun 7 2018 12:00AM
[0]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/05/19 11:42	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/05/19 11:42	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
16	13/05/19 11:42	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
17	13/05/19 11:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	13/05/19 11:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	13/05/19 11:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	13/05/19 11:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	13/05/19 11:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/18 15:50	PRS	Load PDF	
2	11/06/18 15:50	TP GIA REPORT	Load PDF	
3	24/07/18 15:04	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>		

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118010597/KQD3E2

Date: 14/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1444721703

Claimant Vehicle
No : XD8322MInsured Vehicle
No : XD5527J

Date of Loss: 07/06/2018

Nature of Claim: TP

Claim
No: SNM18D02882C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD8322M

Make & Model: MAN TGS 26.320, 10.5 D 6X4 BB (M)

Engine No: 50535210973520

Reg. Date: 24/12/2013 (Man. Year: 2013)

Chassis No: WMA26SZZ1DP045680

Colour: White

Odometer: 435082 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5

Rear Tyre Size: 295/80R22.5 (D)

Front Left Side: Amberstone 8 mm

Rear Left Side: Amberstone 8/8 mm

Front Right Side: Amberstone 8 mm

Rear Right Side: Amberstone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	516.00	516.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	740.00	210.00	22.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,466.00	1,256.00	210.00	14.32
+ GST 7.00/7.00% (S\$)	102.62	87.92	14.70	14.32
Nett Amount (S\$)	1,568.62	1,343.92	224.70	14.32

INSPECTION

Date of Assignment: 11/06/2018

Date Inspected: 05/07/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 May 2019)	
Parts:	N/A	MAN TGS 26.320 10.5 D 6X4 BB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD8322M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH TAILLAMP	Cracked	158.00 FS	*158.00 FS
2	1		*LH TAILLAMP BRACKET	Bent	185.00 FS	*185.00 FS
3	1		*LH TAILLAMP SOCKET	Cracked	38.00 FS	*38.00 FS
4	1		*LH TAILLAMP PROTECTOR	Bent	120.00 FS	*120.00 FS
5	1		*REAR NUMBER PLATE	Dented	15.00 FS	*15.00 FS
					Total Parts (S\$)	516.00
						516.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR NO PLATE BRACKET, TAILLAMP & BRACKET, KNOCK AND REPAIR REAR CROSS MEMBER, LH PANEL AND RE-ALIGN TO SAME	New	600.00	500.00
2	TO RESPRAY PAINTING	New	300.00	200.00
3	TO REMOVE AND REFIX TAILLAMP WIRE HARNESS, REPAIR AND REWIRING	New	50.00	40.00
Gross Labour Cost (\$\$)			950.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >