

22/03/2002

ASS. REC. BY:

REF:

CS3/CT118010607/VZ4d3er

Special Instruction:

Surveyor
menmen

ASSIGNMENT (Office)

From (Person): Chang Boon Sen

of

CT1

Date/Time: 11/6/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SLU 7593G

Insured:

GBF 76514

at Workshop m/s

Seng Hwee Motor

Tel:

67555205

of

Blk 1018, Yishun Ind. Park A #01-350

Policy No:

DMCVSN 3015081800

Claim No:

SNM18002786C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/06/2018

CA / REV / REP. / REV 24 HRS

(up)

12/06/18 @ after 2pm

H.O.D. Endorsement

Date/Time:

4:58pm @ 11/6/18

Person Contacted:

Mr. Kueh

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLU 7593G-X

GBF 76514-X

REF: CTI

ASSIGNMENT

SLU 7593G

From:

Date:

12/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 7593G

at Workshop m/s

Seng Hwee Motor

of 81K 1018, Yishun Ind. Park A #

Insured:

01-350

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


after 2pm

Make of Veh:

Mr. Kueh @ 6755 5205

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

~~SLU 7593G~~

Yr Regn: Dec / 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Estima

c.c. 2362

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

13357

T/Radio: Insured / Std / NI / NA

Eng/No:

2A24A75228

C/No:

ACR507145894

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55 R17

R: 225/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

1/6/2018

D.O.I.

12/6/2018

Survey held at

SENG HWEI motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 3000 - 4000

* 2 days

21/6/18

Submit 7RS Report

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS) SI

) Photos

) Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2018		11 Jun 2018 16:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	YI CHANG FURNITURE INTERIOR DECORATION, Co. Reg. No.: 53167028K		
Main Claimant:	BOO TIAN SENG, ID: S1220996G		
Vehicle Reg. No.:	SLU7593G	Date of Loss:	01/06/2018 11:00 - :59
Claim Type:	TP / SNM18D02786C02	Policy/Cover Note No.:	DMCVSN3015081800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF7651U	Policy No. (Claimant):	5096561193
		Excess:	S\$0.00
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/06/2018]		
Driver/Custodian (Insured):	NG SIEW GUAT (75 / Female), NRIC: S0593734E, Tel: +6592399388		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your ref : GBF 7651U ; SNM18D02786C02
Our client's vehicle / ref: SLU 7583G ; SW/sy/ms
Date : 11 June 2018

China Taiping Insurance (Singapore) Pte Ltd

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 1 JUNE 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : Seng Hwee Motor
Address : Block 1018 Yishun Industrial Park A
#01-350
Singapore 768760
Contact : Mr Kueh (6755 5205 / 9786 5675)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Your ref : GBF 7651U ; SNM18D02786C02
Our client's vehicle / ref: SLU 7583G ; SW/sy/ms
Date : 11 June 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as
follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (party by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18010607/Vz4d3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-06-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 7651U	Veh. Inspected	SLU 7593G
Policy No.	DMCVSN3015081800	Coverage (\$)	0.00
Claim No.	SNM18D02786C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	11/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/06/2018	Inspection Date
Survey held at	SENG HWEE MOTOR BLK 1018, #01-350 YISHUN INDUSTRIAL PARK A SINGAPORE 768760	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Your ref : GBF 7651U ; SNM18D02786C02
 Our client's vehicle / ref: SLU 7593G ; SW/sy/ms
 Date : 11 June 2018

China Taiping Insurance (Singapore) Pte Ltd

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 1 JUNE 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : Seng Hwee Motor
 Address : Block 1018 Yishun Industrial Park A
 #01-350
 Singapore 768760
 Contact : Mr Kueh (6755 5205 / 9786 5675)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,

Gay

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 15:31
Date Of Accident	01/06/2018 11:35
Exact Location Of Accident	BLK 527 ANG MO KIO AVE 10 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU7593G
Insured/Policyholder	
Name Of Registered Owner	BOO TIAN SENG
NRIC No	S1220996G
Email Address	INFO@KNIGHTAUTOACC.COM
Mobile Phone No	(LOCAL) +65-96719998
Alternative Phone No	OTHERS-96719998
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA AERAS PREMIUM 7 SEATER
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096561193
Cover Note Number	13/12/17 - 12/12/18

Driver

Name of Driver	NG SIEW CHIN
NRIC No	S1357141D
Date Of Birth	15/08/1959
Occupation	INDOOR
Date Of Driving Pass	02/01/1990
Driving Experience	28 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92380271
Fax Number	
Contact Number	
Email Address	INFO@KNIGHTAUTOACC.COM

Address 2A JALAN TAMPANG

Postcode 758947

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT. (THIRD PARTY CLAIM BY SAN HE CAR REPAIRER)

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FOOTAGE WITH OWNER

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF7651U

Vehicle Make/Model/Colour WHITE MIT. CANTER

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20180604/2105

Police Station Of Origin:

Yishun North N.P.C

Yishun Central SINGAPORE 768827

No. 1800-8529999

2 of 3

Report No. T/20180604/2105

CONTINUATION OF REPORT

Brief Details.

On 01/06/2018, at 1133hrs, I parked my vehicle, bearing vehicle plate number SLU7593G, at Blk 527 Ang Mo Kio. My vehicle was parked in a vertical parking lot.

At about 1200hrs, I went back to my vehicle and discovered the rear right passenger door had suffered a dent. My vehicle did not had such damage before, and no contact or notes were left behind by the person that caused the damage. I reviewed my in car camera footage and found that the damage was caused by a vehicle, bearing vehicle plate number GBF7651U. I proceeded to contact the company of the vehicle, USAHA Furniture, HP-9239 9388. The person that I spoke to from the company was Joanne, and she advised me to claim insurance against her company. I am lodging this report to facilitate the process of my insurance claim.

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20180604/2105

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No: T/20180604/2105

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/06/2018 14:58		Video Report No.:		Station Diary No. 39	
Informant's Particulars					
Name of Informant: NG SIEW CHIM			Address: 2A JALAN TAMPANG SINGAPORE 758947		
ID Type / ID No. NRIC NO / S1367141D			Contact No: Home/Office: Mobile: 92380271		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 58	Date of Birth: 15/06/1959	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: ADMIN CLERK			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 01/06/2018 11:35	Type of Location: Car Park
Location: Along Road 1 ANG MO KIO AVENUE 10 Carpark of Block 527 Ang Mo Kio Avenue 10				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF7651U	Lorry	MITSUBISHI	CANTER FEA01BR1S DEB (CBU)	White		0
SLU7593G	Car	TOYOTA	ESTIMA AERAS PREMIUM 7 SEATER	White	Slightly Damaged	0

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		11 Jun 2018 16:19 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YI CHANG FURNITURE INTERIOR DECORATION , Co. Reg. No.: 53167028K								
Main Claimant:	BOO TIAN SENG , ID: S1220996G								
Vehicle Reg. No.:	SLU7593G	Date of Loss:	01/06/2018 11:00 - :59 [5 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02786C02	Policy/Cover Note No.:	DMCVSN3015081800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF7651U	Policy No. (Claimant):	5096561193						
		Excess:	S\$0.00						
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 21/06/2018]								
Driver/Custodian (Insured):	NG SIEW GUAT (75 / Female), NRIC: S0593734E, Tel: +6592399388								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU7593G (SNM18D02786C02)

[GBF7651U]

TP

BOO TIAN SENG

Jun 1 2018 11:00AM













[YI CHANG FURNITURE INTERIOR DECORATION]

Seng Hwee Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	04/06/18 17:21	Accident Statement		
			1 Load HTM <input type="checkbox"/>	
Photos/Images			3 per page <input type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	04/06/18 17:20	Accident Photo [Linked Accident Report Documents]		
2	04/06/18 17:20	Accident Photo [Linked Accident Report Documents]		
3	04/06/18 17:20	Accident Photo [Linked Accident Report Documents]		
4	04/06/18 17:20	Accident Photo [Linked Accident Report Documents]		
5	04/06/18 17:20	Driving License [Linked Accident Report Documents]		
6	04/06/18 17:20	Accident Photo [Linked Accident Report Documents]		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	14/06/18 10:03	General View		
2	14/06/18 10:03	General View		
3	14/06/18 10:03	General View		
4	14/06/18 10:03	General View		
5	14/06/18 10:03	General View		
6	14/06/18 10:03	General View		
7	14/06/18 10:03	General View		
8	14/06/18 10:03	General View		
9	14/06/18 10:03	General View		
10	14/06/18 10:03	General View		
11	14/06/18 10:03	General View		
12	14/06/18 10:03	General View		
13	14/06/18 10:03	General View		
14	14/06/18 10:03	Chassis Number		
15	14/06/18 10:03	Odometer Reading		
16	14/06/18 10:03	General View		
17	14/06/18 10:03	General View		
18	14/06/18 10:03	General View		
19	14/06/18 10:03	General View		
20	22/06/18 08:50	Dismantled Parts		
21	22/06/18 08:50	Dismantled Parts		
22	22/06/18 08:50	Dismantled Parts		
23	22/06/18 08:50	Dismantled Parts		
Documentation			1 per page <input type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	11/06/18 16:18	PRS	 Load PDF	
2	11/06/18 16:19	OI GIA REPORT	 Load PDF	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail Print
1	04/06/18 17:17	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/18 17:17	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/18 17:17	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/18 17:17	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	04/06/18 17:17	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/06/18 13:49	LKKPhotosIn6-1.pdf	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	04/06/18 17:21	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	04/06/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/06/18 17:20	Driving License	 Load JPG	<input checked="" type="checkbox"/>
6	04/06/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	04/06/18 17:17	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/18 17:17	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/18 17:17	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/18 17:17	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>
5	04/06/18 17:17	Sketch Plan #5	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18010607/VZ4D3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3015081800

Claimant Vehicle
No : SLU7593GInsured Vehicle
No : GBF7651U

Date of Loss: 01/06/2018

Nature of Claim: TP

Claim
No: SNM18D02786C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU7593G

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZ4A75228

Reg. Date: 13/12/2017 (Man. Year: 2017)

Chassis No: ACR507145894

Colour: White

Odometer: 13357 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/06/2018

Date Inspected: 12/06/2018 Inspected At:

Seng Hwee Motor (HQ)
Blk 1018 Yishun Industrial Park A #01-350
Singapore 768760

Estimated Period of Repair: 2.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7593G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >