Surveyor Raci | REF: ATLG | 63064

ASSIGNMENT

From: | Date: 25.06.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 861E

at Workshop m/s Performance

of 305 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Chuu.

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP 861E Yr Regn: 2016 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: B.M.W 420I GRAN COUPE c.c 1998

Colour RED A/C: Insured / Std / NI / NA

Sp.Reading 21924 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA4D32080G382738

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R: -"-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	02/06/18	D.O.I.	25/06/18

Survey held at PERFORMANCE

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL