



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18010648/T1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-05-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 5080E	Veh. Inspected	SLN 362P
Policy No.	P1874030	Coverage (\$)	0.00
Claim No.	S8M00K4A	Excess (\$)	0.00
Assign From		Assign Date	08/06/2018

2. Vehicle Particulars & Condition

Make & Model	KIA NIRO	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNACC81CVH5062252	Colour	BLUE
Odometer	43148	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	6 mm
L/H Front Tyre	205/60 R16	MICHELIN	6 mm
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/06/2018	Inspection Date	12/06/2018
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------