

ASS. REC. BY:

REF:

CS/7CL18010673/Ksd3

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCL

Date/Time: 12/6/18 @ 11:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 6185Y

Insured:

SHB 3101S

at Workshop m/s

Massive trading

Tel:

9108 2728

of

Blk 5038 # 01-405 AMK Ind. park 2

Policy No:

Claim No:

D18004647MFSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:40pm @ 12/6/18

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJR 6185Y - NS/INC 14011354 / Hlgbw2 DA: 150614
	SHB 3101S - 737 FCL15007962 / M10063 DA: 090915
13/06/18 @ 16:04 p.m.	revert pending estimate from repairer to sithara via email.

ASS. REC. BY:

REF: 15021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 817k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STR 01854 Yr Regn: 07, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Vios C.G. 1497

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 185902 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053149305117258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: Maxxis 195/80R15

R: Le90

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 6 mm

L/Bal. 8 mm L/Bal. 6 mm

D.O.A. 10/8/18 D.O.I. 12/6/18

Survey held at _____

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/6 for PSS to Catherine, RM not ready

(\$ 1,749.37 Red - 47%)

RECEIVED 23 AUG 2018

Date/Time, File Pass to?

23/08/18

☐ : Prel. Report

1) Type

☒ : Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 1,950/- Hs

130
50
50
20
250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010673/Ksd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3101S	Veh. Inspected	SJR 6185Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004647MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/06/2018	Inspection Date	12/06/2018	
Survey held at	BLK 5038 AMK IND PARK 2 #01-405			
Repairer	MASSIVE TRADING & AUTO			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	11-06-2018	Our Ref No. D18004647MFSH
Accident Date	10-06-2018	Claim Type. Third Party
Insured Vehicle	SHB3101S	Third Party Vehicle. SJR6185Y
Survey Location	Blk 5038 #01-405 Ang mo kio industrial Pk 2	
Contact Person.	WILLIAM	
Contact No.	0/ 90088431	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MASSIVE TRADING & AUTO	Attention. NIL
Cc : TP Solicitor	TEO KENG SIANG LLC	TP Solicitor Fax No. 63335676
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241332)



PRI Documents



Close



PRI Header Details

Claim No	D18004647MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TEO KENC
Workshop Name	MASSIVE TRADING & AUTO (Contact Person : WILLIAM)	Survey Location & Contact Details	Blk 5038 #01-405 Ang mo kio industrial Pk 2 Mobile: 90088431 , Phone: 0 , Fax: 0 EmailId: JANICE.KEE@KSTEOPTR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3101S	TP Vehicle No	SJR6185Y
PRI Recieved Date	11-06-2018 07:54:18 PM	Surveyor Appointed Date	12-06-2018 11:27:20 AM	Surveyor Accept Date	12-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 13 June 2018 4:04 PM
To: SITHARA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: "SUR"; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18004647MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SJR 6185Y on 12/06/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 12 June 2018 12:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; "SUR" <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004647MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 12 June 2018 11:27 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004647MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2590E
Vehicle Details	
Vehicle No.:	SJR6185Y
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZX921426
Chassis No.:	MR053HY9305117258
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,047.00
Original Registration Date:	01 Jul 2009
First Registration Date:	01 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$12,047.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2019
PARF Rebate Amount:	\$6,625.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$1,350.00
Total Rebate Amount:	\$7,975.00

The information contained herein is correct as at 13 Jun 2018

OK

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Chubby Limo
Blk 106 Bishan St 12
#04-218
Singapore 570106

Vehicle No : SJR 6185 Y
Make : Toyota Vios
Year : 2008

Not withank
11 Day @ 19.50
Runny After Point

3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

2 pcs	Front headlamp assy	427.80 <i>along CM</i>	577.60	\$1,155.20	<i>CM</i>
1 pc	Front bumper	482.20		\$577.60	<i>Am</i>
1 pc	Front bumper top sponge			\$145.70	<i>Sn</i>
1 pc	Front bumper reinforcement			\$379.50	<i>R</i>
1 pc	Front bumper lower spoiler			\$485.10	<i>CM</i>
1 pc	Front bumper lower grille			\$105.60	<i>Sn</i>
1 pc	Front bumper tow cover			\$55.80	<i>mi</i>
1 pc	Front grille	213.50		\$284.10	<i>CM</i>
1 pc	Front grille moulding			\$98.30	<i>Am</i>
1 pc	Front grille emblem			\$45.60	<i>Am</i>
				\$3,332.50	
				Less 25 %	\$833.13
					\$2,499.37

S Nett

1 pc	Front no plate		\$45.00	<i>Rd</i>
10 pcs	Front bumper clip		\$25.00	<i>Am</i>
			\$70.00	

Labour Charges

Remove/renew the above parts including knocking, welding etc.	\$500.00	<i>30d</i>
To putty & spray paint front accident affected portion.	\$500.00	<i>40d</i>
Check/reconnect wiring.	\$30.00	<i>20d</i>
To spray anti rust on accident affected portion.	\$100.00	<i>XX</i>

Total \$3,699.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010673/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3101S	Veh. Inspected	SJR 6185Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004647MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305117258	Colour	METALLIC SILVER	
Odometer	185902	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MAXXIS	8 mm	
L/H Front Tyre	195/60 R15	MAXXIS	8 mm	
R/H Rear Tyre	195/60 R15	LEAO	6 mm	
L/H Rear Tyre	195/60 R15	LEAO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2018	Inspection Date	12/06/2018	
Survey held at	BLK 5038 AMK IND PARK 2 #01-405			
Repairer	MASSIVE TRADING & AUTO			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 6185Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT HEADLAMP ASSY @\$577.60	O/S CRACKED / N/S MTG CRACKED	1,155.20	855.60
1	FRONT BUMPER	BUCKLED	577.60	482.20
1	FRONT BUMPER TOP SPONGE	SERVICEABLE	145.70	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	379.50	-
1	FRONT BUMPER LOWER SPOILER	CRACKED	485.10	485.10
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	105.60	-
1	FRONT BUMPER TOW COVER	MISSING	55.80	55.80
1	FRONT GRILLE	CRACKED	284.10	213.50
1	FRONT GRILLE MOULDING	NECESSARY	98.30	98.30
1	FRONT GRILLE EMBLEM	NECESSARY	45.60	45.60
	LESS 25% DISCOUNT		-833.13	-559.02
			2,499.37	1,677.08
SPECIAL NETT ITEMS				
1	FRONT NO PLATE (SN)	DENTED	45.00	45.00
10	FRONT BUMPER CLIP @\$2.50 (SN)	NECESSARY	25.00	25.00
			70.00	70.00
LABOUR				
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	300.00
	TO PUTTY & SPRAY PAINT FRONT ACCIDENT AFFECTED PORTION.		500.00	400.00
	CHECK/RECONNECT WIRING.		30.00	20.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	100.00	-
			1,130.00	720.00
GRAND TOTAL			3,699.37	2,467.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00



Report Ref No. CS/FCI18010673/Ksd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.