

ASS. REC. BY:

REP:

093/ms618010692 / Uz403ez

Special Instruction:

Survivor:
Meinmen

Marcus

ASSIGNMENT (Office)

From (Person):

Monica chung

of

MSIG

Date/Time:

12/6/18 @ 9:20am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 6607E

Insured:

FBC 9378L

at Workshop m/s

Alpha Car Services

Tel:

6509 8258

of

Blk C, Kaki Bukit Ave 6 # 01-59

Policy No:

MSD / VMT / 18-988834-WTT

Claim No:

MSC / V / 18-000798-WTT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/06/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10:06am @ 12/6/18

Person Contacted:

cai ling

Vehicle

IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

GBF 6607E - X

FBC 9378L - X

12/6/18

Dismantled

Bureau

Mofca

REF:

MSIG

ASSIGNMENT

From:

Date:

12/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBF 6607 E

at Workshop m/s

Alpha Car Services

of

Blkc Kaki Blk Ave 6 #01-59

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

NAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1up

19/10/18

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBF 6607 E

Yr Regn:

2,17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

C.C.

2488

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

5448

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1MC2E2620007027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

VANMAX

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

6/6/18

D.O.I.

12/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Body.

The U/C / Chassis frame / Body structure affected due to collision.

Date / Time

Action / Instruction

No settlement.

1600 - 2500k. <

13/6/18 Submit PRS Report.

RECEIVED 13 JUN 2018

Date/Time: File Pass to?



: Preli. Report



: Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

120

50

10

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2018		12 Jun 2018 09:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	TAN TECK LEE , ID: S0140602G								
Main Claimant:	BEST DOORS PTE LTD , Co. Reg. No.: 201101910G								
Vehicle Reg. No.:	GBF6607E	Date of Loss:	06/06/2018 00:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000798-WTT	Policy/Cover Note No.:	MSD/VMT/18-988839-WTT Coverage: 22/02/2018 - 21/02/2019						
Vehicle Reg. No. (Insured):	FBC9378L	Policy No. (Claimant):							
		Excess:							
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/06/2018]								
Adj Asg. Remarks:	on WP. Liability: 100%. TP Reject SJE - assign LKK Auto Consultants.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18010692/Uz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-06-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBC 9378L	Veh. Inspected	GBF 6607E
Policy No.	MSD/VMT/18-988839-WTT	Coverage (\$)	0.00
Claim No.	MSC/V/18-000798-WTT	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	12/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/06/2018	Inspection Date	12/06/2018
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2018 16:51
Date Of Accident	06/06/2018 16:25
Exact Location Of Accident	PIE (TUAS) AFTER KALLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF6607E
Insured/Policyholder	
Name Of Registered Owner	BEST DOORS PTE LTD
Co Reg No	201101910G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67423633

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV18S001846
Cover Note Number	

Driver

Name of Driver	FAN WAH TONG
NRIC No	S2589593B
Date Of Birth	07/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	19/11/1982
Driving Experience	35 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81828476
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 159 TAMPINES ST 12 #08-103
Postcode	521159
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE ABOVE MENTIONED DATE AND TIME, I WAS TRAVELLING ALONG PIE (TUAS) AFTER KALLANG. VEHICLE B (YL6610R) TRYING TO CUT INTO MY LANE AND COLLIDED INTO VEHICLE C (FBC9378L) RESULTING VEHICLE C BANG ONTO MY VEHICLE RIGHT HAND SIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL6610R
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	FBC9378L
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEHICLE C

MOTORCYCLE

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



vehicle A: GBF 6607E
vehicle B: 4L 6610R
vehicle C: FBL 9378L

On the above mentioned date and time, I was travelling along P/e
Tuas after Kallang.

Vehicle B (YL 661OR) trying to cut into my lane and collided into vehicle C (FB C 937FL) resulting vehicle C hang onto my vehicle Right hand side.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name: _____
NRIC/FIN No.: _____

Driving License



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

2005-7	Motor Cars and Motor Tractors the weight of which unloaded does not exceed 2500 kilograms	10 Nov 1942
--------	---	-------------

PASS DATE:

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

00000000000000000000000000000000

52589693B



MALAYSIAN
 BANGKOK 189 17 945
 B- 00-12-1944

APT BLK 150 TAMPINES STREET 12-405-105
SINGAPORE 621455
NRIC No: S4425444 Date: 05-10-2014 No: 0156300

INSURANCE



UNO

1. The insured hereby declares that the Motor Vehicle is registered in the name of the insured and is used for the purpose of the Motor Vehicle Insurance Policy.

2. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

3. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

4. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

5. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

6. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

7. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

8. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

9. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

10. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

11. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

12. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

13. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

14. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

15. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

16. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

17. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

18. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

19. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

20. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

21. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

22. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

23. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

24. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

25. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

26. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

27. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

28. The insured hereby declares that the Motor Vehicle is not used for the purpose of the Motor Vehicle Insurance Policy.

Insured signed by
KCS INVESTMENTS PTE LTD

KCS INVESTMENTS PTE LTD
Co Reg No. 1981030452
200 Jooe Street
Singapore 109019
Tel: 6052 2817 Fax: 6052 1300

KCS INVESTMENTS PTE LTD

CITY INSURANCE AGENCY PTE LTD
Block 9 Sea Wing Industrial Estate
Sector 7 #01-00 Singapore 479441
Tel: +65 6436077 Fax: +65 6436079
E-mail: cityinsurance@18g.com.sg
A/C: 2612345678

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1910G
Vehicle Details	
Vehicle No.:	GBF6607E
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	YD25404631A
Chassis No.:	JN1MC2E26Z0007027
Maximum Power Output:	-
Open Market Value:	\$23,668.00
Original Registration Date:	03 Feb 2017
First Registration Date:	03 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$1,184.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$45,643.00
COE Rebate Amount:	\$39,437.00
Total Rebate Amount:	\$39,437.00

The information contained herein is correct as at 12 Jun 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2018		12 Jun 2018 09:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN TECK LEE , ID: S0140602G									
Main Claimant: BEST DOORS PTE LTD , Co. Reg. No.: 201101910G									
Vehicle Reg. No.: GBF6607E		Date of Loss: 06/06/2018 00:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000798-WTT		Policy/Cover Note No.: MSD/VMT/18-988839-WTT Coverage: 22/02/2018 - 21/02/2019							
Vehicle Reg. No. (Insured): FBC9378L		Policy No. (Claimant):							
		Excess:							
Repairer: Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 13/06/2018]									
Adj Asg. Remarks: on WP. Liability: 100%. TP Reject SJE - assign LKK Auto Consultants.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF6607E (MSC/V/18-000798-WTT)
[FBC9378L]**






































TP






































BEST DOORS PTE LTD

Jun 6 2018 12:00AM

[TAN TECK LEE]

Alpha Car Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 17:10	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	12/06/18 17:10	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/06/18 17:11	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/06/18 17:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	12/06/18 17:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/06/18 17:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/06/18 17:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/06/18 17:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	13/06/18 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/18 09:28	YL6610R e-file report	 Load PDF	
2	11/06/18 09:28	GBF6607E e-file report	 Load PDF	
3	11/06/18 09:33	TP reject SJE - assign LKK	 Load PDF	
4	11/06/18 09:35	tp pri request	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18010692/UZ4D3E2

Date: 18/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-988839-WTT
Claimant Vehicle No :	GBF6607E	Insured Vehicle No :	FBC9378L
Date of Loss:	06/06/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000798-WTT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6607E	Engine No:	YD25404631A
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0007027
Reg. Date:	03/02/2017 (Man. Year: 2016)	Odometer:	54481 km
Colour:	Silver		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	VANMAX 6 mm	Rear Left Side:	VANMAX 6 mm
Front Right Side:	VANMAX 6 mm	Rear Right Side:	VANMAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/06/2018	
Date Inspected:	12/06/2018 Inspected At:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay Singapore 417883
Estimated Period of Repair:	0.0 days	

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,600.00 -\$2,500.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jun 2018)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF6607E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >