

ASS. REC. BY:

REF: CS/AGI18010696/Ksd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Julie Mangubat

of AGI

Date/Time: 12/6/18 @ 10:14am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HD 383D

Insured:

SJW 5542E

at Workshop m/s

Trans-Cab

Tel:

6287 6666

of

No. 2 AMK 8f-63

Policy No:

Claim No:

C10001663/JM

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 10:37am @ 12/6/18

Person Contacted:

Ceudy

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|----------------------------------|
| | SHD 383D - CS/FCL17017723/Ksd3n2 |
| | OLA: 100917 |
| | |
| | |
| | |
| | |
| | |

ASS. REC. BY:

REF: AG-21

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/6

File sent to Corbina

4296.94

(Reel 48,354.66, 92%)

13/6/18

(852,651.60 - 4296.94)

Reduction = 91%

RECEIVED 4 JUN 2018

Date/Time, File Pass to?

13/6/18

1)

Typ. 3+

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 2.5

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (5



: Interview (5



: Tech Invs (5



: Weekend (5

Survey Fee:

Transportation:

) S + RS. SI

) Fixing

) Others

TOTAL

450

Report Format:

Lump Sum / I.B.I. (S

P/P 4,296.94

Veh No:

S140 3830

Yr Regn:

05.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

202273

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABL 15AUC 282810

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil S/Rim / STD A/Rim or

Tyre Size:

F: Giti

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

4

mm

Rear

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

10/6/18

D.O.I.

12/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Tuesday, 12 June 2018 10:14 AM
To: 'SUR'; 'assignments'
Subject: FW: ARRANGE FOR SURVEY SHD383D | Our ref: C10001663/JM
Attachments: img-612085602-0001.pdf

Hi Team

Please accept TPPD survey and survey the TP vehicle on a without prejudice basis.
In addition, the estimates are extremely exaggerated please note.

Thank you,
-Julie

-----Original Message-----

From: Candy Kong <candy.kong@transcab.com.sg>
Sent: Tuesday, 12 June 2018 9:16 AM
To: Lincoln Yeo <lincoln.yeo@budgetdirect.com.sg>
Cc: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: ARRANGE FOR SURVEY SHD383D

Hi Albert,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SJW5542E - 10.06.2018 at 1440Hrs - SHD383D

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18010696/Ksd3

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 12-06-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------|----------------|------------|
| Insured Veh. | SJW 5542E | Veh. Inspected | SHD 383D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | C10001663/JM | Excess (\$) | 0.00 |
| Assign From | JULIE | Assign Date | 12/06/2018 |

2. Vehicle Particulars & Condition

| | |
|--------------|--------------|
| Make & Model | c.c |
| Engine No. | Year of Reg. |
| Chassis No. | Colour |
| Odometer | Steering |
| Brakes | Modification |
| General | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| |
|--|
| |
|--|

5. General Information

| | | |
|----------------|------------|-----------------|
| Accident Date | 10/06/2018 | Inspection Date |
| Survey held at | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID: | 3878K |

Vehicle Details

| | |
|--------------------------------|---------------------------------|
| Vehicle No.: | SHD383D |
| Vehicle to be Exported: | Yes |
| Intended De-registration Date: | 11 Jun 2018 |
| Vehicle Make: | RENAULT |
| Vehicle Model: | LATITUDE 2.0L DCI AUTO D/AB 4DR |
| Primary Colour: | Red |
| Manufacturing Year: | 2015 |
| Engine No.: | M9R8839C003056 |
| Chassis No.: | VF1ABL15AUC282610 |
| Maximum Power Output: | 127.0 kW (170 bhp) |
| Open Market Value: | \$19,998.00 |
| Original Registration Date: | 31 May 2016 |
| First Registration Date: | 31 May 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$19,998.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 30 May 2024 |
| PARF Rebate Amount: | \$14,998.00 |

Intended COE Rebate Details

| | |
|-----------------------------|--------------------------------------|
| COE Expiry Date: | 30 May 2024 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$36,463.00 |
| COE Rebate Amount: | \$27,200.00 |
| Total Rebate Amount: | \$42,198.00 |

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jun 2018.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------------------|
| Date Of Report | 11/06/2018 09:18 |
| Date Of Accident | 10/06/2018 14:40 |
| Exact Location Of Accident | CTE, FILTER LANE TO PIE EXIT |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SHD383D |
| Insured/Policyholder | |
| Name Of Registered Owner | TRANS-CAB SERVICES PTE LTD |
| Co Reg No | 200303878K |
| Email Address | CLAIMS@TRANSCAB.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-62866666 |

Vehicle Particulars

| | |
|--|--------------------|
| Manufacturer | RENAULT |
| Model | LATITUDE-2.0 L (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARD |

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI

Insurance Company

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | THIRD PARTY |
| Fleet Policy | YES |
| Policy Number | VPX/P1680520 |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | SIM KWONG YAN |
| NRIC No | S1825720C |
| Date Of Birth | 17/04/1967 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 17/08/2009 |
| Driving Experience | 8 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-87817644 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|---|
| Address | BLK 527C PASIR RIS STREET 51 #12-713 |
| Postcode | 513527 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | PASIR RIS NEIGHBOURHOOD POLICE CENTRE |
| Police Station Address | ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: 1800-5852999 - FAX NO: 65855261 |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180610/2084

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------|
| Vehicle Registration Number | SJW5542E |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | TOH HAN KAIT |
| NRIC/Passport Number | S8102244E |
| Contact Number | 98337047 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SIM KWONG YAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD383D

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180610/2084

1 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20180610/2084

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|------------------|--------------------------|
| Date/Time Report Made: 10/06/2018 18:25 | Vide Report No.: | Station Diary No.: 81 |
|--|------------------|--------------------------|

Informant's Particulars

| | | | | | |
|--|------------|------------------------------|--|--|----------------------------|
| Name of Informant: SIM KWONG YAN | | | Address: APT BLK 527C PASIR RIS STREET 51 #12-713 SINGAPORE 513527 | | |
| ID Type / ID No.: NRIC NO / S1825720C | | | Contact No.: Home/Office: 87817644 Mobile: | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 51 | Date of Birth: 17/04/1967 | Type of Informant: Driver | | |
| Race: Chinese | | | Language: | | Institution / School Name: |
| Occupation: TAXI DRIVER | | | Driving Licence Information: Class: 3 | | Date of Expiry: |

General Information of the Accident

| | | | | |
|--|------------------|------------------------------------|---|--|
| Type of Accident: | Injury Others | Drink Drive: No | Date/Time of Accident: 10/06/2018 14:15 | Type of Location: Straight Road |
| Location: Along Road 1 CENTRAL EXPRESSWAY | | | | |
| CTE, Filter Lane to PIE Exit. | | | | |
| Weather: Clear | | Road Surface: Dry | Road Speed Limit: | |
| Traffic Flow: One Way | | Traffic Control: Not Controlled | Traffic Volume: Moderate | |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|------|-------|-------|---------------------|-----------------|
| SHD383D | Car | | | | Slightly Damaged | 0 |
| SJW5542E | Car | | | | Slightly Damaged | 1 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | Use of Pedestrian Crossing: NA |
| No. of Pedestrians Injured: NIL | |

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180610/2084

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20180610/2084

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|---------------------|--|-----------------------------------|
| Driver | | | |
| Name | SIM KWONG YAN | ID No. | S1825720C |
| Related Vehicle | SHD383D (Car) | Contact No. | 87817644 |
| Hospital/Clinic | VIVA MEDICAL CLINIC | Class of Driving Licence & Expiry Date | Class: 3 Date of Expiry: NIL |
| Date Treatment | 10/06/2018 | Date Discharge | 10/06/2018 |
| No. of Days granted Medical Leave | 03 | Degree of Injury | Slight |
| Driver | | | |
| Name | Toh Han Kait | ID No. | S8102244E |
| Related Vehicle | NIL | Contact No. | 98337047 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On the 10th of June 2018 at about 1415hrs, while I was driving along CTE in the filter lane to PIE (Changi) Exit. The traffic was a start stop situation. Suddenly a black car bearing number SJW5542E hit my rear. I then made a check and discovered my rear bumper was broken due to the collision. I then exchanged particulars and moved off. I then felt pain on the lower, upper back and neck. I then went to the doctor and received 3 days MC for the injuries.

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180610/2084

3 of 3

Report No. T/20180610/2084

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt MUHAMMAD ZAMAKHSYARII BIN
MOHAMED ALBAKRI

Signature Of Interpreter:
Not applicable

Signature Of Informant:

Date/Time:
10/06/2018 18:25

Officer In Charge Of Case:

TP / AEIT /

SSI 2 SITIMARSITA BINTE BOHA

Contact No.: 65476219



SINGAPORE
POLICE FORCE

Classification Of Case:

Authentication Stamp
NP168

| |
|---------------|
| SIGNATURE |
|---------------|

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 383D**AAD1806-083**

Not Authorized
Rebony B4 point \$4296.94

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 383D

VF1ABL15AUC282610

RENAULT

LATITUDE

10.6.2018

AUTO & GENERAL**PART****LIST**

| | | | |
|----|-------------------------------|----|----------------------|
| 1 | 1 BUMPER COVER REAR | \$ | <i>Br</i> 1,108.46 ✓ |
| 2 | 1 BUMPER LOWER REAR | \$ | <i>Nil</i> 768.84 ✓ |
| 3 | 1 BUMPER BRACKET CTR REAR | \$ | <i>Sn</i> 113.47 X |
| 4 | 1 BUMPR BRACKET SIDE RH REAR | \$ | <i>Sn</i> 135.97 X |
| 5 | 1 BUMPR RETAINER RH REAR | \$ | <i>Sn</i> 44.99 X |
| 6 | 1 BUMPER REFLECTOR RH | \$ | <i>Sn</i> 43.61 X |
| 7 | 1 BUMPR BRACKET SIDE LH REAR | \$ | <i>Sn</i> 135.97 X |
| 8 | 1 BUMPR RETAINER LH REAR | \$ | <i>Sn</i> 44.99 X |
| 9 | 1 BUMPER REFLECTOR LH | \$ | <i>CM</i> 43.61 ✓ |
| 10 | 1 BUMPER BEAM REAR | \$ | <i>B</i> 777.52 ✓ |
| 11 | 1 BUMPER BEAM BRACKET LH REAR | \$ | <i>R</i> 225.95 ✓ |
| 12 | 1 BUMPER BEAM BRACKET RH REAR | \$ | <i>R</i> 225.95 X |
| 13 | 1 BOOT REAR | \$ | <i>R</i> 2,872.68 |
| 14 | 1 BOOT FINISHER | \$ | <i>Sn</i> 470.06 |
| 15 | 1 BOOT WHEATERSTRIP | \$ | <i>Sn</i> 323.05 |
| 16 | 1 BOOT REFLECTOR LAMP LH | \$ | <i>Sn</i> 493.35 |
| 17 | 1 BOOT REFLECTOR LAMP RH | \$ | <i>Sn</i> 493.35 |
| 18 | 1 BOOT BADGE 'RENAULT' | \$ | <i>Sn</i> 225.36 |
| 19 | 1 BOOT BADGE | \$ | <i>Sn</i> 225.36 |
| 20 | 1 BOOT STRUT LH | \$ | <i>Sn</i> 276.08 |
| 21 | 1 BOOT STRUT RH | \$ | <i>Sn</i> 276.08 |
| 22 | 1 BOOT HINGE LH | \$ | <i>R</i> 367.84 |
| 23 | 1 BOOT HINGE RH | \$ | <i>R</i> 367.84 |
| 24 | 1 BOOT INNER TRIM | \$ | <i>Sn</i> 586.45 |
| 25 | 1 BOOT SWITCH | \$ | <i>Sn</i> 168.13 |
| 26 | 1 BOOT LOCK | \$ | <i>R</i> 202.67 |
| 27 | 1 BOOT LOCK CATCH | \$ | <i>R</i> 74.40 |
| 28 | 2 LICENCE PLATE LAMP | \$ | <i>Sn</i> 50.52 |
| 29 | 2 BOOT RUBBER PLUG | \$ | <i>Sn</i> 221.81 |

Trans-cab Auto Services Pte Ltd**AAD1806-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 383D

| | | | | |
|----|---|----|------------|---|
| 30 | 1 DOOR PANEL REAR LH | \$ | R 2,844.66 | } |
| 31 | 1 FENDER PANEL INNER TRIM REAR LH | \$ | Sn 671.45 | |
| 32 | 1 FENDER PANEL REAR LH | \$ | R 3,299.13 | |
| 33 | 1 WHEELARCH REAR LH | \$ | Sn 543.47 | |
| 34 | 1 FENDER PANEL INNER TRIM REAR RH | \$ | Sn 671.45 | |
| 35 | 1 FENDER PANEL REAR RH | \$ | R 3,299.13 | |
| 36 | 1 WHEELARCH REAR RH | \$ | Sn 543.47 | |
| 37 | 1 TAILLAMP RH | \$ | Sn 552.55 | |
| 38 | 1 TAILLAMP PANEL RH | \$ | R 986.70 | |
| 39 | 1 TAILLAMP LH | \$ | Sn 552.55 | |
| 40 | 1 TAILLAMP PANEL LH | \$ | R 986.70 | |
| 41 | 1 OUTER PANEL REAR (End Panel) | \$ | R 1,471.77 | |
| 42 | 1 OUTER PANEL REAR (End Panel)TRIM | \$ | Sn 404.56 | |
| 43 | 1 SPARE WHEEL PANEL (Luggage Floor Panel) | \$ | R 2,189.88 | |
| 44 | 1 SPARE WHEEL PANEL TRIM | \$ | Sn 612.21 | |
| 45 | 1 EXHAUST REAR | \$ | R 7,489.05 | |
| 46 | 1 EXHAUST CAP REAR | \$ | R 230.49 | |
| 47 | 1 FUEL FLAP L70Y | \$ | Sn 343.57 | |
| 48 | 1 FENDER WHEEL HOUSE PANEL REAR LH | \$ | R 3,039.04 | |

| | | |
|--------------|-----------|------------------|
| TOTAL | \$ | 42,096.20 |
| 10% | \$ | 4,209.62 |
| | \$ | 37,886.58 |

Special Nett

| | | | | |
|----|-------------------------------------|----|-------------|-------|
| 1 | 1SET PARKING AID | \$ | Shan 700.00 | Boosa |
| 2 | 1SET REAR BUMPER CLIP | \$ | na 66.00 | — |
| 3 | 1SET BUMPER BRACKET CTR CLIP | \$ | na 33.00 | — |
| 4 | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | na 10.00 | X |
| 5 | 1SET BUMPER RETAINER RH CLIP RR | \$ | na 20.00 | X |
| 6 | 1SET BUMPER BRACKET SIDE CLIP LH RR | \$ | na 10.00 | X |
| 7 | 1SET BUMPER RETAINER CLIP LH RR | \$ | na 20.00 | X |
| 8 | 1SET BUMPER LOWER REAR RIVET | \$ | na 22.00 | X |
| 9 | 1SET BUMPER LOWER REAR CLIP | \$ | na 66.00 | ✓ |
| 10 | 1 EXHAUST MOUNTING REAR | \$ | na 17.82 | X |
| 11 | 1SET BOOT FINISHER CLIP | \$ | na 24.20 | X |
| 12 | 1 BOOT STICKER "Trans-cab" | \$ | na 30.00 | X |
| 13 | 1 BOOT STICKER "6555-3333" | \$ | na 30.00 | X |

Trans-cab Auto Services Pte Ltd**AAD1806-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 383D

| | | | | |
|----|-------------------------------------|----|------------------|---|
| 14 | 1 BOOT INNER TRIM CLIP | \$ | <i>nn</i> 45.00 | } |
| 15 | 1SET FENDER WHEELARCH REAR RH CLIP | \$ | <i>nn</i> 35.00 | |
| 16 | 1SET FENDER WHEELARCH REAR LH CLIP | \$ | <i>nn</i> 35.00 | |
| 17 | 1 FENDER INNER TRIM CLIP LH | \$ | <i>nn</i> 28.00 | |
| 18 | 1 FENDER INNER TRIM CLIP LH | \$ | <i>nn</i> 28.00 | |
| 19 | 1 TAILLAMP CLIP RH | \$ | <i>nn</i> 5.00 | |
| 20 | 1 TAILLAMP CLIP LH | \$ | <i>nn</i> 5.00 | |
| 21 | 2 REAR WINDSCREEN SELANT | \$ | <i>nn</i> 80.00 | |
| 22 | 1 WINDSCREEN MOULDING | \$ | <i>nn</i> 100.00 | |
| 23 | 1 REAR WINDSCREEN INNER SPONGE SEAL | \$ | <i>nn</i> 100.00 | |
| 24 | 1 SPARE TYRE RIM (ROUE 7J 16H 2547) | \$ | <i>sn</i> 385.00 | } |
| 25 | 1 SPARE TYRE | \$ | <i>sn</i> 330.00 | |

TOTAL \$ 2,225.02**TOTAL PARTS \$ 40,111.60****LABOUR**

| | | | |
|---|----|------------------|-------------|
| Putty And Spray Painting Of The Affected Portion. | \$ | 6,000.00 | <i>4401</i> |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 4,200.00 | <i>4001</i> |
| To Rust-Proofing Of The Affected Areas. | \$ | <i>nn</i> 170.00 | <i>X</i> |
| To reinstall rear bumper parking sensor. | \$ | 170.00 | <i>601</i> |
| To transfer of bootlid fittings, attachments and perform water seepage test. | \$ | <i>nn</i> 170.00 | <i>X</i> |
| To repair and realign rear exhaust pipe. | \$ | <i>nn</i> 170.00 | <i>X</i> |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | <i>nn</i> 170.00 | <i>X</i> |

Trans-cab Auto Services Pte Ltd**AAD1806-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 383D

| | | | |
|--|----|------------------|----------|
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | <i>nn</i> 170.00 | <i>X</i> |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | <i>4</i> 170.00 | <i>X</i> |
| To supply and re-do rear luggage floor panel insulation padding. | \$ | <i>4</i> 380.00 | <i>X</i> |
| To transfer of rear fender fittings, attachment and perform water seepage test. | \$ | <i>4</i> 380.00 | <i>X</i> |
| To transfer of rear windscreen fittings and conduct water seepage test. | \$ | <i>4</i> 170.00 | <i>X</i> |
| To check steering geometry and computer wheel alignment | \$ | <i>4</i> 220.00 | <i>X</i> |
| To transfer of rear door fittings, attachment and perform water seepage test. | \$ | <i>4</i> 380.00 | <i>X</i> |

TOTAL \$ 12,540.00**Over All Total \$ 52,651.60***53031.60***(LUMP SUM)****Repair Days***20 DAYS**2 1/2 day,*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|-----------------------------|---|
| AUTO & GENERAL INSURANCE (S) PL | | Ref : CS/AGI18010696/Ksd3n2 | |
| (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | Date : 19-06-2018 |  |
| Code : AGI | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SJW 5542E | Veh. Inspected | SHD 383D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | C10001663/JM | Excess (\$) | 0.00 |
| Assign From | JULIE | Assign Date | 12/06/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | RENAULT LATITUDE (A) | c.c | 1995 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | VF1ABL15AUC282610 | Colour | METALLIC WHITE / RED |
| Odometer | 202273 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 215/60 R16 | GITI | 4 mm |
| L/H Front Tyre | 215/60 R16 | GITI | 4 mm |
| R/H Rear Tyre | 215/60 R16 | GITI | 5 mm |
| L/H Rear Tyre | 215/60 R16 | GITI | 5 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 10/06/2018 | Inspection Date | 12/06/2018 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2.500 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 383D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | BUMPER COVER REAR | BUCKLED | 1,108.46 | 1,108.46 |
| 1 | BUMPER LOWER REAR | DISTORTED / BENT | 768.84 | 768.84 |
| 1 | BUMPER BRACKET CTR REAR | SERVICEABLE | 113.47 | - |
| 1 | BUMPER BRACKET SIDE RH REAR | SERVICEABLE | 135.97 | - |
| 1 | BUMPER RETAINER RH REAR | SERVICEABLE | 44.99 | - |
| 1 | BUMPER REFLECTOR RH | SERVICEABLE | 43.61 | - |
| 1 | BUMPER BRACKET SIDE LH REAR | SERVICEABLE | 135.97 | - |
| 1 | BUMPER RETAINER LH REAR | SERVICEABLE | 44.99 | - |
| 1 | BUMPER REFLECTOR LH | CRACKED | 43.61 | 43.61 |
| 1 | BUMPER BEAM REAR | BENT | 777.52 | 777.52 |
| 1 | BUMPER BEAM BRACKET LH REAR | BENT | 225.95 | 225.95 |
| 1 | BUMPER BEAM BRACKET RH REAR | TO REPAIR SEE LABOUR | 225.95 | - |
| 1 | BOOT REAR | TO REPAIR SEE LABOUR | 2,872.68 | - |
| 1 | BOOT FINISHER | SERVICEABLE | 470.06 | - |
| 1 | BOOT WEATHERSTRIP | SERVICEABLE | 323.05 | - |
| 1 | BOOT REFLECTOR LAMP LH | SERVICEABLE | 493.35 | - |
| 1 | BOOT REFLECTOR LAMP RH | SERVICEABLE | 493.35 | - |
| 1 | BOOT BADGE "RENAULT" | NOT NECESSARY | 225.36 | - |
| 1 | BOOT BADGE | NOT NECESSARY | 225.36 | - |
| 1 | BOOT STRUT LH | SERVICEABLE | 276.08 | - |
| 1 | BOOT STRUT RH | SERVICEABLE | 276.08 | - |
| 1 | BOOT HINGE LH | TO REPAIR SEE LABOUR | 367.84 | - |
| 1 | BOOT HINGE RH | TO REPAIR SEE LABOUR | 367.84 | - |
| 1 | BOOT INNER TRIM | SERVICEABLE | 586.45 | - |
| 1 | BOOT SWITCH | SERVICEABLE | 168.13 | - |
| 1 | BOOT LOCK | TO REPAIR SEE LABOUR | 202.67 | - |
| 1 | BOOT LOCK CATCH | TO REPAIR SEE LABOUR | 74.40 | - |
| 2 | LICENCE PLATE LAMP | SERVICEABLE | 50.52 | - |
| 2 | BOOT RUBBER PLUG | SERVICEABLE | 221.81 | - |

Report Ref No. CS/AGI18010696/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| 1 | DOOR PANEL REAR LH | TO REPAIR SEE LABOUR | 2,844.66 | - |
| 1 | FENDER PANEL INNER TRIM REAR LH | SERVICEABLE | 671.45 | - |
| 1 | FENDER PANEL REAR LH | TO REPAIR SEE LABOUR | 3,299.13 | - |
| 1 | WHEELARCH REAR LH | SERVICEABLE | 543.47 | - |
| 1 | FENDER PANEL INNER TRIM REAR RH | SERVICEABLE | 671.45 | - |
| 1 | FENDER PANEL REAR RH | TO REPAIR SEE LABOUR | 3,299.13 | - |
| 1 | WHEELARCH REAR RH | SERVICEABLE | 543.47 | - |
| 1 | TAILLAMP RH | SERVICEABLE | 552.55 | - |
| 1 | TAILLAMP PANEL RH | TO REPAIR SEE LABOUR | 986.70 | - |
| 1 | TAILLAMP LH | SERVICEABLE | 552.55 | - |
| 1 | TAILLAMP PANEL LH | TO REPAIR SEE LABOUR | 986.70 | - |
| 1 | OUTER PANEL REAR (END PANEL) | TO REPAIR SEE LABOUR | 1,471.77 | - |
| 1 | OUTER PANEL REAR (END PANEL) TRIM | SERVICEABLE | 404.56 | - |
| 1 | SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | TO REPAIR SEE LABOUR | 2,189.88 | - |
| 1 | SPARE WHEEL PANEL TRIM | SERVICEABLE | 612.21 | - |
| 1 | EXHAUST REAR | TO REPAIR SEE LABOUR | 7,489.05 | - |
| 1 | EXHAUST CAP REAR | TO REPAIR SEE LABOUR | 230.49 | - |
| 1 | FUEL FLAP L70Y | SERVICEABLE | 343.57 | - |
| 1 | FENDER WHEEL HOUSE PANEL REAR LH | TO REPAIR SEE LABOUR | 3,039.04 | - |
| | LESS 10% DISCOUNT | | -4,209.61 | -292.44 |
| | | | 37,886.58 | 2,631.94 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET PARKING AID (SN) | SHORTED | 700.00 | 600.00 |
| 1 | SET REAR BUMPER CLIP (SN) | NECESSARY | 66.00 | 66.00 |
| 1 | SET BUMPER BRACKET CTR CLIP (SN) | NECESSARY | 33.00 | 33.00 |
| 1 | SET BUMPER BRACKET SIDE CLIP RH RR (SN) | NOT NECESSARY | 10.00 | - |
| 1 | SET BUMPER RETAINER RH CLIP RR (SN) | NOT NECESSARY | 20.00 | - |
| 1 | SET BUMPER BRACKET SIDE CLIP LH RR (SN) | NOT NECESSARY | 10.00 | - |
| 1 | SET BUMPER RETAINER CLIP LH RR (SN) | NOT NECESSARY | 20.00 | - |

Report Ref No. CS/AGI18010696/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| 1 | SET BUMPER LOWER REAR RIVET (SN) | NOT NECESSARY | 22.00 | - |
| 1 | SET BUMPER LOWER REAR CLIP (SN) | NECESSARY | 66.00 | 66.00 |
| 1 | EXHAUST MOUNTING REAR (SN) | NOT NECESSARY | 17.82 | - |
| 1 | SET BOOT FINISHER CLIP (SN) | NOT NECESSARY | 24.20 | - |
| 1 | BOOT STICKER "TRANS-CAB" (SN) | NOT NECESSARY | 30.00 | - |
| 1 | BOOT STICKER "6555-3333" (SN) | NOT NECESSARY | 30.00 | - |
| 1 | BOOT INNER TRIM CLIP (SN) | NOT NECESSARY | 45.00 | - |
| 1 | SET FENDER WHEELARCH REAR RH CLIP (SN) | NOT NECESSARY | 35.00 | - |
| 1 | SET FENDER WHEELARCH REAR LH CLIP (SN) | NOT NECESSARY | 35.00 | - |
| 1 | FENDER INNER TRIM CLIP LH (SN) | NOT NECESSARY | 28.00 | - |
| 1 | FENDER INNER TRIM CLIP LH (SN) | NOT NECESSARY | 28.00 | - |
| 1 | TAILLAMP CLIP RH (SN) | NOT NECESSARY | 5.00 | - |
| 1 | TAILLAMP CLIP LH (SN) | NOT NECESSARY | 5.00 | - |
| 2 | REAR WINDSCREEN SEALANT (SN) | NOT NECESSARY | 80.00 | - |
| 1 | WINDSCREEN MOULDING (SN) | NOT NECESSARY | 100.00 | - |
| 1 | REAR WINDSCREEN INNER SPONGE SEAL (SN) | NOT NECESSARY | 100.00 | - |
| 1 | SPARE TYRE RIM (ROUE 7J 16H 2547)(SN) | SERVICEABLE | 385.00 | - |
| 1 | SPARE TYRE (SN) | SERVICEABLE | 330.00 | - |
| | | | 2,225.02 | 765.00 |
| | LABOUR | | | |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 6,000.00 | 440.00 |
| | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. } | | 4,200.00 | 400.00 |
| | INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET RH REAR,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,DOOR PANEL REAR LH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,OUTER PANEL REAR (END PANEL),SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR,EXHAUST CAP REAR AND FENDER WHEEL HOUSE PANEL REAR LH. } | | - | - |
| | TO RUST-PROOFING OF THE AFFECTED AREAS. | NOT NECESSARY | 170.00 | - |
| | TO REINSTALL REAR BUMPER PARKING SENSOR. | | 170.00 | 60.00 |
| | TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO REPAIR AND REALIGN REAR EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| | TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING. | NOT NECESSARY | 380.00 | - |
| | TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 380.00 | - |
| | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | - |
| | TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 380.00 | - |
| | | | 12,920.00 | 900.00 |
| | GRAND TOTAL | | 53,031.60 | 4,296.94 |
| RECOMMENDED COST OF REPAIRS | | | | 4,296.94 |

Report Ref No. CS/AGI18010696/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.