

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA INSURANCE	DATE	: 11/06/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKZ3039C		<i>pass to Adrian</i>
MODEL	: KIA CERATO FORTE 1.6A		<i>Vivian</i>
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 11-Jun-18
		TIME	: 12:30HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Repis</i>	1	\$ 688.90	\$ 688.90
2	REAR BUMPER LOWER LIP <i>cut</i>	1	\$ 360.00	\$ 360.00
3	REAR BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 89.60	\$ 89.60
4	REAR BUMPER REFLECTOR RH <i>cracked</i>	1	\$ 103.00	\$ 103.00

463 TOTAL PRICE \$ 1,241.50
 416.70 LESS 10% \$ 124.15
 SUB TOTAL PRICE \$ 1,117.35 *416.70*

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00

20 TOTAL \$ 240.00 *20*

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 800.00	<i>200</i>	
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 800.00	<i>200</i>	

3	TUFF COAT	\$ 250.00	X	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	
TOTAL		\$2,090.00	480	480

ESTIMATE REPORT

TOTAL PARTS COST : \$ 1,357.35
TOTAL LABOUR COST : \$ 2,090.00
TOTAL REPAIR COST : \$ 3,447.35

total: 916.70
h/s: 700

Adrian being
12/08/18
02 Days

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

416.70
+ 20.00
+ 480.00

916.70
- 20% 183.34

733.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lump Sum
\$ 700
2 days