

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3532G

DATE 11/6/2018 15:00

MAKE :

DOA: 11.06.18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet — <i>Paint</i>			\$ 1,526.00
	Front Bumper Cover — <i>cr</i>			\$ 562.30
	Front Bumper Sponge <i>X 500</i>			\$ 142.20
	Front Bumper Grille (LH) <i>X 500</i>			\$ 40.30
	Headlamp Support Panel Assy — <i>cr</i>			\$ 1,067.50
	Headlamp (LH) — <i>cr</i>			\$ 1,388.00
	Front Fender (LH) — <i>Paint</i>			\$ 619.00
	Front Fender Shield (LH) — <i>tin</i>			\$ 169.80
	Air Cleaner Assy <i>✓</i> <i>cr</i>			\$ 188.00
	Air Cleaner Bottom Assy <i>X 500</i>			\$ 325.00
	Front Door Mirror (LH) <i>X repair</i>			\$ 980.50
	Front Wheel Rim (LH) <i>✓</i> <i>Paint</i>			\$ 351.90
	Front Wheel Hub Cap (LH) — <i>cr</i>			\$ 150.70
	Front Wheel Bearing <i>X 500</i>			\$ 258.50
	Front Suspension Lower Arm (LH) — <i>Paint</i>			\$ 715.10
	Knuckle Arm (LH) <i>X 500</i>			\$ 582.95
	SUB TOTAL			\$ 9,067.75
	LESS 20%			\$ 1,813.55
	DISCOUNTED TOTAL			\$ 7,254.20
	Front Fender Advertisement Logo (LH) — <i>acc</i>			\$ 100.00 Nett
	Front Door Comfort Logo (LH) — <i>acc</i>			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) — <i>acc</i>			\$ 100.00 Nett
	Front Tyre (LH) — <i>64</i>			\$ 216.00 Nett
				\$ 491.00
	Labour Charge			600
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,000.00 <i>850</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 100.00 <i>50</i>
	Towing Charge			\$ 60.00 <i>—</i>
	Remove/Refix Undercarriage (FRT)			\$ 400.00 <i>100</i>
	FRT Wheel Alignment			\$ 120.00 <i>60</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>80</i>
	TOTAL LABOUR			\$ 3,380.00
	ESTIMATE TOTAL			\$ 11,125.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Ka lora 11/6/18
12/6/18 1030 hrs

4 11-15

4/5

After Repair photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.