

ASS. REC. BY:

REF:

CS/MSG 18010735/A qd302

Special Instruction:

Survivor:

Meinher

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

12/6/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLW 466B

Insured:

FBA 7083K

at Workshop m/s

Juek Cars

Tel: 9220 6746

of

Blk 3007, ubi Rd 1 # 01-450

Policy No:

MSD / VM7 / 17-368293

Claim No:

MSC / V / 18-000803

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/06/2018

18/06/2018 @ after 2pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

'up'

Date/Time:

4.47pm @ 12/6/18

Person Contacted:

Thana

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLW 466B-X

FBA 7083K-X

19/6/18@

2.20pm Informed Katherine Wong, we are pending estimate from repairer.

26/7/18@

2.49pm refused to Katherine Wong via Meinher.

20/9/18@

5.10pm confirmed with Thana Anul Ag \$1089.60, 2 days.
(Red \$878.40, 45%)

REF: MSLH

mermen

ASSIGNMENT

From: Date: 18062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 466B

at Workshop m/s

Jack Cars

of

816 2007 Wbi Rd 1 # 01-450

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

after 2pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 466B.

Yr Regn:

2018 / Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

5731

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU11230924

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16.

R:

215/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

18/06/18

Survey held at

Jack Car.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSLG.

RECEIVED 27 SEP 2018

26/9/2018.

Date/Time, File Pass to?

☐

Preli. Report

1) 29/9 1450

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

150

Transportation

) \$ + R\$ SI

) Photos

) Others

10

TOTAL

160

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

1089.60

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2018		12 Jun 2018 16:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ANG POH ENG, ID: S1565244F			
Main Claimant:	CHAN LAW LAM, ID: S2166219D			
Vehicle Reg. No.:	SLW466B	Date of Loss:	08/06/2018 09:00 - :59 [4 Months and 13 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/18-000803	Policy/Cover Note No.:	MSD/VMT/17-368293 (Third Party Only) Coverage: 29/07/2017 - 28/07/2018	
Vehicle Reg. No. (Insured):	FBA7083K	Policy No. (Claimant):		
		Excess:		
Repairer:	Jack Cars Enterprise Pte Ltd () BLK3007 UBI ROAD 1 #01-450, 408700 Ubi - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/06/2018]			
Adj Asg. Remarks:	on WP. SJE Agree Please appoint LKK Auto Consultancy Pte Ltd and contact Ms S.Thanaletchumi @ 92206746 Liability (Non-reporting)			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Thanaletchumi Santerashigaram <thana@jackcars.com.sg>
Sent: Thursday, 20 September 2018 5:18 PM
To: Shiau Chan (LKKAuto); Adrian Ling (LKKAuto)
Subject: Re: SLW466B

Greetings,

For an amicable settlement , would accept the offer of \$1,089.60 before GST with 2days of repair works.

Kindly revert.

Thank You.

*Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 92206746
Fax : 67488834
Email : thana@jackcars.com.sg*

On Wed, Sep 12, 2018 at 12:24 PM, Thanaletchumi Santerashigaram <thana@jackcars.com.sg> wrote:
Greetings Mr. Adrian ,

Kindly revert on the finalized COR.

Thank You.

*Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 92206746
Fax : 67488834
Email : thana@jackcars.com.sg*

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 26 Sep 2018

Preliminary Advice

Insured Vehicle No	: FBA7083K	Accident Date	: 08/06/2018
TP Vehicle No	: SLW466B	Assignment Date	: 12/06/2018
Make	: HONDA VEZEL	Est. Duration of Repair	: 2
Date of Inspection	: 18/06/2018		
Inspection At	: JACK CARS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,968.00
Revised Amount	:S\$	1,089.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,089.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 19 June 2018 2:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLW 466B (YOUR REF: MSC/V/18-000803)

This mail is associated with :
***SLW466B (MSC/V/18-000803)**
[FBA7083K]
TP
CHAN LAW LAM
Jun 8 2018 9:00AM
[ANG POH ENG]
Jack Cars Enterprise Pte Ltd

Dear Katherine,

Please be informed that we have inspected the vehicle SLW 466B on 18/06/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/06/2018 09:39
Date Of Accident	08/06/2018 09:35
Exact Location Of Accident	ALONG UPPER TIMAH ROAD TURNING TO DAIRY FARM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW466B
Insured/Policyholder	
Name Of Registered Owner	CHAN LAW LAM
NRIC No	S2166219D
Email Address	LEE.SOO.KHOONG@CPGCORP.COM.SG
Mobile Phone No	(LOCAL) +65-96612290
Alternative Phone No	OFFICE-96612290

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 1.5X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	51001004

Driver

Name of Driver	CHAN LAW LAM
NRIC No	S2166219D
Date Of Birth	15/02/1957
Occupation	INDOOR
Date Of Driving Pass	28/06/1996
Driving Experience	21 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96612290
Fax Number	
Contact Number	OFFICE-96612290
EMail Address	LEE.SOO.KHOONG@CPGCORP.COM.SG

Address	6 PETIR ROAD #20-02 MAYSPRINGS
Postcode	678267
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MICHELLE LEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

----- REFER TO ATTACHMENT -----

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RECORDING WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBA7083K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packager); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-448 / 450 / 452
SINGAPORE 408701
TEL: 6748 8824 FAX: 6748 8834
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08/06/2018 at about 0935 hrs, I was driving my car bearing registration number SLW 466B along upper Timah Road turning to Dairy Farm Road.

All off a sudden I felt an impact on the rear of my car. I stopped and came out to make a check. I discovered that a motorcycle bearing registration number FBA 7083 K had self-skipped and hit the rear of my car.

my daughter namey: michelle Lee Hp: 81289689 was in the car with me at the point of accident.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 9-6-2018 9am.

Driver's Signature
(if driver is not the policyholder)
Date & Time:

JACK CARS ENTERPRISE PTE LTD
BLK 3007 UBI ROAD 1
#01-448 / 450 / 452
SINGAPORE 408701
TEL: 6748 8824 FAX: 6748 8834
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



TP MSLG.
Xiao Chen.

ESTIMATE

DATE OF ACCIDENT : 08/06/2018
VEHICLE : SLW466B
MAKE & MODEL : HONDA VEZEL
INSURANCE : MSIG INSURANCE
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	REAR BUMPER <i>Deformed</i>		\$ 960
2.	REAR BOOT LID <i>Repair</i>	REPAIR	
SPECIAL NETT			
2.	REVERSE SENSOR <i>not in</i>		\$ 200
4.	CLIPS <i>Nh</i>		\$ 50
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 450
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$ 400
3.	TO REMOVE & REINSTALL REVERSE SENSOR		\$ 100
PARTS - 20%:		\$ 768	
SPECIAL NETT :		\$ 250	
LABOUR :		\$ 950	
TOTAL :		\$ 1,968	
7% GST :		\$ 137.76	
GRAND TOTAL :		\$ 2,105.76	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
P/P 18/06/16
02 Camp

total: 1089.60
(P/P)

762
↓
609.60

30 30

200
200
50
450














...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		12 Jun 2018 16:18 Edit Adj Rpt	S\$1,089.60 Edit Estimates	S\$1,089.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ANG POH ENG , ID: S1565244F									
Main Claimant: CHAN LAW LAM , ID: S2166219D									
Vehicle Reg. No.: SLW466B		Date of Loss: 08/06/2018 09:00 - :59 [4 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000803		Policy/Cover Note No.: MSD/VMT/17-368293 (Third Party Only) Coverage: 29/07/2017 - 28/07/2018							
Vehicle Reg. No. (Insured): FBA7083K		Policy No. (Claimant):							
		Excess:							
Repairer: Jack Cars Enterprise Pte Ltd () BLK3007 UBI ROAD 1 #01-450, 408700 Ubi - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/07/2018]									
Adj Asg. Remarks: on WP. SJE Agree Please appoint LKK Auto Consultancy Pte Ltd and contact Ms S.Thanaletchumi @ 92206746 Liability (Non-reporting)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLW466B (MSC/V/18-000803)**
[FBA7083K]
TP
CHAN LAW LAM
Jun 8 2018 9:00AM
[ANG POH ENG]
Jack Cars Enterprise Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 14:49	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/09/18 09:35	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010735/AQD3E2

Date: 27/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: MSD/VM/17-368293

Claimant Vehicle No: SLW466B

Insured Vehicle No: FBA7083K

Date of Loss: 08/06/2018

Nature of Claim: TP

Claim No: MSC/V/18-000803

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW466B

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4430928

Reg. Date: 26/01/2018 (Man. Year: 2017)

Chassis No: RU11230924

Colour: White

Odometer: 5731 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,018.00	639.60	378.40	37.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	450.00	500.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,968.00	1,089.60	878.40	44.63
+ GST 7.00/7.00% (S\$)	137.76	76.27	61.49	44.64
Nett Amount (S\$)	2,105.76	1,165.87	939.89	44.63

INSPECTION

Date of Assignment: 12/06/2018

Date Inspected: 18/06/2018 Inspected At:

Jack Cars Enterprise Pte Ltd
BLK3007 UBI ROAD 1 #01-450
Singapore 408700

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW466B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	960.00 FL	*762.00 FL
2	1		*REAR BOOT LID (NPA)	Repair	0.00 FL	*- FL
3	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
4	1		*CLIPS	Necessary	50.00 FS	*30.00 FS
					Sub Total (S\$)	1,210.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	192.00
					Total Parts (S\$)	639.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	450.00	200.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	400.00	200.00
3	TO REMOVE & REINSTALL REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			950.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >