

INS. CASE OWNER: Shawn CC 6 /AIG1801 0727, Upbng LKK: 12/6/18 IDAC: 12/6/18

Surveyor: Murcus DOI: 12/6/18 Date / Time: 12/6/18 Registered in Merimen: 12/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SGW 4717K
Name of Insured: LEE WING SIN
Insured Tel No.: HP: 11/6/18
Excess Sec II :\$5
Is driver the owner? (YES / NO) Nature of Accident:
If NO, Driver Name / Age: PETRA ONG YIMMIN
Driver Tel No.: (V/L) YES / NO

Claim No.: 24046444456
Policy No.: 20002255
Make / Model: TOYOTA
Place of Accident: NEW BRIDGE
OI GIA REPORT: YES NO : TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No



INSRS: Kim
WSP: Chwee
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<u>12/6/18</u>	Non-Reporting 1st (1st):	
<u>12/6/18</u>	Non-Reporting 1st (2nd):	
<u>12/6/18</u>	Non-Reporting 1st (Final):	
<u>12/6/18</u>	Notification 1st (if non-pickup):	
<u>12/6/18</u>	Call OE:	<u>24/5/18</u>
<u>12/6/18</u>	After call 1st to OE:	
<u>12/6/18</u>	Documentation Check List: Handler Typist	
<u>12/6/18</u>	Notification 1st (if non-pickup):	
<u>12/6/18</u>	After call 1st to OE:	
<u>12/6/18</u>	Authorisation To Act:	
<u>12/6/18</u>	Release Voucher:	
<u>12/6/18</u>	Final Repair Bill:	
<u>12/6/18</u>	Car Rental Invoice:	
<u>12/6/18</u>	Towing Invoice:	
<u>12/6/18</u>	LTA / GIA:	
<u>12/6/18</u>	Medical Bill:	
<u>12/6/18</u>	PDR:	
<u>12/6/18</u>	Mandate/Reject Instruction:	
<u>12/6/18</u>	LOD:	
<u>12/6/18</u>	Payment Breakdown Form:	
<u>12/6/18</u>	Post-Repair Photos:	
<u>12/6/18</u>	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$5	(days) Reduction:
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	\$5	
Loss of Rental (LOR):	\$5	(days)
Loss of Use (LOU):	\$5	(days)
Loss of Income (LOI):	\$5	(days)
LOR only	<input type="checkbox"/>	LOU only
GIA/LTA Search	\$5	
Medical:	\$5	
Disbursement:	\$5	(e.g. Tow/Independent)
Legal Cost	\$5	
Total:	\$5	Global Sum \$5:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$5	Name 1:
Payee 2 (Strike if N.A.):	\$5	Name 2:
Payee 3 (Strike if N.A.):	\$5	Name 3:

03/11/13 wef
ASS. REC. BY: MORIS

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLJ93292

at Workshop m/s Kinchua

of SW 4717K

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 110

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 8617E

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

17A 92532 22/10 24/10

26/6/14 4/5 @ 4600 confirmed with Alu.

(Reel # 10313.71/6971)

Veh No: SLJ93292 Yr Regn: 4 13

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Lexus GS350 c.c. 3456

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 95547 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHBE1BL005014005

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40ZR19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

L/Bal: 6 mm D.O.A: 11/6/18 D.O.I: 12/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010737/Upb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-06-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 4717K	Veh. Inspected	SLJ 9329Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/06/2018	Inspection Date	12/06/2018	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Not Affected
 4/5 4600
 427.
 12/6/18

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHICLE NO: SLJ 9329Z

QTY	PARTICULAR	AMOUNT
1 PCS	BOOTLID <i>11</i>	\$2,048.10 <i>X</i>
1 PCS	BOOTLID WEATHERSTRIP <i>11</i>	\$399.20 <i>X</i>
1 PCS	REAR BUMPER <i>70/02 1451.20</i>	\$2,166.20 <i>✓</i>
1 PCS	REAR BUMPER REINFORCEMENT <i>sent 866.01</i>	\$1,065.10 <i>✓</i>
1 PCS	REAR BUMPER SPONGE <i>70/11 266.05</i>	\$342.20 <i>✓</i>
2 PCS	REAR BUMPER REVERSE ULTRASONIC SENSORS @\$325.20 <i>86006</i>	\$650.40 <i>✓</i>
1 PCS	REAR BUMPER SIDE RETAINER N/S <i>sent</i>	\$89.20 <i>✓</i>
1 SET	REAR BUMPER CLIPS <i>new</i>	\$50.00 <i>✓</i>
2 PCS	TAILLAMPS @\$765.10 <i>N/S/scr</i>	\$1,530.20 <i>120</i>
1 PCS	TAILLAMP LOWER BRACKET N/S <i>N/S</i>	\$45.30 <i>X</i>
1 PCS	REAR END PANEL <i>12</i>	\$966.01 <i>X</i>
1 PCS	REAR BUMPER LOWER SKIRTING <i>de/4m1</i>	\$766.20 <i>✓</i>
1 PCS	REAR BUMPER REFLECTOR N/S <i>11</i>	\$85.50 <i>X</i>
1 PCS	REAR EXHAUST <i>11</i>	\$1,655.10 <i>X</i>
1 PCS	REAR EXHAUST CHROME N/S <i>sent 195</i>	\$385.00 <i>✓</i>
		<i>(102)</i> <i>5099.96</i> <i>4888.24</i>
		\$12,243.71
LABOUR CHARGES:		
	TO CHECK WIRING	\$80.00 <i>20</i>
	TO DISMENTLE & REPLACING REVERSE SENSOR	\$120.00 <i>50</i>
	TO TRANSFER BOOTLID MECHANISM <i>11</i>	\$100.00 <i>X</i>
	TO DISMENTLE & REFIX REAR EXHAUST <i>11</i>	\$180.00 <i>X</i>
	TO DISMENTLE & REFIX SEAT CUSHION UPHOLSTREY	\$180.00 <i>60</i>
	TO SPRAY RUST PROOFING <i>11</i>	\$80.00 <i>X</i>
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$850.00 <i>480</i>
	TO PUTTY & SPRAY PAINTING	\$1,080.00 <i>600</i>
	TOTAL	\$14,913.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

5798.24

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 13.07.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SLJ9329Z AND SGW4717K ON 11.06.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SLJ9329Z**, which was involved in the captioned accident with your insured vehicle no: **SGW4717K**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	4,922.00	✓
2) Loss Of Use (4days + 1holiday x \$150)	\$	750.00	✓
3) GIA Search Fee	\$	2.00	✓
	<u>\$</u>	<u>5,674.00</u>	SW

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Result |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.


Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd



Name of Policyholder : Jeremy Lim Keng Swee
Period of Insurance : 06 Oct 2017 To 05 Oct 2018
Engine No. : 2GR8772141
Chassis No. : JTHBE1BL005014005

Vehicle No. : SLJ9329Z
Policy No. : 2100485835-01
Endorsement No. :
Issued Date : 18 Sep 2017

Make/Model : LEXUS GS350
Engine Capacity/Tonnage : 3,456.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2013
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorized Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or record-keeping. The operator of a vehicle shall have no liability in connection with any trade or business or use for any purpose in connection with Motor Trade.

^a Limitations rendered inoperative by Section 3 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 98 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage – \$0

Wurfschrauben : 3100

Named Driver and Excess (where applicable)

Jengry Lim Kang Swee - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Regulators (For claims related repairs)

any accident repairs to the Vehicle can be carried out at the repairer of Your choice (unless specifically excluded by Us)

For Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency hotline at +852 8356 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 195), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

052225-000

SAFE HARBOUR ASSURANCE AGENCY

BLK 208 HOUGANG ST 21 #04-207

SINGAPORE 530208

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8378617E



Name

JEREMY LIM KENG SWEE

Race

CHINESE

Date of birth

27-06-1983

Country/Place of birth

MALAYSIA

Sex

M

S8378617E



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8378617E

Name

JEREMY LIM KENG SWEE

Birth Date 27 Jun 1983

Issue Date 03 Apr 2013



5402398

NRIC No. S8378617E



Date of expiry
10-12-2014

Address

APT BLK 875A JURONG WEST STREET 84
#05-211
SINGAPORE 641875

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 2B Motorcycles <= 200 cc 26 Jun 2008
Class 2 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 26 Jun 2008

NP 425A



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8617E
Vehicle Details	
Vehicle No.:	SLJ9329Z
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS350 F SPORT AUTO
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	2GR8772141
Chassis No.:	JTHBE1BL005014005
Maximum Power Output:	233.0 kW (312 bhp)
Open Market Value:	\$66,239.00
Original Registration Date:	02 Apr 2013
First Registration Date:	02 Apr 2013
Transfer Count:	2
Actual ARF Paid:	\$66,239.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Apr 2023
PARF Rebate Amount:	\$46,367.00
Intended COE Rebate Details	
COE Expiry Date:	01 Apr 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$96,101.00
COE Rebate Amount:	\$46,165.00
Total Rebate Amount:	\$92,532.00

The information contained herein is correct as at 12 Jun 2018

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 28 July 2018 9:11 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg)
Subject: Your Ref: SLJ 9329Z *Our Ref: CC6/AIG18010737/Upb3 [ACCIDENT INVOLVING SGW 4717K(AIG) & SLJ 9329Z ON 11/06/2018]

Your Ref: **SLJ 9329Z** *Without Prejudice*
Our Ref: CC6/AIG18010737/Upb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SGW 4717K(AIG) & SLJ 9329Z ON 11/06/2018

We refer to the above matter.

We propose settlement at a global sum of **\$5,420.00(all-in).**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Wednesday, 1 August 2018 10:18 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: SLJ 9329Z *Our Ref: CC6/AIG18010737/Upb3 [ACCIDENT INVOLVING SGW 4717K(AIG) & SLJ 9329Z ON 11/06/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$5,420.00(all-in).

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, July 28, 2018 9:11 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: Your Ref: SLJ 9329Z *Our Ref: CC6/AIG18010737/Upb3 [ACCIDENT INVOLVING SGW 4717K(AIG) & SLJ 9329Z ON 11/06/2018]

Your Ref: **SLJ 9329Z** Without Prejudice
Our Ref: CC6/AIG18010737/Upb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SGW 4717K(AIG) & SLJ 9329Z ON 11/06/2018

We refer to the above matter.

We propose settlement at a global sum of **\$5,420.00(all-in)**.

Please confirm acceptance.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18010737/Upb3

03 JULY 2018

LEE LAY SIN
BLK 219 BISHAN ST 23
#04-289
SINGAPORE 570219

Dear Sir/Madam,

ACCIDENT INVOLVING SGW 4717K & SLJ 9329Z ON 11/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLJ 9329Z against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Jeremy Lim Ken Snee ("the third party claimant")
of BIK 675A Jurong West St 64 # 05-211 5641675 (address),
owner of SLJ9329Z (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLJ9329Z that was
damaged pursuant to the accident which occurred on 11/6/18 (date) along
BIK 675A Jurong West St 64 # 05-211 5641675 (location)
involving vehicle no/s SGW 4717K ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 12 day of 06 (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 5420.00 (repair costs), S\$ _____ (loss of use/rental) S\$ _____ (search fees) for vehicle no. SLJ 9329Z that was damaged pursuant to the accident which occurred on 11/6/18 (date) along New Bridge Road (location) involving vehicle no/s S2W 4717K.

This is pursuant to the inspection conducted on 12/6/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Lim Key Swee ("third party claimant") of vehicle no. SLJ 9329Z to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLJ 9329Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.



Dated this 03 day of 08 (month) 20 18 (year)

CKS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20344

Date: 13.07.2018

Vehicle No: SLJ9329Z

Make/Model: TOYOTA LEXUS

Chassis/Eng# :

Accident Date: 11.06.2018

Claim No : 0618-20344

:

		Amount
To proceed on lump sum repair	S\$	4,600.00

E. & O. E.

Total : S\$ 4,600.00

GST @ 7% : S\$ 322.00

Amount Due : **S\$ 4,922.00**


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-089849

Date of Request: 12/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 12/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SGW4717K
Accident Date 11/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-089849

Date of Request: 12/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 12/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SGW4717K
Accident Date 11/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGW4717K	AIG Asia Pacific Insurance Pte. Ltd.	19/07/2017-18/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane












































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 Edit Reg		12 Jun 2018 00:00 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE LAY SIN, ID: -								
Main Claimant:	LIM KENG SWEE JEREMY								
Vehicle Reg. No.:	SLJ9329Z	Date of Loss:	11/06/2018 19:00 - :59 [62 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7404654254SG	Policy/Cover Note No.:	2100032855 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGW4717K	Policy No. (Claimant):	2100485835-01						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (13/06/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ9329Z (7404654254SG)
[SGW4717K]
TP
LIM KENG SWEE JEREMY
Jun 11 2018 7:15PM
[LEE LAY SIN]
Kim Chwee Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/06/18 14:26	Accident Statement <small>From: SC - Reg. No: SGW4717K, Claimant: LEE LAY SIN</small>		Load HTM
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 18:04	Chassis Number		Load JPG <input checked="" type="checkbox"/>
2	12/06/18 18:04	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
3	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
4	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
5	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
6	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
7	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
8	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
9	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
10	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
11	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
12	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
13	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
14	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
15	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
16	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
17	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
18	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
19	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
20	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
21	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
22	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
23	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
24	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
25	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
26	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
27	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
28	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
29	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>
30	12/06/18 18:04	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/06/18 18:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/06/18 18:05	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/06/18 18:05	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	28/07/18 09:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 08:48	TP GIA REPORT	 Load PDF	
2	28/07/18 09:05	TP ESTIMATE_MARKED	 Load PDF	
3	15/08/18 08:49	WORKSHOP INVOICE	 Load PDF	
4	15/08/18 08:49	AUTHORISATION TO ACT FORM	 Load PDF	
5	15/08/18 08:49	Release Voucher	 Load PDF	
6	15/08/18 08:49	GIA SEARCH	 Load PDF	
7	15/08/18 08:49	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGW4717K (Insd veh)	Model:	LEXUS GS350 3.5 (A)
	SLJ9329Z (TP veh)		
Date of Accident:	11/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		15,957.67
Final Repair Cost	:	\$		5,420.00
Loss of Use	:	\$		5.00 days at \$100.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		5,420.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown				
1)	Kim Chwee Auto Pte Ltd	:	\$	5,420.00
2)		:	\$	
3)		:	\$	

JOANNE LEE KHANG MIN

15 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010737/UPB3Q2

Date: 15/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100032855
 Claimant Vehicle No: SLJ9329Z Insured Vehicle No: SGW4717K
 Date of Loss: 11/06/2018 Nature of Claim: TP Claim No: 7404654254SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ9329Z
 Make & Model: LEXUS GS350, 3.5 (A) Engine No: 2GR8772141
 Reg. Date: 02/04/2013 (Man. Year: 2012) Chassis No: JTHBE1BL005014005
 Colour: Silver Odometer: 95547 km
 Engine Capacity: 3456 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R19 Rear Tyre Size: 245/40Z R19
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,243.71	4,589.24	7,654.47	62.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,210.00	1,460.00	54.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,913.71	5,799.24	9,114.47	61.11
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	14,913.71	4,600.00	10,313.71	69.16
+ GST 7.00/7.00% (S\$)	1,043.96	322.00	721.96	69.16
Nett Amount (S\$)	15,957.67	4,922.00	11,035.67	69.16
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,424.00		
Global Sum Settlement (S\$)		5,420.00		

INSPECTION

Date of Assignment: 12/06/2018
 Date Inspected: 12/06/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	2,048.10 F	*- FL
2	1		*BOOTLID WEATHERSTRIP	Not Necessary	399.20 F	*- FL
3	1		*REAR BUMPER	Dented / Deformed	2,166.20 F	*1,451.20 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	1,065.10 F	*866.01 FL
5	1		*REAR BUMPER SPONGE	Torn	342.20 F	*266.05 FL
6	2		*REAR BUMPER REVERSE ULTRASON SENSORS	Shorted	650.40 F	*650.40 FL
7	1		*REAR BUMPER SIDE RETAINER N/S	Bent	89.20 F	*89.20 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
9	1		*TAILLAMPS	N/S Cracked	1,530.20 F	*765.10 FL
10	1		*TAILLAMP LOWER BRACKET N/S	No such part	45.30 F	*- FL
11	1		*REAR END PANEL	Repair	966.01 F	*- FL
12	1		*REAR BUMPER LOWER SKIRTING	Deformed / Twisted	766.20 F	*766.20 FL
13	1		*REAR BUMPER REFLECTOR N/S	Not Necessary	85.50 F	*- FL
14	1		*REAR EXHAUST	Not Necessary	1,655.10 F	*- FL
15	1		*REAR EXHAUST CHROME N/S	Bent	385.00 F	*195.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$) 12,243.71 5,099.16
 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00 509.92

Total Parts (S\$) 12,243.71 4,589.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	120.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	180.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	180.00	60.00
6	TO SPRAY RUST PROOFING	New	80.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	850.00	480.00
8	TO PUTTY & SPRAY PAINTING	New	1,080.00	600.00
Gross Labour Cost (S\$)			2,670.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >