



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

13/06/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▼

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▼

Tyre Condition

Age of Tyres

Front Tyre Size

90/90R17

Front left side

RALLO5mm

Front right side

Spare wheel

Rear Tyre Size

120/80R17

Rear left side

RALLO5mm

Rear right side

