



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD BAJAJ PULSAR-180CC DTS-I (M) (FBH7642K)

Date of Loss

4 June 2018

Time of Loss

13.55

Loss Description

SLN1343M (INSD) C/W FBH7642K (TP)BIKE

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

29/07/2018



Days of work completion *

48



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

FBH7642K

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

20/09/2013



Mileage

46240

Age of Vehicle

4

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2012

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

MOHAMED SATHIK FARLUDEEN

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD BAJAJ

ASSESSMENT INFO... BAJAJ

CATEGORY Model

POLICY INFORMAT... PULSAR-180CC DTS-I (M)

ASSESSMENT INFO... PULSAR DTS-I 180 MANUAL

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... MD2A12DZ1CCG29451

CATEGORY Date of Birth

FNOL INFORMATI... 31 December 1899

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 118

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... DJZCCG39003

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 179

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

G6315178K

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/06/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

90/90R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

120/80R17

Front left side

RALLO5mm

Front right side

RALLO5mm

Rear left side

RALLO5mm

Rear right side

RALLO5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD		Ref: CS3/ASM18010762/T1z4be2	
8 SHENTON WAY #24-01		Date: 09-07-2018	
AXA TOWERS SINGAPORE 068811			
ATTN : VALE OH		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLN 1343M	Veh. Inspected	FBH 7642K
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00JNJ	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	11/06/2018
2. Vehicle Particulars & Condition			
Make & Model	BAJAJ PULSAR	c.c	179
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	MD2A12DZ1CCG29451	Colour	BLACK
Odometer	46240 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	90/90 R17	RALLO	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/80 R17	RALLO	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.			
5. General Information			
Accident Date	04/06/2018	Inspect Date / Time	13/06/2018 (04:45 PM)
Survey held at	UNIVERSAL MOTORS PTE LTD BLK 1006 BUKIT MERAH LANE 2 #01-04 SINGAPORE 159762		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18010762/T1z4be2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.