

ASS. REC. BY:

REP

CS/MSG18010778/Ktd3

6-27-18 Instruction:

Surveyor

Mann

ASSIGNMENT (Office)

From (Person):

Christopher Wang

of

MSG

Date/Time:

13/6/18 @ 9:50am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JL 3490S

Insured:

GBA 1807D

at Workshop n/s:

Accord Auto

Tel:

64819517

of

10 AMK Ind. Park 2A #03-11

Policy No:

MSD/VCT/17-002073

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/06/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

1008am @ 13/6/18

Person Contacted:

jessy

Vehicle IN / (OUT)

Date/Time

Action/Instruction (✓) Estimate

8JL 3490S -X

GBA 1807D -X

2417 L/Ly @ 2200 email &amp; confirm (Red: 4345.96 !66%)

ASS. REC. BY:

REF: MSG /

Kinnersh

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/6 Repairs to Carburine

RECEIVED 2 JUL 2018

Date/Time, File Pass to?

☐

Prell. Report

1) 26/7 2018

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Functos

Others

TOTAL

Report Format:

Lump Sum / A.B.I. (\$)

2000

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		13 Jun 2018 09:50 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200868060W		
Main Claimant:	TAY BUCK KOON, ID: S7415840D		
Vehicle Reg. No.:	SJL3490S	Date of Loss:	09/06/2018 00:00 - :59 [114 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VCT/17-002073 Coverage: 29/09/2017 - 28/09/2018
Vehicle Reg. No. (Insured):	GBA1807D	Policy No. (Claimant):	
		Excess:	
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/06/2018]		
Adj Asg. Remarks:	Liability unclear, Non Reporting.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5840D
<b>Vehicle Details</b>	
Vehicle No.:	SJL34905
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3L AT
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13Z11009055
Chassis No.:	JHMGE68509S209003
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$19,038.00
Original Registration Date:	25 Nov 2008
First Registration Date:	25 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$19,038.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2018
PARF Rebate Amount:	\$9,519.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$13,289.00
COE Rebate Amount:	\$572.00
<b>Total Rebate Amount:</b>	<b>\$10,091.00</b>

The information contained herein is correct as at 19 Jun 2018

OK

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle No.:	SJL3490S
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3L AT
Chassis No.:	JHMGE68509S209003
Propellant:	Petrol
Engine No.:	L13Z11009055
Engine Capacity:	1339 cc
Maximum Power Output:	73.0 kW ( 97 bhp)
Maximum Laden Weight:	1540 kg
Unladen Weight:	1060 kg
Year Of Manufacture:	2008
Original Registration Date:	25 Nov 2008
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
Quota Premium:	\$13,289.00
COE Expiry Date:	24 Nov 2018
Road Tax Expiry Date:	24 Nov 2018
PARF Eligibility Expiry Date:	24 Nov 2018
Inspection Due Date:	24 Nov 2019
Intended Transfer Date:	11 Jun 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/06/2018 10:19
Date Of Accident	09/06/2018 12:50
Exact Location Of Accident	QUEENSWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL3490S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAY BUCK KOON
NRIC No	S7415840D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97683939
Alternative Phone No	OTHERS-97683939

### Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05016232
Cover Note Number	25/11/2017 - 24/11/2018

### Driver

Name of Driver	GOH LINDA (WU LINDA)
NRIC No	S7809861I
Date Of Birth	07/04/1978
Occupation	INDOOR
Date Of Driving Pass	29/06/2004
Driving Experience	13 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81883939
Fax Number	
Contact Number	
E-Mail Address	LINDAGOH7478@GMAIL.COM

Address	BLK 544 HOUGANG AVE 8 #05-1259
Postcode	530544
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAY JUN YAO DAMIEN
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT NO.: T/20180610/2002.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA1807D
Vehicle Make/Model/Colour	RENAULT
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOHD AMIN BIN JAMIN
NRIC/Passport Number	S2708060Z
Contact Number	90405352
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number FBK9036G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver MUHAMAD AZMI BIN SARU

NRIC/Passport Number G2742798M

Contact Number 82788869

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name MUHAMAD AZMI BIN SARU

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode



## Sketch Plan

### SKETCH PLAN

SJL34905 (Longpac)  
DOA: 09/06/18 @ 1250

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 11/06/2018

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 11/06/2018

Reporting Centre Personnel's Signature  
Name: Amy (AWK) 11/06/18  
NRIC/FIN NO.


### Sketch Plan #2

### SKETCH PLAN

Vehicle A: STL 3490 S

Vehicle B: GBA1807 D

Vehicle C: FBK 90266



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Date of Accident:	09/06/2018	Time of Accident:	12:50pm
-------------------	------------	-------------------	---------

Please refer to Police Report. (Report No: T/20180610/2003)

## DECLARATION

*I/We declare the foregoing particulars are true in every respect.*

Policyholder's Signature \_\_\_\_\_

Date & Time: 11/06/2018

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

Date & Time: 11/06/2018

Reporting Center Personnel's Signature \_\_\_\_\_

Name: \_\_\_\_\_

NARC/ETN No. \_\_\_\_\_

## Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20180610/2002

1 of 4

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

Report No. T/20180610/2002

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 10/06/2018 00:05	Vide Report No.:	Station Diary No.: 1
--	------------------	-------------------------

Informant's Particulars			
Name of Informant: GOH LINDA		Address: APT BLK 544 HOUGANG AVENUE 8 #05-1259 SINGAPORE 530544	
ID Type / ID No.: NRIC NO / S78098611		Contact No.: Home/Office: Mobile: 81883939	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 40	Date of Birth: 07/04/1978	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Other administrative and related associate professionals nec		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/06/2018 12:50	Type of Location: Straight Road
Location: Along Road 1 QUEENSWAY				
Opposite blk 95, Just after Esso Petrol Kiosk				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Chain Collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
FBF5867C	Motorcycle				No Damage	0
FBK9036G	Motorcycle				Slightly Damaged	0
GBA1807D	Van				Slightly Damaged	1
SJL3490S	Car				Slightly Damaged	1

## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20180610/2002

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

2 of 4

Report No. T/20180610/2002

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	Muhanad Azmi Bin Saru	ID No.	G2742798M
Related Vehicle	FBK9036G (Motorcycle)	Contact No.	82788869
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	Mohd Amin Bin Jamin	ID No.	S2708060Z
Related Vehicle	GBA1807D (Van)	Contact No.	90405352
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Passenger</b>			
Name	Tay Jun Yao, Damien	ID No.	T0008206B
Related Vehicle	SJL3490S (Car)	Contact No.	86683939
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20180610/2002

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

3 of 4

Report No. T/20180610/2002

## CONTINUATION OF REPORT

Driver			
Name	GOH LINDA	ID No.	S78098611
Related Vehicle	SJL3490S (Car)	Contact No.	81883939
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On 09/06/2018 at about 1250hrs, I was driving my vehicle registration plate (SJL3490S) along the straight road at Queensway. Everything was fine. However, just after passing by the Esso Petrol Kiosk, the vehicle in front of me stopped and I managed to brake in time. However, the van (registration plate: GBA1807D) behind me did not manage to stop in time, thus, colliding to the rear of my car. Another two motorcycle behind the van tried to avoid the van. Only one motorcycle (registration plate: FBF5867C) managed to avoid the collision. On the other hand, the other motorcycle (FBK9036G) collided to the rear of the van. We exchanged particulars, except for the rider of the motorcycle bearing the registration plate of FBF5867C. As we were about to enter our own vehicle and leave the location, a police car spotted us and stopped behind the motorcycle. All our particulars was taken down. An ambulance was activated as there was slight injury to the motorcyclist (FBK9036G). We were further advised to make a police report. I sustained a slight injury to my wrist and went to the doctor located at Buangkok MRT. After an examination by the doctor, I did not receive any MC and was prescribed for slight injury to the wrist. I have an in-car camera for my front and rear vehicle and the rear camera video had been saved to my handphone.

Sketch Plan #6



**SINGAPORE  
POLICE FORCE**



T/20180610/2002

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

4 of 4

Report No. T/20180610/2002

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
F /  
Staff Sgt NUR NADHIRAH BINTE HASHIM

Signature Of Informant:  
*[Handwritten Signature]*

Signature Of Interpreter:  
Not applicable

Date/Time:  
10/06/2018 00:05

Officer In Charge Of Case:  
TP / AEIT /  
SI DZUL HAIRIE BIN RAMLI  
Contact No.: 65476220

Classification Of Case

Authentication Stamp  
NP166



# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

## ESTIMATE

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581  
Attn: Accident Claims Department

*Not Authored  
6/1/18 @ 2200  
Resurvey After Paint  
- 5 days*

Date : 11/06/2018  
Vehicle No : SJL3490S  
Veh Make/Model : Honda Jazz 1.3L AT  
YOM : 2008  
Chassis No : JHMGE68509S209003  
Date of Accident : 09/06/2018

No	Qty	Description	Amount \$
<b>List Items:-</b>			
1	1	Tailgate <i>762.20</i>	\$ <i>By</i> 771.50 ✓
2	1	Tailgate "Jazz" emblem	\$ <i>me</i> 26.20 ✓
3	1	Tailgate logo	\$ <i>me</i> 25.00 X
4	1	Tailgate center garnish	\$ <i>sm</i> 110.10 X
5	1	Tailgate windscreen glass moulding	\$ <i>me</i> 90.00 ✓
6	2	Tailgate number plate lamp	\$ <i>sm</i> 65.60 X
7	1	Tailgate weatherstrip	\$ <i>sm</i> 92.30 X
8	1	Tailgate lock	\$ <i>me</i> 189.50 ✓
9	1	LH tail lamp	\$ <i>sm</i> 206.20 X
10	1	RH tail lamp	\$ <i>sm</i> 206.20 ✓
11	1	Rear LH fender	\$ <i>me</i> 652.00 X
12	1	Rear LH fender splash shield	\$ <i>sm</i> 42.90 X
13	8	Rear LH fender splash shield clip	\$ <i>me</i> 30.40 X
14	1	Rear bumper	\$ <i>me</i> 474.40 ✓
15	1	Rear bumper tow cover	\$ <i>me</i> 13.30 ✓
16	2	Rear bumper side retainer	\$ <i>sm</i> 33.00 X
17	10	Rear bumper clip	\$ <i>me</i> 38.00 ✓
18	1	End panel	\$ <i>By</i> 276.00 ✓
19	1	End panel top garnish	\$ <i>sm</i> 60.80 X
20	6	End panel top garnish clip	\$ <i>me</i> 22.80 X
<b>Total - List Item</b>			\$ 3,426.20
<b>Less 20%</b>			\$ 685.24
<b>Total</b>			\$ 2,740.96
<b>Special Nett Items:-</b>			
1	1	Rear number plate with holder	\$ <i>sm</i> 55.00 X
2	1 Set	Rear reverse sensor	\$ <i>sm</i> 380.00 X
3	1	Tailgate windscreen glass gum	\$ <i>me</i> 60.00 <i>4050</i>
<b>Total - SN Item</b>			\$ 495.00
<b>Balance b/f</b>			\$ 3,235.96

Accord Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Winning Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: [claims@mycarworkshop.com.sg](mailto:claims@mycarworkshop.com.sg)

### ESTIMATE

Attn: Accident Claims Department

Date of Accident : 09/06/2018

[illegible]



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		13 Jun 2018 09:50 <a href="#">Edit Adj Rpt</a>	<b>S\$2,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>KST AUTO RENTAL PTE LTD</b> , Co. Reg. No.: 200868060W								
Main Claimant:	<b>TAY BUCK KOON</b> , ID: S7415840D								
Vehicle Reg. No.:	<b>SJL3490S</b>	Date of Loss:	09/06/2018 00:00 - :59 [114 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MSC/V/18-000814</b>	Policy/Cover Note No.:	MSD/VCT/17-002073 Coverage: 29/09/2017 - 28/09/2018						
Vehicle Reg. No. (Insured):	<b>GBA1807D</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Accord Auto Services Pte Ltd (HQ)</b> 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Imm.Advice due 14/06/2018]								
Adj Asg. Remarks:	Liability unclear. Non Reporting.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJL3490S (MSC/V/18-000814)  
[GBA1807D]  
TP  
TAY BUCK KOON  
Jun 9 2018 12:00AM  
[KST AUTO RENTAL PTE LTD]  
Accord Auto Services Pte Ltd

Upload Documents

Upload Photos


















Compose New Letter

View

View in Browser



Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/07/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/07/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/07/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
15	25/07/18 17:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
16	25/07/18 17:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
17	25/07/18 17:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/06/18 15:59	SJL3490S GIA Rpt	 Load PDF	
2	12/06/18 16:11	Email correspondence with TP on PRI & TP choose Kenneth Kong frm LKK as the SJE	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010778/TD3Q2

Date: 01/08/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCT/17-002073
Claimant Vehicle No :	SJL3490S	Insured Vehicle No :	GBA1807D
Date of Loss:	09/06/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000814

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJL3490S</b>	Engine No:	L13Z11009055
Make & Model:	HONDA JAZZ, 1.3 L (A)	Chassis No:	JHMGE68509S209003
Reg. Date:	25/11/2008 (Man. Year: 2008)	Odometer:	168524 km
Colour:	Metallic Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,235.96	1,384.08	1,851.88	57.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	1,395.00	1,915.00	57.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,545.96</b>	<b>2,779.08</b>	<b>3,766.88</b>	<b>57.55</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
(S\$)	6,545.96	2,200.00	4,345.96	66.39
<b>+ GST 7.00/7.00% (S\$)</b>	<b>458.22</b>	<b>154.00</b>	<b>304.22</b>	<b>66.39</b>
<b>Nett Amount (S\$)</b>	<b>7,004.18</b>	<b>2,354.00</b>	<b>4,650.18</b>	<b>66.39</b>

### INSPECTION

Date of Assignment:	13/06/2018	
Date Inspected:	18/06/2018 Inspected At:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	5.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
<b>Parts:</b> 144	HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJL3490S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	771.50 FL	*762.20 FL
2	1		*TAILGATE JAZZ EMBLEM	Necessary	26.20 FL	*26.20 FL
3	1		*TAILGATE LOGO	Not Necessary	25.00 FL	*- FL
4	1		*TAILGATE CENTER GARNISH	Serviceable	110.10 FL	*- FL
5	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	90.00 FL	*90.00 FL
6	2		*TAILGATE NUMBER PLATE LAMP	Serviceable	65.60 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Serviceable	92.30 FL	*- FL
8	1		*TAILGATE LOCK	Repair	189.50 FL	*- FL
9	1		*LH TAIL LAMP	Serviceable	206.20 FL	*- FL
10	1		*RH TAIL LAMP	Serviceable	206.20 FL	*- FL
11	1		*REAR LH FENDER	Repair	652.00 FL	*- FL
12	1		*REAR LH FENDER SPLASH SHIELD	Serviceable	42.90 FL	*- FL
13	8		*REAR LH FENDER SPLASH SHIELD CLIP	Not Necessary	30.40 FL	*- FL
14	1		*REAR BUMPER	Buckled	474.40 FL	*474.40 FL
15	1		*REAR BUMPER TOW COVER	Dented	13.30 FL	*13.30 FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	33.00 FL	*- FL
17	10		*REAR BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
18	1		*END PANEL	Bent	276.00 FL	*276.00 FL
19	1		*END PANEL TOP GARNISH	Serviceable	60.80 FL	*- FL
20	6		*END PANEL TOP GARNISH CLIP	Not Necessary	22.80 FL	*- FL
21	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	55.00 FS	*- FS
22	1		*SET REAR REVERSE SENSOR	Serviceable	380.00 FS	*- FS
23	1		*TAILGATE WINDSCREEN GLASS GUM	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,921.20</b>	<b>1,720.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>685.24</b>	<b>336.02</b>
<b>Total Parts (\$\$)</b>	<b>3,235.96</b>	<b>1,384.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	1,200.00	500.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,300.00	600.00
3	TO APPLY ANTI RUST TREATMENT	New	150.00	30.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	80.00	15.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	60.00	0.00
6	TO CHECK AND TEST TAILGATE WATER LEAKING	New	100.00	20.00
7	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
8	TO REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST ON REPAIR	New	150.00	120.00
9	TO REMOVE AND REINSTALL TAILGATE ATTACHMENT AND INTERIOR UPHOLSTERY	New	150.00	60.00
Gross Labour Cost (S\$)			<b>3,310.00</b>	<b>1,395.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >