

ASS. REC. BY:

REF:

CS3/MSG18010780/D24d3⁵²

Special Instruction:

Surveyor:
Mehmen

Bryen

ASSIGNMENT (Office)

From (Person):

Lionel tan

of

MSIG

Date/Time:

12/6/18 @ 4:15pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 1167M

Insured:

SLJ 4811E

at Workshop in/:

Hiap Lek Automobile

Tel:

G4531743

of

160 Sin Ming Drive # 05-17

Policy No:

28795104MCX

Claim No:

560871

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/06/2018

CA / REV / REP. / REV 24 HRS

hp

H.O.D. Endorsement:

Date/Time:

10:10am @ 13/6/18

Person Contacted:

Mr. Choon

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SLV 1167M - NBA/ALG18010609/Y

DOA: 8/6/18

SLJ 4811E - NBA/ALG18010609/Y

DOA: 8/6/18

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		12 Jun 2018 16:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	DIANA GOH MUI MUI (WU MWIMWI), ID: S7147273F		
Vehicle Reg. No.:	SLV1167M	Date of Loss:	08/06/2018 23:00 - :59 [5 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560871	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLJ4811E	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/06/2018]		
Driver/Custodian (Insured):	GAN CHIN HUAT (), NRIC: S7707993I, Tel: +6591994915		
Adj Asg. Remarks:	on WP. SJE - DISAGREED Please appoint LKK AUTO CONSULTANTS to conduct the survey . Kindly contact Choon Yong @ 6453 1743 to arrange for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

of Accident: 08/06/18 Accident Time: 03 28 (24-HR-FORMAT)
ent Place: CTG (city) Before PIG (change) Exit
le Reg. No (Car plate No.): SLV 1167M
le Make/Model: Kia Cerato K3 1.6 EX
nce Company: AIG Policy No.:
or Company Names /IC NO: Diana Goh Mu. Mu. / 57147273F
or Company Contact No.: 90622884 Owner's HP: Company Tel:
ER'S Name & IC no.: as above
ER'S Date of Birth: 06/12/71 DRIVER'S License Pass Date: 20/12/93
inship bet. Owner & Driver: Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner
ER'S Address: Blk 427 Yishun Ave 11 # 09-612 5 (76) 429
ER'S Contact No./ Alt No.: 1) 2)
ER'S Occupation: INDOOR OUTDOOR (eg. working inside or outside of an office)
Address:
r & Road Surface: CLEAR & DRY RAINING & WET AFTER RAIN & WET
ng Type: Reporting Only \ Claim Other Party \ Claim Own Ins
r of Passengers (including Driver): 1
re any video Captured by car camera: YES NO
urpose for which vehicle was being used at the time of accident: Private use Work purpose

Other Party Driver's Particulars (if any)

eg No: SLJ4811Z
ake/Model: Honda Vezel
IVER: Gan Chin Hoot
IVER: 57707993F
Contact & add: 91995915

Vehicle Reg No: _____
Vehicle Make/Model: _____
Name DRIVER: _____
IC NO. DRIVER: _____
DRIVER'S Contact & add: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to invalidate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of these companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and the copies of this report will for a fee be made available upon application to interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices which could involve disclosure of certain personal data about me to bring about delivery of the same as well as external cover of envelopes/mali packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may, to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing claims, regulators, law enforcement and government agencies as reasonably required for the purposes stated;
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person
Name:
NRIC/PIN No.:

SKETCH PLAN

① SLV 716 T.M.

② SLJ 418 HZ

CTE → City

LADY LADY LADY

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On mentioned date and time, I was travelling along CTE towards city on lane 1. Before the yellow light, front vehicle suddenly slow down and stop. I stop accordingly. Moment later, vehicle B rear ended my vehicle at a relatively great impact. I did feel some pain on my shoulder. If the pain persist, I may consult doctor if need to.

DECLARATION

I declare the foregoing particulars are true in every respect.

holder's signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NAICATIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7273F
Vehicle Details	
Vehicle No.:	SLV1167M
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G4FGHH688148
Chassis No.:	KNAFX411MJ5755811
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$12,563.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$12,563.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2027
PARF Rebate Amount:	\$9,422.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$44,099.00
Total Rebate Amount:	\$53,521.00

The information contained herein is correct as at 18 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		12 Jun 2018 16:15 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	DIANA GOH MUI MUI (WU MWIMWI), ID: S7147273F		
Vehicle Reg. No.:	SLV1167M	Date of Loss:	08/06/2018 23:00 - :59 [5 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560871	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLJ4811E	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 13/06/2018]		
Driver/Custodian (Insured):	GAN CHIN HUAT (), NRIC: S77079931, Tel: +6591994915		
Adj Asg. Remarks:	on WP. SJE - DISAGREED Please appoint LKK AUTO CONSULTANTS to conduct the survey , Kindly contact Choon Yong @ 6453 1743 to arrange for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV1167M (560871)
[SLJ4811E]
TP
DIANA GOH MUI MUI (WU MWIMWI)
Jun 8 2018 11:00PM
[SKYWAY MOTOR PTE LTD]
Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/07/18 18:03	Rear View Right		Load JPG	☒
2	18/07/18 18:03	Rear View Left		Load JPG	☒
3	18/07/18 18:03	General View		Load JPG	☒
4	18/07/18 18:03	General View		Load JPG	☒
5	18/07/18 18:03	General View		Load JPG	☒
6	18/07/18 18:03	General View		Load JPG	☒
7	18/07/18 18:03	General View		Load JPG	☒
8	18/07/18 18:03	General View		Load JPG	☒
9	18/07/18 18:03	General View		Load JPG	☒
10	18/07/18 18:03	General View		Load JPG	☒
11	18/07/18 18:03	General View		Load JPG	☒
12	18/07/18 18:03	General View		Load JPG	☒
13	18/07/18 18:03	General View		Load JPG	☒
14	18/07/18 18:03	General View		Load JPG	☒
15	18/07/18 18:03	General View		Load JPG	☒
16	18/07/18 18:03	General View		Load JPG	☒
17	18/07/18 18:03	General View		Load JPG	☒
18	18/07/18 18:03	General View		Load JPG	☒
19	18/07/18 18:03	General View		Load JPG	☒
20	18/07/18 18:03	General View		Load JPG	☒
21	18/07/18 18:03	General View		Load JPG	☒
22	18/07/18 18:03	General View		Load JPG	☒
23	18/07/18 18:03	General View		Load JPG	☒
24	18/07/18 18:03	General View		Load JPG	☒
25	18/07/18 18:03	General View		Load JPG	☒
26	18/07/18 18:03	General View		Load JPG	☒
27	18/07/18 18:03	General View		Load JPG	☒
28	18/07/18 18:03	General View		Load JPG	☒
29	18/07/18 18:03	General View		Load JPG	☒
30	18/07/18 18:03	General View		Load JPG	☒
31	18/07/18 18:03	General View		Load JPG	☒
32	18/07/18 18:03	General View		Load JPG	☒
33	18/07/18 18:03	General View		Load JPG	☒
34	18/07/18 18:03	General View		Load JPG	☒
35	18/07/18 18:03	General View		Load JPG	☒

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/07/18 18:03	General View	 Load JPG	
37	18/07/18 18:03	General View	 Load JPG	
38	18/07/18 18:03	General View	 Load JPG	
39	18/07/18 18:03	General View	 Load JPG	
40	18/07/18 18:03	General View	 Load JPG	
41	18/07/18 18:03	General View	 Load JPG	
42	18/07/18 18:03	General View	 Load JPG	
43	18/07/18 18:03	General View	 Load JPG	
44	18/07/18 18:03	General View	 Load JPG	
45	18/07/18 18:03	General View	 Load JPG	
46	18/07/18 18:03	General View	 Load JPG	
47	18/07/18 18:03	General View	 Load JPG	
48	18/07/18 18:03	General View	 Load JPG	
49	18/07/18 18:03	Odometer Reading	 Load JPG	
50	18/07/18 18:03	Chassis Number	 Load JPG	
51	18/07/18 18:04	Reinspection Photo	 Load JPG	
52	18/07/18 18:04	Reinspection Photo	 Load JPG	
53	18/07/18 18:04	Reinspection Photo	 Load JPG	
54	18/07/18 18:04	Reinspection Photo	 Load JPG	
55	18/07/18 18:04	Reinspection Photo	 Load JPG	
56	18/07/18 18:04	Reinspection Photo	 Load JPG	
57	18/07/18 18:04	Reinspection Photo	 Load JPG	
58	18/07/18 18:04	Reinspection Photo	 Load JPG	
59	18/07/18 18:04	Reinspection Photo	 Load JPG	
60	18/07/18 18:04	Reinspection Photo	 Load JPG	
61	18/07/18 18:04	Reinspection Photo	 Load JPG	
62	18/07/18 18:04	Reinspection Photo	 Load JPG	
63	18/07/18 18:04	Reinspection Photo	 Load JPG	
64	18/07/18 18:04	Reinspection Photo	 Load JPG	
65	18/07/18 18:04	Reinspection Photo	 Load JPG	
66	18/07/18 18:04	Reinspection Photo	 Load JPG	
67	18/07/18 18:04	Reinspection Photo	 Load JPG	
68	18/07/18 18:04	Reinspection Photo	 Load JPG	
69	18/07/18 18:04	Reinspection Photo	 Load JPG	
70	18/07/18 18:04	Reinspection Photo	 Load JPG	
71	18/07/18 18:04	Reinspection Photo	 Load JPG	
72	18/07/18 18:04	Reinspection Photo	 Load JPG	
73	18/07/18 18:04	Reinspection Photo	 Load JPG	
74	18/07/18 18:04	Reinspection Photo	 Load JPG	
75	18/07/18 18:04	Reinspection Photo	 Load JPG	
76	18/07/18 18:04	Reinspection Photo	 Load JPG	
77	18/07/18 18:04	Reinspection Photo	 Load JPG	
78	18/07/18 18:04	Reinspection Photo	 Load JPG	
79	18/07/18 18:04	Reinspection Photo	 Load JPG	
80	18/07/18 18:04	Reinspection Photo	 Load JPG	
81	18/07/18 18:04	Reinspection Photo	 Load JPG	
82	18/07/18 18:04	Reinspection Photo	 Load JPG	
83	18/07/18 18:04	Reinspection Photo	Load JPG	

Photos/Images					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
84	18/07/18 18:04	Reinspection Photo		Load JPG	
85	18/07/18 18:04	Reinspection Photo		Load JPG	
86	18/07/18 18:04	Reinspection Photo		Load JPG	
87	18/07/18 18:04	Reinspection Photo		Load JPG	
88	18/07/18 18:04	Reinspection Photo		Load JPG	
89	18/07/18 18:04	Reinspection Photo		Load JPG	
90	18/07/18 18:04	Reinspection Photo		Load JPG	
91	18/07/18 18:04	Reinspection Photo		Load JPG	
92	18/07/18 18:04	Reinspection Photo		Load JPG	
93	18/07/18 18:04	Reinspection Photo		Load JPG	
94	18/07/18 18:04	Reinspection Photo		Load JPG	
95	18/07/18 18:04	Reinspection Photo		Load JPG	
96	18/07/18 18:04	Reinspection Photo		Load JPG	
97	18/07/18 18:04	Reinspection Photo		Load JPG	
98	18/07/18 18:04	Reinspection Photo		Load JPG	
99	18/07/18 18:04	Reinspection Photo		Load JPG	
100	18/07/18 18:04	Reinspection Photo		Load JPG	
101	18/07/18 18:04	Reinspection Photo		Load JPG	
102	18/07/18 18:04	Reinspection Photo		Load JPG	
103	18/07/18 18:04	Reinspection Photo		Load JPG	
104	18/07/18 18:04	Reinspection Photo		Load JPG	
105	18/07/18 18:04	Reinspection Photo		Load JPG	
106	18/07/18 18:04	Reinspection Photo		Load JPG	
107	18/07/18 18:04	Reinspection Photo		Load JPG	
108	18/07/18 18:04	Reinspection Photo		Load JPG	
109	18/07/18 18:04	Reinspection Photo		Load JPG	
110	18/07/18 18:04	Reinspection Photo		Load JPG	
111	18/07/18 18:04	Reinspection Photo		Load JPG	
112	18/07/18 18:04	Reinspection Photo		Load JPG	
113	18/07/18 18:04	Reinspection Photo		Load JPG	
114	18/07/18 18:04	Reinspection Photo		Load JPG	
115	18/07/18 18:04	Reinspection Photo		Load JPG	
116	18/07/18 18:04	Reinspection Photo		Load JPG	
117	18/07/18 18:04	Reinspection Photo		Load JPG	
118	18/07/18 18:04	Reinspection Photo		Load JPG	
119	18/07/18 18:04	Reinspection Photo		Load JPG	
120	18/07/18 18:04	Reinspection Photo		Load JPG	
121	18/07/18 18:04	Reinspection Photo		Load JPG	
122	18/07/18 18:04	Reinspection Photo		Load JPG	
123	18/07/18 18:04	Reinspection Photo		Load JPG	
124	18/07/18 18:04	Reinspection Photo		Load JPG	
125	18/07/18 18:04	Reinspection Photo		Load JPG	
126	18/07/18 18:04	Reinspection Photo		Load JPG	
127	18/07/18 18:04	Reinspection Photo		Load JPG	
128	18/07/18 18:04	Reinspection Photo		Load JPG	
129	18/07/18 18:04	Reinspection Photo		Load JPG	
130	18/07/18 18:04	Reinspection Photo		Load JPG	
131	18/07/18 18:04	Reinspection Photo		Load JPG	

Photos/Images				☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	18/07/18 18:04	Reinspection Photo	 Load JPG	☒
133	18/07/18 18:04	Reinspection Photo	 Load JPG	☒
134	18/07/18 18:04	Reinspection Photo	 Load JPG	☒
135	18/07/18 18:04	Reinspection Photo	 Load JPG	☒
136	18/07/18 18:04	Reinspection Photo	 Load JPG	☒
137	18/07/18 18:05	Finishing Photo	 Load JPG	☒
138	18/07/18 18:05	Finishing Photo	 Load JPG	☒
139	18/07/18 18:05	Finishing Photo	 Load JPG	☒
140	18/07/18 18:05	Finishing Photo	 Load JPG	☒
141	18/07/18 18:05	Finishing Photo	 Load JPG	☒
142	18/07/18 18:05	Finishing Photo	 Load JPG	☒
143	18/07/18 18:05	Finishing Photo	 Load JPG	☒
144	18/07/18 18:05	Finishing Photo	 Load JPG	☒
145	18/07/18 18:05	Finishing Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/18 16:34	TPD SLV1167M - PRI	 Load PDF	
2	12/06/18 10:57	TPD SLV1167M - SURVEY LISTING	 Load PDF	
3	12/06/18 10:57	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18010780/DZ4D3S2
Date: 19/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28795104MCX
Claimant Vehicle No : SLV1167M **Insured Vehicle No :** SLJ4811E
 Date of Loss: 08/06/2018 Nature of Claim: TP Claim No: 560871

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV1167M**
 Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGHH688148
 Reg. Date: 22/12/2017 (Man. Year: 2017) Chassis No: KNAFX411MJ5755811
 Colour: Blue Odometer: 6462 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/06/2018
 Date Inspected: 13/06/2018 Inspected At: 160 Sin Ming Drive, #05-17 Sin Ming Autocity
 Estimated Period of Repair: 0.0 days Singapore 575722
 Repairer: Hiap Lek Automobile Trading

Adjuster: BRYAN TANI

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2018)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue;Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1167M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >