

ASS. REC. BY

REF: CS3/ICS18010798/R/24d3^{sr} Special Instruction:Survivor
Meymen

Rasu

ASSIGNMENT (Office)

From (Person)

Janice Goh

of

ECICS

Date/Time

13/6/18 @ 12.22pm

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 4357L

Insured:

81Z 3787P

at Workshop m/s

One flexi pte. Ltd

Tel:

9667 5455 / 8292 2866

of

8 Kaki Bkt Ave 4 # 06-33 premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A

09/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time: 3:17pm @ 13/6/18

Person Contacted:

Rejiner

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

81J 4357L - X

81Z 3787P - X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS3/ICS18010798/R1z4d3		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 13-06-2018		
		Code : ICS		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLZ 3787P	Veh. Inspected	SLJ 4357L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JANICE GOH	Assign Date	13/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/06/2018	Inspection Date	13/06/2018	
Survey held at	ONE FLEXI PTE LTD 8 KAKI BUKIT AVENUE 4 #06-33 PREMIER @KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 13 June 2018 12:22 PM
To: Ong & Shan LLC; assignments@lkkauto.com
Cc: ECICS Claims; regina@wellscope.com.sg
Subject: RE: Pre Repair Inspection Your ref: SLZ 3787P DOA: 09.06.2018 Our ref: SRSTP.8181.18

Without Prejudice

Dear Chen

Thank you for your email.
We are not agreeable with your surveyor list and we will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Ong & Shan LLC [mailto:ongshanllc@gmail.com]
Sent: Wednesday, 13 June, 2018 9:58 AM
To: ECICS Claims; regina@wellscope.com.sg
Subject: Re: Pre Repair Inspection Your ref: SLZ 3787P DOA: 09.06.2018 Our ref: SRSTP.8181.18

Dear Sirs,

We refer to the above matter and your email.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

- | | |
|------------------------|--------------|
| 1. Dennis Yap Teck Wee | 2. Dixon Yeo |
| 3. Yap Teck Lee | 4. Mark |
| 5. Yap Teck Chye | |

As our client's repairer is a small workshop, we are unable to provide you with more than the above listed motor surveyors. We trust you will be able to choose a surveyors from the above.

Please be informed that the said vehicle can be inspected at:-

Name of workshop : One Flexi Pte Ltd
Address : 8 Kaki Bukit Ave 4, #06-33 Premier @ Kaki Bukit Singapore 415875
Contact person : Regina Tan
Telephone no : 9-667-5455
Fax : 6-292-2866

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single Joint Expert".

We will accordingly inform you who the "Single Joint Expert" is to facilitate your conduct of a pre-repair survey.

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-repair survey.

For Surveyor	
Please initial here after completion of pre-repair inspection. Thank you.	
Name:	
Signature:	
Date & Time of Pre-repair inspection:	/

Warmest Regards,

CM Chen
M/s Ong & Shan LLC
Block 184 Toa Payoh Central
#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261
Email: ongshanllc@gmail.com

On Tue, Jun 12, 2018 at 4:17 PM, ECICS Claims <claims@ecics.com.sg> wrote:

Without Prejudice

Dear Chen

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Ong & Shan LLC [<mailto:ongshanllc@gmail.com>]

Sent: Tuesday, 12 June, 2018 11:28 AM

To: ECICS Claims; regina@wellscope.com.sg

Subject: Pre Repair Inspection Your ref: SLZ 3787P DOA: 09.06.2018 Our ref: SRSTP.8181.18

Dear Sirs,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA) ROAD TRAFFIC ACCIDENT INVOLVING SKJ 4357L & SLZ 3787P ON 09.06.2018 ALONG TIONG BAHRU ROAD @ 1635 HRS

We are instructed by our client's repairer workshop M/s One Flexi Pte Ltd to notify you of a road traffic accident on 09.06.2018 at about 1635hrs along Tiong Bahru Road involving our client's customer's vehicle registration number SLJ 4357L and vehicle registration number SLZ 3787P driven by your insured driver at the material time

As the result of the accident, our client's/ customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Warmest Regards,

CM Chen

M/s Ong & Shan LLC

Block 184 Toa Payoh Central

#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261

Email: ongshanllc@gmail.com

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/06/2018 17:39
Date Of Accident	09/06/2018 16:35
Exact Location Of Accident	TIONG BAHRU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ4357L
Insured/Policyholder	
Name Of Registered Owner	YEO HWEE HWEE CANDY
NRIC No	S8021393Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91084130
Alternative Phone No	OFFICE-91084130

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF TSI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA115995
Cover Note Number	

Driver

Name of Driver	YEO HWEE HWEE CANDY
NRIC No	S8021393Z
Date Of Birth	17/07/1980
Occupation	INDOOR
Date Of Driving Pass	26/04/2002
Driving Experience	16 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91084130
Fax Number	
Contact Number	OFFICE-91084130
Email Address	NOEMAIL

Address	BLK 11 PIME CLOSE #18-101
Postcode	391011
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SLZ3787P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reportings may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

 11/06/18
Reporting Centre Personnel's
Name: Alan Quok
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Refer to owner sketch Plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to owner letter

DECLARATION

We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)



Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's
Name: Alan Quik
NRIC/FIN No.:

11/06/18

Accident Sketch Plan



My car A, SKJ4357L, was driving along Tiong Bahru Rd, 9 June 2018, around 4.35 pm and Car B, SLZ3787P, which was supposedly to stop before the STOP LINE sign but did not stop the car and continue to move forward though I have the right of way. As such, I could not brake my car on time and resulted in my car hitting the side of Car B. Car B was not aware of the stop sign until it was informed to Car B by me that there was a STOP sign along the road.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKJ4357L
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	VOLKSWAGEN
Vehicle Model :	NEW GOLF 1.4 AT 5K13G5
Chassis No. :	WVWZZZ1KZAW240330
Propellant :	Petrol
Engine No. :	CAX464580
Engine Capacity :	1390 cc
Maximum Power Output :	90.0 kW (120 bhp)
Maximum Laden Weight :	1850 kg
Unladen Weight :	1241 kg
Year Of Manufacture :	2009
Original Registration Date :	03 Feb 2010
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$18,502.00
COE Expiry Date :	02 Feb 2020
Road Tax Expiry Date :	02 Aug 2018
PARF Eligibility Expiry Date :	02 Feb 2020
Inspection Due Date :	02 Feb 2019
Intended Transfer Date :	20 Jun 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 02 Aug 2018. You may renew the road tax from 03 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 03 Aug 2018 to 02 Feb 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	310.00	-	310.00
Total Amount Payable :			335.00

Amount Payable (From 03 Aug 2018 to 02 Aug 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	620.00	-	620.00
Total Amount Payable :			645.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018 13:28 Edit Reg		13 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: email@yahoo.com		
Main Claimant:	YEO HWEE HWEE CANDY, ID: S8021393Z		
Vehicle Reg. No.:	SKJ4357L	Date of Loss:	09/06/2018 16:00 - :59 [100 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SLZ3787P	Policy No. (Claimant):	
		Excess:	
Repairer:	One Flexi Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #06-33 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)
































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKJ4357L
[SLZ3787P]
TP
YEO HWEE HWEE CANDY
Jun 9 2018 4:00PM
[-]
One Flexi Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
15	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/06/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18010798/R1Z4D3S2
 Date: 25/06/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SKJ4357L	Insured Vehicle No :	SLZ3787P
Date of Loss:	09/06/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ4357L	Engine No:	CAX464580
Make & Model:	VOLKSWAGEN NEW GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZ1KZAW240330
Reg. Date:	03/02/2010 (Man. Year: 2009)	Odometer:	96581 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/06/2018	
Date Inspected:	13/06/2018	Inspected At: One Flexi Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #06-33 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts:	144	VOLKSWAGEN NEW GOLF 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ4357L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >