

ASS. REC. BY:

REF: CS/FCI18010821 / Usd3 n2

Special Instructions:

Surveyor

Melvin

ASSIGNMENT (Office)

From (Person):

Joanne yong

of

FCI

Date/Time: 13/6/18 @ 3:44pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN G875L

Insured:

SH 7117J

at Workshop no/s

Kah Motor

Tel:

6846 5672 / 9072 1766

of

15 Ubi Road 4

Policy No:

Claim No:

D18004695MFSH

Sum Insured:

Excess:

Make of Veh.  
(Client's Record)

D.O.A.

09/06/2018

CA / REV / REP. / REV 24 HRS

(up)

20.062018 @ 11am

H.O.D. Endorsement:

Date/Time:

4:19 pm @ 13/6/18

Person Contacted:

Rueben

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SLN G875L - X

SH 7117J - CS/FCI18009345 / R/d3

DOA: 2/5/2018

21/06/18

@ 15:42 p.m. revised PA to Joanne via email.

ASSIGNMENT

From: \_\_\_\_\_ Date: 20/6/2018  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: SLN 6875L  
 at Workshop m/s: Kah Motor  
 of: 15 Ubi Road 4  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) 11 am  
 Make of Veh: Rueben @ 9072 1766

Veh No: SLN 6875L Yr Regn: 5 17  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CAI  
 Make: Honda HRV C.C. 1496  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 19384 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHMRA18106X202256  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS/DUN/TEXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 80  
 IDAS Accident Report: Consistent?: Yes or No  
 CA / PR Seen: 2 Consistent?: Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: 1151 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 1wp  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. P mm R/Bal. P mm  
 L/Bal. P mm L/Bal. P mm  
 D.O.A. 9/6/18 D.O.I. 20/6/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 O/S Rear  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction 27A 57486  
 20/7/18 confirmed final by #740 with Rueben  
 (\$1,060 Red - 59%)

RECEIVED 23 JUL 2018.

Date/Time: File Pass to? 23/07/18  
 Typist  
 Date/Time: File Return to?  
 Report Format:  
 Lump Sum / I.B.I: (\$) 740.00 PIP

Days Of Repair: 2  
 Resurvey No. of Trip: 1  
 Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Trvs (\$)  
 Weekend (\$)

Survey Fee:	100
Transportation	50
Photos	50
Other	20
TOTAL	220



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010821/Usd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-06-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SH 7117J	Veh. Inspected	SLN 6875L
Policy No.		Coverage (\$)	0.00
Claim No.	D18004695MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	13/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	09/06/2018	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004695MFSH

Date: 21 June 2018

Our Ref: CS/FCI18010821/Usd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 6875L .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/06/2018 at the premises of M/s Kah Motor Co. Sdn. Bhd. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,800.00</u> .
Revised Estimate Amount	: S\$ <u>740.00</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the o/s rear portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 2 Days

Yours faithfully,  
Marcus Chua  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

**Date** 12-06-2018 **Our Ref No.** D18004695MFSH

**Accident Date** 09-06-2018 **Claim Type.** Third Party

**Insured Vehicle** CH7117J **Third Party Vehicle.** SLN6875L

**Survey Location** 35 UBI ROAD 4

**Contact Person.** RESHURUEBEN RAO THOMAS (RUEBEN)

**Contact No.** 68465672/ 90721766 **Fax No.** 0

**Survey Type** WITHOUT PREJUDICE:

**Appointed Surveyor** UKK AUTO CONSULTANTS PTE LTD

**Contact Person** NA **Fax No.** 68416315

**Contact Number.** NA

**FOR DIRECT SETTLEMENT**

Please submit to us the ~~TP~~ invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST:**

**Cc : Working** MOTOR CO SDN Attention. NIL

**Cc : TP Solicitor** TP Solicitor Fax No. NA

**Officer Incharge** J. TANNEY

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241389)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18004695MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & KAH MOTI
<b>Workshop Name</b>	KAH MOTOR CO SDN BHD (Contact Person : JESHURUEBEN RAO THOMAS (RUEBEN))	<b>Survey Location &amp; Contact Details</b>	15 UBI ROAD 4 <b>Mobile:</b> 90721766 , <b>Phone:</b> 68465672 , <b>Fax:</b> 0 <b>EmailId:</b> JESHURUEBEN@HONDA.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SH7117J	<b>TP Vehicle No</b>	SLN6875L
<b>PRI Recieved Date</b>	12-06-2018 07:19:54 PM	<b>Surveyor Appointed Date</b>	13-06-2018 03:43:42 PM	<b>Surveyor Accept Date</b>	13-06-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	13-06-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 21 June 2018 3:42 PM  
**To:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'  
**Cc:** "SUR"; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: SURVEY ASSESSMENT - D18004695MFSH/1  
**Attachments:** SLN 6875L - Preli Advise.pdf

Dear Joanne,

Enclosed preliminary revised for SLN 6875L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)]  
**Sent:** Wednesday, 13 June 2018 4:27 PM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; "SUR" <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18004695MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)]  
**Sent:** Wednesday, 13 June 2018 3:43 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [JOANNEYONG@MSFIRSTCAPITAL.COM.SG](mailto:JOANNEYONG@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004695MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9569J
<b>Vehicle Details</b>	
Vehicle No.:	SLN6875L
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	L15B4532256
Chassis No.:	JHMRU1810GX202256
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,951.00
Original Registration Date:	15 May 2017
First Registration Date:	15 May 2017
Transfer Count:	0
Actual ARF Paid:	\$14,951.00 7415
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2027
PARF Rebate Amount:	\$11,213.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$46,273.00
<b>Total Rebate Amount:</b>	<b>\$57,486.00</b>

The information contained herein is correct as at 20 Jun 2018

OK

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No: 192300014M) (GST Reg No: M2-0000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: tmis@tokiomarine.com.sg W: www.tokiomarine.com

A member of the  
Tokio Marine Group



**TOKIO MARINE**  
**INSURANCE GROUP**  
FORM MX1

**Certificate of Insurance**

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960**  
**ROAD TRANSPORT ACT, 1987 (MALAYSIA)**  
**MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Policy No.: 18-MU005778-R01 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SLN6875L **Chassis No.:** JHMRU1810GX202256
2. **Name of Policyholder** MR KENNETH LIM BOON TONG (KENNETH LIN WENZHONG)
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 15/05/2018
4. **Date of Expiry of Insurance** 14/05/2019
5. **Persons or Class of Persons entitled to drive\***  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his permission.

\* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. **Limitations as to use\***

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* *Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

**IMPORTANT NOTICE**

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

**ADDITIONAL INFORMATION**

Account: E2316DDA

<b>Insurance Plan:</b>	Comprehensive Approved Workshop Plan
<b>Limit for total loss or theft:</b>	Prevailing Market Value
<b>Policy Excess:</b>	Own Damage Claims SGD 600
	Windscreen Excess SGD 100
<b>Financial Interest:</b>	MALAYAN BANKING BERHAD

Tokio Marine Insurance Singapore Ltd.

Authorised Signature



# SINGAPORE ARMED FORCES IDENTITY CARD

Name

**KENNETH LIM BOON  
TONG**



NRIC No

**S7729569J**

This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Manpower Base or any Police Station.

0EMALTOGGP109451900813

0000050209622

NRIC No / Colour

**S7729569J / PINK**

Race

**CHINESE**

Date Of Birth

**18/10/1977**

Service Status

**REGULAR**

Address

**176 CACTUS ROAD**

**SINGAPORE 809656**

Blood Group

**O (+)**

Country Of Birth

**SINGAPORE**

Military Rank Status

**OFFICER**

Sex

**M**





# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

KINDLY HELP TO ARRANGE  
SURVEYOR TO SURVEY  
THIS VEHICLE:

THANKS,  
[Signature]

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877

Registration No : SLN6875L  
 Chassis No : JHMRU1810GX202256  
 Model : HRV DX-SIN CVT YM 2016  
 Owner's Name : KENNETH LIM BOON TONG  
 Ins Policy No. :  
 Date of Accident : 9/6/2018

Document No. : SQT18002432 Page 1  
 Date : 12. Jun 2018  
 Customer No. : WZF002  
 Svc Advisor : ARY CHUA WAI NGEE  
 Engine No : L15B4532256  
 Date | Time : 12. Jun 2018 2:49:43 PM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO : ) OWNER: KENNETH LIM BOON TONG OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE LT ACC DATE: 09/06/2018 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SH7117J						
BOSUN	SUNDRIES <i>sw</i>	1	50.00	10	50.00	3.50	53.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	250.00	11	250.00	17.50	267.50
BKRP22S	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW <i>Damage parts</i>	1	900.00	280	900.00	63.00	963.00
BP01R	SPRAY PAINTING ON RR R FENDER	1	600.00	450	600.00	42.00	642.00
				<b>Sum Labor</b>	<b>1800.00</b>	<b>126.00</b>	<b>1,926.00</b>

Survey By marcus lkh  
 Date & Time 20 20/6/18 @  
 Excess \_\_\_\_\_  
 Status not allowed  
 Signature \_\_\_\_\_

RUEBEN  
9072 1766

Total Amount 1,800.00 126.00 1,926.00  
 Total (Inclusive of GST) 1,926.00

tel: 62563581  
 TOTAL \$ 740  
 207

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Printed on 12/6/2018 3:03:17 PM  
 This is a computer generated invoice. No signature is required.  
 Part prices are subjected to change without notice.  
 The above estimated cost of repair do not include any unforeseen damages.  
 GST Amount is calculated from individual line(s)

13/7/2018

PAGE 1/1



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS CHUA

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 2 DAYS.

**Customer:** WZF002 / MS FIRST CAPITAL  
**Chassis No:** JHMRU1810GX202256  
**License No:** SLN6875L  
**Mileage:** 20424  
**Engine No:** L15B4532256

**Document No:** SVO18040127  
**Printed By:** JESHURUEBEN  
**Order Date:** 10. July 2018  
**Order Time:** 1:11:06 PM  
**Service Advisor:** RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70834 ) OWNER: KENNETH LIM BOON TONG OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE LT ACC DATE: 09/06/2018 SURVEYED BY: MARCUS (LKK) DATE: 20/6/2018 REF NO: D18004695MFSH TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SH7117J						
BOSUN	0672	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BKRP22S	EXT-YJ STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW DAMAGE PARTS.	1	280.00		280.00	19.60	299.60
BP01R	EXT-YBH SPRAY PAINTING ON RR R FENDER	1	450.00		450.00	31.50	481.50
					<b>SUM LABOUR:</b>	<b>740.00</b>	<b>51.80</b>
					<b>TOTAL SGD</b>	<b>740.00</b>	<b>51.80</b>
					<b>Total Payable (SGD)</b>		<b>791.80</b>

GST Amount is calculated from individual line(s)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010821/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7117J	Veh. Inspected	SLN 6875L
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004695MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	13/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA HRV (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1810GX202256	Colour	WHITE
Odometer	19384	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	8 mm
L/H Front Tyre	215/60 R16	DUNLOP	8 mm
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/06/2018	Inspection Date	20/06/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6875L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	SUNDRIES (SN)	NECESSARY	50.00	10.00
			50.00	10.00
	<b>LABOUR</b>			
	REMOVE & INSTALL REAR COMPARTMENT LININGS.	NOT NECESSARY	250.00	-
	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW DAMAGE PARTS.		900.00	280.00
	SPRAY PAINTING ON RR R FENDER.		600.00	450.00
			1,750.00	730.00
	<b>GRAND TOTAL</b>		<b>1,800.00</b>	<b>740.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>740.00</b>

Report Ref No. CS/FC118010821/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.