

INSURANCE

INS. CASE OWNER:

transhup CC 4 km AXA1801 0879, KH639

LKK

IDAC

Surveyor:

KENATH

DOI:

ASSIGNMENT

1810618

Date / Time:

14/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKR 90985

Claim No.:

SSMOCKLE/51655

Name of Insured:

ABDUL WANIS SAMABUDEEN

Policy No.:

GA091287

Insured Tel No.:

HP: 91079583

Make / Model:

MERCEDES

Excess Sec II :SS

D.O.A: 6/6/18

Place of Accident:

Campung KAPOR RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

RK 1132T



INSRS:
WSP:
Tel:
Liability:
RMKS:

km
Tan



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

19/6/18

VC

RK 1132T - X

SKR 90985 - X

RECEIVED 02 JAN 2019

of sum of claim

DIME

PRIVATE

25/10/18 @ 2:12PM

25/10/18

01/11/18

Wrote to OI. He confirmed accident details & was parked to where returning to park. Informed to claim, agreed to settle & make new keys. Send letter & email to OI. To LOD in by email. Give WhatsApp in OC. Ask approved WhatsApp send acceptance to TP. EV IN. All docs in order.

STAGE	DATE/PIC
Non-Reporting hr (1st):	
Non-Reporting hr (2nd):	
Non-Reporting hr (Final):	
Notification hr (if non-pickup):	
Call OI:	25/10/18 - VIC
After call hr to OI:	
Documentation Check List:	Handler Typist
Notification hr (if non-pickup):	
After call hr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE

Date/Time: 19/10/18

Sent By: 63

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

K/P

SS 260.00

days/Reduction:

30

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

(w/gov)

SS 278.20

(OI was parked to)

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

80.00 x 30 = 1 days

Loss of Income (LOI):

SS

15 x 1 days

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

363.65

Global Sum SS:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

363.65

Name 1:

LIM TAN MOTOR PTB LTD

Payee 2 (Strike if N.A.):

SS

Name 2:

—

Payee 3 (Strike if N.A.):

SS

Name 3:

—

COPY SENT 1/1/19

REF: ASM (AXA)

h

ASSIGNMENT

From: Date: 18062018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No.

at Workshop min

of

Insured.

Policy No.

Claims No.

Sum Insured

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / FR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/6 File pass to Customer
 @ 260.
 (Rev: 610.00 (30%))

Date/Time, File Pass to:

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to:

2)

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Workshop (\$

Report Format:

Lump Sum / LB. I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

I. S + P. S

I. Photo

I. Travel

I. Other

TOTAL:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010879/hb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 14-06-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 9998S	Veh. Inspected	QX 1132T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/06/2018	Inspection Date		
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ESTIMATE TO REPAIR

VEHICLE NO. : QX 1132 T
 MAKE : TOYOTA
 MODEL : WISH 1.8 CVT
 YEAR : 2016
 CHASSIS NO : JTDGG20W00J003663

SURVEYOR NAME	:	
DATE OF SURVEY	:	18.06.2018
TIME OF SURVEY	:	

DATE : 13-Jun-18
 DATE OF ACCIDENT : 6-Jun-18
 THIRD PARTY REF : SKQ 9998 S / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	To putty and spray painting.			2008 \$	250.00
	To repair rear bumper			\$601	120.00
<div data-bbox="544 889 970 1149"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> <div data-bbox="704 1279 1030 1420"> <p>Not Authorized 1 day</p> </div>					
TG-RA/-	TOTAL				\$ 370.00

Lim Tan Motor Pte Ltd

Bld 176 Sin Ming Drive #01-08 Sin Ming Autocare Singapore 570721
 Tel: 65-64520803 Fax: 65-64550177 Website: www.ltm.sg
 Co-Reg No: 196007277D GST Reg No: M2-0019035-0

Text size + -

Enquire Vehicle Information

Vehicle No.

Vehicle No.: QX1132T

Vehicle Details

Vehicle Type:	Road Tax Exempted Company Station Wagon (Single Rate)
Vehicle Scheme:	Government
Vehicle Attachment 1:	No Attachment
Make / Model:	TOYOTA / WISH 1.8 CVT
Primary Colour:	Silver
Year of Manufacture:	2016
Maximum Laden Weight:	1935 kg
Unladen Weight:	1360 kg
No. Of Axles:	2
Engine No.:	2ZR1719062
Chassis No.:	JTDGG20W00J003663
Engine Capacity:	1798 cc
Maximum Power Output:	105.0 kW (140 bhp)
IU Label No.:	1126395002
Propellant:	Petrol
Passenger Capacity:	6
Original Registration Date:	08 Mar 2016
First Registration Date:	08 Mar 2016
Open Market Value:	\$19,953.00
PARF Eligibility:	Yes
Minimum PARF Benefit:	\$0.00
PARF Eligibility Expiry Date:	07 Mar 2026
COE No.:	2016030103000038M
COE Category:	B - Car (above 1600cc or 97kW (130bhp))
COE Expiry Date:	07 Mar 2026
Quota Premium (QP):	\$38,610.00
QP Paid:	\$38,610.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$38,610.00
CO2 Emission:	159.00 (g/km)
CEVS Rebate Utilised Amount:	

Previous

OK

Vic (LKKAUTO)

From: richard <richard@ltm.sg>
Sent: Thursday, 1 November, 2018 9:59 AM
To: Vic (LKKAUTO)
Cc: Admin A; mandy@ltm.sg
Subject: RE: DV Submission - QX1132T Third Party Claim against AXA LKK REF CC4/ASM18010879/Khb3
Attachments: SIGNED DV.pdf
Importance: High

WITHOUT PREJUDICE

Our ref : LTP062018/057 (QX 1132 T)

Dear Vic,

In reference to your email dated 25th October 2018, we hereby now enclosed the duly signed DV by our client for payment processing.

We look forward receiving the settlement cheque soonest.

Thank you and regards,

Richard Ang

Claims Executive
Lim Tan Motor Pte Ltd

www.LTM.sg

+65 6452 0893 (Office)

+65 6458 9127 (Facsimile)

+65 8484 5418 (Mobile)

Like us in Facebook!!

www.facebook.com/LTMsg

www.facebook.com/LTM.Performance.Singapore



Re:<SEEK MANDATE> S8M00KLE ACCIDENT INVOLVING VEHICLES SKQ 9998S AND QX 1132T ON 06/06/2018

Type

🔗 Question

Message

PLS PROCEED QUANTUM AS PROPOSED

Reply



Date: 07 AUG 2018

Your Ref: CC4/ASM18010879/Khb3

Our ref: LTP062018/057 (QX 1132 T)

(WITHOUT PREJUDICE)

Attention To : Mr Vic Alpeh (From LKK Auto Consultants Pte Ltd)

Insurance Company : AXA INSURANCE PTE LTD

Dear Sir/Mdm,

IN THE MATTER OF ACCIDENT INVOLVING QX1132T & SKQ9998S ON 06.06.2018

We refer to the above matter.

We are instructed and authorised by our client to quantify, to act and negotiate settlement in related to the above road traffic accident that was caused by your insured.

All supporting documents are enclosed herewith:-

<input checked="" type="checkbox"/> Authorization To Act	<input checked="" type="checkbox"/> Original Tax Invoice no. INV35438
<input type="checkbox"/> Original Rental Receipt and Agreement	<input checked="" type="checkbox"/> LTA Search Receipt
<input type="checkbox"/> Letter Of Discharge	<input type="checkbox"/> _____

Survey was done by Insurance instruction and was surveyed by Mr Kenneth
on 18-Jun-18

As a result of the accident, our client's vehicle was damaged and has been put to loss and Expenses, particulars of which are as follows:-

1] Cost of repair (inclusive of 7% GST)	\$	278.20
2] Loss of Use (\$80.00 x 1 Day)	\$	80.00
3] LTA Search Fee	\$	7.45
Total	\$	<u>365.65</u>

Please acknowledge receipt of this letter within 14 days. If you agreeable to the above, please forward your payment. Payment to be issued directly to LIM TAN MOTOR PTE LTD within 4 weeks. Should there be any injury related to this matter, any settlement agreed is WITHOUT PREJUDICE to the related injury claim.

Your faithfully

Mandy Lim

Email: mandy@ltm.sg

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127

Website: www.LTM.sg

Co.Reg No 199307277D

GST Reg No M2-0019085-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 JUNE 2018

ABDUL WAHID SAHABUDEEN
BLOCK 551 ANG MIO KIO AVENUE 10
#08-2224
SINGAPORE 560551

By Post and By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18010879/Khb3
YOUR REF : SKQ 9998S
ACCIDENT INVOLVING SKQ 9998S AND QX1132T(SKS2302K) ALONG KAMPONG
KAPOR ROAD ON 06.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s LIM TAN MOTOR PTE LTD, acting on behalf of the owner of QX 1132T(SKS2320K) against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle QX 1132T(SKS2320K). As such, liability may not be to your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Deen67@live.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Monday, 25 June, 2018 3:33 PM
To: Deen67@live.com
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SKQ 9998S_ACCIDENT INVOLVING SKQ 9998S AND QX1132T(SKS2302K) ALONG KAMPONG KAPOR ROAD ON 06.06.2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 JUNE 2018

ABDUL WAHID SAHABUDEEN
BLOCK 551 ANG MIO KIO AVENUE 10
#08-2224
SINGAPORE 560551

By Post and By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18010879/Khb3

YOUR REF : SKQ 9998S

ACCIDENT INVOLVING SKQ 9998S AND QX1132T(SKS2302K) ALONG KAMPONG KAPOR ROAD ON 06.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s LIM TAN MOTOR PTE LTD, acting on behalf of the owner of QX 1132T(SKS2302K) against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle QX 1132T(SKS2302K). As such, liability may not be to your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

To Whom It May Concern

AUTHORIZATION TO ACT

I/We, MINISTRY OF MANPOWER ('the third party Claimant') of 1500 BENDEMEER ROAD #02-01 SINGAPORE 339946 (Address) owner of QX1132T (vehicle number) hereby authorize LIM TAN MOTOR PTE LTD ('the workshop') to act for me with respect to my/our claim for repair costs and/or rental and/or Loss of use ('claim') for my/our vehicle number QX1132T that was damaged pursuant to the accident which occurred on 06-Jun-18 (date) along KAMPONG KAPOR PARALLEL PARKING LOT 9 (locate on) involving vehicle number SKQ9998S (the accident').

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

Dated this 18th (day) of June (month) 2018 (year)


FOREIGN MANPOWER MANAGEMENT DIVISION
MINISTRY OF MANPOWER SERVICES CENTRE
1500 BENDEMEER ROAD #02-01
SINGAPORE 339946

Signed By ' the third party claimant '





Signed By ' the workshop '



redefining / insurance

CLAIM REF : S8M00KLE
INSURED : ABDUL WAHID SAHABUDEEN

DISCHARGE VOUCHER

We/I, MINISTRY OF MANPOWER, NRIC. NO. T08GA0019C hereby agree to accept the sum of dollars THREE HUNDRED SIXTY FIVE AND CENTS SIXTY FIVE ONLY (\$\$365.65) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. SKQ 99985 as a result of an accident along KAMPONG KAPOR ROAD on 06/06/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. QX 1132T.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SKQ 99985 in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SKQ 99985.

Dated this 31st day of October 2018

FOREIGN MANPOWER MANAGEMENT DIVISION
MINISTRY OF MANPOWER SERVICES CENTRE
1500 BENDEMEER ROAD #02-01
SINGAPORE 339946

Claimant's Signature : [Signature]
NRIC no./ Company Stamp : T08GA0019C
Occupation/ Business : Government Property
Address : 1500 Bendemeer Rd #02-01 Se 339946
Telephone No. : 66924323
Witness's Name : Richard Ang
Witness's Signature : [Signature]
Witness's NRIC No. : S8410708E



LIM TAN MOTOR PTE LTD
林陳摩哆私人有限公司

Company's Registration No. : 199802273D
GST Registration No. : 312-0119084-0

Branch
(Warranty and Performance) Blk 9 Sector C #01-38/40/42
Sin Ming Industrial Estate, Singapore 575644
Tel: +65 6452 2135 Fax: +65 6452 2159

Blk 17 Sector A #01-65
Sin Ming Industrial Estate, Singapore 575675

Main Office / Workshop
Blk 176 Sin Ming Drive #03-09/10/06
Sin Ming Autocare Singapore 575721

Tel: +65 6452 0893 (24Hrs)
Fax: +65 6458 9127
Email: sales@LTM.sg

WWW.LTM.SG

MINISTRY OF MANPOWER
1500 BENDEMEER ROAD
#02-01
SINGAPORE 339946

ATTN : MOTOR CLAIMS DEPT
TEL :
FAX :
A/C NO. : 30M0/121

MILEAGE :
W.O NO. : SO36152
CAR NO. : QX1132T
MAKE : TOYOTA
MODEL : WISH

TAX INVOICE

NO : INV35438
DATE : 03-08-2018
TERMS : COD
PAGE : 1

DESCRIPTION	QTY	U.PRICE	DIS	AMOUNT
1 TO PUTTY AND SPRAY PAINTING	1 UNIT	200.00		200.00
2 TO REPAIR REAR BUMPER	1 PCS	60.00		60.00

SINGAPORE DOLLARS : TWO HUNDRED SEVENTY EIGHT AND TWENTY CENTS ONLY

REMARKS: D.O.A : 06.06.2018
AXA REF : SKQ9998S
LKK REF : CC4/ASM18010879/Kbb3

TOTAL QTY: 2.00

SUBTOTAL	260.00
DISCOUNT	0.00
TOTAL	260.00
GST 7 %	18.20
NET	278.20
Deposit	0.00
Balance	278.20



AUTHORISED SIGNATURE(S)

CUSTOMER NAME / SIGNATURE / DATE

Customer Acknowledgement

I/We confirm that I/We incurred the repair costs herein and will observe my/our Agreement with the repairer. I/We declare the repair for the above vehicle have been completed to my/our satisfaction

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 09 Jun 2018 / 14:50:54

Receipt Date/Time : 09 Jun 2018 / 14:50:54

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180609-000820

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Result of Insurance Enquiry - SKQ9998S				
As at 06 Jun 2018/12:30:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SKQ9998S Enquiry Fee 20180609144934425716	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx7458	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKQ 9998S (Insd veh)	Model:	TOYOTA WISH (A)
	QX 1132T (TP veh)		
Date of Accident:	06/06/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		395.90
Final Repair Cost	: \$		278.20
Loss of Use	: \$		80.00
Rental (if any)	: \$		1 days at \$80.00 per day
LTA / GIA Search Fee	: \$		7.45

Others:	: \$		0.00
---------	------	--	------

	: \$		
Final Settlement Sum	: \$		365.65

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____ _____			

Payment Instruction: Payee's Breakdown			
1)	LIM TAN MOTOR PTE LTD	: \$	365.65

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

04/01/2019
Date


Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010879/Khb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date : 04-01-2019 Code : ASM	
				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 9998S	Veh. Inspected	QX 1132T	
Policy No.	GA091287	Coverage (\$)	0.00	
Claim No.	S8M00KLE	Excess (\$)	0.00	
Assign From		Assign Date	14/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDGG20W00J003663	Colour	METALLIC SILVER	
Odometer	19892	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	7 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/06/2018	Inspection Date	18/06/2018	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. QX 1132T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PUTTY AND SPRAY PAINTING.		250.00	200.00
	TO REPAIR REAR BUMPER.		120.00	60.00
			370.00	260.00
	GRAND TOTAL		370.00	260.00
RECOMMENDED COST OF REPAIRS				260.00

Report Ref No. CC4/ASM18010879/Khb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

