



ESTIMATE TO REPAIR

VEHICLE NO. : QX 1132 T
 MAKE : TOYOTA
 MODEL : WISH 1.8 CVT
 YEAR : 2016
 CHASSIS NO : JTDGG20W00J003663

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 13-Jun-18
 DATE OF ACCIDENT : 6-Jun-18
 THIRD PARTY REF : SKQ 9998 S / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	To putty and spray painting.				\$ 250.00
	To repair rear bumper				\$ 120.00
TG-RA/-	TOTAL				\$ 370.00

Lim Tan Motor Pte Ltd

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 570721

Tel 65 64526893 Fax 65 64583127

Website: www.LTM.sg

Ce Reg No 199307277D

GST Reg No M2 0019035 0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd