

ASS. REC. BY:

REP:

CS/AGL18010897/Tigber

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person):

Lincoln Yeo

of

AGL

Date/Time:

14062018 3:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 6856A

Insured:

SHE 8760C

at Workshop m/z

Pegasus

Tel:

of

74 Kian Teck Road

Policy No:

Claim No:

C10 00166 / JM

Sum Insured:

Excess:

Make of Veh:

D.O.A

09062018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

14062018

Person Contacted:

Avin

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLV 6856A - X

SHE 8760C - (CS/AGL) 1807189 / G201

DA: 060418

REF: 4621

Tauflin

ASSIGNMENT

From: _____ Date: _____ Estimated Cost: _____ OD / <u>TP</u> / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: _____ at Workshop no: _____ of: _____ Insured: _____ Policy No: _____ Claims No: _____ Sum Insured: _____ Excess: _____ (Client's Record) Make of Veh: _____ (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: <u>978K</u> IDAC Accident Rpt: _____ Consistent? Yes or No GIA / PP Seen: _____ Consistent? Yes or No Est. Repairs: <u>12</u> days Res: Yes or No Lum Sum: _____ % 3 Val: Yes or No CA / REV / REP. / 24 HRS <u>wp</u> Date: _____ Person Contacted: _____	Veh No: <u>SLV6856A</u> or Regn: <u>2018 Jan.</u> Type: <u>M</u> Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: <u>Mazda3</u> CC: <u>1496</u> Colour: <u>Silver</u> A/C: _____ Insured / Std / NI / NA Sp. Reading: <u>2965</u> T/Radio: Insured / Std / NI / NA Eng/No: _____ C/No: <u>JM6BN22A8H D160593</u> Gen. Cond: <u>Good</u> / Fair / Poor / Burnt Steering: <u>In order</u> / Jammed / Leaked / Burnt or Brake: <u>In order</u> / Jammed / Leaked / Burnt or Mod: <u>Nil</u> / Rim / STD A/Rim or Tyre Size: F: <u>205/60R16</u> R: <u>7</u> BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / <u>TOYO</u> / YOKO or <table border="0" style="width: 100%;"> <tr> <td>Front</td> <td><u>6</u></td> <td>Rear</td> <td><u>6</u></td> </tr> <tr> <td>R/Bal</td> <td>mm</td> <td>R/Bal</td> <td>mm</td> </tr> <tr> <td>L/Bal</td> <td>mm</td> <td>L/Bal</td> <td>mm</td> </tr> <tr> <td>D.O.A</td> <td></td> <td>D.O.I</td> <td><u>13/6/18 @ 12:49pm</u></td> </tr> </table> Survey held at: <u>Pogson</u> Des. of Damages: Frt / Rear / O/S / <u>(N/S)</u> / <u>(U/C)</u> / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision:	Front	<u>6</u>	Rear	<u>6</u>	R/Bal	mm	R/Bal	mm	L/Bal	mm	L/Bal	mm	D.O.A		D.O.I	<u>13/6/18 @ 12:49pm</u>
Front	<u>6</u>	Rear	<u>6</u>														
R/Bal	mm	R/Bal	mm														
L/Bal	mm	L/Bal	mm														
D.O.A		D.O.I	<u>13/6/18 @ 12:49pm</u>														

RECEIVED 8 APR 2019

Date/Time: File Pass to: <u>08/4/19</u> Date/Time: File Return to: _____ Report Format: <u>71</u> Lump Sum / LB: <u>12688.40</u>	☐ : Preli. Report ☐ : Final Report Add Fee: ☐ Site Insp: \$ ☐ Interview: \$ ☐ Tech. Insp: \$ ☐ Workshop: \$	Days Of Repair: <u>12</u> Resurvey No. of Trip: <u>1</u> Survey Fee: <u>490</u> Transportation: _____ Other: _____ Other: _____ Other: _____
--	---	---

Catherine Chong (LKK Auto)

From: Claims <claims@budgetdirect.com.sg>
Sent: Thursday, 14 June, 2018 3:17 PM
To: SUR; assignments@lkkauto.com
Cc: Julie Mangubat
Subject: FW: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018 | Claim ref: C10001666/JM
Attachments: GIA REPORT-SLV6856A.PDF

Urgent

Hi Team,

Please help arrange Mohamad Taufihk to survey SLV6856A.
No estimates given.

Warmest Regards,

Lincoln Yeo
Manager, Claims

T +65 6540 2180
F +65 6725 0853 (Claims)
M +65 8382 8999
E lincoln.yeo@budgetdirect.com.sg

**Budget
Direct
insurance**

Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Sent: Thursday, 14 June 2018 11:43 AM
To: Claims <claims@budgetdirect.com.sg>
Subject: Fwd: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018 | Claim ref: C10001666/JM

Dear All,

FYI.

Alvin Low
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road
Singapore
628800

Tel

6513 7748

Fax :
6251 3161

Email : ar_claims@pegasusengrg.com.sg

----- Forwarded message -----

From: **Pegasus Engineering** <ar_claims@pegasusengrg.com.sg>

Date: Wed, Jun 13, 2018 at 11:56 AM

Subject: Re: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018 | Claim ref: C10001666/JM

To: Julie Mangubat <julie.m@budgetdirect.com.sg>

Dear Julie,

We would like to choose Mohamad Taufihk LKK Auto Consultants Pte Ltd to the survey this vehicle.

Thanks and regards.

Alvin Low
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road
Singapore
628800

Tel

6513 7748

Fax :
6251 3161

Email : claims@pegasusengrg.com.sg

On Tue, Jun 12, 2018 at 2:01 PM, Julie Mangubat <julie.m@budgetdirect.com.sg> wrote:

Without Prejudice

Dear Sir

We refer to the notice of accident sent to us on 12 June 2018.

Please find the list of your surveyors to choose from.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Mohammed Rasul LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Simon Ho LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Chow Bo Xiong FormTeam Adjusters Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you,

-Julie

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>

Sent: Tuesday, 12 June, 2018 12:12 PM

To: Claims <claims@budgetdirect.com.sg>

Subject: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018

Your Ref: SGE8760C

Our Ref: SLV6856A

DOA: 09.06.2018

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair (will send shortly).

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have **a list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

The vehicle currently grounded in our premises, please arrange for survey as soon as possible at 74 Kian Teck Road Singapore 628800.

Thanks & Regards,

Alvin Low
Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road

Singapore

628800

Tel

:

6513 7748

Fax :

6251 3161

Email : ar_claims@pegasusengr.com.sg

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Celine Fong (LKKAuto)

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Sent: Thursday, 4 April 2019 10:02 AM
To: Taufikh (LKKAuto)
Subject: Re: SLV6856A TP- Budget Direct (DOA 09062018) Finalised

Good morning Taufikh,

COR (P/P) confirmed at \$12,688.40 (before GST) & DOR @ 12 days.

Thank You

Best Regards,
Vivian Tan
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

On Wed, Apr 3, 2019 at 12:12 PM Taufikh (LKKAuto) <Taufikh@lkkauto.com> wrote:

Hi Lionel,

Item 79 n/s front wheel rim revised to \$200 and item 80 n/s front tyre 80% depreciation therefore its \$200.

The rest is the same. So total repair cost **\$12688.40, 12 repair days**. For additional days claiming when the car is down and waiting for survey and weekends, you can inform the insurance.

Regards

Taufikh

Lkk Auto

From: Pegasus Engineering [mailto:ar_claims@pegasusengrg.com.sg]
Sent: Friday, 1 March 2019 12:00 PM
To: Taufikh (LKK Auto)
Cc: Admin A; Lionel Chua <lionelchua@pegasusengrg.com.sg>; admin-d@lkkauto.com; Pegasus Engineering
Subject: Re: SLV6856A TP- Budget Direct (DOA 09062018) Finalised

Morning Taufikh,

Celine Fong (LKKAuto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Wednesday, 3 April 2019 5:57 PM
To: Shiau Chan (LKKAuto); Admin-D (LKKAuto); SUR; assignments
Cc: Lincoln Yeo
Subject: RE: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018 | Claim ref: C10001666/JM

Hi Shiau Chan

Any updates on this case?

Thank you,
-Julie

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 22 January, 2019 3:20 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Julie Mangubat <julie.m@budgetdirect.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Lincoln Yeo <lincoln.yeo@budgetdirect.com.sg>
Subject: RE: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018 | Claim ref: C10001666/JM

Dear Julie,

Thank you for the email.

Please be informed that we are in the midst of finalise with repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 22 January 2019 11:36 AM
To: 'Julie Mangubat' <julie.m@budgetdirect.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: 'Lincoln Yeo' <lincoln.yeo@budgetdirect.com.sg>
Subject: RE: Third party survey SLV6856A Your insured SGE8760C on 09.06.2018 | Claim ref: C10001666/JM

Dear Julie,

Thank you for your email.

Dear Shiau Chan,

FYNA. Our Ref: CS/AGI18010897/T1qb

Best Regards,

Catherine Chong | Admin

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1345N
Vehicle Details	
Vehicle No.:	SLV6856A
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	P520453003
Chassis No.:	JM6BN22A8H0160593
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,938.00
Original Registration Date:	11 Jan 2018
First Registration Date:	11 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$14,938.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2028
PARF Rebate Amount:	\$11,203.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$34,320.00
Total Rebate Amount:	\$45,523.00

The information contained herein is correct as at 12 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/06/2018 13:53
Date Of Accident	09/06/2018 16:20
Exact Location Of Accident	UPPER EAST COAST ROAD BEFORE EXIT TO BEDOK AVE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLV6856A
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29069766MKF
Cover Note Number	
Driver	
Name of Driver	ONG WAN BENG
NRIC No	S1436144H
Date Of Birth	20/03/1960
Occupation	OUTDOOR
Date Of Driving Pass	13/09/1977
Driving Experience	40 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91193149
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : P1 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was on the right lane going straight. Upon approaching SPC PETROL STATION, suddenly a vehicle from left. Abruptly swerved into my lane and as a result hit directly onto my vehicle left portion.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	YES-RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGE8760C
Vehicle Make/Model/Colour	HONDA/CRV 2.0 A/RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KNIGHT HASSELL CHRISTOPHER KARL
NRIC/Passport Number	S2691213Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)
Passenger 1

2

NAME: : P1

GENDER: : FEMALE

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available at/through.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my solicitors and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer/collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"); the insurer's insurer/s law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the making of correspondence, statements, reviews, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in the accident and the insurer's insurer/s law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/s law firm), which may be staff outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was on the right lane going straight. Upon approaching SPC PETROL STATION, suddenly a vehicle from left. Abruptly swerved into my lane and as a result hit directly onto my vehicle left portion.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

10 June 2018 at 1:30 PM

Date/Time:

10 June 2018 at 1:30 PM



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer :
GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C, DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BONNET	1	1,068.0000	1,068.00
2	BONNET HINGES	2	41.0000	82.00
3	BONNET UNDERSEAL WEATHERSTRIP CLIPS	10	4.5000	45.00
4	FRONT BUMPER	1	1,075.0000	1,075.00
5	FRONT BUMPER SIDE RETAINER	2	92.0000	184.00
6	FRONT BUMPER INDICATION LIGHT	1	140.0000	140.00
7	FRONT BUMPER INDICATION LIGHT GARNISH	1	5.0000	5.00
8	FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION	1	48.0000	48.00
9	FRONT BUMPER AIR GUIDE	1	56.0000	56.00
10	FRONT BUMPER LOWER SUPPORT GARNISH	1	96.0000	96.00
11	FRONT BUMPER LOWER SPLASHIELD COVER	1	84.0000	84.00
12	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	6	4.0000	24.00
13	FRONT BUMPER CLIPS	10	5.0000	50.00
14	RADIATOR GRILLE	1	150.0000	150.00
15	N/S RADIATOR GRILLE CHROME GARNISH	1	183.0000	183.00
16	N/S RADIATOR GRILLE CHROME GARNISH BASE	1	20.0000	20.00
17	N/S RADIATOR GRILLE INNER SIDE BRACKET	2	20.0000	40.00
18	N/S RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS	2	5.0000	10.00
19	N/S RADIATOR GRILLE INNER SIDE BRACKET CLIP HOLDER	2	5.0000	10.00
20	RADIATOR GRILLE OUTER GARNISH RIVETS	4	9.0000	36.00
21	RADIATOR GRILLE OUTER GARNISH CLIPS	2	5.0000	10.00
22	N/S HEADLAMP	1	1,020.0000	1,020.00
23	N/S FRONT FENDER	1	334.6000	334.60

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :
--

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C, DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	N/S FRONT FENDER INNER COWLING	1	146.0000	146.00
25	N/S FRONT FENDER INNER COWLING CLIPS	6	5.0000	30.00
26	N/S FRONT FENDER INNER WHEEL HOUSE PANEL	1	1,547.0000	1,547.00
27	FRONT BUMPER LOWER SPLASHIELD COVER	1	84.0000	84.00
28	N/S FRONT DOOR	1	1,062.0000	1,062.00
29	N/S FRONT DOOR HINGE TOP <i>Ry</i>	1		
30	N/S FRONT DOOR HINGE BOTTOM <i>Ry</i>	1		
31	N/S FRONT DOOR CHECKER/ARRESTOR <i>x</i>	1		
32	N/S FRONT DOOR OUTER WEATHERSTRIP MOULDING <i>x</i>	1		
33	N/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>x</i>	1		
34	N/S FRONT DOOR WEATHERSTRIP <i>x</i>	1		
35	N/S FRONT DOOR WINDOW FRAME TOP GARNISH <i>x</i>	1		
36	N/S FRONT DOOR WINDOW FRAME REAR GARNISH <i>x</i>	1		
37	N/S FRONT DOOR SIDE MIRROR - COVER <i>Ry</i>	1		
38	N/S FRONT DOOR SIDE MIRROR MOTOR ASSY <i>?</i>	1		
39	N/S ROCKER PANEL <i>Ry</i>	1		
40	DOOR CENTER "B" PILLIAR <i>Ry</i>	1		
41	N/S REAR DOOR <i>H /</i>	1		
42	N/S REAR DOOR HINGE BOTTOM <i>Ry</i>	1		
43	REAR DOOR WEATHERSTRIP <i>all /</i>	1		
44	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING <i>?</i>	1		
45	N/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>?</i>	1		

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :
--

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C, DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	REAR FENDER <i>bt ✓</i>	1		
47	N/S FRONT SHOCK ABSORBER ?	1		
48	N/S FRONT SHOCK ABSORBER TOP MOUNT ?	1		
49	N/S FRONT LOWER ARM <i>bt ✓</i>	1		
50	FRONT KNUCKLE <i>bt ✓</i>	1		
51	N/S FRONT WHEEL BEARING WITH HUB <i>bt ✓</i>	1		
52	FRONT ANTI ROLL BAR <i>x ?</i>	1		
53	FRONT ANTI ROLL BAR LINK ?	2		
54	N/S DRIVE SHAFT ?	1		
55	N/S DRIVE SHAFT OIL SEAL ?	1		
56	STEERING RACK AND PINION ?	1		
57	ENGINE SUSPENSION CROSS-MEMBER <i>x</i>	1		
58	O/S ENGINE MOUNT <i>x</i>	1		
59	ENGINE MOUNT REAR <i>x</i>	1		
60	ENGINE LOWER SPLASHIELD COVER <i>x</i>	1		
61	REAR SHOCK ABSORBER ?	1		
62	REAR BUMPER <i>Rx</i>	1		
63	REAR WHEEL HUB CAP <i>cut ✓</i>	1		
64	FRONT WHEEL HUB CAP <i>mis ✓</i>	1		
65	N/S REAR DOOR HINGE TOP <i>Rx</i>	1		
66	REAR DOOR CHECKER/ARRESTOR <i>x</i>	1		
67	REAR DOOR OUTER 1/4 GLASS CHROME MOULDING ?	1		

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :
--

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
68	REAR SHOCK ABSORBER ?	1		
69	REAR SHOCK ABSORBER TOP MOUNT ?	1		
70	REAR LOWER ARM ?	1		
71	REAR WHEEL KNUCKLE ?	1		
72	REAR WHEEL BEARING WITH HUB ?	1		
73	REAR STABILIZE BAR BUSHING ✓	1		
74	REAR STABILIZE BAR LINK X	1		
75	REAR FENDER INNER COWLING X	1		
76	REAR FENDER INNER COWLING CLIPS X	4		
77	LESS 20% ITEM (1-76)	1		
78	N/S FRONT WHEEL RIM ✓	1		
79	N/S FRONT WHEEL TYRE punctured - 800/0	1		
80	TOWING CHARGES.	1	120.0000	120.00
81	TO CHECK ELECTRICAL CONCERNED.	1	80.0000	80.00
82	TO TRANSFER OF BOTH FRONT TYRE, RIM AND ON WHEEL BALANCING.	1	50.0000	50.00
83	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT.	1	800.0000	800.00
84	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	150.0000	150.00
85	TO TRANSFER OF BOTH N/S DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1	250.0000	250.00
86	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

GRAB RENTALS 2 PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GRAB RENTALS 2 PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C, DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
87	TO DROP N/S FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESING.	1	480.0000	150? 480.00 plate
88	TO REMOVE AND RENEW ENGINE AND GEARBOX MOUNTINGS.	1	180.0000	X 180.00
89	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	1	120.0000	80 120.00
90	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,400.0000	(1200) 1,400.00
91	PUTTY AND SPRAY PAINTING OF THE AFFECTED.	1	1,200.0000	✓ 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Lim 97495749
- up
13/6/18 @ 12:00 pm
Lumpsum
Resurvey after repair
Sub E/Kh auto. was
12 days

19/6/18

Sub Total 12,649.60
GST(7.00%) 885.47
Total (SGD) 13,535.07

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
--	---

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BONNET	1	1,068.0000	1,068.00 ✓
2	BONNET HINGES	2	41.0000	82.00 ✓
3	BONNET UNDERSEAL WEATHERSTRIP CLIPS	10	4.5000	45.00 ✓
4	FRONT BUMPER	1	1,075.0000	1,075.00 ✓
5	FRONT BUMPER SIDE RETAINER LH/RH X 2	2	92.0000	184.00 92 ✓
6	FRONT BUMPER INDICATION LIGHT	1	140.0000	140.00 ? X m ✓
7	FRONT BUMPER INDICATION LIGHT GARNISH	1	25.0000	25.00 ? X m ✓
8	FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION	1	48.0000	48.00 ✓
9	FRONT BUMPER AIR GUIDE	1	56.0000	56.00 ? X } m ✓
10	FRONT BUMPER LOWER SUPPORT GARNISH	1	96.0000	96.00 ? X } m ✓
11	FRONT BUMPER LOWER SPLASHIELD COVER	1	84.0000	84.00 ? X } m ✓
12	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	6	4.0000	24.00 ? X } m ✓
13	FRONT BUMPER CLIPS	10	5.0000	50.00 ? X } m ✓
14	RADIATOR GRILLE	1	150.0000	150.00 X ✓
15	N/S RADIATOR GRILLE CHROME GARNISH	1	183.0000	183.00 X ✓
16	N/S RADIATOR GRILLE CHROME GARNISH BASE	1	20.0000	20.00 X ✓
17	N/S RADIATOR GRILLE INNER SIDE BRACKET	2	20.0000	40.00 X ✓
18	N/S RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS	2	5.0000	10.00 X ✓
19	N/S RADIATOR GRILLE INNER SIDE BRACKET CLIP HOLDER	2	5.0000	10.00 X ✓
20	RADIATOR GRILLE OUTER GARNISH RIVETS	4	9.0000	36.00 X ✓
21	RADIATOR GRILLE OUTER GARNISH CLIPS	2	5.0000	10.00 X ✓
22	N/S HEADLAMP	1	1,020.0000	1,020.00 ✓
23	N/S FRONT FENDER	1	334.6000	334.60 ✓

Supplement Parts

* Converter, DC/DC \$481.40

C/F 0.00

Page 1 of 5

3682.60 ✓

3290.60

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
--	---

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV5856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	N/S FRONT FENDER INNER COWLING	1	146.0000	146.00 ✓
25	N/S FRONT FENDER INNER COWLING CLIPS	6	5.0000	30.00 ✓
26	N/S FRONT FENDER INNER WHEEL HOUSE PANEL	1	1,547.0000	1,547.00 x m
27	FRONT BUMPER LOWER SPLASHIELD COVER	1	84.0000	84.00 x m
28	N/S FRONT DOOR	1	1,062.0000	1,062.00 R
29	N/S FRONT DOOR HINGE TOP	1	42.0000	42.00 R
30	N/S FRONT DOOR HINGE BOTTOM	1	40.0000	40.00 R
31	N/S FRONT DOOR CHECKER/ARRESTOR	1	37.0000	37.00
32	N/S FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	77.0000	77.00 x
33	N/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	105.0000	105.00 x m
34	N/S FRONT DOOR WEATHERSTRIP	1	107.0000	107.00 x
35	N/S FRONT DOOR WINDOW FRAME TOP GARNISH	1	84.0000	84.00 x
36	N/S FRONT DOOR WINDOW FRAME REAR GARNISH	1	64.0000	64.00 x
37	N/S FRONT DOOR SIDE MIRROR - COVER	1	123.0000	123.00 R
38	N/S FRONT DOOR SIDE MIRROR MOTOR ASSY	1	378.0000	378.00 x m
39	N/S ROCKER PANEL	1	309.0000	309.00 R
40	DOOR CENTER	1	785.0000	785.00 R
41	N/S REAR DOOR	1	1,006.0000	1,006.00 ✓
42	N/S REAR DOOR HINGE BOTTOM	1	43.0000	43.00 R
43	REAR DOOR WEATHERSTRIP	1	121.0000	121.00 ✓
44	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING	1	141.0000	141.00 x m
45	N/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	117.0000	117.00 x m
				1303 //
				C/F 0.00

6048

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	--

Quotation No : QQ18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV5856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	REAR FENDER	1	334.0000	334.00 ✓
47	N/S FRONT SHOCK ABSORBER	1	287.0000	287.00 ✓
48	N/S FRONT SHOCK ABSORBER TOP MOUNT	1	92.0000	92.00 ✓
49	N/S FRONT LOWER ARM	1	485.0000	485.00 ✓
50	FRONT KNUCKLE	1	384.0000	384.00 ✓
51	N/S FRONT WHEEL BEARING WITH HUB	1	542.0000	542.00 ✓
52	FRONT ANTI ROLL BAR	1	1,219.0000	1,219.00 ✓
53	FRONT ANTI ROLL BAR LINK	2	65.0000	130.00 ✓
54	N/S DRIVE SHAFT	1	1,336.0000	1,336.00 ✓
55	N/S DRIVE SHAFT OIL SEAL	1	24.0000	24.00 ✓
56	STEERING RACK AND PINION	1	916.0000	916.00 ✓
57	ENGINE SUSPENSION CROSS-MEMBER	1	1,791.0000	1,791.00 X
58	O/S ENGINE MOUNT	1	402.0000	402.00 X
59	GEARBOX MOUNT	1	335.0000	335.00 X
60	ENGINE MOUNT REAR	1	315.0000	315.00 X
61	ENGINE LOWER SPLASHIELD COVER	1	287.0000	287.00 X
62	REAR SHOCK ABSORBER	1	307.0000	307.00 ? X
63	REAR BUMPER	1	1,075.0000	1,075.00 R
64	FRONT WHEEL HUB CAP	1	250.0000	250.00 ✓
65	REAR WHEEL HUB CAP	1	250.0000	250.00 ✓
66	N/S REAR DOOR HINGE TOP	1	46.0000	46.00 R
67	REAR DOOR CHECKER/ARRESTOR	1	37.0000	37.00 X
				5333

C/F 0.00

Page 3 of 5

102114

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
--	---

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV8858A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
68	REAR DOOR OUTER 1/4 GLASS CHROME MOULDING	1	77.0000	77.00
69	REAR SHOCK ABSORBER	4	307.0000	307.00
70	REAR SHOCK ABSORBER TOP MOUNT	1		
71	REAR LOWER ARM	1	233.0000	233.00
72	REAR WHEEL KNUCKLE	1	654.0000	654.00
73	REAR WHEEL BEARING WITH HUB	1	416.0000	416.00
74	REAR STABILIZE BAR BUSHING	1	30.7000	30.70
75	REAR STABILIZE BAR LINK	1	65.0000	65.00
76	REAR FENDER INNER COWLING	1	146.0000	146.00
77	REAR FENDER INNER COWLING CLIPS	4	5.0000	20.00
78	LESS 20% ITEM (1-76)	1	-4,806.0800	-4,806.08
79	N/S FRONT WHEEL RIM	1	300.0000	300.00
80	N/S FRONT WHEEL TYRE	1	250.0000	250.00
81	TOWING CHARGES.	1	120.0000	120.00
82	TO CHECK ELECTRICAL CONCERNED.	1	80.0000	80.00
83	TO TRANSFER OF BOTH FRONT TYRE, RIM AND ON WHEEL BALANCING.	1	50.0000	50.00
84	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT.	1	800.0000	800.00
85	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	150.0000	150.00
86	TO TRANSFER OF BOTH N/S DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1	250.0000	250.00

C/F 0.00
Page 4 of 5

10/10/24

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
--	---

Quotation No : QO18/06-1132	Quotation Date : 12/06/2018	Terms : 30 DAYS
Vehicle No : SLV6856A	Chassis No : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
				B/F	0.00
87	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00	60
88	TO DROP N/S FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESING.	1	480.0000	480.00	150.00
89	TO REMOVE AND RENEW ENGINE AND GEARBOX MOUNTINGS.	1	180.0000	180.00	0.00
90	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	1	120.0000	120.00	60
91	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,400.0000	1,400.00	200
92	PUTTY AND SPRAY PAINTING OF THE AFFECTED.	1	1,200.0000	1,200.00	120.00
				2690.00	2690.00

Sub Total 24,784.24
 GST(7.00%) 1,734.90
Total (SGD) 26,519.14

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--	--

Quotation No. : QO18/06-1185	Quotation Date : 19/06/2018	Terms : 30 DAYS
Vehicle No. : SLV6856A	Chassis No. : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : SUPPLEMENTARY FOR SLV6856A, TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C, DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR WINDSCREEN GLASS WEATHERSTRIP ✓	1	68.0000	68.00 ✓
2	LESS 20%	1	-13.6000	-13.60 ✓
3	REAR WINDSCREEN GLASS SEALANT ✓	1	80.0000	80.00 ✓
4	REAR WINDSCREEN GLASS SPONGE SEAL ✓	1	120.0000	120.00 ✓

254.40

Sub Total	254.40
GST(7.00%)	17.81
Total (SGD)	272.21

Please conduct the survey at

http://54.255.197.135:8118/v50foldersetadmin/v50stringadmin/v50master/contentadmin/sal_quo_view11... 19/6/2018



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/06-1183	Quotation Date : 19/06/2018	Terms : 30 DAYS
Vehicle No. : SLV6856A	Chassis No. : JM6BN22A8H0160593	Third Party Insurer : p180621142445364625051
Model : MAZDA 3		Date of Accident : 09/06/2018
Remarks : SUPPLEMENTARY ITEM, TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8760C, DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT ENGINE COVER	1	295.0000	295.00
2	CONTROL ARM	1	185.0000	185.00
3	LESS 20% ITEM 1 -2	1	-96.0000	-96.00

480
20% 384

Sub Total	384.00
GST(7.00%)	26.88
Total (SGD)	410.88

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO18/06-1183	Quotation Date : 19/06/2018	Terms : 30 DAYS
Vehicle No. : SLV6856A	Chassis No. : JM6BN22A8H0160593	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : SUPPLEMENTARY ITEM, TP INSURER: AGI, INSURED'S VEHICLE NO: SGE8780C , DATE OF ACCIDENT: 09.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	DC CONVERTER <i>Car</i>	1	481.4000	481.40 <i>3851</i>
2	LESS 20% ITEM (1)	1	96.2800	96.28
3	N/S REAR WHEEL RIM ?	1	300.0000	300.00 <i>add x n</i>
4	N/S REAR WHEEL TYRE ?	1	250.0000	250.00 <i>x n</i>

10318.60
20% →
Parts : \$ 8,254.88 ✓
Supp parts : \$ 1,023.52
Labour : \$ 3,560.00 3410
\$ 12,838.40 12688.40

385.12 ✓

Sub Total 1,127.69
 GST(7.00%) 78.94
 Total (SGD) 1,206.62

26550.32



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18010897/T1qbe2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 11-04-2019



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGE 8760C	Veh. Inspected	SLV 6856A
Policy No.		Coverage (\$)	0.00
Claim No.	C1000166/JM	Excess (\$)	0.00
Assign From	LINCOLN YEO	Assign Date	14/06/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JM6BN22A8H0160593	Colour	SILVER
Odometer	29685	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/06/2018	Inspection Date	13/06/2018
Survey held at	74 KIAN TECK RD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6856A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BENT	1,068.00	1,068.00
2	BONNET HINGES @\$41.00	TO REPAIR SEE LABOUR	82.00	-
10	BONNET UNDERSEAL WEATHERSTRIP CLIPS @\$4.50	NECESSARY	45.00	45.00
1	FRONT BUMPER	DEFORMED	1,075.00	1,075.00
2	FRONT BUMPER SIDE RETAINER @\$92.00	N/S NECESSARY / O/S NOT NECESSARY	184.00	92.00
1	FRONT BUMPER INDICATION LIGHT	NOT NECESSARY	140.00	-
1	FRONT BUMPER INDICATION LIGHT GARNISH	NOT NECESSARY	25.00	-
1	FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION	CUT	48.00	48.00
1	FRONT BUMPER AIR GUIDE	NOT NECESSARY	56.00	-
1	FRONT BUMPER LOWER SUPPORT GARNISH	NOT NECESSARY	96.00	-
1	FRONT BUMPER LOWER SPLASHIELD COVER	NOT NECESSARY	84.00	-
6	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS @\$4.00	NOT NECESSARY	24.00	-
10	FRONT BUMPER CLIPS @\$5.00	NOT NECESSARY	50.00	-
1	RADIATOR GRILLE	NOT NECESSARY	150.00	-
1	N/S RADIATOR GRILLE CHROME GARNISH	NOT NECESSARY	183.00	-
1	N/S RADIATOR GRILLE CHROME GARNISH BASE	NOT NECESSARY	20.00	-
2	N/S RADIATOR GRILLE INNER SIDE BRACKET @\$20.00	NOT NECESSARY	40.00	-
2	N/S RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS @\$5.00	NOT NECESSARY	10.00	-
2	N/S RADIATOR GRILLE INNER SIDE BRACKET CLIP HOLDER @\$5.00	NOT NECESSARY	10.00	-
4	RADIATOR GRILLE OUTER GARNISH RIVETS @\$9.00	NOT NECESSARY	36.00	-
2	RADIATOR GRILLE OUTER GARNISH CLIPS @\$5.00	NOT NECESSARY	10.00	-
1	N/S HEADLAMP	CRACKED	1,020.00	1,020.00
1	N/S FRONT FENDER	BENT	334.60	334.60
1	N/S FRONT FENDER INNER COWLING	DEFORMED	146.00	146.00
6	N/S FRONT FENDER INNER COWLING CLIPS @\$5.00	NECESSARY	30.00	30.00
1	N/S FRONT FENDER INNER WHEEL HOUSE PANEL	NOT NECESSARY	1,547.00	-
1	FRONT BUMPER LOWER SPLASHIELD COVER	NOT NECESSARY	84.00	-
1	N/S FRONT DOOR	TO REPAIR SEE LABOUR	1,062.00	-

Report Ref No. CS/AGI18010897/T1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	N/S FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	42.00	-
1	N/S FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	40.00	-
1	N/S FRONT DOOR CHECKER / ARRESTOR	NOT NECESSARY	37.00	-
1	N/S FRONT DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	77.00	-
1	N/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	105.00	-
1	N/S FRONT DOOR WEATHERSTRIP	NOT NECESSARY	107.00	-
1	N/S FRONT DOOR WINDOW FRAME TOP GARNISH	NOT NECESSARY	84.00	-
1	N/S FRONT DOOR WINDOW FRAME REAR GARNISH	NOT NECESSARY	64.00	-
1	N/S FRONT DOOR SIDE MIRROR - COVER	TO REPAIR SEE LABOUR	123.00	-
1	N/S FRONT DOOR SIDE MIRROR MOTOR ASSY	NOT NECESSARY	378.00	-
1	N/S ROCKER PANEL	TO REPAIR SEE LABOUR	309.00	-
1	DOOR CENTER	TO REPAIR SEE LABOUR	785.00	-
1	N/S REAR DOOR	BENT	1,006.00	1,006.00
1	N/S REAR DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	43.00	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	121.00	121.00
1	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	141.00	-
1	N/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	117.00	-
1	REAR FENDER	BENT	334.00	334.00
1	N/S FRONT SHOCK ABSORBER	BENT	287.00	287.00
1	N/S FRONT SHOCK ABSORBER TOP MOUNT	NECESSARY	92.00	92.00
1	N/S FRONT LOWER ARM	BENT	485.00	485.00
1	FRONT KNUCKLE	BENT	384.00	384.00
1	N/S FRONT WHEEL BEARING WITH HUB	BENT	542.00	542.00
1	FRONT ANTI ROLL BAR	BENT	1,219.00	1,219.00
2	FRONT ANTI ROLL BAR LINK @\$65.00	BENT	130.00	130.00
1	N/S DRIVE SHAFT	BENT	1,336.00	1,336.00
1	N/S DRIVE SHAFT OIL SEAL	NECESSARY	24.00	24.00
1	STEERING RACK AND PINION	NOT NECESSARY	916.00	-
1	ENGINE SUSPENSION CROSS-MEMBER	NOT NECESSARY	1,791.00	-
1	O/S ENGINE MOUNT	NOT NECESSARY	402.00	-
1	GEARBOX MOUNT	NOT NECESSARY	335.00	-

Report Ref No. CS/AGI18010897/T1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE MOUNT REAR	NOT NECESSARY	315.00	-
1	ENGINE LOWER SPLASHIELD COVER	NOT NECESSARY	287.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	307.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,075.00	-
1	FRONT WHEEL HUB CAP	CUT	250.00	250.00
1	REAR WHEEL HUB CAP	MISSING	250.00	250.00
1	N/S REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	46.00	-
1	REAR DOOR CHECKER/ARRESTOR	NOT NECESSARY	37.00	-
1	REAR DOOR OUTER 1/4 GLASS CHROME MOULDING	NOT NECESSARY	77.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	307.00	-
1	REAR SHOCK ABSORBER TOP MOUNT (NPA)	NOT NECESSARY	-	-
1	REAR LOWER ARM	NOT NECESSARY	233.00	-
1	REAR WHEEL KNUCKLE	NOT NECESSARY	654.00	-
1	REAR WHEEL BEARING WITH HUB	NOT NECESSARY	415.00	-
1	REAR STABILIZE BAR BUSHING	NOT NECESSARY	30.70	-
1	REAR STABILIZE BAR LINK	NOT NECESSARY	65.00	-
1	REAR FENDER INNER COWLING	NOT NECESSARY	146.00	-
4	REAR FENDER INNER COWLING CLIPS @\$5.00	NOT NECESSARY	20.00	-
1	REAR WINDSCREEN GLASS WEATHERSTRIP (ADDITIONAL)	NECESSARY	68.00	68.00
1	FRONT ENGINE COVER (ADDITIONAL)	DEFORMED	295.00	295.00
1	CONTROL ARM (ADDITIONAL)	BENT	185.00	185.00
1	DC CONVERTER (ADDITIONAL)	CRACKED	481.40	481.40
	LESS 20% DISCOUNT		-5,011.94	-2,269.60
			20,047.76	9,078.40
SPECIAL NETT ITEMS				
1	N/S FRONT WHEEL RIM (SN)	BENT	300.00	200.00
1	N/S FRONT WHEEL TYRE (SN) (80%)	PUNCTURE	250.00	200.00
1	REAR WINDSCREEN GLASS SEALANT (SN) (ADDITIONAL)	NECESSARY	80.00	80.00
1	REAR WINDSCREEN GLASS SPONGE SEAL (SN) (ADDITIONAL)	NECESSARY	120.00	120.00
1	N/S REAR WHEEL RIM (SN) (ADDITIONAL)	NOT NECESSARY	300.00	-
1	N/S REAR WHEEL TYRE (SN) (ADDITIONAL)	NOT NECESSARY	250.00	-
			1,300.00	600.00

Report Ref No. CS/AGI18010897/T1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING CHARGES.		120.00	120.00
	TO CHECK ELECTRICAL CONCERNED.		80.00	30.00
	TO TRANSFER OF BOTH FRONT TYRE, RIM AND ON WHEEL BALANCING.		50.00	30.00
	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT.	NOT NECESSARY	800.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		150.00	80.00
	TO TRANSFER ON BOTH N/S DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.		250.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		180.00	60.00
	TO DROP N/S FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING.		480.00	150.00
	TO REMOVE AND RENEW ENGINE AND GEARBOX MOUNTINGS.	NOT NECESSARY	180.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		120.00	80.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BONNET HINGES, N/S FRONT DOOR, N/S FRONT DOOR HINGE TOP, N/S FRONT DOOR HINGE BOTTOM, N/S FRONT DOOR SIDE MIRROR - COVER, N/S ROCKER PANEL, DOOR CENTER, N/S REAR DOOR HINGE BOTTOM, REAR BUMPER AND N/S REAR DOOR HINGE TOP.		1,400.00	1,200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED.		1,200.00	1,200.00
			5,010.00	3,010.00
	GRAND TOTAL		26,357.76	12,688.40
RECOMMENDED COST OF REPAIRS				12,688.40

Report Ref No. CS/AGI18010897/T1qbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.