

ASS. REC. BY:

REF: CS/AIG18010904/Uvd3/n2

Special Instruction:

Surveyor: meiminASSIGNMENT (Office)From (Person): Chan Yoke Shi of AIG Date/Time: 14/6/18 @ 3.33pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKF 9658G Insured: SDP 8832Gat Workshop m/s Imperium Automotive Tel: 9748 9940of 25 kaki Bukit Rd 4 #01-49 Synergy

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13/06/2018
(Client's Record)CA / REV / REP. / REV 24 HRS lup 18/06/2018
H.O.D. Endorsement: _____Date/Time: 4.26pm @ 14/6/18 Person Contacted: Shawn Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKF 9658G - X</u>
	<u>SDP 8832G - CC3 / AIG 15017704 / R / ea3q.2 DOA: 16/10/15</u>

(08/11/13) waf

ASS. REC. BY: MORUJ

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKF9658at Workshop n/s ingan

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 51k.IDAC Accident Rpt: ✓ Consistent?: Yes or NoGLA / PR Seen: ✓ Consistent?: Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

27A42142

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKF9658 Regn: 712Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Traller or CA1Make: Volkswagen SCIROCCO 1390Colour: white A/C: Insured / Std / NI / NASp. Reading: 141195 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ13ZCV038544Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/35-ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 13/6/18 D.O.I. 18/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

41/5 mbk. Rep 9500net 888819/6/18 confirmed 4/5 & 7500 will shown. (Red 4903.98, 409)

RECEIVED 19 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/6 - typistDays Of Repair: 5Resurvey No. of Trip: -

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

25020270Report Format: merimenLump Sum / I.B.I: (\$ 7500)

- Pre repair inspection request - SKF9658G VS SDP8832G (OI) DOA: 13/06/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, admin-ai@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshene, Mithoosingh, Aashweenjeethaur, A
Sent: 14/6/2018 3:33:39 PM
Attachments: ☐ FaxBAEE.TIF

Hi,

Please refer to the enclosed request from **IMPERIUM AUTOMOTIVE**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]

Sent: Thursday, June 14, 2018 3:30 PM

To: Chan, Yoke Shi

Subject: Fw: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDP8832G AND SKF9658G ON 13/06/2018

Your ref: SDP8832G

Our ref: JEQ/180489/0618/IMP

Dear Yoke Shi,

We refer to your email dated 14 June 2018.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Marcus Chua-LKK Auto Consultants Pte Ltd

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

IMPERIUM AUTOMOTIVE
25 Kaki Bukit Road 4 #01-49,
Synergy@KB
Singapore 417800
Tel:9748 9940 Fax: 6346 7213

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

From: JUSEQ

To: alfred_ng@juseq.com.sg

Sent: Thursday, June 14, 2018 2:45 PM

Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDP8832G AND SKF9658G ON 13/06/2018

From: Chan, Yoke Shi [mailto:yokeshi.chan@aig.com]

Sent: Thursday, June 14, 2018 2:41 PM

To: jusen@singnet.com.sg

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDP8832G AND SKF9658G ON 13/06/2018

Without Prejudice

Your Reference : JEQ/180489/0618/IMP
Our Reference : SDP8832G

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



JusEquity Law Corporation

ADVOCATES & SOLICITORS - COMMISSIONER FOR OATHS

171 Chin Swee Road #02-08 CES Centre Singapore 169877
 Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2006, (65) 6533 2327
 Fax : (65) 6253 0120 (Conveyancing) , (65) 6536 5368 (Litigation)
 Email : jus501@alingsnet.com.sg Website: www.jus501.com.sg

Our Ref: JEQ/180489/0618/IMP
 Your Ref: SDP8832G

14 June 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
 (Claims Department)
 78 Shenton Way
 #08-16, AIG Building
 Singapore 079120

VIA FAX
 (Fax No. 6835-7416)

Dear Sir


ACCIDENT INVOLVING SKF9658G AND SDP8832G ON 13.06.2018

We act for Koh Wei Liang, the owner of vehicle no. SKF9658G.

We hereby notify you of a road traffic accident on 13/06/2018 at about 0515 hours at junction of Thomson Road and Newton Road involving our client's vehicle and vehicle registration no. SDP8832G driven by your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

CC 
YAP SIEW KEE
 25 Thomson Terrace
 Singapore 574556
 (Your Ref: SDP8832G)

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

Book now with your UOB Card!

UOB Travel

Find out more



Volkswagen Scirocco

Price Range

Depreciation

2012

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Hanns Auto » Volkswagen Scirocco 1.4A TSI

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Trim your debts and enjoy
interest rate
from as low
as 4.70% p.a.
(EIR: 8.48% p.a.)
Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply.



Maybank

Compare

Volkswagen Scirocco 1.4A TSI

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$51,800**Depreciation** \$9,720 /yr

View models with similar depreciation

Reg Date 19-Jun-2012
(4yrs COE left)**Manufactured** 2012**Mileage** 43,754 km (7.3k /yr)**Transmission** Auto**Engine Cap** 1,390 cc**Road Tax** \$620 /yr**Power** 118.0 kW (158 bhp)
View specs of the Volkswagen Scirocco (2009-2017)**Curb Weight** 1,285 kg**Features** 1.4L Twin Charged TSI Engine Producing 158bhp, 7 Speed DSG With Paddle Shift, ABS, SRS Airbags, ESP, Side Mirror Indicators, Multi Function Steering.**Accessories** 18" Sports Rims, Factory Integrated Audio, Bluetooth, Multi Function Steering, 2 Tone Leather Seat, Auto Electric Folding Mirrors**Description** 1 Owner, Low Mileage Used, 1 Year Warranty Provided. Sporty Red With Original Paintwork. Stock Condition No Modification. Well Maintained By Previous Owner. Keyless Entry/ Keyless Start /Stop. Contact Us For Viewing.**COE** \$56,551**OMV** \$25,809**ARF** \$25,809**Dereg Value** \$40,702 as of today (change)**No. of Owners** 1**Type of Veh** Sports Car**Category** PARF Car, Low Mileage Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 13-Jun-2018 | Last Updated on: 18-Jun-2018

Tags: Volkswagen Scirocco, 2012 Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen

Upfront Payment

» more Financial info



Location Map



Price Analysis

Seller Information

Company	Hanns Auto
	• dealer's pricelist
	• 42 vehs sold 14 vehs available
Address	1 Commonwealth Lane #03-17
	Search cars nearby this location
Location	One Commonwealth
Office No	62712252
Contact Person(s)	Desmond Chan 91717808

Useful Services



VEHICLE INSPECTION

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Volkswagen Scirocco

Price Range

Depreciation

2012

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Creation Auto » Volkswagen Scirocco 1.4A TSI

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Trim your debts and enjoy
interest rate
from as low
as 4.70% p.a.
(EIR: 8.48% p.a.)
Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply.



Maybank

Compare

Volkswagen Scirocco 1.4A TSI

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$50,800

Depreciation \$9,780 /yr

View models with similar depreciation

Reg Date 26-Apr-2012
(3yrs 10mths 7days COE left)

Manufactured 2012

Mileage 55,888 km (9.1k /yr)

Transmission Auto

Engine Cap 1,390 cc

Road Tax \$620 /yr

Power 118.0 kW (158 bhp)
View specs of the Volkswagen Scirocco (2009-2017)

Curb Weight 1,285 kg

Features Volkswagen 1.4L Twin-charged Engine, 7 Speed DSG
Transmission, Dual Sport Seats, Multi Function
Steering, Dual Climate Control, ABS, SRS Airbags.Accessories Black Leather Interior, Sports Rims, Auto Lights, Sporty
Front Lip, Window Tints, Reverse Camera, Factory
Keyless Entry, Engine Start And Stop ButtonDescription Rare 2012 Keyless Option Dark Bronze Scirocco!
Genuinely Well Maintained By Previous Owner, Never
Been Modified Before! Comes With Bidded Number
Plate! High Trade-in, Minimum Down Payment And
Attractive Loan Packages Available. Call To Arrange For
Viewing And Test Drive Now!

COE \$58,501

OMV \$26,168

ARF \$26,168

Dereg Value \$39,560 as of today (charge)

No. of Owners 2

Type of Veh Sports Car

Category PARF Car, Low Mileage Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 07-Jun-2018 | Last Updated on: 16-Jun-2018

Tags: Volkswagen Scirocco, 2012 Volkswagen Scirocco, Volkswagen, Scirocco, Used
Volkswagen

Location Map



Price Analysis

Seller Information

Company

Creation Auto

* dealer's pricelist
* 22 vehs sold | 21 vehs available

Address

3 Ang Mo Kio Street 62 #01-12
Search cars nearby this location

Location

Link @ AMK

Contact Person(s)

Mr Kok	83233834
Mr Ho	82286226
Stanley Lee	93255355
Ms Tan	96428388

Useful Services

Afraid of lemons? Request to have
this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car.
Get a free Car Valuation.

Free Valuation

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2788F

Vehicle Details

Vehicle No.: SKF9658G
Vehicle to be Exported: No
Intended De-registration Date: 18 Jun 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour: White
Manufacturing Year: 2012
Engine No.: CAV419998
Chassis No.: WVVZZZ13ZCV038544
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$25,695.00
Original Registration Date: 23 Jul 2012
First Registration Date: 23 Jul 2012
Transfer Count: 0
Actual ARF Paid: \$25,695.00 12847

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Jul 2022
PARF Rebate Amount: \$17,986.00

Intended COE Rebate Details

COE Expiry Date: 22 Jul 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$59,004.00
COE Rebate Amount: \$24,156.00
Total Rebate Amount: \$42,142.00

The information contained herein is correct as at 18 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/06/2018 11:17
Date Of Accident	13/06/2018 05:15
Exact Location Of Accident	JUNCTION OF THOMSON ROAD & NEWTON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF9658G
Insured/Policyholder	
Name Of Registered Owner	KOH WEI LIANG
NRIC No	S8622788F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91388024
Alternative Phone No	OFFICE-91388024
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SCIROCCO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5081909850-01
Cover Note Number	
Driver	
Name of Driver	POON HENG PING, ELVIN
NRIC No	S9215124G
Date Of Birth	23/04/1992
Occupation	INDOOR
Date Of Driving Pass	22/11/2016
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91388024
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 417 EUNOS ROAD #04-08
Postcode	400417
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : JASON TEO GENDER: : MALE
Passenger 2	NAME: : ALLEN TEO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDP8832G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YAP SIEW WEE
NRIC/Passport Number	
Contact Number	93690010
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	POON HENG PING, ELVIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKF9658G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 417 EUNOS ROAD 5 #04-08
Postcode	400417

DETAILS OF INJURED PERSON 2

Name	PASSENGER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKF9658G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.


(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/06/2018 at about 17:15 Hrs, I was driving my vehicle (SKF96586) along the 3rd left lane of Thompson Road towards the direction of Newton Road.

While approaching the junction of the aforesaid road with Newton/Maulmein road, the driver of vehicle SDP8832G on my left suddenly cut across the double white line and made a sudden stop in front of my vehicle when she realised that the traffic light signal had changed from green to amber. Due to her stopping her vehicle abruptly, I was not given any reasonable opportunity to stop my vehicle safely, resulting the left portion of my vehicle had collided into the rear right portion of the vehicle.

I wish to emphasise that at the material time of the accident, left portion of the said vehicle SDP8832G was still on the 2nd left lane.

As a result of the accident, the front left portion of my vehicle was damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9748 9940 Fax: 6346 7213

Vehicle No: SKF9685G

Model: Volkswagen Scirocco

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Acknowledged by Repairer

Signature:

Date:

Prices \$

QTY

List Price:

1	Front Bumper	1409.06	DD/Tox	1,609.06	✓
2	Front Bumper Side Retainer		bet	74.52	✓
1	Front Bumper Reinforcement		bet	708.85	✓
1	Front Bumper Sponge	212.60	Tox	320.32	✓
2	Front Bumper Foglamp	112.9	M/S one	225.80	APC
2	Front Bumper Foglamp Cover	44.6	M/S good	89.20	WC
2	Front Bumper Signal Lamp		one	180.50	✓
1	Front Bumper Lower Grille		one	325.60	✓
1	Front Grille		one	586.45	✓
1	Front Support Panel	1004.32	one	1,340.90	✓
2	Headlamp		one	1,790.00	✓
2	Headlamp Top Panel	144.55	M/S two	289.10	PC
2	Headlamp Lower Bracket		11	60.52	X
1	Bonnet		DD/Suc	1,590.20	✓
1	Bonnet Emblem		one	129.30	✓
1	Bonnet Lock		two	172.90	✓
1	Bonnet Safety Striker		11	72.63	X
1	Bonnet Rubber Seal		11	49.68	X
2	Bonnet Hinge		one	180.40	X
1	Front LH Fender		11	652.80	X
1	Aircon Condenser		11	1,250.23	X
1	Radiator		11	1,865.08	X
1	Radiator Fan Assy		11	750.60	X
1	Intercooler		11	1,320.50	X

Less 10%

15635.14 9,615.53
Subtotal 8,653.98

14071.63

Special Nett Items

1 set	Front Bumper Clips
1 set	Front Grille Clips
1 set	Coolant

one 60.00 50
one 60.00 20
1 PC 80.00 50
Subtotal 200.00

Labour Charges:

Panel Beating On Affected Areas	1,500.00	700
Spray Painting On Affected Areas	1,000.00	750
Tuff kote	200.00	50
Remove & Refix Condenser & Top Up Gas	200.00	100
Remove & Refit Radiator & Top Up Coolant	200.00	50
Diagnostic Check & Clearing Off Fault Code	350.00	50
Wiring Check	100.00	20

Subtotal 3,550.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 12,403.98

17821.63

not allowed
date
18/6/18
d/s #75001
5 day
Take photo after repair

8487.35
10%
7638.61

9418.61
7542

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18010904/UVD3N2

Date: 21/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100367579
 Claimant Vehicle No : SKF9658G Insured Vehicle No : SDP8832G
 Date of Loss: 13/06/2018 Nature of Claim: TP Claim No: 5664793578SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF9658G Engine No: CAV419998
 Make & Model: VOLKSWAGEN SCIROCCO, 1.4 (A) Chassis No: WWWZZZ13ZCV038544
 Reg. Date: 23/07/2012 (Man. Year: 2012) Odometer: 141195 km
 Colour: White
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35ZR19 Rear Tyre Size: 235/35ZR19
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,271.63	7,758.61	6,513.02	45.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,670.00	1,880.00	52.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,821.63	9,428.61	8,393.02	47.09
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	17,821.63	7,500.00	10,321.63	57.92

INSPECTION

Date of Assignment: 14/06/2018

Date Inspected: 18/06/2018 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)
 25 Kaki Bukit Road 4, #01-49
 Synergy@KB
 Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Torn	1,609.06 FL	*1,409.06 FL
2	2		*FRONT BUMPER SIDE RETAINER	Bent	74.52 FL	*74.52 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	708.85 FL	*708.85 FL
4	1		*FRONT BUMPER SPONGE	Torn	320.32 FL	*212.60 FL
5	1		*FRONT BUMPER FOGLAMP	N/s Cracked	225.80 FL	*112.90 FL
6	1		*FRONT BUMPER FOGLAMP COVER	N/s Grazed	89.20 FL	*44.60 FL
7	2		*FRONT BUMPER SIGNAL LAMP	Cracked	180.50 FL	*180.50 FL
8	1		*FRONT BUMPER LOWER GRILLE	Grazed	325.60 FL	*325.60 FL
9	1		*FRONT SUPPORT PANEL	Cracked	1,340.90 FL	*1,005.32 FL
10	2		*HEADLAMP	Cracked	1,790.00 FL	*1,790.00 FL
11	1		*HEADLAMP TOP PANEL	N/s Twisted	289.10 FL	*144.55 FL
12	2		*HEADLAMP LOWER BRACKET	Not Necessary	60.52 FL	*- FL
13	1		*BONNET	Dented/Buckled	1,590.20 FL	*1,590.20 FL
14	1		*BONNET EMBLEM	Necessary	129.30 FL	*129.30 FL
15	1		*BONNET LOCK	Twisted	172.90 FL	*172.90 FL
16	1		*BONNET SAFETY STRIKER	Not Necessary	72.63 FL	*- FL
17	1		*BONNET RUBBER SEAL	Not Necessary	49.68 FL	*- FL
18	2		*BONNET HINGE	Serviceable	180.40 FL	*- FL
19	1		*FRONT LH FENDER	Repair	652.80 FL	*- FL
20	1		*AIRCON CONDENSER	Not Necessary	1,250.23 FL	*- FL
21	1		*RADIATOR	Not Necessary	1,865.08 FL	*- FL
22	1		*RADIATOR FAN ASSY	Not Necessary	750.60 FL	*- FL
23	1		*INTERCOOLER	Not Necessary	1,320.50 FL	*- FL
24	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
25	1		*SET FRONT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
26	1		*SET COOLANT	Necessary	80.00 FS	*50.00 FS
27	1		*FRONT GRILLE	Cracked	586.45 FL	*586.45 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,835.14	8,607.35
- List Item Discount on L Items 10.00/10.00% (S\$)	1,563.51	848.74
Total Parts (S\$)	14,271.63	7,758.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	750.00
3	TUFFKOTE	New	200.00	50.00
4	REMOVE & REFIX CONDENSER & TOP UP GAS }	New	200.00	100.00
5	REMOVE & REFIT RADIATOR & TOP UP COOLANT }	New	200.00	-
6	DIAGNOSTIC CHECK & CLEARING OFF FAULT CODE	New	350.00	50.00
7	WIRING CHECK	New	100.00	20.00
Gross Labour Cost (\$\$)			3,550.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >