

ASS. REC. BY:

REF:

CS3 / CT18010972 / U24b

Special Instruction:

SUNVAJOY

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time:

18062018 3:47pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGR 5231U

Insured:

SLB 647C

at Workshop m/s

Blumel Automotive

Tel:

6745 2088

of

Blk 1 Kaki Bukit Ave 6 #01-28

Policy No:

DMPCSN3051811700

Claim No:

SNM18D03000C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13062018

CA / REV / REP. / REV 24 HRS Wp:

06072018

H.O.D. Endorsement:

Date/Time:

18062018 4:53pm

Person Contacted:

Sally.

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

SGR 5231U - RCH / III 17021060 / Uj63

DLA: 020916

SLB 647C - NA / CT1 8010913 / h4

DLA: 130618

9/7/18

Dismantled.

11/7/18

After Repair

(08/11/13) wef

REF: CTI

ASS. REC. BY:

## ASSIGNMENT

From: Date: 6/7/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SQQ 5231 U  
at Workshop m/s Blumel Automotive  
of Blk 1, Kaki Bkt Ave 6 #01-28

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

4404A

Date: Person Contacted: 17/1/2022 Vehicle: IN / OUT

Veh No: 56452314 Yr Regn: 1 / 07

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 3 sp c.c. 1598

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 209758 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BK106270329990

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R:

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/6/18

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 6/7/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No repair @ 10am L1A 17835

3-4k.

24/7/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Lump Sum / I.B.I. (\$) )

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2018		18 Jun 2018 15:47 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:		MOHAMAD RAZALI BIN ABD MAJIB, ID: S1541856G							
Main Claimant:		MOHD ADIFF BIN JATFFAR, ID: S7814404A							
Vehicle Reg. No.:		SGQ5231U	Date of Loss:	13/06/2018 19:00 - :59					
Claim Type:		TP / SNM18D03000C02	Policy/Cover Note No.:	DMPCSN3051811700					
Vehicle Reg. No. (Insured):		SLQ647C	Policy No. (Claimant):	M495327					
		Excess:	S\$0.00						
Repairer:		Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Claimant's Insurer:		India International Insurance Pte Ltd (HQ) - Tel: 63476100							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/06/2018]							
Adj Asg. Remarks:		DEAR KAVLIN/MARCUS, PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Catherine Chong (LKK Auto)

---

**From:** Angie Foo <angie.foo@sg.cntaiping.com>  
**Sent:** Monday, 18 June, 2018 2:41 PM  
**To:** Serene Tan  
**Cc:** Irene Tay; Admin A; assignments@lkkauto.com; Catherine Chong (LKK Auto); 'SUR'  
**Subject:** RE: OUR REF: PRS/SNM18D03000C2/7 & YR REF:MN/IG/B1/1812483/ST -TO CONDUCT PRE-REPAIR SURVEY - SGQ 5231U  
**Attachments:** SNM18D03000C02 20180618 FR M NEDUMARAN -PRS LTR W TP SAS REPORT.pdf

Without Prejudice

Save As To Costs

Dear Serene,

We refer to your email on even date.

We are objecting to your list of surveyors and shall be appointing M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Calvin / Marcus,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Irene Tay 63896192

Thank you.

Best Regards,

**Angie Foo**

Claims Executive

Claims Department – Motor Division

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Serene Tan [mailto:serene.tan@mneduco.com.sg]

**Sent:** Monday, 18 June, 2018 1:58 PM

**To:** Angie Foo

**Cc:** Irene Tay

**Subject:** RE: OUR REF: PRS/SNM18D03000C2/7 & YR REF:MN/IG/B1/1812483/ST -TO CONDUCT PRE-REPAIR SURVEY - SGQ 5231U

Our Ref : MN.IG.B1.1812483.st

WITHOUT PREJUDICE

SAVE AS TO COSTS

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Hi Angie,

1. We refer to your email below.
2. We are instructed by **MOHD ADIFF BIN JATFFAR**, the claimant and/or **BLUWEL AUTOMOTIVE SERVICE PTE LTD**, the motor workshop for **SGQ 5231U** that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	<b>NICKY SEAH</b> (Absolute Appraisal Services)	6.	<b>ANDREW HOW</b> (Prominent Appraiser Services)
2.	<b>MICHAEL YAP TECK CHYE</b> (MC-COY Appraiser Pte Ltd)	7.	<b>LOI BOON JUAN</b> (PAR Automotive)
3.	<b>DIXON YEO</b> (Treasure Appraisal Services)	8.	<b>ANANDA KUMAR BISWAS S/O B N BISWAS</b> (United Appraisal & Management Pte Ltd)
4.	<b>LAWRENCE NG</b> (PRIORITY Services)	9.	<b>DENNIS YAP TECK WEE</b> (PAL's Appraiser Pte Ltd)
5.	<b>AMAS ONG</b> (AEON Auto Consultants LLP)	10.	<b>ANDY YAP TECK LEE</b> (LCW Appraiser Pte Ltd)

4. Please let us know within two (2) working days whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,

(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)

**M NEDUMARAN & CO**  
Advocates & Solicitors  
Commissioner for Oaths

**Branch Office:**

11 Sin Ming Road  
#B2-09 (Unit 2), Thomson V Two  
Singapore 575629  
Tel: 6509-8480 / 6509-8481  
Fax: 6509-8482

**Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)**

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

---

**From:** Angie Foo [<mailto:angie.foo@sg.cntaiping.com>]

**Sent:** Monday, June 18, 2018 1:26 PM

**To:** Serene Tan <[serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)>

**Cc:** Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>

**Subject:** OUR REF: PRS/SNM18D03000C2/7 & YR REF:MN/IG/B1/1812483/ST -TO CONDUCT PRE-REPAIR SURVEY - SGQ 5231U

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Serene,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
XING GUO QIANG
KALVIN ANG
MARCUS CHUA
SIMON HO
KENETH KONG
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

**REMARKS:**

Kindly take note, the claim handler on this case is Irene Tay 6389 6192

Thank you.

Best Regards,

**Angie Foo**

Claims Executive

Claims Department – Motor Division

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6186

Fax (65) 6224 7175 / 6224 7478

Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Serene Tan [<mailto:serene.tan@mneduco.com.sg>]

**Sent:** Monday, 18 June, 2018 10:19 AM

**To:** Claims Dept of CTI

**Subject:** PRE-REPAIR SURVEY - SGQ 5231U

**URGENT**

WITHOUT PREJUDICE

Our Ref: MN.IG.B1.1812483.st

Dear Sirs,

Notice of Accident dated **18/6/2018** attached herein.

Thanks & Best Regards,

(For and on behalf of Mr Nedumaran Muthukrishnan)

**Serene Tan (Ms)**

**M NEDUMARAN & CO**

Advocates & Solicitors

Commissioner for Oaths

**Branch Office:**

11 Sin Ming Road  
#B2-09 (Unit 2), Thomson V Two  
Singapore 575629  
Tel: 6509-8480 / 6509-8481  
Fax: 6509-8482

**Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)**

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 14/06/2018 14:21  
Date Of Accident 13/06/2018 19:15  
Exact Location Of Accident SLE(WOODLANDS)  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SGQ5231U  
**Insured/Policyholder**  
Name Of Registered Owner MOHD ADIFF BIN JATFFAR  
NRIC No S7814404A  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-98267366  
Alternative Phone No OFFICE-NOPHONE  
**Vehicle Particulars**  
Manufacturer MAZDA  
Model 3-1.5 (A)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR  
**Insurance Company**  
Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD  
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
Fleet Policy NO  
Policy Number  
Cover Note Number M495327  
**Driver**  
Name of Driver MOHD ADIFF BIN JATFFAR  
NRIC No S7814404A  
Date Of Birth 08/06/1978  
Occupation INDOOR  
Date Of Driving Pass 06/03/2002  
Driving Experience 16 YEARS AND 3 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-98267366  
Fax Number  
Contact Number OFFICE-NOPHONE  
Email Address NOEMAIL

Address APT BLK 369 WOODLANDS AVE 1 #03-861  
 Postcode 730369  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? YES  
 Foreign Vehicle Registration Number WPV4032 (PRIVATE CAR)  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name KIM KEAT NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 231 LORONG 8 TOA PAYOH , POSTCODE: 310231 ,  
 COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-2529999 - FAX NO: 63554311  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SLQ647C  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

## DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 14/6/18, 2:15pm

SIAT/MS SketchPlanForm\_V2

Driver's Signature

(If driver is not the policyholder)

Date & Time: 14/6/18, 2:15pm

Reporting Centre Personnel's Signature

Name:

NRIC/PAN No:



# SINGAPORE POLICE FORCE



T/20180614/2060

1 of 4

Police Station Of Origin:  
Kim Keat NPP  
231 Lorong 8 Toa Payoh #01-186  
SINGAPORE 310231  
Tel No: 1800-2529999

Report No. T/20180614/2060

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/06/2018 13:18		Vide Report No.:		Station Diary No.: 12	
Name of Informant: MOHAMMED ADIFF BIN JAFFAR		Address: APT BLK 369 WOODLANDS AVENUE 1 #03-861 SINGAPORE 730369			
ID Type / ID No.: NRIC NO / S7814404A		Contact No.: Home/Office:		Mobile: 98267366	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 40	Date of Birth: 08/06/1978	Type of Informant: Driver		
Race: Malay		Language: English		Institution / School Name:	
Occupation: ASSISTANT SUPERVISOR		Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 13/06/2018 19:15	Type of Location: Expressway
Location: Along Road 1 SELETAR EXPRESSWAY				
SLE (Woodlands) > 8km Before Sembawang Flyover				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Chain Collision				Anyone conveyed by ambulance: No

SGQ5231U	Car	MAZDA	MAZDA3 SP	Red	Slightly Damaged	0
SLQ647C	Car				Slightly Damaged	0
WPV4032	Car				Slightly Damaged	0



# SINGAPORE POLICE FORCE



T/20180614/2060

2 of 4

Police Station Of Origin:  
Kim Keat NPP  
231 Lorong 8 Toa Payoh #01-186  
SINGAPORE 310231  
Tel No: 1800-2529999

Report No. T/20180614/2060

## CONTINUATION OF REPORT

SGQ5231U	INDIA INTERNATIONAL INSURANCE PTE LTD	M495327	18/01/2018	17/01/2019
----------	--	---------	------------	------------

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	MOHAMMED ADIFF BIN JAFFAR	ID No.	S7814404A
Related Vehicle	SGQ5231U (Car)	Contact No.	98267366
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	Mohamad Shafiq Bin Mohamad Razali	ID No.	S9010200A
Related Vehicle	SLQ647C (Car)	Contact No.	98670711
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	Toh Andrew	ID No.	921026016817
Related Vehicle	WPV4032 (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20180614/2060

3 of 4

Report No. T/20180614/2060

Police Station Of Origin:  
Kim Keat NPP  
231 Lorong 8 Toa Payoh #01-186  
SINGAPORE 310231  
Tel No: 1800-2529999

**CONTINUATION OF REPORT**

**Brief Details.**

On 13/06/2018 at about 1914hrs, I was driving my Red-coloured Mazda3 bearing Regn No SGQ5231U, along SLE (Woodlands) on Lane 1. While on the 8km mark along SLE, before Sembawang Flyover, the traffic along Lane 1 was slowed down and stopped intermittently. As such, I had stopped before a vehicle, when another vehicle collided on to the rear of my vehicle, causing an impact.

I subsequently discovered that a Blue-coloured Toyota Harrier bearing Regn No SLQ647C had collided on to my vehicle from the rear, arising out of a chain collision involving a Malaysian-Registered vehicle bearing Regn No WPV4032. The Toyota Harrier was jolted to the front when it was hit from the rear by the Malaysian Vehicle.

My vehicle had since sustained damages on the rear bumper and the boot was unable to be opened. The rear bumper had sustained some dents as well. I have also exchanged particulars with the drivers of the Toyota Harrier and the Malaysian-registered vehicles respectively.

There were no injuries sustained at the incident location. I wish to state that I have In-Vehicle Video Recording System installed in my vehicle (Front & Back) and I am lodging this report for record and insurance purposes.



**SINGAPORE  
POLICE FORCE**



T/20180614/2060

4 of 4

Police Station Of Origin:  
Kim Keat NPP  
231 Lorong 8 Toa Payoh #01-186  
SINGAPORE 310231  
Tel No: 1800-2529999

Report No. T/20180614/2060

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 R RENGAMURTHI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI-ANG-YI-TING, STEPHANIE

Contact No: 60476414

POLICE FORCE

SN 064

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

14/06/2018 13:18

Classification Of Case:



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4404A
<b>Vehicle Details</b>	
Vehicle No.:	SGQ5231U
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SP
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	Z6516745
Chassis No.:	JM6BK106270329990
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$14,709.00
Original Registration Date:	18 Jan 2007
First Registration Date:	18 Jan 2007
Transfer Count:	1
Actual ARF Paid:	\$16,180.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,323.00
COE Rebate Amount:	\$17,835.00
<b>Total Rebate Amount:</b>	<b>\$17,835.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Jul 2018

OK



Mazda 3

Price Range ▼

Depreciation ▼

&gt; 10 year(: ▼

Vehicle Type ▼

Home » Used Cars » Hua Yang Credit Pte Ltd » Mazda 3 1.6A SP Luxury (COE till 02/2022)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Mazda 3 1.6A SP Luxury (COE till 02/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map



HUA YANG CREDIT PTE

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

## Car Details

Price	\$26,800	
Depreciation	\$7,360 /yr	?
Reg Date	28-Feb-2007 (3yrs 7mths 18days COE left)	
Manufactured	2007	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,598 cc	
Road Tax	\$816 /yr	?
Power	79.0 kW (105 bhp) View specs of the Mazda 3 Sedan (2004-2009)	
Curb Weight	1,235 kg	?
Features	Powered By 1.6L 4 Cylinder DOHC 16 Values Engine, 4 Speed Auto Transmission With Tiptronic, Knock Down Rear Seats, Immobilizer Remote Key, Airbags.	
Accessories	Original Leather Upholstery, Upgraded Sports Rim, Upgraded Mazda Touch Screen System, Reverse Sensors, Solar Film Etc.	
Description	New Paintwork! Very Well Taken Care Off! Owner's Reluctant Sale! 100% Finance Available, Lowest Interest Rates With Fast Approval! Same Day Delivery! New Road Tax, Inspection Cleared! 2 x Free In House	



Location Ma

## Car Rental

For Private & Commercial Vehicles  
Rental From  
\$50/Day

2ent



Compare

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2018		18 Jun 2018 15:47 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>MOHAMAD RAZALI BIN ABD MAJIB</b> , ID: S1541856G									
Main Claimant: <b>MOHD ADIFF BIN JATFFAR</b> , ID: S7814404A									
Vehicle Reg. No.: <b>SGQ5231U</b>		Date of Loss:	13/06/2018 19:00 - :59 [136 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>TP / SNM18D03000C02</b>		Policy/Cover Note No.:	DMPCSN3051811700						
Vehicle Reg. No. (Insured): <b>SLQ647C</b>		Policy No. (Claimant):	M495327						
		Excess:	S\$0.00						
Repairer: <b>Bluwel Automotive Service Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]									
Claimant's Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 27/06/2018]									
Adj Asg. Remarks: DEAR KAVLIN/MARCUS, PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGQ5231U (SNM18D03000C02)  
[SLQ647C]  
TP  
MOHD ADIFF BIN JATFFAR  
Jun 13 2018 7:00PM  
[MOHAMAD RAZALI BIN ABD MAJIB]  
Bluwel Automotive Service Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 14:47	Accident Statement	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 14:40	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	14/06/18 14:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	14/06/18 14:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	14/06/18 14:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	14/06/18 14:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	14/06/18 14:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	14/06/18 14:41	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	14/06/18 14:41	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	14/06/18 14:41	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/07/18 09:26	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	07/07/18 09:26	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/07/18 09:27	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
22	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/07/18 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/07/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/07/18 18:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/07/18 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
72	11/07/18 18:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	11/07/18 18:14	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
75	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
76	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
77	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
78	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
79	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
80	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
81	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
82	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
83	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
84	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	24/07/18 14:05	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/06/18 15:49	THIRD PARTY SGQ5231U -PRS EMAIL BTE CIC AND M NEDUMARAN	Load PDF	
2	18/06/18 15:49	THIRD PARTY SGQ5231U -FROM M NEDUMARAN - PRS LTR W SAS REPORT	Load PDF	
3	18/06/18 15:49	INSURED SAS REPORT SLQ647C	Load PDF	
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 14:35	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 14:47	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	14/06/18 14:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	14/06/18 14:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	14/06/18 14:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	14/06/18 14:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	14/06/18 14:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	14/06/18 14:41	Police Report	Load JPG	<input checked="" type="checkbox"/>
8	14/06/18 14:41	Police Report	Load JPG	<input checked="" type="checkbox"/>
9	14/06/18 14:41	Police Report	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ryder Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 14:35	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118010972/UZ4BE2

Date: 25/07/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3051811700

Claimant Vehicle  
No : SGQ5231UInsured Vehicle  
No : SLQ647C

Date of Loss: 13/06/2018

Nature of Claim: TP

Claim  
No: SNM18D03000C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGQ5231U

Make &amp; Model: MAZDA 3, 1.5 (A)

Reg. Date: 18/01/2007 (Man. Year: 2006)

Colour: Red

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: Z6516745

Chassis No: JM6BK106270329990

Odometer: 209758 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 18/06/2018

Date Inspected: 06/07/2018 Inspected At:

 Bluwel Automotive Service Pte Ltd (HQ)  
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
 Autobay@Kaki Bukit  
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 25 Jul 2018)

**Parts:** 144      MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGQ5231U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >