

A.C.S. REC. BY:

REF: CS/GAL18010984/Ksbnz Special Instruction:

SUBV./OY

ASSIGNMENT (Office)

From (Person): Rachel Tan of GAL Date/Time: 18062018 1:50pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 913G Insured: YP 4105A

at Workshop m/s Alan's United Tel: 6453 8686

of 31k 7 Sin Ming Ind Est #01-76

Policy No: Claim No: CLMOMVC000003305

Sum Insured: Excess:

Make of Veh: D.O.A. 13062018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 18062018 2:14pm Person Contacted: Kenny Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBB 913G - CS/GAL18010984/Mig2n3g2 DCA: 260613
	YP 4105A - NA/GAL18010984/24 DCA: 130618
26/06/18 @ 14:41 p.m.	revised PA to Rachel via email.
6/7/18 @ 4:55 p.m.	Confirm

ASS. REC. BY:

REF:

G821

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G8B 913G

Yr Regn:

07.08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S Cgbsr

c.c

295.3

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

400457

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1SC2F2470800497

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: B.S

195R15X8

R: Yoko

155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

44

mm

L/Bal.

8

mm

L/Bal.

44

mm

D.O.A.

13/6/18

D.O.I.

25/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/6

File sent to Customer

(82.675.54 Rd - 36%)

RECEIVED 10 JUL 2018

Date/Time, File Pass to?

10/07/18



: Prel. Report

1)

Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trlp:

1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

4,650.00 H/s

TOTAL

250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 26 June 2018

Our Ref: CS/GAI18010984/Ksb

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. GBB 913G .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/06/2018 at the premises of M/s Alan's United Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,325.54</u> .
Revised Estimate Amount	: S\$ <u>5,839.04</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 27 June 2018 8:55 AM
To: Shirley Hiew (LKK Auto)
Subject: RE: RE: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)

CLMOMVC000003305

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, June 26, 2018 2:41 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: sur@lkkauto.com; 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; 'LKK Assignments' <assignments@lkkauto.com>
Subject: [External] RE: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)

Dear Rachel,

Enclosed herewith preliminary advice of GBB 913G.

Kindly provide us the claim reference no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 18 June 2018 2:16 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'LKK Assignments' <assignments@lkkauto.com>
Cc: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; sur@lkkauto.com
Subject: RE: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)

Dear Rachel,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Monday, 18 June, 2018 1:50 PM
To: LKK Assignments <assignments@lkkauto.com>

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 26 June 2018 2:41 PM
To: 'Ngian, Kelvyna'; 'Tan, Rachel'
Cc: sur@lkkauto.com; 'Catherine Chong (LKK Auto)'; 'LKK Assignments'
Subject: RE: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)
Attachments: GBB 913G - Preli Advise.pdf

Dear Rachel,

Enclosed herewith preliminary advice of GBB 913G.

Kindly provide us the claim reference no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 18 June 2018 2:16 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'LKK Assignments' <assignments@lkkauto.com>
Cc: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; sur@lkkauto.com
Subject: RE: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)

Dear Rachel,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]
Sent: Monday, 18 June, 2018 1:50 PM
To: LKK Assignments <assignments@lkkauto.com>
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: FW: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)

Without prejudice

Dear Kenny

We will arrange for LKK to conduct PRI on a without prejudice basis.

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Monday, 18 June, 2018 1:50 PM
To: LKK Assignments
Cc: Ngian, Kelvyna
Subject: FW: RE: PRI - GBB913G v YP4105A (GA) (DOA 13.6.18)
Attachments: SKM_284e18061809250.pdf

Without prejudice

Dear Kenny

We will arrange for LKK to conduct PRI on a without prejudice basis.
Kelvyna will assist on liability.

Dear Kelvyna
Please assist, thank you.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: kennychan@alanutd.com <kennychan@alanutd.com>
Sent: Monday, June 18, 2018 12:55 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: admin-a@lkkauto.com
Subject: [External] RE: PRI - GBB913G v YP4105A (DOA 13.6.18)

Dear Rachel

Thank you for sending us SJE , we have decided to let LKK Auto Consultants Pte Ltd to conduct the pre repair survey .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Monday, June 18, 2018 11:40 AM
To: kennychan@alanutd.com
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: PRI - GBB913G v YP4105A (DOA 13.6.18)

Without Prejudice

Dear Kenny

GA Veh reference: YP4105A

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Ng, Sharon
Sent: Monday, June 18, 2018 10:22 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; kennychan@alanutd.com
Subject: FW: [External] ATTACHED GBB913G REPAIR ESTIMATE , GIA REPORT TO REQUEST JOINT EXPERT SURVEYOR LIST FOR T.P. PRE SURVEY

Hi Rachel- FYA

From: kennychan@alanutd.com <kennychan@alanutd.com>
Sent: Monday, June 18, 2018 9:28 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: [External] ATTACHED GBB913G REPAIR ESTIMATE , GIA REPORT TO REQUEST JOINT EXPERT SURVEYOR LIST FOR T.P. PRE SURVEY

Dear Motor Claims Dept.

Morning , attached our client vehicle GBB913G repair estimate , GIA report to request joint expert survey list for us to choose surveyor to conduct pre repair survey , meant time kindly check the liability to go for direct settle thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Transaction ref 20180413083005072613

The owner and vehicle particulars for Vehicle No. GBB913G as at 13 Apr 2018 are as follows:

1.	Name	: QUANFENG ENGINEERING CONTRACTOR PTE LTD
2.	Identification No. Type	: Company
3.	Identification No.	: 201500909K
4.	Country/Region	: -
5.	Vehicle No.	: GBB913G
6.	Previous Vehicle No.	: -
7.	Effective Date of Ownership	: 13 Apr 2018
8.	Original Registration Date	: 12 Jul 2008
9.	First Registration Date	: 12 Jul 2008
10.	Vehicle Type	: B31 - Goods (Open) Lorry (Metal Body)/Pickup
11.	Vehicle Scheme	: Normal
12.	Attachment 1	: With Hood
13.	Attachment 2	: -
14.	Attachment 3	: -
15.	Vehicle Make	: NISSAN
16.	Vehicle Model	: CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
17.	Year of Manufacture	: 2008
18.	Primary Colour	: White
19.	Secondary Colour	: -
20.	Passenger Capacity	: 2
21.	Chassis/Trailer Chassis No.	: JN1SC2F24Z0800497 / -
22.	Propellant	: Diesel
23.	Engine No./Motor No.	: ZD30187007K / -
24.	Engine Capacity(cc)/Power Rating(kW)	: 2953 / -
26.	Unladen Weight(kg)	: 1800
27.	Maximum Laden Weight(kg)	: 3400
28.	Open Market Value	: \$23,905.00
29.	PARF Eligibility	: No
30.	PARF Eligibility Expiry Date	: -
31.	Minimum PARF Benefit	: \$0.00
32.	No. of Transfers	: 2
33.	IU Label No.	: 1042309848
34.	COE No.	: 2008050107001734E
35.	COE Expiry Date	: 11 Jul 2018
36.	COE Category	: E - Open Category
37.	Quota Premium/Prevailing Quota Premium	: \$18,151.00 / -
38.	Actual Quota Premium/PQP Paid	: \$18,451.00
39.	Actual ARF Paid	: \$1,196.00
40.	CO2 Emission(g/km)	: -
41.	CO Emission(g/km)	: -
42.	HC Emission(g/km)	: -
43.	NOx Emission(g/km)	: -
44.	PM Emission(mg/km)	: -
45.	Actual CEVS/VES Rebate Utilised	: -
46.	CEVS/VES Surcharge Paid	: -
47.	Actual Green Vehicle Rebate Utilised	: -
48.	Vehicle Lifespan Expiry Date	: 11 Jul 2028
49.	Road Tax Amount	: -
50.	Road Tax Start Date	: -

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/06/2018 17:02
 Date Of Accident 13/06/2018 06:30
 Exact Location Of Accident JUNCTION OF EUNOS LINK AND BEDOK RESERVOIR ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBB913G
Insured/Policyholder
 Name Of Registered Owner QUANFENG ENGINEERING CONTRACTOR PTE LTD
 Co Reg No 201500909K
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-91195098
 Alternative Phone No OFFICE-91195098

Vehicle Particulars

Manufacturer NISSAN
 Model CABSTAR-3.0 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 COMMERCIAL VEHICLE

Vehicle Category

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy NO
 Policy Number 5099933806
 Cover Note Number

Driver

Name of Driver SUNDARAMOORTHY JAYARAJ
 Passport No/FIN G2251912W
 Date Of Birth 16/05/1992
 Occupation OUTDOOR
 Date Of Driving Pass 21/11/2016
 Driving Experience 1 YEAR AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-84393029
 Fax Number
 Contact Number
 Email Address YITING@QUANFENG.COM.SG

Address 30 SHAW ROAD #07-01
ROCHE BUILDING
Postcode 367957

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-

Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP4105A
Vehicle Make/Model/Colour MITSUBISHI FUSO
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver THIRUGNANAM BABU
NRIC/Passport Number G7104510U
Contact Number 98901460
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SUNDARA MOORTHY JAYARAJ

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

FOREHEAD SWOLLEN

GBB913G

YES

NO

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 5/12/17


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 14/6/18 E
10.40 AM

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE 13-6-2018 AT ABOUT 6.30 AM, I WAS DRIVING ALONG ABOVE MENTION RD AND STOP AT THE TRAFFIC LIGHT JUNCTION DUE TO RED LIGHT, WHILE WAITING SUDDENLY I FELT A IMPACT FROM THE REAR OF MY VEHICLE AND THE STRONG IMPACT PUSH MY VEHICLE OUT TO THE STOP LINE, ONCE THE VEHICLE HAD STOP BY THE IMPACT, I QUICKLY pull my HANDBRACE AND CAME OUT TO CHECK. REALISED THAT VEHICLE YP 4105A WAS HIT ONTO THE REAR OF MY VEHICLE, ACCORDING TO THE DRIVER SAY HE COULD NOT STOP IN TIME AND CAUSE THE ACCIDENT, WE EXCHANGE PARTICULAR FOR INSURANCE CLAIM, MY FORE HAND FELT PAIN NEED TO SEE DOCTOR, DUE TO THE BOX WAS UP RIGHT TOP DROP DOWN WHEN THE IMPACT OCCURRED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



S. Jayaraj
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Phuman
Reporting Centre Personnel's Signature
Name: *14/6/18 @*
NRIC/FIN No.: *10.40 AM*

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5099933806

Cover : Third Party

- | | |
|---|---|
| 1. Index mark and Registration Number of Vehicle | : GBB913G |
| Chassis Number | : JN1SC2F24Z0800497 |
| 2. Name of Policyholder | : QUANFENG ENGINEERING CONTRACTOR PTE LTD |
| 3. Effective Date of Insurance | : 16 Apr 2018 |
| 4. Expiry Date of Insurance | : 15 Apr 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : KINETIC INSURANCE AGENCY (00000573090)

Date of Issue : 16 Apr 2018 08:58 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05796

Vehicle Insured : YP4105A
Accident Date : 13-Jun-2018

Date : 16-Jun-2018

Our Ref : 218101 (GREAT AMER) / CHAN

PAGE : 1

QUANFENG ENGINEERING CONTRACTOR PTE LTD
30 SHAW ROAD
#07-01 ROCHE BUILDING
Singapore 367957

*Not Authorised
C/Lm & ?
Resurvey After Paint
6 days*

ESTIMATED COST OF REPAIR FOR NISSAN CABSTAR GBB913G

1 pc N/s side gate *2915.10*
1 pc Tail gate *1519.*
1 pc N/s tail gate lock hook
1 pc N/s tail gate open handle
1 pc Rear end panel
1 pc N/s taillamp *247.50*
1 pc N/s taillamp bracket

BT/BN
2,600.60 n ✓
As 1,399.70 n ✓
Dis 33.30 n ✓
As 163.40 n ✓
n 450.00 n x
cm 268.60 n ✓
n 35.00 n x

4,950.60

Less 10% : 495.06

1 pc Rear n/s step bar
1 pc Tail gate 70km/h sticker
1 pc Tail gate 13pax sticker
1 pc Tail gate company sticker
1 pc N/s side gate company sticker
1 pc Rear bumper reverse sensor(set)

As 4,455.54
n 120.00 sn ✓
n 15.00 sn ✓
n 15.00 sn ✓
n 120.00 180.00 sn
n 150.00 240.00 sn
n 300.00 sn x

To putty and spray replaced parts

600l 800.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800l 1,200.00

Total : S\$ 7,325.54

Singapore Dollars Seven Thousand Three Hundred
and Twenty Five and Cents Fifty Four Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18010984/Ksbn2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 11-07-2018		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 4105A	Veh. Inspected	GBB 913G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003305	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	18/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1SC2F24Z0800497	Colour	WHITE	
Odometer	400457	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	4/4 mm	
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2018	Inspection Date	25/06/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 913G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	N/S SIDE GATE (N)	BENT / BUCKLED	2,600.60	2,600.60
1	TAIL GATE (N)	BENT	1,399.70	1,399.70
1	N/S TAIL GATE LOCK HOOK (N)	DISTORTED	33.30	33.30
1	N/S TAIL GATE OPEN HANDLE (N)	BENT	163.40	163.40
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	450.00	-
1	N/S TAILLAMP (N)	CRACKED	268.60	247.50
1	N/S TAILLAMP BRACKET (N)	TO REPAIR SEE LABOUR	35.00	-
	LESS 10% DISCOUNT		-495.06	-444.45
			4,455.54	4,000.05
<u>SPECIAL NETT ITEMS</u>				
1	REAR N/S STEP BAR (SN)	BENT	120.00	120.00
1	TAIL GATE 70KM/H STICKER (SN)	NECESSARY	15.00	15.00
1	TAIL GATE 13PAX STICKER (SN)	NECESSARY	15.00	15.00
1	TAIL GATE COMPANY STICKER (SN)	NECESSARY	180.00	120.00
1	N/S SIDE GATE COMPANY STICKER (SN)	NECESSARY	240.00	150.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
			870.00	420.00
<u>LABOUR</u>				
	TO PUTTY AND SPRAY REPLACED PARTS.		800.00	600.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND N/S TAILLAMP BRACKET.		1,200.00	800.00
			2,000.00	1,400.00
GRAND TOTAL			7,325.54	5,820.05

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,650.00
---	--	--	-----------------

Report Ref No. CS/GAI18010984/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.