

ASS. REC. BY:

REF: CS/ASM18 011052/Tq d322

Special Instruction:

Surveyor

Tqufikh

ASSIGNMENT (Office)

From (Person):

Yvonne Ang

of

ASM (AXA)

Date/Time:

16/06/2018

Estimated Cost:

Bill to:

☒ OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 53664

Insured:

at Workshop m/s

A.S. phoon

Tel:

65150770

of

Blk 36, Joh Guan Rd East # 01-35

Policy No:

Claim No:

S8M00B92

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A. 20/03/2018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:08am @ 19/6/18

Person Contacted:

Mr. Kee

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

pls check Reason letter Submission

OD claim.

FBM 53664-X

75/6/18 @ 2:11pm revert to Yvonne Ang via Smart Claim.

75/6/18 @ 5:43pm Yvonne Ang informed C/A via Smart Claim.

76/6/18 @ 1:37pm Informed Kee C/A to ex: \$500 by email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop n/a
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **1500**
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: **413K**
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: **5** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA ☒ REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: **FBM 5366U** 11 Regn: **2017 Dec**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer n/a
 Make: **Honda CR50** CC: **149**
 Colour: **Red** A/C Insured / Std / NI / NA
 Sp Reading: **4112** TiRadio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MLH15C-2881 55007272**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: ☒ N / S/Rim / STD A/Rim or
 Tyre Size F: **110/70 R17**
 R: **150/60 R17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A. _____ D.O.I. **24/6/18**
 Survey held at: **AS Phnom**
 Des. of Damages: ☒ FA ☒ Rear ☒ O/S ☒ N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

25072.10 5 days finish with Mr Kee
CRD & 1794.10, 26/10

RECEIVED 05 NOV 2018

Date/Time: File Pass to?

05/11 14:12

Date/Time: File Return to?

☐ Prel. Report
☐ Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

TOTAL:

Add Fee:

☐ Site Insp. 1\$
☐ Interview 1\$
☐ Traffic Jams 1\$
☐ Workshop 1\$

Report Format:

Lump Sum / A.B.H. 1\$

Smart Claim
507290

200

200



Service Request Details

Claim

S8M00B92

Reference

None 

LKK AUTO CONSULTANTS PTE LTD (OD) ▼

Loss Date

March 20, 2018

Request Date

June 16, 2018

Due Date

June 22, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBM5366U

Make

HONDA CB150R MANUAL

SERVICE ADDRESS

...

Primary Contact/Insured

SOH BOON KEONG
629 YISHUN STREET 61, #10-03, 760629, Singapore

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 500 PLEASE CHECK REASON LATE SUBMISSION OD CLAIM

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

KADRI Mateen

From: CST <cst@axa.com.sg>
Sent: Thursday, June 14, 2018 2:02 PM
To: kee@asphoon.com; SG AXA Insurance SM AXA SGP - Motor Survey
Subject: RE: OD CLAIM FBM5366U & SFT5516U ON 20/03/2018 / P2055400
Attachments: Accident Report_FBM5366U.pdf; FBM5366U REPAIR LIST.pdf

Categories: MATEEN

Dear Sir/Madam,

Thank you for contacting AXA Insurance.

We will forward the attached repair estimate and accident report to the relevant team for filing and registration.

We have copied them in the email to be notified and for their necessary action.

Best Regards,

Jessebel Perez
Specialist, GI Call Centre

AXA Insurance Pte Ltd
8 Shenton Way #24-01 AXA Tower, Singapore 068811
customer.care@axa.com.sg
Tel: 1800-880-4888 (Within Singapore) / (65) 68804888 (International)
Fax: (65) 6880 4283
Website: www.axa.com.sg

----- Original Message -----

From: kee@asphoon.com
Sent: 14/06/2018
To: cst@axa.com.sg
Subject: OD CLAIM FBM5366U & SFT5516U ON 20/03/2018

Dear OIC ,

FYA .

RE : OD CLAIM (FBM5366U)

- We are appointed repairers
for
bike number FBM5366U
by
Mr SOH BOON KEONG

- We are helping Mr Soh Boon Keong to do an OD claim.
- Kindly set for an appointment date for your surveyor to survey the
above mentioned bike at our Toh Guan branch .
- We will submit repair list with price to AXA soonest .

Thank you and have a nice day **

Sincerely,

Kee Ger Ong
Motor Claim Dept

A.S.Phoon Pte Ltd

Blk 36 Toh Guan Road East

Enterprise Hub # 01-35

Singapore 608580

T : 6515 0770

F : 6515 0779

E : kee@asphoon.com

W : www.asphoon.com

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Should you require further assistance, please contact us at 1800 880 4888.

Best Regards,

Jessebel Perez
Specialist, GI Call Centre

AXA Insurance Pte Ltd
8 Shenton Way #24-01 AXA Tower, Singapore 068811
customer.care@axa.com.sg
Tel: 1800-880-4888 (Within Singapore) / (65) 68804888 (International)
Fax: (65) 6880 4283

Website: www.axa.com.sg



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

ref:_00Db0Ky1f_5006FlwPtO:ref

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 26 June 2018 1:37 PM
To: kee kee
Cc: SUR
Subject: MOTORBIKE FBM 5366U (DOA: 20/03/2018)

Dear Mr Kee,

As instructed by our client AXA Insurance, please proceed to repair the insured motorbike **FBM 5366U (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Authorized

Type

🔔 Question

Message

Please proceed to authorize repair

Reply

⏪ IA OF MOTORBIKE FBM 5366U UPLOADED.

Type

🔗 Question

Message

Dear Yvonne, please be informed that the IA of motorbike FBM 5366U uploaded. According to the repairer, the reason late submission OD claim is due to the insured hospitalized after accident. - Shiau Chan

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE L, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/06/18

Survey Details:

Date of loss	20-Mar-18
Date of appointment	16-Jun-18
Date of survey	20-Jun-18
Location of survey	A. S. PHOON

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	FBM 5366U
Make and Model	HONDA CB150R MANUAL
Date of registration	12/12/2017
Excess	\$ 500.00
Market Value	\$ 13,000.00
Part Rebate	\$ 5,211.00
Nett Loss	\$ 7,789.00

Repair details:

Initial Estimate	\$ 6,782.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,394.00
Check items (estimate)	\$ 2,503.00
Labour	\$ 590.00
Total	\$ 6,487.00
Lump Sum(if applicable)	\$

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR. ACCORDING TO THE REPAIRER, THE REASON LATE SUBMISSION OD CLAIM IS DUE TO THE INSURED HOSPITALIZED AFTER ACCIDENT.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3098I
Vehicle Details	
Vehicle No.:	FBM5366U
Vehicle to be Exported:	No
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CB150R MANUAL
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	KC32E0007272
Chassis No.:	MLHKC2881J5007272
Maximum Power Output:	-
Open Market Value:	\$3,957.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$594.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,502.00
COE Rebate Amount:	\$5,211.00
Total Rebate Amount:	\$5,211.00

The information contained herein is correct as at 21 Jun 2018

OK

Transfer Fee Enquiry

Page 1 of 1

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	FBMS366U		
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	HONDA		
Vehicle Model:	CB150R MANUAL		
Chassis No.:	MUHKC2881J5007272		
Propellant:	Petrol		
Engine No.:	KC3E0007272		
Engine Capacity:	149 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	253 kg		
Unladen Weight:	123 kg		
Year Of Manufacture:	2017		
Original Registration Date:	12 Dec 2017		
Lifespan/Expiry Date:	-		
COE Category:	D - Motorcycle		
Quota Premium:	\$5,502.00		
COE Expiry Date:	11 Dec 2027		
Road Tax Expiry Date:	11 Jun 2018		
Inspection Due Date:	11 Dec 2020		
Intended Transfer Date:	01 Jun 2018		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 11 Jun 2018. You may renew the road tax from 12 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 11 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 12 Jun 2018 to 11 Dec 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	32.00	-	32.00
Total Amount Payable:			57.00
Amount Payable (From 12 Jun 2018 to 11 Jun 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	64.00	-	64.00
Total Amount Payable:			89.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 31/05/2018 09:54
 Date Of Accident 20/03/2018 08:10
 Exact Location Of Accident MARYMOUNT ROAD BEF BISHAN ST 22 BEF BUS STOP 53169
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBM5366U
Insured/Policyholder
 Name Of Registered Owner SOH BOON KEONG
 NRIC No S9133098I
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-98572816
 Alternative Phone No HOME-98572816

Vehicle Particulars

Manufacturer HONDA
 Model CB150R MANUAL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number AN3161301
 Cover Note Number

Driver

Name of Driver SOH BOON KEONG
 NRIC No S9133098I
 Date Of Birth 18/09/1991
 Occupation INDOOR
 Date Of Driving Pass 26/10/2017
 Driving Experience 0 YEAR AND 4 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-98572816
 Fax Number
 Contact Number HOME-98572816
 EMail Address NOEMAIL

Address APT BLK 629 YISHUN STREET 61 #10-03 SINGAPORE
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name 10 UBI AVENUE 3
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFT5516U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SOH BOON KEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBM5366U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01 AXA Tower
Singapore 068811
Customer Service Centre 881-01
Tel: 6336 7289 Fax: 6336 3322
Website: www.axa.com.sg
GST Registration Number: 199903912M



Original

File No: 03375
Policy No (if any):
New Business
SmartDrive Quote Ref:

MOTOR COVER NOTENo. **AN3161301 ()**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) – Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

NR-SIM YEE KENG

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	SON BOON KEONG
MAKE AND DESCRIPTION OF VEHICLE	HONDA CB150R MANUAL
VEHICLE REGISTRATION NO.	FBMS366U
YEAR OF MANUFACTURE	2017
ENGINE NO.	KC32E0007272
CHASSIS NO.	MLHKC288175007272
ENGINE CAPACITY/TONNAGE	149
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	N/A
VALUE (\$)	MARKET VALUE
PERIOD OF INSURANCE	FROM: 16-Dec-2017 TO: 15-Dec-2018
EXCESS (\$)	500
AXA PREMIUM WORKSHOP?	No

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Issued by AXA INSURANCE AGENCIES P.L. on

13-Dec-2017 10:31:32 AM

Authorised Signature

Note: This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

<http://www.axa.com.sg/MOTOR/AXA.asp>

12/13/2017



redefining insurance

Date: 31/05/2018

To: Owner of Vehicle Number: FRM 53664

The following has been advised to you via your workshop, REPORTING OFFICE ETHAZ PROTECT through their staff, HASBULLAH

Please tick the applicable box if you had been advice on the content as seen below:

- ? ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence. *(TAKE NOTE) I was not inform of such clause by the workshop*
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☒ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☒ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☒ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☒ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others _____

Signed and acknowledge by:

Name and signature of policyholder/authorised driver

Hasbullah

Hasbullah



Name and signature of workshop personnel including company stamp

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S91330981



SOH BOON KEONG
(SU WENQIANG)
苏文强

Chinese
Date of birth: 18-09-1991
Sex: M
Country of birth: SINGAPORE

Signature: 

Valid till: 18-09-2015

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S91330981

SOH BOON KEONG
(SU WENQIANG)

Issued Date: 18 Sep 1991
Valid till: 18 Jun 2015

Signature: 

Barcode: 002438911X

4719003

Barcode: 002438911X

Identity Card No. S91330981



Date of issue: 09-04-2011

Address:
APT BLK 629 YISHUN STREET 61
#10-03
SINGAPORE 760629

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE:
18 Oct 2011
11 Dec 2015

Motorcycle up to 250 cc
Motor car up to 3500 cc with up to 7 passengers, excluding of the driver, and engine displacement up to 2000 cc

Class 2B
Class 3


S / No. 9000274922

Signature: 

Barcode: 002438911X

NP 426A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO SKETCH PLAN

Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.	☐	- Reporting Only
	☐	- Claim OD
	☐	- Claim TP
	☒	- Claim <u>OD</u> TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time
31 MAY 2018 10:53

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:
 31 MAY 2015 10:13

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 KHC/TRE H:



**SINGAPORE
POLICE FORCE**



T/20180328/7016

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180328/7016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2018 20:39	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars

Name of Informant: SOH BOON KEONG			Address: APT BLK 629 YISHUN STREET 61 #10-03 SINGAPORE 760629		
ID Type / ID No.: NRIC NO / S91330981			Contact No.: Home/Office: Mobile: 98572816		
Nationality: SINGAPORE CITIZEN			Email: sohbk8@hotmail.com		
Sex: Male	Age: 26	Date of Birth: 18/09/1991	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Systems designer/analyst			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/03/2018 08:11	Type of Location: Straight Road
Location: MARYMOUNT ROAD before bishan street 22 before busstop 53169				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Colour	Condition	No. of Passengers
FBM5386U	Motorcycle	HONDA	CB150R	Red		0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180328/7016

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180328/7016

CONTINUATION OF REPORT

Folder			
Name	SOH BOON KEONG	ID No.	S9133098I
Related Vehicle	FBM5366U (Motorcycle)	Contact No.	98572816
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	20/03/2018	Date Discharge	26/03/2018
No. of Days granted Medical Leave	14	Degree of Injury	Serious

Brief Details.

At around 8.11am on 20 march 2018, I soh boon keong S9133098I was riding my motorcycle FBM5366U. Along marymount road towards thomson road to head for my work. I was on the extreme right lane (1st lane). I slowed down my vehicle as a van signaled right from the 2nd lane. Upon seeing the vehicle made the lane change with plenty of road space ahead. I wanted to change to the 2nd lane and maintain on the left side within my lane. Upon spotting a opening on my left, I signaled left and checked my left blind spot. When I completed my blindspot check I see the van stopped in front of me. The next moment, I flew from my motorcycle and rolled on to the 2nd lane.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180328/7016

3 of 3

Report No. T/20180328/7016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
NOR FAIZAL BIN YAHYA
Contact No.: 65476202

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
28/03/2018 20:39

Classification Of Case:



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM5366U HONDA CB150R REPAIR ESTIMATE (14/06/2018)

ITEM	DESCRIPTION	AMOUNT SGD
1	FRONT FENDER	car ✓ \$105.00
2	FRONT FORK ASSY RH & LH @\$715	ht ✓ \$1,430.00
3	STEM STERRING	ht ✓ \$225.00
4	CONE BEARING SET	new ? \$60.00
5	FRONT LICENCE PLATE	mis ✓ \$12.00
6	HEADLAMP ASSY	cut ✓ \$535.00
7	HEADLAMP COVER OUTER -(BLACK)	cut ✓ \$42.00
8	METER ASSY	cut ✓ \$495.00
9	STAY . METER	ht ✓ \$48.00
10	FRONT SIGNAL LH	dis ✓ \$75.00
11	STAY. FRONT SIGNAL LH	ht ✓ \$14.00
12	CLUTCH LEVER	cut ✓ \$24.00
13	IU UNIT	cut ✓ \$160.00
14	IU BRACKET	bl ✓ \$40.00
15	SIDE MIRRORS RH & LH @\$68	cut ✓ \$136.00
16	HANDLEBAR	bl ✓ \$110.00
17	HANDLE END X2	mis ✓ \$28.00
18	FUEL TANK COVER LH (RED)	cut ✓ \$120.00
19	FUEL TANK COVER INNER LH (BLACK)	nn ✗ \$70.00
20	REAR TOP BOX	cut ✓ \$280.00
21	TOP BOX BRACKET	cut ✓ \$160.00
22	REAR SIGNAL LH	cut ✓ \$75.00
23	REAR LICENCE PLATE	bl ✓ \$18.00
24	STAY. REAR LICENCE PLATE	cut ✓ \$38.00
25	BRACKET REAR LICENCE PLATE	cut ✓ \$85.00
26	REAR FAIRING RH	cut ✓ \$65.00
27	FUEL TANK COVER RH	cut ✓ \$120.00
28	RADIATOR	ny ✗ \$300.00
29	COOLANT	ny ✗ \$50.00
30	AIR GUARD OUTER RH	cut ✓ \$58.00
31	AIR GUARD INNER RH	cut ✓ \$65.00
32	EMBLEM X1	res ✓ \$15.00
33	ENGINEGUARD	nn ✗ \$280.00
34	BRAKE PEDAL	bl ✓ \$45.00
35	FRONT FOOTREST ASSY RH	bns ✓ \$65.00
36	HOLDER. FRONT FOOTREST RH	bl ✓ \$30.00
37	FRONT FOOTREST BRACKET RH	ht ✓ \$5.00
38	REAR LICENCE PLATE LIGHT	ny ✗ \$55.00
39	TAILLAMP COVER	ny ✗ \$265.00
40	EMBLEM X1	ny ✗ \$8.00
41	TAILLAMP BRACKET	cut ✓ \$85.00



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580. Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM5366U HONDA CB150R REPAIR ESTIMATE (14/06/ 2018)

ITEM	DESCRIPTION	AMOUNT SGD
42	FRONT BRAKE SWITCH	^{ant} 2 \$28.00
43	BRAKE LEVER	^{ant} 2 \$28.00
44	WORKMANSHIP	250 \$350.00
45	TRANSPORTATION TO -IDAC- BIKESHOP	80 \$100.00
46	BODY CHASSIS REPAIR	180 \$280.00
47	TRANSPORTATION 2 WAY RTO REPAIR CHASSIS	80 \$100.00
Frt RH switch <i>ant</i> ✓ \$85		
TOTAL		\$6,782.00

Tan Kah 9749 5749
Ex \$500
Revert, Not Authorised
* Re survey new parts
surv @ lkkauto.com
5 days
20/6/18 2/2pm
21/6/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



潘發展私人有限公司
A. S. PHOON PTE LTD
as na nne else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Bk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Bk 36 Toh Guan Road East #01-35 S'pore 608580. Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM5366U HONDA CB150R REPAIR ESTIMATE (14/06/2018)

ITEM	DESCRIPTION	AMOUNT SGD
✓ 1	FRONT FENDER	car \$105.00 ✓
✓ 2	FRONT FORK ASSY RH & LH @\$715	? \$1,430.00 ✓
✓ 3	STEM STERRING	? \$225.00 ✓
✓ 4	CONE BEARING SET	? \$60.00 ✓
✓ 5	FRONT LICENCE PLATE	m.s \$12.00 ✓
✓ 6	HEADLAMP ASSY	cut \$535.00 ✓
✓ 7	HEADLAMP COVER OUTER - (BLACK)	cut \$42.00 ✓
✓ 8	METER ASSY	cut \$495.00 ✓
✓ 9	STAY METER	\$48.00 ✓
✓ 10	FRONT SIGNAL LH	dis \$75.00 ✓
✓ 11	STAY FRONT SIGNAL LH	\$14.00 ✓
✓ 12	CLUTCH LEVER	cut \$24.00 ✓
✓ 13	IU UNIT	cut \$160.00 ✓
✓ 14	IU BRACKET	bl \$40.00 ✓
✓ 15	SIDE MIRRORS RH & LH @\$68	cut \$136.00 ✓
✓ 16	HANDLEBAR	bl \$110.00 ✓
✓ 17	HANDLE END X2	m.s \$28.00 ✓
✓ 18	FUEL TANK COVER LH (RED)	cut \$120.00 ✓
✓ 19	FUEL TANK COVER INNER LH (BLACK)	Xm \$70.00 x
✓ 20	REAR TOP BOX	cut \$280.00 ✓
✓ 21	TOP BOX BRACKET	cut \$160.00 ✓
✓ 22	REAR SIGNAL LH	cut \$75.00 ✓
✓ 23	REAR LICENCE PLATE	bl \$18.00 ✓
✓ 24	STAY REAR LICENCE PLATE	cut \$38.00 ✓
✓ 25	BRACKET REAR LICENCE PLATE	cut \$85.00 ✓
✓ 26	REAR FAIRING RH	cut \$65.00 ✓
✓ 27	FUEL TANK COVER RH	cut \$120.00 ✓
✓ 28	RADIATOR	xm \$300.00 x
✓ 29	COOLANT	xm \$50.00 x
✓ 30	AIR GUARD OUTER RH	cut \$58.00 ✓
✓ 31	AIR GUARD INNER RH	cut \$65.00 ✓
✓ 32	EMBLEM X1	cut \$15.00 ✓
✓ 33	ENGINEGUARD	cut \$280.00 x
✓ 34	BRAKE PEDAL	bl \$45.00 ✓
✓ 35	FRONT FOOTREST ASSY RH	bl \$65.00 ✓
✓ 36	HOLDER FRONT FOOTREST RH	bl \$30.00 ✓
✓ 37	FRONT FOOTREST BRACKET RH	\$5.00 ✓
✓ 38	REAR LICENCE PLATE LIGHT	Sum \$55.00 x
✓ 39	TAILLAMP COVER	xm \$265.00 x
✓ 40	EMBLEM X1	xm \$8.00 x
✓ 41	TAILLAMP BRACKET	cut \$85.00 ✓

4868



潘發展私人有限公司
A. S. PHOON PTE LTD
as na one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM5366U HONDA CB150R REPAIR ESTIMATE (14/06/ 2018)

ITEM	DESCRIPTION	AMOUNT SGD
42	FRONT BRAKE SWITCH	<i>X12</i> \$28.00*
43	BRAKE LEVER	<i>out</i> \$28.00
44	WORKMANSHIP	<i>250</i> \$350.00
45	TRANSPORTATION TO -IDAC- BIKESHOP	<i>80</i> \$100.00
46	BODY CHASSIS REPAIR	<i>180</i> \$280.00
47	TRANSPORTATION 2 WAY RTO REPAIR CHASSIS	<i>80</i> \$100.00
Frt RH switch <i>Car ✓</i> \$85		TOTAL \$6,782.00

Parts - 4981

10% - 4482.90

Labour - 590

\$5072.90

5 days. #

Tan Kah 9749 5749
Ex \$500

Revent, Not the insurance

* Receiving new parts
supp. The auto.com

5 days

20/6/18 2/2pm

SATISFACTION NOTE

Claim reference number: AN3161301

Policy no: AN3161301

Date: 14 JULY 2018

To: AXA INSURANCE PTE LTD

I/We hereby certify that the repairs to my/our vehicle bearing registration number FBM5366U which was involved in an accident on 20 MARCH 2018 along MARYMOUNT ROAD BEF BISHAN ST 22 BFE BUS STOP 53169 has been completed by A.S.PHOON PTE LTD to my/our satisfaction.

I/We agree that payment to the workshop for such repairs shall be in full satisfaction and discharge of all claims which I/we may have in respect of our mentioned vehicle and said policy number insured by AXA INSURANCE PTE LTD .

Signature :



Policyholder's name : SOH BOON KEONG

Nric : S 9133098 I

Tel : 98572816

'cos no one else

Buy and sell Motor-cycles for Cash, Hire Purchase, Spare Parts, Repair and Insurance Agents

* 本號 *

GST REG. NO: M2-0026983-7

FBM 53664 Repair Bill

Date: 05 Nov 2018

茲付下列各貨無誤 Please receive the following goods in good order and condition:

貨離出門概不退回 Goods sold are not returnable

鯉牛人



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18011052/T1qd3e2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-11-2018



ATTN : YVONNE ANG

Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	FBM 5366U
Policy No.	AN3161301	Coverage (\$)	0.00
Claim No.	S8M00B92	Excess (\$)	500.00
Assign From	YVONNE ANG	Assign Date	16/06/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CB150	c.c	149
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MLHKC2881J5007272	Colour	RED
Odometer	4112	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70 R17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60 R17	DUNLOP	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY, FRONT AND REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/03/2018	Inspection Date	20/06/2018
Survey held at	A.S. PHOON PTE LTD BLK 36 TOH GUAN ROAD EAST #01-35 SINGAPORE 608580		

5a. Remarks

A)THE MARKET VALUE IS S\$13,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 5366U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER (CONSISTENT)	CRACKED	105.00	105.00
2	FRONT FORK ASSY RH & LH @\$715.00 (CONSISTENT)	BENT	1,430.00	1,430.00
1	STEM STEERING (CONSISTENT)	BENT	225.00	225.00
1	SET CONE BEARING (CONSISTENT)	NECESSARY	60.00	60.00
1	FRONT LICENCE PLATE (CONSISTENT)	MISSING	12.00	12.00
1	HEADLAMP ASSY (CONSISTENT)	CUT	535.00	535.00
1	HEADLAMP COVER OUTER - (BLACK) (CONSISTENT)	CUT	42.00	42.00
1	METER ASSY (CONSISTENT)	CUT	495.00	495.00
1	STAY.METER (CONSISTENT)	BENT	48.00	48.00
1	FRONT SIGNAL LH (CONSISTENT)	DISTORTED	75.00	75.00
1	STAY.FRONT SIGNAL LH (CONSISTENT)	BENT	14.00	14.00
1	CLUTCH LEVER (CONSISTENT)	CUT	24.00	24.00
1	IU UNIT (CONSISTENT)	CUT	160.00	160.00
1	IU BRACKET (CONSISTENT)	BENT	40.00	40.00
2	SIDE MIRRORS RH & LH @\$68.00 (CONSISTENT)	CUT	136.00	136.00
1	HANDLEBAR (CONSISTENT)	BENT	110.00	110.00
2	HANDLE END (CONSISTENT)	MISSING	28.00	28.00
1	FUEL TANK COVER LH (RED)	CRACKED	120.00	120.00
1	FUEL TANK COVER INNER LH (BLACK) (CONSISTENT)	NOT NECESSARY	70.00	-
1	REAR TOP BOX (CONSISTENT)	CUT	280.00	280.00
1	TOP BOX BRACKET (CONSISTENT)	CUT	160.00	160.00
1	REAR SIGNAL LH (CONSISTENT)	CUT	75.00	75.00
1	REAR LICENCE PLATE (CONSISTENT)	BENT	18.00	18.00
1	STAY. REAR LICENCE PLATE (CONSISTENT)	CUT	38.00	38.00
1	BRACKET REAR LICENCE PLATE (CONSISTENT)	CUT	85.00	85.00
1	REAR FAIRING RH (CONSISTENT)	CUT	65.00	65.00
1	FUEL TANK COVER RH (CONSISTENT)	CUT	120.00	120.00
1	RADIATOR (CONSISTENT)	NOT NECESSARY	300.00	-
1	COOLANT (CONSISTENT)	NOT NECESSARY	50.00	-
1	AIR GUARD OUTER RH (CONSISTENT)	CUT	58.00	58.00
1	AIR GUARD INNER RH (CONSISTENT)	CUT	65.00	65.00

Report Ref No. CS/ASM18011052/T1qd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EMBLEM (CONSISTENT)	NECESSARY	15.00	15.00
1	ENGINEGUARD (CONSISTENT)	NOT NECESSARY	280.00	-
1	BRAKE PEDAL (CONSISTENT)	BENT	45.00	45.00
1	FRONT FOOTREST ASSY RH (CONSISTENT)	BROKEN	65.00	65.00
1	HOLDER, FRONT FOOTREST RH (CONSISTENT)	BENT	30.00	30.00
1	FRONT FOOTREST BRACKET RH (CONSISTENT)	BENT	5.00	5.00
1	REAR LICENCE PLATE LIGHT (CONSISTENT)	NOT NECESSARY	55.00	-
1	TAILLAMP COVER (CONSISTENT)	NOT NECESSARY	265.00	-
1	EMBLEM (CONSISTENT)	NOT NECESSARY	8.00	-
1	TAILLAMP BRACKET (CONSISTENT)	CUT	85.00	85.00
1	FRONT BRAKE SWITCH (CONSISTENT)	NOT NECESSARY	28.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	28.00	28.00
1	FRT RH SWICTH (CONSISTENT)	CRACKED	85.00	85.00
	LESS 10% DISCOUNT		-	-498.10
			6,037.00	4,482.90
	LABOUR			
	WORKMANSHIP.		350.00	250.00
	TRANSPORTATION TO - IDAC - BIKESHOP.		100.00	80.00
	BODY CHASSIS REPAIR.		280.00	180.00
	TRANSPORTATION 2 WAY RTO REPAIR CHASSIS.		100.00	80.00
			830.00	590.00
	GRAND TOTAL		6,867.00	5,072.90
	RECOMMENDED COST OF REPAIRS			5,072.90
	LESS EXCESS			-500.00
	NETT LIABILITY			4,572.90

Report Ref No. CS/ASM18011052/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.