

ASS. REC. BY:

REF: CS/MSG18011065 | ASD3 | ⁿ²

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

Member

From (Person): Christina Wong of

MSIG

Date/Time: 18/6/18 @ 4:28pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

YN 5195 T

Insured:

SKA 7547H

at Workshop m/s

Green Forest Automobile

Tel:

92712214

of

& Kaki Bkt Ave 4 # 05-25 premier

Policy No.:

B29 04 0710 TMC

Claim No.:

561347

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/06/2018

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time:

10:46am @ 1/6/18

Person Contacted:

Chris Chan

Vehicle

IN

OUT

Date/Time

Action/Instruction (✓) Estimate

YN 5195 T - X

SKA 7547 H - NBA/MSG17014542 / Y

DOA: 26/07/2017

20/06/18

@ 15:35 p.m. revert pending estimate from repairer to Christina Wong via email.

02/07/18

@ 11:11 a.m. revised IA to Christina Wong via member.

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: YH5195T Yr Regn: 2014, June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Fuso c.c. 2998
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 208751 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: FEB21FA00496
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: (Nil) / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195R15C
 R: 195R15C

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 19/06/18
 Survey held at Forest Green
 Des. of Damages: Frt / Rear / (O/S) / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP MSIG
	(\$10,551.73 Red - 71%)

RECEIVED @ 2 JUL 2018

Date/Time, File Pass to? 02/07/18
 1) Typist
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / L.B.I. (\$) 4,200.00 4/5

Days Of Repair: 5
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

7841R

Survey Fee:	
Transportation:	<u>200</u>
(\$ + RS. \$)	<u>10</u>
Photos	
Other	
TOTAL	<u>210</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jun 2018		18 Jun 2018 16:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Sime Darby Services Pte Ltd, Co. Reg. No.: 197501065 W		
Main Claimant:	GREEN FOREST LANDSCAPE PTE LTD, Co. Reg. No.: 200707841R		
Vehicle Reg. No.:	YN5195T	Date of Loss:	14/06/2018 09:00 - :59 [48 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561347	Policy/Cover Note No.:	B29040710TMC (Comprehensive) Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SKA7547H	Policy No. (Claimant):	
		Excess:	
Repairer:	GREEN FOREST AUTOMOBILE (HQ) 8 KAKI BUKIT AVENUE 4, #05-25 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63846383		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2018]		
Driver/Custodian (Insured):	INDRA KAMERLING (43 / Female), NRIC: G3344838X		
Adj Asg. Remarks:	SJE Agree Please appoint LKK and contact Chris Chan @ 92712214 Liability (Not Clear)		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18011065/Asd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 19-06-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKA 7547H	Veh. Inspected	YN 5195T
Policy No.	B29040710TMC	Coverage (\$)	0.00
Claim No.	561347	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	19/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/06/2018	Inspection Date	19/06/2018
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 7841R

Vehicle Details

Vehicle No: YN5195T
 Vehicle to be Exported: Yes
 Intended De-registration Date: 15 Jun 2018
 Vehicle Make: MITSUBISHI
 Vehicle Model: CANTER FEB21ER+5DEB (CBU)
 Primary Colour: White
 Manufacturing Year: 2014
 Engine No: 4P10B20040
 Chassis No: FEB21EA00495
 Maximum Power Output: -
 Open Market Value: \$29,761.00
 Original Registration Date: 13 Jun 2014
 First Registration Date: 13 Jun 2014
 Transfer Count: 0
 Actual ARF Paid: \$1,489.00

Intended PARF Rebate Details

PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Jun 2024
 COE Category: C - Goods Vehicle & Bus
 COE Period (Years): 10
 PQP Paid: \$13,100.00
 COE Rebate Amount: \$7,850.00
Total Rebate Amount: \$7,850.00

The information contained herein is correct as at 15 Jun 2018.

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 02 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKA7547H	Accident Date	: 14/06/2018
TP Vehicle No	: YN5195T	Assignment Date	: 18/06/2018
Make	: MITSUBISHI CANTER	Est. Duration of Repair	: 5 days
Date of Inspection	: 19/06/2018		
Inspection At	: GREEN FOREST AUTOMOBILE (HQ) 8 KAKI BUKIT AVENUE 4, #05-25 PREMIER @ KAKI BUKIT Singapore 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,751.73
Revised Amount	:S\$	5,310.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,310.13

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/06/2018 17:01
Date Of Accident	14/06/2018 09:00
Exact Location Of Accident	DUNEARN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN5195T
Insured/Policyholder	
Name Of Registered Owner	GREEN FOREST LANDSCAPE PTE LTD
Co Reg No	200707841R
Email Address	CATHERINE@LANDSCAPE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64825191

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P1775496
Cover Note Number	13/06/2018-12/06/2019

Driver

Name of Driver	KARYMP AYERAM SIVAS ANKER
Passport No/FIN	G7977861W
Date Of Birth	25/04/1983
Occupation	OUTDOOR
Date Of Driving Pass	27/02/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82874737
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO WITH INSURED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKA7547H
 Vehicle Make/Model/Colour NISSAN
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SCHAKELAAR INDRA WENDY
 NRIC/Passport Number G3344838X
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


K. Sivasankar

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 14 JUN 2018 @ 0900HRS, I WAS TRAVELLING ALONG DUNEARN ROAD ON LANE 2. SUDDENLY, A CAR (VEHICLE B) FROM THE THIRD LANE CUT OUT AND HIT INTO MY LORRY (VEHICLE A). NO ONE WAS INJURED IN THIS ACCIDENT.

DECLARATION

I/We declare the above particulars are true in every respect.

Policyholder's Signature: 
Date & Time:

Driver's Signature: K. Sivasankar
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature: 
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



redefining / insurance

Date: 14/06/18

To: Owner of Vehicle Number: VN5915T

The following has been advised to you via your workshop, _____ through their staff, _____



Please tick the applicable box if you had been advice on the content as seen below:

- You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- You had been advised by the workshop on the liability and merits of the case accordingly.
- You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- Others Claims 3rd party @ other workshop

Signed and acknowledge by:

 _____
Name and signature of policyholder/authorised driver

 _____
Name and signature of workshop personnel including company stamp

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

GREEN FOREST LANDSCAPE PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BUKIT
Singapore 415875

FEB21EA00496

18th June 2018

TPMSIG.
Shirley

Accident date: JUNE 2018

Estimated repair cost for vehicle no: YN5195T Mitsubishi canter '14

1	1	Front head lamp -RH	cut d		\$420.20	✓
2	2	head lamp bracket	new		\$102.20	+
3	1	Front bumper	Beut		\$824.58	✓
4	2	Front bumper side bracket	Beut RH	\$38.20	\$76.40	38-20
5	8	Front bumper clips	new	\$12.90	\$103.20	+
6	1	front bumper Side protector	cut		\$371.80	✓
7	1	front bumper number plate	new		\$50.00	+
8	2	front bumper bracket		\$185.00	\$370.00	+
9	1	Front bumper reinforcement	new		\$380.10	+
10	1	Front bumper fog lamp			\$125.20	+
11	1	Front grille	new		\$454.25	+
12	1	front grille logo	new		\$42.10	+
13	1	front water tank	new		\$280.00	+
14	1	Front support panel	new		\$320.00	+
15	1	front support garnish		\$98.10	\$98.10	+
16	1	Front side panel-RH	Dented		\$291.40	✓
17	1	RH front door side mirror	new		\$358.00	+
18	1	Front R/H Door	Dented		\$1,759.00	✓
19	2	Front R/H Door Hinge	1 piece Beut	\$250.00	\$500.00	144
20	1	Front R/H Door Top Moulding	new		\$142.00	+
21	1	Front R/H Door step panel	cut		\$165.00	✓
22	1	Front R/H Door Sticker (Advertisement)	new		\$300.00	200(SW)
23	1	Front R/H Door Outer Handle	new		\$129.00	✓
24	1	Front R/H Door Lower Garnish	cut		\$125.00	✓
25	1	Front R/H Door Inner Trim Board	Reformed		\$568.00	✓
26	1	Front R/H Door Inner Lock	new		\$326.00	+
27	1	Front R/H Door Inner Rubber	new		\$300.00	+
28	1	front RH door glass	new		\$520.00	+
29	1	Front R/H Door Gear Motor Assy	new		\$1,469.00	+

Front RH Signal Lamp
Front RH Reflector

Page 131 Missing
Missing

313.60

80.40

30	1	front RH Mud flap		\$120.00	X
31	1	front RH door lower garnish	3 AM me	\$188.00	X
32	1	front RH door side pillar	egis	\$1,200.00	X
				Subtotal :-	\$12,061.73

5200.18
3900.13
S.N. 200

Labour charges

remove & Refix front RH door	\$200.00	80 X
To remove & refix front R/H door glass, gear motor	\$180.00	80
To check wheel alignment computer	\$150.00	X
To Check Wiring System	\$60.00	30
Tuff kote	\$100.00	X
Panel beating	\$1,000.00	500.
Spray painting	\$1,000.00	600.

1210

Subtotal :- \$2,690.00

Total :- \$14,751.73

15532.53

total: 531013
L/S 4.21K
05Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011065/ASD3N2

Date: 04/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29040710TMC
Claimant Vehicle No :	YN5195T	Insured Vehicle No :	SKA7547H
Date of Loss:	14/06/2018	Nature of Claim:	TP
		Claim No:	561347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN5195T	Engine No:	4P10B20040
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21 (M)	Chassis No:	FEB21EA00496
Reg. Date:	13/06/2014 (Man. Year: 2014)	Odometer:	228751 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	12,842.53	4,100.13	8,742.40	68.07	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,690.00	1,210.00	1,480.00	55.02	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (\$\$)	15,532.53	5,310.13	10,222.40	65.81	
Approved Total (Overridden) (\$\$)		4,200.00			
	(\$\$)	15,532.53	4,200.00	11,332.53	72.96
	+ GST 7.00/7.00% (\$\$)	1,087.28	294.00	793.28	72.96
	Nett Amount (\$\$)	16,619.81	4,494.00	12,125.81	72.96

INSPECTION

Date of Assignment: 18/06/2018

Date Inspected: 19/06/2018 Inspected At:

GREEN FOREST AUTOMOBILE (HQ)
8 KAKI BUKIT AVENUE 4, #05-25
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jul 2018)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN5195T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT HEAD LAMP-RH	Cracked	420.20 F	*420.20 FL
2	2	*HEAD LAMP BRACKET	Not Necessary	102.20 F	*- FL
3	1	*FRONT BUMPER	Deformed	824.58 F	*824.58 FL
4	1	*FRONT BUMPER SIDE BRACKET	O/s Bent	76.40 F	*38.20 FL
5	8	*FRONT BUMPER CLIPS	Not Necessary	103.20 F	*- FL
6	1	*FRONT BUMPER SIDE PROTECTOR	Cut	341.80 F	*341.80 FL
7	1	*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
8	2	*FRONT BUMPER BRACKET	Not Necessary	370.00 F	*- FL
9	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	380.10 F	*- FL
10	1	*FRONT BUMPER FOG LAMP	Not Necessary	125.20 F	*- FL
11	1	*FRONT GRILLE	Not Necessary	454.25 F	*- FL
12	1	*FRONT GRILLE LOGO	Not Necessary	42.10 F	*- FL
13	1	*FRONT WATER TANK	Not Necessary	280.00 F	*- FL
14	1	*FRONT SUPPORT PANEL	Not Necessary	320.00 F	*- FL
15	1	*FRONT SUPPORT GARNISH	Not Necessary	98.10 F	*- FL
16	1	*FRONT SIDE PANEL-RH	Dented	291.40 F	*291.40 FL
17	1	*RH FRONT DOOR SIDE MIRROR	Not Necessary	358.00 F	*- FL
18	1	*FRONT R/H DOOR	Dented	1,759.00 F	*1,759.00 FL
19	2	*FRONT R/H DOOR HINGE	Bent (1 Pc Only)	500.00 F	*144.00 FL
20	1	*FRONT R/H DOOR TOP MOULDING	Not Necessary	142.00 F	*- FL
21	1	*FRONT R/H DOOR STEP PANEL	Cut	165.00 F	*165.00 FL
22	1	*FRONT R/H DOOR OUTER HANDLE	Necessary	129.00 F	*129.00 FL
23	1	*FRONT R/H DOOR LOWER GARNISH	Cut	125.00 F	*125.00 FL
24	1	*FRONT R/H DOOR INNER TRIM BOARD	Deformed	568.00 F	*568.00 FL
25	1	*FRONT R/H DOOR INNER LOCK	Not Necessary	326.00 F	*- FL
26	1	*FRONT R/H DOOR INNER RUBBER	Not Necessary	300.00 F	*- FL
27	1	*FRONT R/H DOOR GLASS	Not Necessary	520.00 F	*- FL
28	1	*FRONT R/H DOOR GEAR MOTOR ASSY	Not Necessary	1,469.00 F	*- FL
29	1	*FRONT RH SIGNAL LAMP	Missing	313.60 F	*313.60 FL
30	1	*FRONT RH REFLECTOR	Missing	80.40 F	*80.40 FL
31	1	*FRONT R/H DOOR STICKER (ADVERTISEMENT)	Necessary	300.00 FS	*200.00 FS
32	1	*FRONT RH MUD FLAP	Not Necessary	120.00 FS	*- FS
33	1	*FRONT R/H DOOR LOWER GARNISH	Not Necessary	188.00 FS	*- FS
34	1	*FRONT R/H DOOR SIDE PILLAR	Repair	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,842.53	5,400.18
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,300.05
Total Parts (S\$)	12,842.53	4,100.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRONT RH DOOR	New	200.00	-
2	TO REMOVE & REFIX FRONT R/H DOOR GLASS,GEAR MOTOR	New	180.00	80.00
3	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	-
4	TO CHECK WIRING SYSTEM	New	60.00	30.00
5	TUFF KOTE	New	100.00	-
6	PANEL BEATING	New	1,000.00	500.00
7	SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,690.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >