

ASS. REC. BY:

REF: CS3/MSG18011066/V21d3/02

Official Instruction:

Surveyor:

Sathya

ASSIGNMENT (Office)

Munnen

From (Person):

Katherine Wong

of

MSIG

Date/Time:

14/06/18 @ 4:59pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 80455

Insured:

GT 4423Z

at Workshop m/s

Choon Hock Autocare

Tel:

6453 0778

of

81k 176, Sin Ming Drive # 05-03

Policy No:

D29003238 TMV

Claim No:

561066

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

10:49am @ 14/6/18

Person Contacted:

caleb

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKD 80455 - X
	GT 4423Z - NA INC10013485/Ac2
	DOA: 08/07/2010
20/6/18	Dismantled

REF: MSIG

ASSIGNMENT

From: Date: 19/6/18
 Estimated Cost:
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: SKD 80455
 at Workshop m/s Choon Hock Autocare
 of Blk 176, Sin Ming Drive # 05-03
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lups

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKD 80455 Yr Regn: Jan / 2007
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Civic C.C. 1998
 Colour: Gold A/C Insured / Std / NI / NA
 Sp. Reading: 203089 T/Radio: Insured / Std / NI / NA
 Eng/No: K20322500232
 C/No: JHMFD26407S200231
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45 R17
 R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	7/6/2018 Autocare e	D.O.I.	19/6/18
Survey held at		1200pm	
Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

* Repair Estimate : S\$ 9800 - 11,000

* 6 days

7/6/18 Submit PRS Report.

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Lump Sum / I.B.I. : \$

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech Ins \$
☐ Weekend \$

Survey Fee:

Transportation:

F 3+PS \$

Photos

Others

TOTAL

120

50

10

(80)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jun 2018		14 Jun 2018 16:59 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Yong Tai Loong Pte Ltd, Co. Reg. No.: 197201054D		
Main Claimant:	TAN YAN YI, ID: S8851061E		
Vehicle Reg. No.:	SKD8045S	Date of Loss:	07/06/2018 18:00 - :59 [136 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561066	Policy/Cover Note No.:	D29003238TMV (Third Party Only) Coverage: 09/09/2017 - 08/09/2018
Vehicle Reg. No. (Insured):	GT4423Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Choon Hock Autocare Pte Ltd (HQ) Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare Singapore 575721, 575721 Sin Ming - Tel: 64530778		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/06/2018]		
Driver/Custodian (Insured):	NEO BOON HONG (41 / Male), NRIC: S7629976E		
Adj Asg. Remarks:	on WP. SJE Agree Please appoint LKK and contact Caleb @ 6453 0778 to conduct the survey. Liability (100%)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18011066/Vz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-06-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GT 4423Z	Veh. Inspected	SKD 8045S
Policy No.	D29003238TMV	Coverage (\$)	0.00
Claim No.	561066	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/06/2018	Inspection Date	19/06/2018
Survey held at	CHOON HOCK AUTOCARE PTE LTD BLK 176 SIN MING DRIVE #05-03 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2018 18:47
Date Of Accident	07/06/2018 18:00
Exact Location Of Accident	BKE TOWARDS PIE BEFORE KJE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD8045S
Insured/Policyholder	
Name Of Registered Owner	TAN YAN YI
NRIC No	S8851061E
Email Address	YANYI88@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94526999
Alternative Phone No	OFFICE-94526999

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMPC17S008597
Cover Note Number	

Driver

Name of Driver	TAN YAN YI
NRIC No	S8851061E
Date Of Birth	18/12/1988
Occupation	INDOOR
Date Of Driving Pass	15/01/2008
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94526999
Fax Number	
Contact Number	OFFICE-94526999
Email Address	YANYI88@HOTMAIL.COM

Address	BLK 209 BUKIT BATOK ST 21 # 13- 172
Postcode	650209
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO : T/20180608/2118.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT4423Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN YAN YI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKD8045S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 08/06/18 10:30am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

☐ Claim Own Damage ☒ Claim TP ☐ Reporting Only ☐ Claim OD/TP at other workshop

Workshop Name: Zhou Hock Motor Trading Co.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was the driver of Car A(A). A was driving along RKE towards PIE. When A was approaching near to KJE exit, a blue comfort taxi suddenly turn out from lane 4 into lane 3, where lane 4 was in a slow & traffic condition. So A had to do a emergency brake to avoid collision with the taxi and A eventually came to a complete stop. Next morning after A stopped, lorry B(B) crashed into A's back, pushing A forward.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
08/06/18
10:30 AM
Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

[Signature]
Reporting Centre Personnel's Signature
Name
NR-C744 No

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2018		14 Jun 2018 16:59 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------



































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Yong Tai Loong Pte Ltd, Co. Reg. No.: 197201054D	
Main Claimant:	TAN YAN YI, ID: S8851061E	
Vehicle Reg. No.:	SKD8045S	Date of Loss: 07/06/2018 18:00 - :59 [136 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561066	Policy/Cover Note No.: D29003238TMV (Third Party Only) Coverage: 09/09/2017 - 08/09/2018
Vehicle Reg. No. (Insured):	GT4423Z	Policy No. (Claimant):
		Excess:
Repairster:	Choon Hock Autocare Pte Ltd (HQ) Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare Singapore 575721, 575721 Sin Ming - Tel: 64530778	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Imm.Advice due 15/06/2018]	
Driver/Custodian (Insured):	NEO BOON HONG (41 / Male), NRIC: S7629976E	
Adj Asg. Remarks:	on WP. SJE Agree Please appoint LKK and contact Caleb @ 6453 0778 to conduct the survey. Liability (100%)	



















































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		
















































ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKD8045S (561066)**
[GT4423Z]
TP
TAN YAN YI
Jun 7 2018 6:00PM
[Yong Tai Loong Pte Ltd]
Choon Hock Autocare Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/06/18 11:30	Accident Statement From: SC - Reg. No: GT4423Z, Claimant: YONG TAI LOONG	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
18	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
19	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
20	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
21	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
23	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
24	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
25	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
26	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
27	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
28	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
29	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
30	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
31	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/18 09:26	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/18 09:26	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	20/06/18 18:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/06/18 11:30	Third Party Accident Report From: SC - Reg. No: GT4423Z, Claimant: YONG TAI LOONG	 Load PDF	
2	13/06/18 11:30	fax to arrange surveyors From: SC - Reg. No: GT4423Z, Claimant: YONG TAI LOONG	 Load PDF	
3	13/06/18 11:30	PRI	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
		From: SC - Reg. No: GT4423Z, Claimant: YONG TAI LOONG			
4	13/06/18 17:13	reject surveyor		Load PDF	
5	13/06/18 17:13	workshop propose surveyor		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011066/VZ4D3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: D29003238TMV

Claimant Vehicle No: SKD8045S

Insured Vehicle No: GT4423Z

Date of Loss: 07/06/2018

Nature of Claim: TP

Claim No: 561066

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD8045S

Make & Model: HONDA CIVIC, 2.0 (A)

Engine No: K20Z22500232

Reg. Date: 11/01/2007 (Man. Year: 2006)

Chassis No: JHMFD26407S200231

Colour: Gold

Odometer: 203089 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Goodyear 7 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 7 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/06/2018

Date Inspected: 19/06/2018 Inspected At:

Choon Hock Autocare Pte Ltd (HQ)
Blk 176 Sin Ming Drive #05-03, Sin Ming
AutoCare Singapore 575721
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,800.00 -\$11,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts:	143	HONDA CIVIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD8045S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >