

ASS. REC. BY:

Surveyor:

Farrul

REF

CS1 FWD18011085/R1.9d302

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Belliana

of

FWD

Date/Time:

18/06/18 @ 3.53pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SKG 882 D

Insured:

FBE 8849R

at Workshop m/s

RS Automotive

Tel:

9182 6089

of

Blk 3006 - Ubi Rd 1 # 01-394 / 384

Policy No:

PNMC 2018 - 00001105

Claim No:

1201800007444

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/06/2018

CA / REV / REP. / REV 24 HRS

'wup'

20/06/2018

H.O.D. Endorsement:

Date/Time:

9.10am @ 19/6/18

Person Contacted:

Richard

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBE 8849R-X
	SKG 882D-X
	Ramul finalised LS \$1200, 3 days (Red \$986, 45%)

Signature

Faran

REF: FWD

83000

ASSIGNMENT

From: _____ Date: **20/06/2018**
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: **SKG 8820**
at Workshop m/s: **RS Automotive**
of **Blk 3006, Ubi Rd 1 #01-394/384**
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: **3** days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS **(up)**

Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: **SKG 8820** Yr Regn: **2012 / MMY**
Type: **(M) Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **NISSAN ELGRAND 2-5** c.c. **2488**
Colour: **BLACK** A/C: Insured / Std / NI / NA
Sp. Reading: **159868** T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **TDBARTWES2ED841322**
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: **235/50R18**
R: **21**
BS / DUN / EXNOVA / GY / FS / LIZA / **(MIC)** / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. **6** mm R/Bal. **6** mm
L/Bal. **6** mm L/Bal. **6** mm
D.O.A. **14/06/18** D.O.I. **20/06/18**
Survey held at **RS AUTOMOTIVE**
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
old frt
The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 25 JUL 2018

Date/Time File Pass to? ☐ : Preli. Report
1) 25/7/18 ☐ : Final Report
Date/Time File Return to? _____

Report Format : **7P**
Lump Sum / I.B.I. (\$) **1200**

Days Of Repair: **3**
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
) S + RS. SI
) Photos
) Others

200
50
10
260

TOTAL

Nivitha (LKK Auto)

From: belliana@fwd.com
Sent: Monday, 18 June 2018 3:53 PM
To: admin-a@lkkauto.com; admin-d@lkkauto.com; sur@lkkauto.com
Cc: motorclaims.sg@fwd.com; kurulegal@yahoo.com.sg
Subject: NEW CASE- TP PRS: FW: Our Ref: L.18.0924.AT//Your Ref: FBE 8849R//PRS; FWD Policy Number PNMC2018-00001105 (Claim Ref: TBA)

Hi LKK Team

Please liaise with TP to arrange PRS.

Thanks.

Belliana Lim
Claims Manager, Operations



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986
T +65 6727 5721
E belliana@fwd.com

	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	--

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Monday, 18 June, 2018 3:46 PM
To: Belliana - SGUser
Cc: Motor Claims SG - SG Common
Subject: Re: FW: Our Ref: L.18.0924.AT//Your Ref: FBE 8849R//PRS; FWD Policy Number PNMC2018-00001105 (Claim Ref: TBA)

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **LKK AUTO CONSULTANTS PTE LTD**

Please arrange for your surveyor to survey our client's vehicle at the following address:

RS AUTOMOTIVE PTE LTD
Blk 3006 Ubi Rd 1
#01-394/384
Singapore 408700

Contact: Richard/ 9182 6089-**Kindly contact Richard to make the arrangement**

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards

Anne

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

On Monday, 18 June 2018, 3:32:12 PM SGT, belliana@fwd.com <belliana@fwd.com> wrote:

WITHOUT PREJUDICE

Hi Anne

We refer to your email dated 18 June 2018 of the PRI Notice of your client's vehicle SKG882D.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Regards

Belliana Lim

Claims Manager, Operations



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower 4, Singapore 038986

T +65 6727 5721

E belliana@fwd.com

	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
---	--	--	--

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]
Sent: Monday, 18 June, 2018 10:17 AM
To: Motor Claims SG - SG Common; SG Corporate Contact
Subject: Our Ref: L.18.0924.AT//Your Ref: FBE 8849R//PRS

Dear Sirs

ACCIDENT INVOLVING SKG 882D & FBE 8849R ON 14.06.2018

ALONG JALAN DAUD

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Kok Hon Por**, whose vehicle registration number **SKG 882D** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS/FWD18011085/R1qd3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986		Date : 19-06-2018	
		Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBE 8849R	Veh. Inspected	SKG 882D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	BELLIANA LIM	Assign Date	19/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/06/2018	Inspection Date	20/06/2018
Survey held at	RS AUTOMOTIVE WORKSHOP BLK 3006 UBI ROAD 1 #01-394 SINGAPORE 408700		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

RS AUTOMOTIVE PTE LTD

Workshop : Blk 3006 Ubi Road 1 #01-394 Singapore 408700
Mailing : 109 Pasir Ris Grove, #09-23 The Palette Singapore 518199
Tel No. : 67483032 Fax No. : 67499469
E-Mail : rsautomotive@yahoo.com.sg
Website : www.rsautomotive.com.sg
Tax Reg. No. : 201230654Z Buss. Reg. No. : 201230654Z

BODDY KOK

Works Order : WO002346

Date Printed : 20/06/2018
Vehicle Num. : SKG 882 D
Make/Model : NISSAN ELGRAND
Mileage(Km) :
P.O./R.O No. :
Ref./Remark :

Contact : 93860803

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	FRONT BUMPER	1226 980.00	980.00
2.	1PC	BUMPER BRACKET (FRONT RH)	30% 48.00	48.00
3.	1PC	WHEEL HOUSING GARNISH RH	198.00	198.00
4.	1PC	WASHER TANK	200.00	200.00

LABOUR CHARGE TO PANEL BEATING AND REPLACE ABOVE ITEMS
JOB
TO RESPRAY PAINT FRONT BUMPER AND RH FENDER JOB

250
650
280.00
480.00
400

858.20
650.00
1508.20

20%
1206.56

43-1,200
3 days

Hp 90010068

3 days

4/5

20/06/18 @ 1400h

Resay after paint

SingDollars : Two Thousand Three Hundred Thirty-Nine & Cents Two Only

E. & O.E.

Total S\$: 2,186.00
GST @ 7% S\$: 153.02
Amount Due S\$: 2,339.02
=====

Terms : Cash

Customer's Signature/Co. Stamp

for RS AUTOMOTIVE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/06/2018 11:26
Date Of Accident	14/06/2018 20:00
Exact Location Of Accident	JALAN DAUD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG882D
Insured/Policyholder	
Name Of Registered Owner	KOK HON POR
NRIC No	S1768300D
Email Address	OASISINGAPORE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93860803
Alternative Phone No	OTHERS-93860803
Vehicle Particulars	
Manufacturer	NISSAN
Model	ELGRAND
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100301684
Cover Note Number	
Driver	
Name of Driver	KOK HON POR
NRIC No	S1768300D
Date Of Birth	11/05/1966
Occupation	INDOOR
Date Of Driving Pass	24/11/1988
Driving Experience	29 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93860803
Fax Number	
Contact Number	OTHERS-93860803
EMail Address	OASISINGAPORE@GMAIL.COM

Address	84 JALAN DAUD #04-03
Postcode	415953
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : PAX 1 GENDER: : FEMALE
Passenger 2	NAME: : PAX 2 GENDER: : MALE
Passenger 3	NAME: : PAX 3 GENDER: : MALE
Passenger 4	NAME: : PAX 4 GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE AUTOMOTIVE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBE8849R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the nearest of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that a copy of this report will for a fee be made available upon application to interested parties.
7. By the signing of this report to the Insurer, you hereby consent to the archiving of this report as the person and to ensure the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and/or process my Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers' lawyer allow them, the Monetary Authority of Singapore and any other government agency/authority (such as the police), for the purpose(s) of:
 - (i) assessing, handling and/or dealing with my claim including the settlement of the claims and any necessary investigation relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) administering and/or dealing with my distribution or responding to any enquiries by me;
 - (iv) administering my claim including the mailing of correspondence, statements, invoices, receipts or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same or was as on the external cover of a envelope/mail package(s); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim, (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TFN No.:

A-5K600 D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

We declare the foregoing statements are true in every respect.
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Date & Time

(If driver is not the policyholder)

Date & Time:

Neufuss

 $\text{NaRC}_2\text{F}_4/\text{F/Nu}$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jun 2018 Edit Reg		18 Jun 2018 00:00 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Mohamed Esa Bin Sidek , ID: S1467934J									
Main Claimant: KOK HON POR , ID: S1768300D									
Vehicle Reg. No.: SKG882D		Date of Loss: 14/06/2018 20:00 - :59 [72 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201800007444		Policy/Cover Note No.: PNMC2018-00001105 (Third Party Only)							
Vehicle Reg. No. (Insured): FBE8849R		Policy No. (Claimant):							
		Excess:							
Repairer: RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/06/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKG882D (1201800007444)**
[FBE8849R]
TP
KOK HON POR
Jun 14 2018 8:00PM
[Mohamed Esa Bin Sidek]
RS Automotive Workshop

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	25/07/18 08:54	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
2	25/07/18 08:54	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
3	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
4	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
5	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
6	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
7	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
8	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
9	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
10	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
11	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
12	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
13	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
14	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
15	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
16	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
17	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					
18	25/07/18 08:54	General View		Load JPG	<input checked="" type="checkbox"/>					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD18011085/R1QD3E2

Date: 25/07/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2018-00001105
Claimant Vehicle No : SKG882D **Insured Vehicle No :** FBE8849R
 Date of Loss: 14/06/2018 Nature of Claim: TP Claim No: 1201800007444

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG882D**
 Make & Model: NISSAN ELGRAND, 2.5 (A) Engine No: QR25944619Q
 Reg. Date: 21/05/2012 (Man. Year: 2012) Chassis No: JN1TBAE52Z0800018
 Colour: Black Odometer: 159868 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,426.00	858.20	567.80	39.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	650.00	110.00	14.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,186.00	1,508.20	677.80	31.01
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,186.00	1,200.00	986.00	45.11
+ GST 7.00/7.00% (S\$)	153.02	84.00	69.02	45.11
Nett Amount (S\$)	2,339.02	1,284.00	1,055.02	45.11

INSPECTION

Date of Assignment: 18/06/2018
 Date Inspected: 20/06/2018 Inspected At: RS Automotive Workshop (HQ)
 3066 Ubi Road 1, #01-394/384
 Singapore 408700
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Jul 2018)	
Parts:	N/A	NISSAN ELGRAND 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG882D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	980.00 F	*980.00 FL
2	1		*BUMPER BRACKET (FRONT RH)	Necessary	48.00 F	*48.00 FL
3	1		*WHEEL HOUSING GARNISH RHF	Cut	198.00 F	*198.00 FL
4	1		*WASHER TANK	Serviceable	200.00 F	*- FL
					Sub Total (S\$)	1,426.00
					- List Item Discount on L Items 0.00/30.00% (S\$)	0.00
					Total Parts (S\$)	858.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO PANEL BEATING AND REPLACE ABOVE ITEMS JOB	New	280.00	250.00
2	TO RESPRAY PAINT FRONT BUMPER AND RH FENDER JOB	New	480.00	400.00
Gross Labour Cost (S\$)			760.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >