

ASS. REC. BY:

REF:

CS/MSC118011090/Ugbn2

Special Instruction:

SILVANO

Mermmen

Mangus

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSCH

Date/Time:

19062018 2:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKN 5056C

Insured:

SBR 3688C

at Workshop m/s

Hock Wah Motor

Tel:

6441 5655

of

Blk 3011 Bedok North Ave 4 #01-2008

Policy No:

A80375756 DMY

Claim No:

360740

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07062018

CA / REV / REP. / REV 24 HRS 'WP'

20062018

H.O.D. Endorsement:

Date/Time:

19062018 3:33pm

Person Contacted:

Jia Yi

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKN 5056C - X

SBR 3688C - CS/MSC116017516 / Mlvbc2

DA: 220516

21/6/18 @ 2:54pm raised to Monica Chung via desimo.

REF: MSIG

ASSIGNMENT

From:

Date:

20/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKN 5056C

at Workshop n/s

Hock Wah Motor

of BIK 3011, Bedok North Ave 4 # 01-2008

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

CIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

1.51 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKN 5056C

Yr Regn:

209

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda Odyssey

C.C.

2354

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

214508

T/Radio: Insured / Std / NI / NA

Eng/No:

JHMRB 38509C 200130

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/6/18

D.O.I.

20/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A18739

17/7/18 Confirmed final by \$400 with Justice.
(Ref B 1739.00, 8/2)

17/7/2018

RECEIVED 17 JUL 2018

Date/Time: File Pass to?



Preli. Report

17/7/2018



Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Surveys (\$)



Weekend (\$)

Survey Fee:

Transportation

1.3 * RS. \$

1. Photos

1. Others

TOTAL

150
10

160

Report Format:

Lump Sum / I.B.F. (\$)

MEK-7P

400

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2018		19 Jun 2018 14:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Yap Cheng Swee, ID: S0146217B		
Main Claimant:	JEGACY TRANSPORT SERVICES, Co. Reg. No.: 51085500L		
Vehicle Reg. No.:	SKN5056C	Date of Loss:	07/06/2018 13:00 - :59 [111 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560740	Policy/Cover Note No.:	A80375756QMY (Comprehensive) Coverage: 25/06/2017 - 24/06/2018
Vehicle Reg. No. (Insured):	SBR3688C	Policy No. (Claimant):	
		Excess:	
Repairer:	Hock Wah Motor Workshop Pte Ltd - bedok (HQ) Blk 3011 Bedok North Avenue 4, #01- 2008/2010/2012/2014, 489977 Bedok - Tel: 64415655		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/06/2018]		
Driver/Custodian (Insured):	TAN YONG KWEE (62 / Male), NRIC: S1154710I		
Adj Asg. Remarks:	SJE Agree Please appoint Marcus Chua from LKK Auto Consultancy Pte. Ltd and contact Jia Yi @ 6441 5655 Liability (100%)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 21 Jun 2018

Preliminary Advice

Insured Vehicle No	: SBR3688C	Accident Date	: 07/06/2018
TP Vehicle No	: SKN5056C	Assignment Date	: 19/06/2018
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 2.00
Date of Inspection	: 20/06/2018		
Inspection At	: HOCK WAH MOTOR WORKSHOP PTE LTD - BEDOK (HQ) BLK 3011 BEDOK NORTH AVENUE 4, #01-2008/2010/2012/2014 SINGAPORE 489977		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,139.80
Revised Amount	:S\$	400.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	400.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5500L
Vehicle Details	
Vehicle No.:	SKN5056C
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT SR
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	K24Z21300134
Chassis No.:	JHMRB38509C200130
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$37,136.00
Original Registration Date:	12 Feb 2009
First Registration Date:	12 Feb 2009
Transfer Count:	1
Actual ARF Paid:	\$37,136.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2019
PARF Rebate Amount:	\$18,568.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$2,656.00
COE Rebate Amount:	\$171.00
Total Rebate Amount:	\$18,739.00

The information contained herein is correct as at 20 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2018 09:59
Date Of Accident	07/06/2018 13:45
Exact Location Of Accident	TAN QUEE LAN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN5056C
Insured/Policyholder	
Name Of Registered Owner	JEGACY TRANSPORT SERVICES
Co Reg No	51085500L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97574743
Alternative Phone No	OFFICE-97574743

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4L AT SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093864320
Cover Note Number	30/08/2017 - 29/08/2018

Driver

Name of Driver	JOHN GOH
NRIC No	S1110060J
Date Of Birth	16/06/1955
Occupation	OUTDOOR
Date Of Driving Pass	22/01/1975
Driving Experience	43 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97574743
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 47 MARINE CRESCENT #05-80
Postcode	440047
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - PRIVATE HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

BASED ON THE STATED DATE AND TIME, I WAS DRIVING STRAIGHT ALONG THE SAID LOCATON. SUDDENLY I FELT AN IMPACT AND NOTICED A VEHICLE B (SBR3688C) COLLIDED ONTO THE REAR LEFT PORTION OF MY VEHICLE. THERE WERE NO INJURIES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBR3688C
Vehicle Make/Model/Colour	VEHICLE B
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN YONG KWEE
NRIC/Passport Number	S1154710I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:


[Signature]



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIM Report.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

Reporting Only
Claim OD
<input checked="" type="checkbox"/> Claim TP
Claim OD/TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Handwritten signature]



HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 51085500L

JEGACY TRANSPORT SERVICES
BLK 304 TAMPINES STREET 32
#08-70
SINGAPORE 520304

TEL : FAX :
PH : 97574743
ATTN :

ESTIMATE BILL

Number : EB00004852
Date : 08/06/2018
Case No : AD00009773
Vehicle No : SKN5056C
Chassis : JHMRB38509C200130
Year of Mfr : 2008
Policy No : 5093864320
Model : HONDA ODYSSEY
2.4L AT SR

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RAER RIM LH	1.0	842.90	0	842.90
2	ROCKER PANEL LH	1.0	296.90	0	296.90
List Price - Parts Sub Total					1,139.80
3	REAR TYRE LH	1.0	400.00	0	400.00
Special Nett Price - Parts Sub Total					400.00
Parts Total					1,539.80
4	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	300.00	0	300.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
Labour 1 Sub Total					600.00
SINGAPORE DOLLARS : TWO THOUSAND TWO HUNDRED EIGHTY-NINE AND CENTS FIFTY-NINE ONLY					
Less Excess					0.00
SUBTOTAL					2,139.80
GST 7.00%					149.79
TOTAL					2,289.59

Date of accident : 07/06/2018 01:45 PM. Place : TAN QUEE LAN STREET

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CUSTOMER SIGNATURE

Signature:
Date:

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011090/UQBN2

Date: 18/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80375756QMY
Claimant Vehicle No :	SKN5056C	Insured Vehicle No :	SBR3688C
Date of Loss:	07/06/2018	Nature of Claim:	TP
		Claim No:	560740

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN5056C	Engine No:	K24Z21300134
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRB38509C200130
Reg. Date:	12/02/2009 (Man. Year: 2008)	Odometer:	214508 km
Colour:	Black		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,539.80	0.00	1,539.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,139.80	400.00	1,739.80	81.31
+ GST 7.00/7.00% (S\$)	149.79	28.00	121.79	81.31
Nett Amount (S\$)	2,289.59	428.00	1,861.59	81.31

INSPECTION

Date of Assignment: 19/06/2018

Date Inspected: 20/06/2018 Inspected At:

Hock Wah Motor Workshop Pte Ltd -
bedok (HQ)
Blk 3011 Bedok North Avenue 4, #01-
2008/2010/2012/2014
Singapore 489977

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN5056C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIM LH	Repair	842.90 FS	*- FS
2	1		*ROCKER PANEL LH	Repair	296.90 FS	*- FS
3	1		*REAR TYRE LH	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,539.80	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS INCLUDING ALIGNMENT	New	300.00	100.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	300.00	300.00
Gross Labour Cost (S\$)			600.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >