

ASS. REC. BY:

REF:

CS3/LCR 18011093/R124d3b2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Maiman

Chin lee Ying

of

LCR

Date/Time:

18/6/18 @ 4:52 pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 6853 K

Insured:

SLL 134 B

at Workshop m/s

G speed Autowerkz

Tel:

8533 2934

of

68 kaki Bkt Ave 6 # 02-05

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/06/2018

CA / REV / REP. / REV 24 HRS

1up?

22062018

H.O.D. Endorsement:

Date/Time:

9:58am @ 18/6/18

Person Contacted:

sun sun

Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate	
	PC 6853 K - NA / AWA 18010669/r3	DOA: 11/06/2018
	SLL 134 B - CS / CTI 18010825 / Vrd3	DOA: 11/06/2018

Person

REF: LCR

06312

ASSIGNMENT

From:

Date:

22/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PC 6853K

at Workshop m/s

G Speed Autowerkz

of

68 Kaki Bk Ave 6 # 02-05

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

24

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PC 6853K

Yr Regn:

2018 7AM

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HAZE 306LA

C.C.

2982

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

3012

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 2230033252

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/80R15

R:

4-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/06/18

D.O.I.

22/06/18

Survey held at

6 SPEED Autowerkz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/7/18 Submit DAR Report

Date/Time File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS: SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

180

20

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLL434B AND PC6853K ON 11/06/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: Monday, 18 June, 2018 4:52:35 PM
Attachments:  SLL434B--PRI.TIF  surveyor list.jpg

Hi LKK,

Kindy assist to survey, vehicle in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0631Z
Vehicle Details	
Vehicle No.:	PC6853K
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER 3.0 GL AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2733873
Chassis No.:	KDH2230033292
Maximum Power Output:	-
Open Market Value:	\$42,327.00
Original Registration Date:	10 Jan 2018
First Registration Date:	10 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$2,117.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jan 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,813.00
COE Rebate Amount:	\$33,109.00
Total Rebate Amount:	\$33,109.00

The information contained herein is correct as at 05 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2018 12:20
Date Of Accident	11/06/2018 10:30
Exact Location Of Accident	YIO CHU KANG TWDS LENTOR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC6853K
Insured/Policyholder	
Name Of Registered Owner	BABY HOLIDAY EVENTS PTE LTD
Co Reg No	201120631Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81180403
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVBPSB0005781800
Cover Note Number	
Driver	
Name of Driver	SENTHEEL SELVERAJOO
NRIC No	S8362643G
Date Of Birth	18/01/1983
Occupation	OUTDOOR
Date Of Driving Pass	09/01/2014
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81180403
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 505B YISHUN ST 51
#13-26
Postcode 762505
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : VIGNESWARI DHAVE JOHN DAS
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: FRONT ONLY
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLL434B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LOW KIAT SENG
NRIC/Passport Number S8701209C
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBF386G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver WONG KOON WAH
NRIC/Passport Number S1853873C
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SENTHEEL SELVERAJOO
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? PC6853K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name VIGNESWARI DHAVE JOHN DAS
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? PC6853K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - (d) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (e) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (f) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (g) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the Policyholder)



Reporting Centre Personnel's Signature

12/06/18

SKETCH PLAN



A = PC 6853K
B = SL 434B
C = GRF 386G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Yio Chu Kang towards to ventor. As I was stationary at traffic light Junction due to red light. During the stationary period, I heard a sound and suddenly I felt an impact hit on my right portion vehicle B hit on my rear boot.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Date & Time:

(If driver is not the policyholder)

Date & Time:



Name:
NRIC/FIN No.:

12/06/18



VOCATIONAL LICENCE

Licence No : S8362843G

Name : SENTHEEL SELVERAJOO



Card Issue Date : 31/08/2017

Please visit www.lta.gov.sg to check the status of this vocational licence

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
03	BUS VL	31/08/2017





Licence Number
 Name

S8362643G
SENTHEEL SELVERAJOO

Birth Date: 18 Jan 1983
 Issue Date: 09 Jan 2014

002263701E



YOU ARE AUTHORISED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)
 Class 3

Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 250kg

EFFECTIVE DATE
 09 Jan 2014

NP 428A

Licence No: S8362643G



COPY 1

THE SCHEDULE

Agency	B280SD7	Class of Policy	COMMERCIAL VEHICLE (BUS)	Policy Number BVBPSE0005761800
Account	B280SD7	Issued on 11/01/2018 in SINGAPORE BRANCH		
Client	0870785	Acceptance Date	10/01/2018		

Period of Insurance from 10/01/2018 to 09/01/2019, both dates inclusive

Insured's Name....	BABY HOLIDAY EVENTS PTE LTD
Address..	83 SYED ALWI ROAD ARIANKA HOTEL SINGAPORE 207662

Business/Occupn... LIMO SERVICES

Premium	BASIC ANNUAL PREMIUM.....	SGD1,947.65		
	Total Annual Premium	SGD1,947.65	Premium Due	SGD1,947.65
			Premium GST	SGD136.34
			Total Due	SGD2,083.99

Risk No. 001	COMMERCIAL VEHICLE (BUS)		
1. Registration	PC 6853 K	Make/Model ..	TOYOTA HIACE HIROOF AUTO
Type of Cover	Comprehensive	Body Type ...	CORCH
Engine No. ..	1KD2713873	No. of seats	14
Chassis No. ..	KDH2230032283	Capacity cc's	2982
Hire Purchase Owner ..	Daimler Financial Services Africa/Asia Pacific Ltd	Yr of Manuf/Regn	2017/2018
		Certificate Ref.	M2501 2

Estimated Value	MARKET VALUE WITH COE/EARF
Named Drivers	SENTHIL SELVERAJOO

MEMORANDUM 1

IT IS HEREBY NOTED AND AGREED, EXCESS ARE AS FOLLOWS:-

EXCESS (SECTION I) SGD2,000.00 - WITHIN SINGAPORE
EXCESS (SECTION II) SGD3,000.00 - WITHIN SINGAPORE

EXCESS (SECTION I) SGD4,000.00 - OUTSIDE SINGAPORE
EXCESS (SECTION II) SGD6,000.00 - OUTSIDE SINGAPORE

THE FOLLOWING CLAUSES AND ENDORSEMENTS APPLY TO THIS RISK:

1. EXCESS - ALL CLAIMS

RIOT & STRIKE, FLOOD, LLP, W/S 35,57,72(b), 89

MEMORANDUM 1

IT IS A CONDITION UNDER THIS POLICY THAT ALL REPAIRS TO THE MOTOR VEHICLE FOR ANY DAMAGE (OTHER THAN BREAKAGE OF GLASS IN WINDSCREEN OR OTHER WINDOW) COVERED UNDER THIS POLICY SHALL BE CARRIED OUT BY THE COMPANY'S QUALITYPLUS WORKSHOPS EXCEPT FOR BRAND NEW VEHICLE WITHIN 12 MONTHS FROM DATE OF REGISTRATION OR VEHICLE UNDER WARRANTY WHERE THE REPAIRS ARE CARRIED OUT AT THE MANUFACTURER'S APPOINTED WORKSHOP.

MEMORANDUM 2

1. IT IS HEREBY DECLARED AND AGREED THAT EXEMPTED PROVIDED UNDER ENDORSEMENT 89 IN THE POLICY IS DELETED AND REPLACED BY THE FOLLOWING:

Continued on page 2

MOTORCAR (Rear)

Vehicle No: **PC 6853 K**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT	✓	1
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	NEC	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____

Assessor: _____

[Signature]
 25/7/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2018 Edit Reg		18 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

LCRF PTE LTD, Co. Reg. No.: 201624597K

Main Claimant:

BABY HOLIDAY EVENTS PTE LTD, Co. Reg. No.: 201120631Z

Vehicle Reg. No.:

PC6853K

Claim Type:

TP / 6590673684SG

Vehicle Reg. No. (Insured):

SLE6571K

Repairer:

6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/07/2018]

Claimant's Solicitor:

CATHERINE LIM LLC - Tel: 6438 5500

[Created by adjuster]

11/06/2018 12:00 - :59

[5 Months and 1 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

0999994804 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- AIG_SG (27/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PC6853K (6590673684SG)**
[SLE6571K]
TP
BABY HOLIDAY EVENTS PTE LTD
Jun 11 2018 12:00PM
[LCRF PTE LTD]
6 Speed Autowerkz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
2	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
3	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
4	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
5	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
6	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
7	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
8	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
9	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
10	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
11	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
12	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
13	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
14	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
15	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
16	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
17	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
18	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
19	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
20	26/06/18 13:43	General View														Load JPG	<input checked="" type="checkbox"/>			
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print			
1	27/06/18 10:03	OI GIA REPORT														Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>					
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.					

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR18011093/R1Z4D3E2

Date: 25/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994804
Claimant Vehicle No : PC6853K **Insured Vehicle No :** SLE6571K
 Date of Loss: 11/06/2018 Nature of Claim: TP Claim No: 6590673684SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC6853K**
 Make & Model: TOYOTA HIACE, 3.0 D GL (A) Engine No: 1KD2733873
 Reg. Date: 10/01/2018 (Man. Year: 2017) Chassis No: KDH2230033292
 Colour: White Odometer: 30172 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/06/2018
 Date Inspected: 22/06/2018 Inspected At: 6 Speed Autowerkz Pte Ltd (HQ)
 68 KAKI BUKIT AVENUE 6, #02-05
 ARK@KB
 Singapore 417896
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REVERSE SENSOR	Cut	0.00 F	*- F
3	1		*REAR END PANEL	Repair	0.00 F	*- F
4	1		*TAILGATE	Dented	0.00 F	*- F
5	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
6	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
7	1		*TAILGATE LOCK	* Check	0.00 F	*- F
8	1		*TAILGATE RUBBER	* Check	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >