

ASS. REC. BY:

REF:

CS3/A1918011096/A24031

Special Instruction:

Surveyor
Munir

Adrian

ASSIGNMENT (Office)

From (Person)

Chin Lee Ying

of

Alq

Date/Time:

rel/6/18 @ 4:51 pm

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 9144R

Insured:

SKX 832J

at Workshop n/o:

HS Automotive

Tel:

6538 1368

of

2 Kaki Bkt Ave 2 #02-25

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

14/06/2018

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

10:01 am @ 19/6/18

Person Contacted:

Alex

Vehicle



1U1

Date/Time

Action/Instruction (X) Estimate

SJS 9144R - CC4/AXA 17013770/K/wb3q2

NA: 14/07/2017

SKX 832J - X

21/6/18

Disassembled

26/6/18

After Repair

ASS. REF. BY: Adrian Ling

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS5144R

Yr Regn: 2009 / MAR 13

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota Isis

cc 1794

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

225489

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

205/50R17

R:

205/50R17

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

12/06/13

Survey held at

H-S

Des. of Damages: ☐ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time

Action / Instruction

TP ALG PRS

27/6/18

Submit DAR Report.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Survey Fee:

Transportation:

3 + PSL 10

Photos:

Others:

TOTAL

180

20

200

Report Format:

Lump Sum / U.B.I / B

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SKX832J AND SJS9144R ON 14/06/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: Monday, 18 June, 2018 4:51:20 PM
Attachments:  Fax2A57.tif

Hi LKK,

Owner will leave vehicle tonight, please arrange survey by tomorrow.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: Monday, June 18, 2018 11:37 AM
To: Chan, Yoke Shi
Subject: ACCIDENT INVOLVING SJS9144R AND SKX832J ON 14 JUNE 2018.

Your ref: SKX832J
Our ref: JEQ/SJS9144R/HS A

Dear Yoke Shi,

We refer to your email dated 18 June 2018.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Kelvin Automotive Appraising Services;
4. Mc Coy Appraiser Pte Ltd;
5. Delta V Consultant

6. Prominent Appraisal Services Pte Ltd;
7. Advance Automotive Consultancy Pte Ltd;
8. Pal's Appraiser Pte Ltd;
9. S K Auto Consultants;
10. Oh Appraisal Services.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

HS Automotive Services

2 Kaki Bukit Ave 2

#02-25

Kaki Bukit Autohub

Singapore 417921

Tel: 6538-1368

Fax: 6538-1367

Person In charge : Mr. Alex

With Regards

Alfred Ng

Executive

On behalf of Mr Michael Yap

M/s JusEquity Law Corporation

No. 171 Chin Swee Road

#02-01/02/06 Singapore 169877

Tel : 6536 9339

Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-08 CES Centre Singapore 169877
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6387 2008, (65) 6533 2327
Fax : (65) 6253 0120 (Conveyancing) , (65) 6536 5368 (Litigation)
Email : juseq@sgnnet.com.sg Website: www.juseq.com.sg

Our Ref: JEQ/SJS9144R/HS A
Your Ref: SKX832J

18 June 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
(Claims Department)
78 Shenton Way
#08-16, AIG Building
Singapore 079120

VIA FAX
(Fax No. 6835-7416)

Dear Sir

ACCIDENT INVOLVING SJS9144R AND SKX832J ON 14.06.2018

We act for Nizam Kamarraj, the owner of vehicle no. SJS9144R.

We hereby notify you of a road traffic accident on 14/06/2018 at about 0950 hours along PIE involving our client's vehicle and vehicle registration no. SKX832J driven by your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Co. BAN SOOCHUN GRACE
92 Branksome Road
Singapore 439615
(Your Ref: SDP832G)

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

18-06-18:09:28 :
18/06/2018 15:33 FAX 87405922
18/06/2018 SAT 14:18 FAX

HUP SOON

;6536 5368

2/ 5

001

001/005

MSME18077009-01 / SME Motor Pte Ltd - Kari Sunk
ENTRY DATE & TIME: 18/06/2018 14:18
SUBMITTED BY: Farida Wan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/06/2018 14:18
Date Of Accident 14/06/2018 08:50
Exact Location Of Accident PIE TOWARDS JURONG.
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJS9144R
Name Of Registered Owner NIZAM KAMARRAJ
NRIC No 37137889C
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-91004804
Alternative Phone No OFFICE-91004804

Manufacturer TOYOTA
Model 181S

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA023817/1

Cover Note Number

Name of Driver JOOLINDA PUTRI SOPRI

NRIC No S7422858E

Date Of Birth 22/07/1974

Occupation INDOOR

Date Of Driving Pass 06/04/2008

Driving Experience 10 YEARS AND 2 MONTHS

Gender FEMALE

Mobile Number +65-98375983

Fax Number

Contact Number

Email Address NOEMAIL

18-06-18:09:28 ;

;6536 5368

3/ 5

16/06 2018 15:33 FAX 67465922

HUP SOON

0002
0027VV5

16/06 2018 SAT 14:17 FAX

Address BLK 134 PASIR RIS ST 11 #06-257
 Postcode 510134
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 2
 Passenger 1 NAME: : NIZAM KAMARRAJ
 GENDER: : MALE

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

I WAS TRAVELLING ALONG PIE TOWARDS JURONG THE CAR IN FRONT OF ME SLOW DOWN, I FOLLOW AND SLOW DOWN MY VEHICLE, OUT OF SUDDEN, I FELT AN IMPACT FRONT MY VEHICLE REAR PORTION.

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number S10X832J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver DAVID KHOO SWEE TAU
 NRIC/Passport Number S1161035G
 Contact Number 96727656
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to question policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

16/6/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre's Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG DIE TOWARDS JURONG
THE CAR IN FRONT OF ME SLOW DOWN. I FOLLOW AND
SLOW DOWN MY VEH OUT OF SUDDEN. I FELT AN
IMPACT FROM MY VEH REAR PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18011096/Az4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 19-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKX 832J	Veh. Inspected	SJS 9144R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/06/2018	Inspection Date	19/06/2018
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

[Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SJS9144R
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	ISIS 1.8LX A
Chassis No. :	ZNM100058671
Propellant :	Petrol
Engine No. :	1ZZ3179045
Engine Capacity :	1794 cc
Maximum Power Output :	97.0 kW (130 bhp)
Maximum Laden Weight :	1785 kg
Unladen Weight :	1400 kg
Year Of Manufacture :	2008
Original Registration Date :	13 Mar 2009
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$7,589.00
COE Expiry Date :	12 Mar 2019
Road Tax Expiry Date :	12 Mar 2019
PARF Eligibility Expiry Date :	12 Mar 2019
Inspection Due Date :	12 Mar 2020
Intended Transfer Date :	26 Jun 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC		6
1147	992976	Rear Bumper Bracket	BT		2
1148	993068	Rear Bumper Side Retainer	DS		2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM		
1159	993327	Rear End Panel	RUC		
1160	993339	Rear End Panel Top Garnish	CRA		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	Lower CRA		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BUC		
1182	991328	Tailgate Emblem	NEC		
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC		
1196	994607	Tailgate Glass Sealant			
1197	994639	Tailgate Lock	BT		
1198	994651	Tailgate Rubber	DD		
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA		

Vehicle No: **SJS 9144R**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover Bracket	DS		
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Signature
27/6/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jun 2018 Edit Reg		18 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BAN SOOI CHUN GRACE , ID: S2156824D									
Main Claimant: NIZAM KAMARRAJ , ID: S7137689C									
Vehicle Reg. No.: SJS9144R		Date of Loss: 14/06/2018 09:00 - :59 [111 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3626835001SG		Policy/Cover Note No.: 2100440388							
Vehicle Reg. No. (Insured): SKX832J		Policy No. (Claimant):							
		Excess:							
Repairer: Hs Automotive (HQ) autohub, 408070 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/06/2018]									
Claimant's Solicitor: JusEquity Law Corporation - Tel: 65369339									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (22/06/2018): NO OI GIA REPORT - AIG_SG (22/06/2018): No OI GIA Report - AIG_SG (22/06/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS9144R (3626835001SG)
[SKX832J]
TP
NIZAM KAMARRAJ
Jun 14 2018 9:00AM
[BAN SOOI CHUN GRACE]
Hs Automotive

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/06/18 21:00	General View		 Load JPG	☒		
2	20/06/18 21:00	General View		 Load JPG	☒		
3	20/06/18 21:00	General View		 Load JPG	☒		
4	20/06/18 21:00	General View		 Load JPG	☒		
5	20/06/18 21:00	General View		 Load JPG	☒		
6	20/06/18 21:00	General View		 Load JPG	☒		
7	20/06/18 21:00	General View		 Load JPG	☒		
8	20/06/18 21:00	General View		 Load JPG	☒		
9	20/06/18 21:00	General View		 Load JPG	☒		
10	20/06/18 21:00	General View		 Load JPG	☒		
11	20/06/18 21:00	General View		 Load JPG	☒		
12	20/06/18 21:00	General View		 Load JPG	☒		
13	20/06/18 21:00	General View		 Load JPG	☒		
14	20/06/18 21:00	General View		 Load JPG	☒		
15	20/06/18 21:00	General View		 Load JPG	☒		
16	20/06/18 21:00	General View		 Load JPG	☒		
17	20/06/18 21:00	General View		 Load JPG	☒		
18	20/06/18 21:00	General View		 Load JPG	☒		
19	20/06/18 21:00	General View		 Load JPG	☒		
20	20/06/18 21:00	General View		 Load JPG	☒		
21	20/06/18 21:00	General View		 Load JPG	☒		
22	20/06/18 21:00	General View		 Load JPG	☒		
23	20/06/18 21:00	General View		 Load JPG	☒		
24	20/06/18 21:00	General View		 Load JPG	☒		
25	20/06/18 21:00	General View		 Load JPG	☒		
26	20/06/18 21:00	General View		 Load JPG	☒		
27	20/06/18 21:00	General View		 Load JPG	☒		
28	20/06/18 21:00	General View		 Load JPG	☒		
29	20/06/18 21:00	General View		 Load JPG	☒		
30	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
31	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
32	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
33	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
34	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
35	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
36	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		
37	23/06/18 11:48	Dismantled Parts		 Load JPG	☒		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
39	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
40	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
41	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
42	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
43	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
44	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
45	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
46	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
47	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
48	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
49	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
50	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
51	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
52	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
53	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
54	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
55	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
56	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
57	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
58	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
59	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
60	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
61	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
62	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
63	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
64	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
65	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
66	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
67	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
68	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
69	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
70	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
71	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
72	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
73	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
74	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
75	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
76	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
77	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
78	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
79	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
80	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
81	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
82	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
83	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
84	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
85	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
86	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
87	23/06/18 11:48	Dismantled Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
89	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
90	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
91	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
92	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
93	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
94	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
95	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
96	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
97	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
98	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
99	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
100	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
101	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
102	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
103	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
104	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
105	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
106	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
107	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
108	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
109	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
110	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
111	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
112	23/06/18 11:48	Dismantled Parts	 Load JPG	☒
113	27/06/18 18:13	Photo After Spray	 Load JPG	☒
114	27/06/18 18:13	Photo After Spray	 Load JPG	☒
115	27/06/18 18:13	Photo After Spray	 Load JPG	☒
116	27/06/18 18:13	Photo After Spray	 Load JPG	☒
117	27/06/18 18:13	Photo After Spray	 Load JPG	☒
118	27/06/18 18:13	Photo After Spray	 Load JPG	☒
119	27/06/18 18:13	Photo After Spray	 Load JPG	☒
120	27/06/18 18:13	Photo After Spray	 Load JPG	☒
121	27/06/18 18:13	Photo After Spray	 Load JPG	☒
122	27/06/18 18:13	Photo After Spray	 Load JPG	☒
123	27/06/18 18:13	Photo After Spray	 Load JPG	☒
124	27/06/18 18:13	Photo After Spray	 Load JPG	☒
125	27/06/18 18:13	Photo After Spray	 Load JPG	☒
126	27/06/18 18:13	Photo After Spray	 Load JPG	☒
127	27/06/18 18:13	Photo After Spray	 Load JPG	☒
128	27/06/18 18:13	Photo After Spray	 Load JPG	☒
129	27/06/18 18:13	Photo After Spray	 Load JPG	☒
130	27/06/18 18:13	Photo After Spray	 Load JPG	☒
131	27/06/18 18:13	Photo After Spray	 Load JPG	☒
132	27/06/18 18:13	Photo After Spray	 Load JPG	☒
133	27/06/18 18:13	Photo After Spray	 Load JPG	☒
134	27/06/18 18:13	Photo After Spray	 Load JPG	☒
135	27/06/18 18:13	Photo After Spray	 Load JPG	☒
136	27/06/18 18:13	Photo After Spray	 Load JPG	☒
137	27/06/18 18:13	Photo After Spray	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011096/AZ4D3E2

Date: 28/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100440388
 Claimant Vehicle No: SJS9144R Insured Vehicle No: SKX832J
 Date of Loss: 14/06/2018 Nature of Claim: TP Claim No: 3626835001SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS9144R
 Make & Model: TOYOTA ISIS, 1.8 (A) Engine No: 1ZZ3179045
 Reg. Date: 13/03/2009 (Man. Year: 2008) Chassis No: ZNM100058671
 Colour: White Odometer: 225489 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/06/2018
 Date Inspected: 19/06/2018 Inspected At: 2 Kaki Bukit Ave 2 #02-25
 Repairer: Hs Automotive (HQ)
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Buckled	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
8	1		*REAR LH TAILLAMP LOWER	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*TAILGATE	Buckled	0.00 F	*- F
11	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
13	1		*TAILGATE LOCK	Bent	0.00 F	*- F
14	1		*TAILGATE RUBBER	Dented	0.00 F	*- F
15	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
16	1		*SPARE TYRE BRACKET	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >