



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/6/2018

### Survey Details:

Date of loss	14-Jun-18
Date of appointment	18-Jun-18
Date of survey	18-Jun-18
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SHB 3999T
Make and Model	MERCEDES BENZ E220CDI E5
Date of registration	31/8/2012
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

### Repair details:

Initial Estimate	\$ 1,210.00
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$ -
Labour	\$ 860.00
<b>Total</b>	<b>\$ 860.00</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>

<b>Number of days for repair</b>	<b>2</b>
----------------------------------	----------



**Remarks:**

*We have not authorized repairs.*

**Mandate:**

<b>Liability(TP)</b>		<b>%</b>
Proposed repair cost	\$	
Loss of use	\$	
Loss of rental	\$	
Loss of income	\$	
LTA search fees	\$	
Others	\$	
<b>Proposed Total</b>		