

ASSIGNMENT

From:

Date:

19062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGQ 1787J

at Workshop m/s

Volkswagen

of

247 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

4.30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SGQ 1787J

Yr Regn:

2011 Sep.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Jetta

Colour:

Blue

c.c 1320

Sp.Reading

107523

A/C: Insured / Std / NI / NA

Eng/No:

T/Radio: Insured / Std / NI / NA

C/No:

www 2221623m105432

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45K17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19/6/180655

Survey held at

247 Alexandra Rd

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?