

ASS. REC. BY:

REF:

CS/FCL18011113 / Kg bml

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): WS Luene Jew of FCL Date/Time: 19062018 1238pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SIN 5212G Insured: SHA 9984Bat Workshop m/s Wei Lee Motor Tel: 64569830of Blk 9 Sin Ming Ind Est #01-32Policy No: _____ Claim No: D180011741mFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13062018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: 19062018 4:13pm Person Contacted: KarenVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SIN 5212G - X</u>
	<u>SHA 9984B - RS3 / FCL15021771 / Grbdll</u>
<u>22/6/18 @ 9.50am</u>	<u>revised to Luene by email.</u>

ASS. REC. BY:

REF: 17021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Nil

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.


D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 27 JUN 2018

Date/Time, File Pass to?



: Prel. Report

1) 22/6 10:00 AM



: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

140
50
19
209

MOTOR SURVEY ASSIGNMENT

Date	14-06-2018	Our Ref No. D18004741MFSH
Accident Date	13-06-2018	Claim Type. Third Party
Insured Vehicle	SHA9984B	Third Party Vehicle. SLN5212G
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241454)



PRI Documents



Close



PRI Header Details

Claim No	D18004741MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & WE
Workshop Name	WEI LEE MOTOR WORKS (Contact Person : KAREN SEAH)	Survey Location & Contact Details	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01- Mobile: 0 , Phone: 64569830 , Fax: 6458012 EmailId: WEILEEMOTORWORKS@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9984B	TP Vehicle No	SLN52:
PRI Recieved Date	18-06-2018 09:20:57 PM	Surveyor Appointed Date	19-06-2018 12:38:51 PM	Surveyor Accept Date	19-06-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-06-2018	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 June 2018 9:56 AM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004741MFSH/1
Attachments: CSFCI18011113Kqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLN 5212G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 19 June 2018 4:14 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004741MFSH/1

Dear Sir / madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 19 June, 2018 12:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004741MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004741MFSH

Date: 27 June 2018

Our Ref: CS/FCI18011113/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 5212G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/06/2018 at the premises of M/s WEI LI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,662.24</u> .
Revised Estimate Amount	: S\$ <u>3,150.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

[# > Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1813C

Vehicle Details

Vehicle No.: SLN5212G

Vehicle to be Exported: No

Intended De-registration Date: 25 Jun 2018

Vehicle Make: HYUNDAI

Vehicle Model: HD AVANTE 1.6 A

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: G4FC9U616966

Chassis No.: KMH DU41BR9U710474

Maximum Power Output: 89.7 kW (120 bhp)

Open Market Value: \$11,943.00

Original Registration Date: 16 Mar 2009

First Registration Date: 16 Mar 2009

Transfer Count: 2

Actual ARF Paid: \$11,943.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Mar 2019

PARF Rebate Amount: \$5,971.00

Intended COE Rebate Details

COE Expiry Date: 15 Mar 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$4,460.00

COE Rebate Amount: \$319.00

Total Rebate Amount: \$6,290.00

The information contained herein is correct as at 25 Jun 2018

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~455 3986~~ 6458 0128

Business Regn No : 269436/00J

18, June 2018

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House S 06877

Attn: motor claim dept-3rd party claim

Claiming against your insured vehicle No: SHA9984B

Accident involving vehicle No: SLN5212G/SHA9984B

DOA: 13/06/2018 AT Pasir Ris Dr 3

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SLN5212G

To supply--

Description	Qty	Amount
Rear bumper	1	491.80
Rear bumper enforcement	1	242.80
Rear bumper sponge	1	128.30
Rear bumper retainer	1	42.10
End panel	1	572.40
End panel top garnish	1	111.40
Taillamp	1	294.30
Boot weather strip	1	96.40
Total		1,979.50
Parts 20%		395.90
		1,583.60
LD		907.00

Reverse sensor

To remove damaged parts and attachments.

Repair/reshape damaged panel, dented areas.

Replace/align above parts into position.

To spray paint

Shot 220.00 2005

650.00

450.00

290360

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 3986~~ 6458 0128
Business Regn No : 269436/00J

MS First Capital Insurance Ltd

Vehicle No: SLN5212G

Supplementary Parts for vehicle No: SLN5212G

To supply—

Description	Qty	Amount
Lid	1 <i>B</i>	907.00 ✓
Lid lock	1 <i>R</i>	119.10 X
Lid-H logo	1 <i>R</i>	47.10 ✓
Lid-Avante emblem	1 <i>R</i>	52.60 ✓
Spare tyre panel	1 <i>R</i>	872.50 X
	Parts	1,998.30
	Parts less 20%	399.66
		1,598.64

To remove rear seater, speaker board, enable repair job carryout, reinstall after Job done.

160.00 *600*

To remove damaged parts.

Cut n weld damaged spare tyre panel.

Replace above parts.

550.00 *200*

To spray paint.

450.00 *200*

2758.64

5662.74



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011113/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9984B	Veh. Inspected	SLN 5212G	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004741MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U710474	Colour	METALLIC SILVER	
Odometer	214749	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	3 mm	
L/H Front Tyre	195/65 R15	MICHELIN	3 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	2 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2018	Inspection Date	22/06/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5212G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	491.80	491.80
1	REAR BUMPER ENFORCEMENT	CRACKED	242.80	242.80
1	REAR BUMPER SPONGE	CRACKED	128.30	128.30
1	REAR BUMPER RETAINER	DISTORTED	42.10	42.10
1	END PANEL	BENT	572.40	572.40
1	END PANEL TOP GARNISH	SERVICEABLE	111.40	-
1	TAILLAMP	MTG CRACKED	294.30	294.30
1	BOOT WEATHERSTRIP	SERVICEABLE	96.40	-
1	LID (ADDITIONAL)	BENT	907.00	907.00
1	LID LOCK (ADDITIONAL)	TO REPAIR SEE LABOUR	119.10	-
1	LID-H LOGO (ADDITIONAL)	NECESSARY	47.10	47.10
1	LID-AVANTE EMBLEM (ADDITIONAL)	NECESSARY	52.60	52.60
1	SPARE TYRE PANEL (ADDITIONAL)	TO REPAIR SEE LABOUR	872.50	-
	LESS 20% DISCOUNT		-795.56	-555.68
			3,182.24	2,222.72
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DAMAGED PANEL,DENTED AREAS.REPLACE/ALIGN ABOVE PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF LID LOCK.		650.00	650.00
	TO SPRAY PAINT.		450.00	450.00
	TO REMOVE REAR SEATER,SPEAKER BOARD,ENABLE REPAIR JOB CARRYOUT,REINSTALL AFTER JOB DONE.(ADDITIONAL)		160.00	60.00
	TO REMOVE DAMAGED PARTS,CUT N WELD DAMAGED SPARE TYRE PANEL.REPLACE ABOVE PARTS.(ADDITIONAL)		550.00	200.00

Report Ref No. CS/FCI18011113/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT. (ADDITIONAL)		450.00	200.00
			2,260.00	1,560.00
GRAND TOTAL			5,662.24	3,982.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CS/FCI18011113/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.