

INSURANCE

INS. CASE OWNER:

CC 4 /AIG1801 1114, Apb34

LKK:
IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

26/6/18

Date / Time:

26/6/18

Registered in Merimen:

14/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SFG 8168P

Name of Insured

HOY NAM LUK

Insured Tel No.

HP:

Excess Sec II :S?

D.O.A:

18/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MOHD YUSOFF BIN MARRUF

Driver Tel No.:

(V/L: YES / NO)

Claim No.

22406672454

Policy No.

200 276018

Make / Model:

TOYOTA

Place of Accident:

Open UP Tant Ro.



INSRS:
WSP:
Tel:
Liability:
RMKS:

Long
Automatic



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/8/18

UIT

5/8/18

SFG 11094

9501168P

OLD brushed TP stationary car.

13/11/18

Free press to shu pi to lue

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI:

20/8/18

After call 1st to OI

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

FINAL SETTLEMENT

Date/Time:

13/11/18

Confirm with:

Leang

Email:

Call:

Final Liability:

%

(

Agreed /

Agreed)

BOLA S/N No.:

23

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

800.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

180.00

(

60

x

3

days)

Loss of Income (LOI):

S\$

(

S

x

days)

LOR only

LOU only

LOR + LOU

LOR + L

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320 + \$20

Total:

S\$

957.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$

957.45

Name 1:

Leang Automotive

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF: CS / ALH1801114 / Arb

Special Instruction:

SUIVADY

ASSIGNMENT (Office)

From (Person):

Mufiman

Ashley Chan

of

Alh

Date/Time:

19062018 3:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIX 1109U

Insured:

STG 8168P

at Workshop m/s:

Leang Automotive

Tel:

9028 7516

of

Blk N Kaki Bukit Ave 6 #01-68

Policy No:

2100376028

Claim No:

2240681364 SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

19062018 358pm

Person Contacted:

Leang

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SIX 1109U - X

STG 8168P - X

16/8/18

Adrian Confirmed LS \$800 (Red 2095.50, 727)

16/8/18

Transfer to DS

INS. REC. BY Adrian King

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 3JX1109U Yr Regn: 2010, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tarean cc 1390

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 135452 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVG222ITZAW077942

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Ling Long

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 26/06/18

Survey held at Kerry

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP PKG.

115 \$ 800 cred \$ 2095.50 / 7277

Date/Time, File Pass to?

☐ : Preli. Report

11

☐ : Final Report

Date/Time, File Return to?

77

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

5 + RS 78

Phone

Other:

(1/18)

Report Format :

Lump Sum / LB.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18011114/Abp3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 19-06-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFG 8168P	Veh. Inspected	SJX 1109U
Policy No.	2100376028	Coverage (\$)	0.00
Claim No.	2240681364SG	Excess (\$)	0.00
Assign From	ASHLEY CHAN	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/06/2018	Inspection Date	26/06/2018
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

PA1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2018 Edit Reg		19 Jun 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Choy Nam Chiu @ Robert Choy, ID: S00476081		
Main Claimant:	-		
Vehicle Reg. No.:	SJX1109U	Date of Loss:	12/06/2018 15:00 - :59
Claim Type:	TP / 2240681364SG	Policy/Cover Note No.:	2100376028 (Comprehensive)
Vehicle Reg. No. (Insured):	SFG8168P	Policy No. (Claimant):	
		Excess:	
Repairer:	Leang Automotive - Kaki Bukit (HQ) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/06/2018]		
Claimant's Solicitor:	BONNIE KWOK LLC - Tel: 65366026		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (03/08/2018): Re: Request for OI GIA [SFG8168P; DOA: 12/06/2018]
- AIG_SG (20/06/2018): No OI GIA Report
- AIG_SG (20/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

TP A16
Vors.

SJX1109U.

Volkswagen Tauran

WVG2221T2AW077942

Rear Bumper	Repair	1154.30	x
Rear Bumper Clips	7H RH	30	x
Rear Bumper Side Holder	RH	62.80	x
Rear Bumper Lower Grinich	at	580.40	/
Rear Bumper Reflector RH	RH	68	x

Panel Beating

~~420~~ 200

Spray Painting

~~420~~ 250

To remove noise sensor

~~140~~ 50

Wiring

100x

2895.50

Labour 500

list 580.40

total 1051.38

ten 5%: 551.38

4/5: 800
020mp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Pre repair inspection request - SJX1109U VS SFG8168P (OI) DOA: 12/06/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKALITO.COM, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshene, Mithoosingh, Aashweenjeetkaur, A
Sent: Tuesday, 19 June 2018 3:46:21 PM
Attachments:  [FacilFATIF](#)

Hi,

Please refer to the enclosed request from **BONNIE KWOK LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel: +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Tuesday, June 19, 2018 3:20 PM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFG8168P AND SJX1109U ON 12/06/2018

Dear Sirs,

Our client agrees to Adrian Ling of LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have his report in due course.

Kindly request for the SJE to contact the repairers, MSLeang Automotive at 9026 6516 to make the necessary arrangements.

Regards,

BT

—

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#06-12 People's Park Centre

Singapore 058258

TEL: 6536 6026

FAX: 6536 2279

email: litigation@bonniekwok.com

GST Reg. No.: 2012035472

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

— Email Disclaimer —

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On 19 June 2018 at 14:52, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:
Without Prejudice

Your Reference : leangAuto-SJX1109U

Our Reference : SFG8168P

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair surveys as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-0)
Menara Worldwide Level 11, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 8000 | Ext 1012102

yokeshi.chen@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
[Not for service of court documents]
GST Reg No. 2012015472

Your Vehicle: SFG 8168 P
Our Vehicle: LeangAuto-SJX 1109 U

Date : 19 June 2018

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

By Fax 6835 7416 only


Dear Sirs,

ACCIDENT INVOLVING SJX 1109 U & SFG 8168 P ON 12 JUNE 2018

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle **SJX 1109 U** at M/s Leang Automotive, No. 1 Kaki Bukit Avenue 6 #01-68 Singapore 417883.

Your faithfully


BONNIE KWOK
c.c. Client

Enquire Vehicle & Owner Information (Vehicle No. SFG8168P As At 12 Jun 2018 / 15:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LEANGAUTO-SJX1109U

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S0047608J

Owner Name: CHOY NAM CHIU @ROBERT CHOY

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 7

Registered Street Name: DRAYCOTT DRIVE

Registered Unit No.: # 07 - 02

Registered Building Name: -

Registered Postal Code: 259421

Current Vehicle Details

Vehicle No.: SFG8168P

Make Description/Model: TOYOTA / ALPHARD 2.4 MOONROOF CVT

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563501 FAX: (065) 62564315

Our Ref: CC4/AIG18011114/Apb3

04 SEPT 2018

CHOY NAM CHIU
7 DRAYCOTT DRIVE
#07-02
SINGAPORE 259421

Dear Sir/Madam,

**ACCIDENT INVOLVING SFG 8168P & SJX 1109U ALONG/AT OPEN
CARPARK TANK ROAD ON 12/06/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJX 1109U against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

Date: 19.06.18

To: M/s Leang Automotive
No. 1 Kaki Bukit Avenue 6
#01-68
Singapore 417883

LETTER OF AUTHORITY & INDEMNITY

I/we SEAH GUAN YAN NRIC No./ Co Registration No.
88425419C of (address) BLK F10A PULUH404 FIELD #08-707 (S) 831170
the registered owner (or his/her/their/agent) of motor vehicle registration no. 87811670
hereby authorise M/s Leang Automotive ("the Repairer") to commence repairs to my/our
vehicle and to forward the claim for inter alia the costs of repairs to the owner/insured of the
Third Party responsible for the said accident on (date) 12-6-2018 involving motor vehicle
nos 3FG8168P along Tank Rd Parallel Open Carpark. I further authorise M/s
Leang Automotive to sign and execute all documents in my name including but not limited to
the Discharge Voucher in connection with the claim against the Third Party.

However, if the third party rejects liability for whatever reasons and/or if the claim is
reverted to my/our insurers and my/our insurers do not settle the repair costs and
disbursements under my/our own insurance policy, I/we will be fully responsible for the
repair costs and disbursements.

I also agree that if I do not fully co-operate in the Third Party claim, I will be
responsible for any losses incurred by my Repairer.

My/our vehicle is repaired by the Repairer on my/our own free will and without any
threat, inducement and/or promise.

In the event that the Repairer is compelled to enforce this undertaking, I/we agree that
I/we shall pay for the legal costs incurred by the Repairer on a solicitor and client full
indemnity basis.



Signature/ Co. Stamp

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, LEANG AUTOMOTIVE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$800.00 (Repair Cost), S\$180.00 (Loss of Use/Rental), S\$7.45 (Disbursement) for vehicle no. SJX 1109U that was damaged pursuant to the accident which occurred on 12/06/2018 (date) along TANK ROAD PARALLEL OPEN CARPARK (location) involving vehicle no/s SFG 8168P. This is pursuant to the inspection conducted on 26/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHOY NAM CHIU (the third party claimant) of vehicle no. SJX 1109U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJX 1109U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 (day) of Nov (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

LEANG AUTOMOTIVE

No.1262

Auto Bay @ Kaki Bukit 1 Kaki Bukit Ave 6 #01-68 Singapore 417883
Tel: 6909 3048 Fax: 6909 3046

Vehicle No: 85X1109U

M/s Alfa Asta Pacific Insurance Plc Ltd

Vehicle Model: VOLKSWAGEN

Date: 2-8-2018

[illegible]

E & O. E

TOTAL \$	3400
----------	------

Authorized Signature

FOR LEANG AUTOMOTIVE

Enquire Vehicle & Owner Information (Vehicle No. SFG8168P As At 12 Jun 2018 / 15:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LEANGAUTO-SJC1109U

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: 50047608J

Owner Name: CHOY NAM CHIU @ROBERT CHOY

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complex

Registered Block/House No.: 7

Registered Street Name: DRAYCOTT DRIVE

Registered Unit No.: # 07 - 02

Registered Building Name: -

Registered Postal Code: 259421

Current Vehicle Details

Vehicle No.: SFG8168P

Make Description/Model: TOYOTA / ALPHARD 2.4 MOONROOF CVT

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408863
Tel: +65 6547 0000
Fax: +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/35687/2018
Date : 13 July 2018

Tan Shu Hui, Debbie
Blk 170A Punggol Field
#08-707
Singapore 821170

Dear Sir / Madam,

**TRAFFIC ACCIDENT INVOLVING SFG8168P AND SJX1109U ALONG TANK ROAD ON
12/06/2018 AT ABOUT 1537 HRS**

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of **SFG8168P** had committed the following offences:
- (i) Careless Driving under Rule 29 of the Road Traffic Rules;
 - (ii) Failing to report an accident within 24 Hours under Section 34(2) of the Road Traffic Act Chapter 276.

Action has been initiated against the driver for the said offences.

3. If you have any clarification, you may contact the Investigation Officer, SSS Leslie Tan at office number: 6547 6144.

4. Thank you.

Yours faithfully,

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2018 Edit Reg		19 Jun 2018 00:00 Edit Adj Rpt	\$5800.00 Edit Estimates	\$5800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Choy Nam Chiu @ Robert Choy , ID: S00476083								
Main Claimant:	SEAH GUAN YAN , ID: S8425419C								
Vehicle Reg. No.:	SJX1109U	Date of Loss:	12/06/2018 15:00 - :59 [96 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2240681364SG	Policy/Cover Note No.:	2100376028 (Comprehensive)						
Vehicle Reg. No. (Insured):	SFG8168P	Policy No. (Claimant):	10789529						
		Excess:							
Repairer:	Leang Automotive - Kaki Bukit (HQ) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/06/2018]								
Claimant's Solicitor:	BONNIE KWOK LLC - Tel: 65366026								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (03/08/2018): Re: Request for OI GIA [SFG8168P; DOA: 12/06/2018] - AIG_SG (20/06/2018): No OI GIA Report - AIG_SG (20/06/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX1109U (2240681364SG)
[SFG8168P]
TP
SEAH GUAN YAN
Jun 12 2018 3:40PM
[Choy Nam Chiu @ Robert Choy]
Leang Automotive - Kaki Bukit

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page ☐	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 14:11	General View	Load JPG	☒
2	27/06/18 14:11	General View	Load JPG	☒
3	27/06/18 14:11	General View	Load JPG	☒
4	27/06/18 14:11	General View	Load JPG	☒
5	27/06/18 14:11	General View	Load JPG	☒
6	27/06/18 14:11	General View	Load JPG	☒
7	27/06/18 14:11	General View	Load JPG	☒
8	27/06/18 14:11	General View	Load JPG	☒
9	27/06/18 14:11	General View	Load JPG	☒
10	27/06/18 14:11	General View	Load JPG	☒
Documentation			1 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 14:10	TP GIA REPORT	Load PDF	
2	27/06/18 14:10	Police Report	Load PDF	
3	03/08/18 08:12	PIR.	Load PDF	
4	16/08/18 13:49	EMAIL FROM AIG DD 19062018	Load PDF	
5	16/08/18 13:49	NOTICE	Load PDF	
6	19/11/18 11:53	WORKSHOP INVOICE	Load PDF	
7	19/11/18 11:53	AUTHORISATION TO ACT FORM	Load PDF	
8	19/11/18 11:53	Release Voucher	Load PDF	
9	19/11/18 11:53	LTA SEARCH	Load PDF	
10	19/11/18 11:53	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/08/18 09:20	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SFG8168P (Insd veh)	Model:	VOLKSWAGEN TOURAN 1.4
	SJX1109U (TP veh)		TSI (A)
Date of Accident:	12/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	2,895.50
Final Repair Cost	:	\$	800.00
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	987.45

3.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Leang Automotive	:	\$ 987.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

19 Nov

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18011114/APB3

Date: 19/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100376028
Claimant Vehicle No : SJX1109U **Insured Vehicle No :** SFG8168P
 Date of Loss: 12/06/2018 Nature of Claim: TP Claim No: 2240681364SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX1109U**
 Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A) Engine No: LTA1401454
 Reg. Date: 14/05/2010 (Man. Year: 2010) Chassis No: WVGZZZ1TZAW077942
 Colour: Grey Odometer: 139452 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Linglong 6 mm Rear Left Side: Linglong 6 mm
 Front Right Side: Linglong 6 mm Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,895.50	551.38	1,344.12	70.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	500.00	500.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,895.50	1,051.38	1,844.12	63.69
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	2,895.50	800.00	2,095.50	72.37
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		987.45		

INSPECTION

Date of Assignment: 19/06/2018
 Date Inspected: 26/06/2018 Inspected At: Leang Automotive - Kaki Bukit (HQ)
 AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT
 AVE 6 #01-68
 Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,154.30 F	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	30.00 F	*- FL
3	1		*REAR BUMPER SIDE HOLDER RH	Not Necessary	62.80 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	580.40 F	*580.40 FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	68.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,895.50	580.40
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	29.02
Total Parts (\$\$)	1,895.50	551.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	400.00	250.00
3	TO REMOVE REVERSE SENSOR	New	100.00	50.00
4	WIRING	New	100.00	0.00
Gross Labour Cost (S\$)			1,000.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >