

ASS. REC. BY:

REF: CS/ASM1801134/Tiqd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yvonne Ang

of

ASM(CAXA)

Date/Time:

19/06/2018

Estimated Cost:

Bill to:

TP/AWS/TP RES / OD RES / EVA / INV / MV 7 CS

To Inspect Vehicle No:

SKG 9172K

Insured:

at Workshop m/s

Ethoz

Tel:

88228339

of

30 Bkt Batak Crescent

Policy No:

Claim No:

38M00KZY

Sum Insured:

Excess:

₹ 400.00

Make of Veh:

(Client's Record)

D.O.A.

16/06/2018

CA /

REV /

REP. /

REV 24 HRS

20/06/2018

H.O.D. Endorsement:

Date/Time:

6:00pm @ 19/6/18

Person Contacted:

Lee Chen Sin

Vehicle

OUT

Date/Time

Action/Instruction

Estimate

SKG 9172K - X

21/6/18 @

2:28pm revert to Yvonne Ang via Smart Claim.

25/6/18 @

11:26am Yvonne Ang informed C/A via Smart Claim.

25/6/18 @

11:57am informed Mr Lee C/A & EX = \$ 400 by email.

24/7/18 @

12:07pm confirmed with Mr Lee final fig \$ 5864, 5 days by email.

CRed \$ 3098, 35%

REF: ASM(AXA)

ASSIGNMENT

From: _____ Date: 20/06/2018
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKG 9172 K
 at Workshop m/s: EThoz
 of: 30 Bkt Batok Crescent
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKG9172K Yr Regn: 2012 / out.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz C180 C.C. 1595
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 119970 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD20403124774244
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$73K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

N/S	O/S

Tyre Size: F: 225/45K17 R: -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 20/6/18
 Survey held at EThoz B/B
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Frt O/S

Date: _____ Person Contacted: Lee
 Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

RECEIVED 24 JUL 2018

Date/Time. File Pass to? : Prel. Report
 11/24/7 *Apriat* : Final Report
 Date/Time. File Return to?
 Report Format: Smart Claim
 Lump Sum / I.B.I. (\$) 5864

Days Of Repair: 5
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$) Interview (\$) Tech Invs (\$) Weekend (\$)
 Survey Fee: 200
 Transportation: _____
) S + RS. SI
) Photos
) Others
 TOTAL 200

◀ Service Request Details

Claim

S8M00KZY

Reference

None 

Loss Date

June 16, 2018

Request Date

June 19, 2018

Due Date

June 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKG9172K

Make

MERCEDES

SERVICE ADDRESS

30 Bukit Batok Crescent, , , 658075

Primary Contact/Insured

LIM KIM HENG KEN
69 CHOACHU KANG LOOP, #06-06, 689672, Singapore
96545272

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions
EXCESS 400

- Messages
 - Invoices
 - History
 - Documents
 - Assessment
 - Metrics
 - Notes
-

New Message

TYPE ?

SENT 6/19/18 5:39 PM

FROM ANG Yvonne

SUBJECT Repairer

BODY Ethoz (Bt Batok)



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 24 July 2018 12:07 PM
To: 'Lee Chen Sin'; Taufikh (LKKAuto); SUR
Subject: RE: REMINDER 1 : FINALIZATION REPORT OF SKG-9172-K MERCEDES C180 (OD) (AXA)

Dear Mr Lee,

WITHOUT PREJUDISE

Confirm final fig \$5,864.00 before excess \$400.00 & GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Tuesday, 24 July 2018 8:26 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: REMINDER 1 : FINALIZATION REPORT OF SKG-9172-K MERCEDES C180 (OD)(AXA)

Hi Taufikh,

Kindly confirm finalize amount.

Thank you.

Best Regards,
Chen Sin

From: Lee Chen Sin
Sent: Wednesday, July 04, 2018 6:50 PM
To: 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>; "SUR" <sur@lkkauto.com>
Subject: FINALIZATION REPORT OF SKG-9172-K MERCEDES C180 (OD)(AXA)

Hi Taufikh,

Attached are the finalization report, supplier invoice, check item photo, supplementary item photo and photo before paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 5,864.00 (Part By Part)
Repair days : 5
Excess : \$400.00

Remark :

1. Front Grille Logo and Front Bumper Towing Cover – Reuse.

Kindly revert.



SUPPLEMENTARY LIST OF VEHICLE SKG 9172K UPLOADED

Type

📍 Question

Message

Dear Yvonne, we have received supplementary of \$166.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 June 2018 11:57 AM
To: 'Lee Chen Sin'
Cc: Jackson Teo Ban Chye; SUR
Subject: RE: SKG9172K MERCEDES C180 (OD)(AXA) - REVERT AUTHORIZE REPAIR

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKG 9172K (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]
Sent: Monday, 25 June 2018 10:52 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: Jackson Teo Ban Chye <jackson.teo@ethozgroup.com>; SUR <sur@lkkauto.com>
Subject: RE: SKG9172K MERCEDES C180 (OD)(AXA) - REVERT AUTHORIZE REPAIR

Hi Denise,

Message noted.

Thank you.

Best Regards,
Chen Sin

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Monday, June 25, 2018 10:51 AM
To: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>; SUR <sur@lkkauto.com>
Subject: RE: SKG9172K MERCEDES C180 (OD)(AXA) - REVERT AUTHORIZE REPAIR

Dear Chen Sin,

Pending authorization from AXA, I've given a chaser to AXA.

Model
C180 BLUE EFFICIENCY

Service Address

30 Bukit Batok Crescent, , , 658075

Primary Contact/Insured

LIM KIM HENG KEN
69 CHOA CHU KANG LOOP, #06-06, 689672, Singapore
96545272

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions
EXCESS 400

- Messages
 - Invoices
 - History
 - Documents
 - Assessment
 - Metrics
 - Notes
-

New Message

TYPE ?

SENT 6/25/18 11:26 AM

FROM ANG Yvonne

SUBJECT **Authorized**

BODY Please proceed to authorize repair



TYPE ?

SENT 6/25/18 10:45 AM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)



IA OF VEHICLE SKG 9172K UPLOADED

Type

🔔 Question

Message

Dear Yvonne, please be informed that the IA of vehicle SKG 9172K uploaded. Kindly advise on the authorisation. - Shiau Chan

Reply



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/06/18

Survey Details:

Date of loss	16-Jun-18
Date of appointment	19-Jun-18
Date of survey	20-Jun-18
Location of survey	ETHOZ (BT BATOK)

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKG 9172K
Make and Model	MERCEDES BENZ C180 BLUEEFFICIENCY
Date of registration	22/10/2012
Excess	\$ 400.00
Market Value	\$ 73,000.00
Parf Rebate	\$ 46,292.00
Nett Loss	\$ 26,708.00

Repair details:

Initial Estimate	\$ 8,796.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,078.00
Check items (estimate)	\$ 1,751.00
Labour	\$ 1,235.00
Total	\$ 7,064.00
Lump Sum(if applicable)	\$

Number of days for repair	<u>6</u>
---------------------------	----------



Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE
HAVE NOT AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8810I
Vehicle Details	
Vehicle No.:	SKG9172K
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 BLUEEFFICIENCY
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	27491030018562
Chassis No.:	WDD2040312A774244
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$30,160.00
Original Registration Date:	22 Oct 2012
First Registration Date:	22 Oct 2012
Transfer Count:	2
Actual ARF Paid:	\$30,160.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Oct 2022
PARF Rebate Amount:	\$21,112.00
Intended COE Rebate Details	
COE Expiry Date:	21 Oct 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$58,001.00
COE Rebate Amount:	\$25,180.00
Total Rebate Amount:	\$46,292.00

The information contained herein is correct as at 18 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 12:42
Date Of Accident	16/06/2018 20:20
Exact Location Of Accident	CHOA CHU KANG LOOP RIGHT TURN TWD NORTHVALE CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG9172K
Insured/Policyholder	
Name Of Registered Owner	LIM KIM HENG KEN
NRIC No	S7418810I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96545272
Alternative Phone No	OTHERS-96545272

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180-1.8 BLUE EFFICIENCY (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA004198/1
Cover Note Number	

Driver

Name of Driver	LIM KIM HENG KEN
NRIC No	S7418810I
Date Of Birth	16/06/1974
Occupation	INDOOR
Date Of Driving Pass	03/12/2001
Driving Experience	16 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96545272
Fax Number	
Contact Number	OTHERS-96545272
Email Address	NOEMAIL

Address	69 CHOA CJU KANG LOOP #06-06
Postcode	689672
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TRACY TAN GENDER: : FEMALE
Passenger 2	NAME: : SAMUEL LIM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 116 TECK WHYE LANE , POSTCODE: 680116 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7629999 - FAX NO: 67636615
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO ATTACH POLICE REPORT NO.T20180616/2124.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG9417L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	CHERYL CHAI
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHERYL CHAI

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBG9417L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



18/6/18

Policyholder's Signature
Date & Time:


12:58

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I wish to add in that there was construction work at the divider, with limited visibility, I was ~~approaching~~ approaching the entrance with care, but the motorcycle was approaching at a high speed. So even though I braked immediately, the motorcyclist still collided into the front head light.

[Signature]

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

	- Reporting Only
✓	- Claim OD
	- Claim TP
	- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

[Signature] 18/6/18
 Policyholder's signature 17:58
 Date & Time

.....
 Driver's Signature
 (if driver not the policyholder)
 Date & Time

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.



**SINGAPORE
POLICE FORCE**



T/20180616/2124

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

2 of 3

Report No. T/20180616/2124

CONTINUATION OF REPORT

Brief Details.

On 16/06/2018 at about 2020 hrs, I was driving my vehicle bearing plate number SKG9172K along Choa Chu Kang Loop. As I was making a right turn into Northvale condominium, a motorcycle bearing plate number FBG9417L who was approaching from the opposite direction collided to my vehicle. Due to the collision, my right headlight and front right bumper was damaged (scratches and dents). The motorcyclist was subsequently conveyed by ambulance. I was unable to get further particulars of the motorcyclist. I wish to state that there are CCTV cameras facing the road where the accident happened.



**SINGAPORE
POLICE FORCE**



T/20180616/2124

3 of 3

Report No. T/20180616/2124

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: SN 120 J/ Sgt 2 ASRAF ZULKARNAIN BIN 'AZIMI Signature: 	Signature Of Informant: 
Signature Of Interpreter: Singapore Police Force Not applicable	Date/Time: 16/06/2018 21:28
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI Contact No.: 65476904	Classification Of Case:

Authentication Stamp
NP168



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 00772

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1959 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	LIM KIM HENG KEN	Certificate number	GA004198 / 1
Cover	Comprehensive	Chassis number	WDD2040312A774244
Plan name	Flexi	Engine number	27491030G18562
NCD applicable	50%		
Vehicle registration number	SKG9172K		
Period of Insurance	from 07/11/2017 to 06/11/2018 (both dates inclusive)		
Finance loan company	CENTURY TOKYO LEASING (S) PTE LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any Named Driver as stated in the Policy
 - 1. TAN MENG YEN TRACY
- (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 400.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5 000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2 500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period falling which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S74188101**
 Name: **LIM KIM HENG (LIN JINXING)**
 Birth Date: **16 Jun 1974**
 Issue Date: **29 Dec 2003**

001065940D




REPUBLIC OF SINGAPORE
 IDENTITY CARD NO: **S74188101**



Name: **LIM KIM HENG KEN**

Race: **林金兴**

Race: **CHINESE**

Date of birth: **16-06-1974** Sex: **M**

Country of birth: **SINGAPORE**

S74188101

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	03 Dec 2001

Licence No: **S74188101**



NP 428A



3658843



NRIC No: **S74188101**

V304210

Date of issue: **05-01-2005**

69 CHOA CHU KANG LOOP #06-06
 SINGAPORE 689672

NRIC No: **S74188101** Date: **14/05/2011** No: **6772684**

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 19/06/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM KIM HENG KEN
: AXA INSURANCE PTE LTD
Certificate No : GA004198/1 Accident Date : 16/06/2018
Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BONNET	1,100.00	bt ✓
1	FRONT BONNET LOGO	49.00	net ✓
10	FRONT BONNET INSULATOR CLIP	38.00	net ✓
1	FRONT BONNET STOPPER (WITH SPRING) LH	12.00	? ✓ bt
1	FRONT BONNET STOPPER (WITH SPRING) RH	12.00	? ✓ bt
1	A PILLAR RH		R
1	FRONT FENDER RH	550.00	bt ✓
1	FRONT FENDER CHROME MOULDING RH	23.00	net ✓
1	FRONT FENDER INNER SHIELD RH (FRONT)	76.00	nn ✓

RESTORE

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT FENDER INNER SHIELD RH (REAR)	76.00	X ny
10	FRONT FENDER INNER SHIELD CLIP	30.00	X ny
1	HEADLAMP RH	600.00	ny
1	HEADLAMP PANEL RH	142.00	ny ✓ bl ✓
1	FRONT GRILLE	380.00	ny
1	FRONT GRILLE LOGO	71.00	ny ✓ ny
1	FRONT BUMPER	730.00	ny ✓
10	FRONT BUMPER CLIP	30.00	ny
1	FRONT BUMPER SIDE BRACKET LH	20.00	X ny
1	FRONT BUMPER SIDE BRACKET RH	20.00	ny

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER TOWING COVER	30.00	de ✓ P mh
1	FRONT NUMBER PLATE BASE	77.00	ms ✓
1	FOG LAMP COVER RH (LED TYPE)	60.00	ms ✓
1	FOG LAMP RH (LED TYPE)	145.00	am ✓
1	FRONT BUMPER CHROME MOULDING LH	50.00	ms ✓
1	FRONT BUMPER CHROME MOULDING RH	50.00	ms ✓
1	FRONT BUMPER LOWER GRILLE	61.00	? ✓ de
1	FRONT BUMPER FOAM	58.00	? ✓ de
1	FRONT BUMPER REINFORCEMENT	175.00	? ✓ BT
1	FRONT BUMPER REINFORCEMENT ARM RH	154.00	? ✓ mh

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SUPPORT PANEL (TOP)	76.00	Pi x hm
1	SUPPORT PANEL TOP GARNISH	53.00	26 } de
1	RADIATOR AIR GUIDE (TOP)	33.00	? } x
1	RADIATOR AIR GUIDE (BOTTOM)	95.00	} x
1	CONDENSER	700.00	} x
1	RADIATOR	730.00	x } x
1	INTERCOOLER	600.00	x } x
	Sub Total	7106.00	
	Add 0% On Parts	0.00	
	<u>Special Nett Item</u>		

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT NUMBER PLATE	35.00	<i>mis</i>
1	RADIATOR COOLANT	30.00	<i>pan</i>
20	RIVET	40.00	<i>na</i>
	Sub Total	105.00	
Labour & Misc			
	LABOUR TO CARRY OUT FRONT REPAIR	700.00	<i>600.</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	<i>✓</i>
	TO SPRAY PAINTING ON FRONT AFFECTED AREA	700.00	<i>600</i>
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	150.00	<i>100? photo & nm</i>

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1585.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Remarks:

SUB TOTAL 8,796.00
GST 7.0 % 615.72
TOTAL 9,411.72

8962

Surveyor's name: Tanpin 97495749

Principal's name: LIM KIM HENG KEN

Survey Date & Time: 20/6/2018 1645
 Ex: \$400

*Not Authorise Resurvey before paint
 5-6 days
 sw@lkkauto.com*

20/6/18

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 04/07/2018
To : AXA INSURANCE PTE LTD

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : LIM KIM HENG KEN
: AXA INSURANCE PTE LTD
Certificate No : GA004198/1 Accident Date : 16/06/2018
Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 400.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	FRONT BUMPER LOWER COVER	99.00	<i>lcy de</i>
1	FRONT BUMPER CENTRE BRACKET	53.00	<i>lcy de</i>
1	HEADLAMP PANEL STOPPER	14.00	<i>lcy de</i>
	Sub Total	166.00	
	Add 0% On Parts	0.00	

Remarks:

SUB TOTAL 166.00
GST 7.0 % 11.62
TOTAL 177.62

Surveyor's name: _____

Principal's name: LIM KIM HENG KEN

Survey Date & Time: _____

PAGE :

FINALIZATION REPORT

PLEASE ARRANGE TO SURVEY VEHICLE AT 30 BUKIT BATOK CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 19/06/2018
To : AXA INSURANCE PTE LTD
Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
: AXA INSURANCE PTE LTD
Certificate No : GA004198/1 Accident Date : 16/06/2018
Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BONNET	1,100.00	ht ✓
1	FRONT BONNET LOGO	49.00	net ✓
10	FRONT BONNET INSULATOR CLIP	38.00	net ✓
1	FRONT BONNET STOPPER (WITH SPRING) LH	12.00	? 1784
1	FRONT BONNET STOPPER (WITH SPRING) RH	12.00	? CHECK ITEM
1	A PILLAR RH		RESTORE
1	FRONT FENDER RH	550.00	ht ✓
1	FRONT FENDER CHROME MOULDING RH	23.00	net ✓
1	FRONT FENDER INNER SHIELD RH (FRONT)	26.00	X

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1
 Vehicle No : SKG-9172-K
 Accident Date : 16/06/2018
 Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1
 Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT FENDER INNER SHIELD RH (REAR)	76.00	X
10	FRONT FENDER INNER SHIELD CLIP	30.00	X
1	HEADLAMP RH	600.00	OK
1	HEADLAMP PANEL RH <i>CHECK ITEM</i>	142.00	OK
1	FRONT GRILLE	380.00	OK
1	FRONT GRILLE LOGO (REUSE)	71.00	OK
1	FRONT BUMPER	730.00	OK
10	FRONT BUMPER CLIP	30.00	OK
1	FRONT BUMPER SIDE BRACKET LH	20.00	X
1	FRONT BUMPER SIDE BRACKET RH	20.00	OK

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER TOWING COVER (REUSE)	30.00	le ✓
1	FRONT NUMBER PLATE BASE	77.00	ms ✓
1	FOG LAMP COVER RH (LED TYPE)	60.00	ms ✓
1	FOG LAMP RH (LED TYPE)	145.00	cm ✓
1	FRONT BUMPER CHROME MOULDING LH	50.00	ms ✓
1	FRONT BUMPER CHROME MOULDING RH	50.00	ms ✓
1	FRONT BUMPER LOWER GRILLE	61.00	? 6/6
1	FRONT BUMPER FOAM	58.00	? } check item
1	FRONT BUMPER REINFORCEMENT	175.00	? }
1	FRONT BUMPER REINFORCEMENT ARM RH	154.00	? }

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1
 Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SUPPORT PANEL (TOP)	76.00 ?	
1	SUPPORT PANEL TOP GARNISH - Check Item	52.00 ?	\$26.00
1	RADIATOR AIR GUIDE (TOP)	33.00 ?	
1	RADIATOR AIR GUIDE (BOTTOM)	95.00 ?	192
1	CONDENSER	700.00 ?	
1	RADIATOR	730.00 ✓	
1	INTERCOOLER	600.00 ✗	
	Sub Total	7106.00	\$4554.00
	Add 0% On Parts	0.00	
	Special Nett Item		

SUPPLEMENTARY Item :

- 1) FRONT BUMPER LOWER COVER - \$ 99.00 LH
- 2) FRONT BUMPER CENTRE BRACKET - \$ 53.00 LH
- 3) HEADLAMP PANEL STOPPER - \$ 14.00 LH

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1
 Vehicle No : SKG-9172-K
 Accident Date : 16/06/2018
 Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1
 Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT NUMBER PLATE	35.00	ris ✓
1	RADIATOR COOLANT	30.00	7
20	RIVET	40.00	na ✓
	Sub Total	105.00	#75.00
Labour & Misc			
	LABOUR TO CARRY OUT FRONT REPAIR	700.00	600.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	✓
	TO SPRAY PAINTING ON FRONT AFFECTED AREA	700.00	600
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	150.00	100? plus

Date : 19/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LIM KIM HENG KEN
 : AXA INSURANCE PTE LTD
 Certificate No : GA004198/1 Accident Date : 16/06/2018
 Vehicle No : SKG-9172-K Make & Model : MERCEDES BENZ C 180 BLUEEFFICIENCY 1
 Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Sub Total		1585.00	1235.00

PART : # 4554.00
 S/N : # 75.00
 LABOUR : # 1235.00

 # 5864.00

COR : # 5,864.00 (PART BY PART)
 5 DAYS REPAIR
 EXCESS : # 400.00

Remarks:

SUB TOTAL 8,796.00
 GST 7.0 % 615.72
 TOTAL 9,411.72

Surveyor's name: Tan Jiah 97495749
 Principal's name: LIM KIM HENG KEN
 Survey Date & Time: 20/6/2018 1645
 Ex: 400

*Not Authorise
 Resurvey before paint
 5-6 days
 sw@ethoz.com*



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
 TEL NO : 64523938 (6 LINES) FAX NO : 64527936
 A/C DEPT : 64590882
 Business Reg & GST NO : 201512120M



D180251

REPRINT

TAX INVOICE

ETHOZ PROTECT PTE LTD
 30 BUKIT BATOK CRESCENT
 SINGAPORE 658075

DELIVER TO :
 ETHOZ TAMPINES
 22 Tampines Street 92


INV NO : I180251
 DATE : 25/06/2018
 A/C NO : 0010300
 TERM : 30
 PAGE : 1 OF 1
 ISSUE : WILIAM

REMARK : PO:156874 (SKG9172K)
 WDD2040312A774244

Printed on 25/06/2018 3:39:52

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	204 817 0616MB	BONNET STAR	SS2D05	1	PCS	49.00	49.00
2	001 988 0325MB	CLIP	SS2B37	10	PC	3.80	38.00
3	204 690 3262MB	FRT FENDER PROTECTOR RH	SS2E37	1	PC	23.00	23.00
4	204 880 0023 9744	GRILL SPORT 9744	3W2D07	1	PCS	380.00	380.00
5	204 880 6147 9999	TRIM BUMPER 9999	3W2C01	1	PCS	730.00	730.00
6	124 990 0492MB	CLIP	SS2A30	10	PC	3.00	30.00
7	204 885 0916MB	STIFFENING RH	SS2C11	1	PC	20.00	20.00
8	204 817 2778MB	FRT NO PLATE COVER	SS2D07	1	PC	77.00	77.00
9	204 880 3324MB	COVER BUMPER AREA RH	SS2C18	1	PC	60.00	60.00
10	204 885 3821MB	FRT BUMPER MOULDING RH	SS2Q11	1	PCS	50.00	50.00
11	204 885 3721MB	FRT BUMPER MOULDING LH	SS2Q11	1	PCS	50.00	50.00
12	204 906 9000ULO	DAYTIME RUNNING LIGHT	SS3D09	1	PC	145.00	145.00
13	204 820 9859MB	HEADLAMP RH	3W	1	PCS	600.00	600.00
14	204 880 1418MB	FRT FENDER RH	LC	1	PCS	550.00	550.00

Dept Head	_____
Agreement No	_____
Job Card No	_____
Finance	_____
Control No	_____
Invoice No	_____
Remarks	_____
Est. finalized Amt	_____

RECEIVED BY  PICKED BY: 8514

Lee Chen Sin



SUB-TOTAL : S\$ 2,802.00
 ADD 7% GST : S\$ 196.14
 TOTAL : S\$ 2,998.14

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



TAX INVOICE

REPRINT

ETHOZ PROTECT PTE LTD
30 BUKIT BATOK CRESCENT
SINGAPORE 658075

DELIVER TO :
ETHOZ TAMPINES
22 Tampines Street 92

INV NO : I180470
DATE : 26/06/2018
A/C NO : 0010300
TERM : 30
PAGE : 1 OF 1
ISSUE : WILIAM

REMARK : PO:156874 (SKG9172K)
WDD2040312A774244

Printed on 26/06/2018 3:30:52

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	204 880 0227MB	BONNET SPRING	SS2C00	2	PCS	12.00	24.00
2	204 620 1291MB	HEAD LAMP PANEL RH	3W3A14	1	PCS	142.00	142.00
3	204 885 0624MB	FRT BUMPER CENTRE GRILL	3W3A04	1	PCS	61.00	61.00
4	204 885 3637MB	FRT BUMPER SPONG	3W3F03	1	PC	58.00	58.00
5	207 620 1600MB	FRT BUMPER MEMBER	3W2F02	1	PCS	175.00	175.00
6	204 500 1455MB	RAD TOP COVERING	3W3A02	1	PCS	26.00	26.00
7	001 997 0101MB	HOLLOW SCREW	SS2A21	1	PC	14.00	14.00
8	204 520 0723MB	UNDER COVER FF BUMPER	3W3J01	1	PCS	99.00	99.00
9	204 885 4065MB	FRT BUMPER BAISC CARRIER	3W3J08	1	PCS	53.00	53.00

Dept Head	_____
Agreement No	_____
Job Card No	_____
Finance	_____
Control No	_____
Invoice No	_____
Remarks	_____
Est. finalized Amt	_____



RECEIVED BY Lee Chen Sin PICKED BY: 8514

SUB-TOTAL : S\$ 652.00
ADD 7% GST : S\$ 45.64
TOTAL : S\$ 697.64

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST-NO : 201512120M



D180289

REPRINT

TAX INVOICE

ETHOZ PROTECT PTE LTD
30 BUKIT BATOK CRESCENT
SINGAPORE 658075

DELIVER TO :
ETHOZ TAMPINES
22 Tampines Street 92

INV NO : I180289
DATE : 25/06/2018
A/C NO : 0010300
TERM : 30
PAGE : 1 OF 1
ISSUE : WILIAM

REMARK : PO:156874 (SKG9172K)
WDD2040312A774244

Printed on 27/06/2018 3:19:57

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	204 880 0957MB	BONNET	3W	1	PCS	1,100.0	1,100.00

RECEIVED BY

Lee Chen Sin

PICKED BY:



SUB-TOTAL : S\$ 1,100.00
ADD 7% GST : S\$ 77.00
TOTAL : S\$ 1,177.00

Goods sold are not returnable except Repairs/Service at authorized workshop.