

INS. CASE OWNER:

LKK: 52580  
IDAC: 52580

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



A member of COMFORTDELGRO

Date/Time: 19.06.2018 18:11

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305177411

CUSTOMER  
NAME COMFORT TRANSPORTATION PTE LTD  
VMS 7010045  
CUSTOMER NO.  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
L. (R) 65508755 (O)  
(P)

VARs

|                                   |                                  |
|-----------------------------------|----------------------------------|
| REGN NO.<br>SHA4412T              | MILEAGE                          |
| MAKE<br>HYUNDAI                   | FUEL<br>E.....1/2.....F          |
| MODEL<br>I-40                     | DATE/TIME IN<br>19.06.2018 10:40 |
| YR OF MANU.<br>13.10.2016         | TARGET DATE                      |
| CHASSIS CODE<br>KMHLB41UMHU095346 | COMPLETION DATE/TIME:            |

(B)

SCOUNT CARD NO.

### JOB DESCRIPTION

Accident Date: 19.06.2018  
NATURE: 3P 19.06.2018

S/NO LABOR CODE DESCRIPTION

AXA - taxi Rear damage

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Signature:  
Vehicle No.: SHA4412T LARRY

Vehicle No.: SHA4412T

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA4412T

MAKE : HYUNDAI

MODEL : i40

Date: 20.06.2018

| Qty                                                                                                | Parts Description / Labour   | Type | Unit Price | Amount         |
|----------------------------------------------------------------------------------------------------|------------------------------|------|------------|----------------|
| 1                                                                                                  | Rear Bumper ✓                |      |            | \$ 603.60      |
| 1                                                                                                  | Rear Bumper Reinforcement ?  |      |            | \$ 504.35      |
| 1                                                                                                  | Rear Bumper Sponge ?         |      |            | \$ 143.40      |
| 10                                                                                                 | Rear Bumper clips @ \$2.20 ✓ |      |            | \$ 22.00       |
| 1                                                                                                  | Rear Bumper Under Cover ✓    |      |            | \$ 225.00      |
| 1                                                                                                  | Rear Bumper Stay - RH X      |      |            | \$ 180.00      |
| 1                                                                                                  | Rear Bumper Stay - LH X      |      |            | \$ 180.00      |
| 1                                                                                                  | Rear Panel X                 |      |            | \$ 592.30      |
| SUB TOTAL                                                                                          |                              |      |            | \$ 2,450.65    |
| LESS 20%                                                                                           |                              |      |            | 490.13         |
| DISCOUNTED TOTAL                                                                                   |                              |      |            | \$ 1,960.52    |
| 1                                                                                                  | Rear Bumper Reverse Sensor ✓ |      |            | \$ 135.70 Nett |
| 1                                                                                                  | Rear Bumper Rubber Mat ✓     |      |            | \$ 50.00 Nett  |
| LKK Auto Consultants hence notify the Repairer of the following:                                   |                              |      |            |                |
| • To resurvey before/after spray painting                                                          |                              |      |            |                |
| • To display damaged part(s) during resurvey                                                       |                              |      |            |                |
| • Parts prices are subject to confirmation                                                         |                              |      |            |                |
| • Third party survey is on a "Without Prejudice" basis                                             |                              |      |            |                |
| • No illegal modification(s) is allowed                                                            |                              |      |            |                |
| • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company |                              |      |            |                |
| Acknowledged by Repairer                                                                           |                              |      |            |                |
| Signature:                                                                                         |                              |      |            |                |
| Date:                                                                                              |                              |      |            |                |
| Labour Charge                                                                                      |                              |      |            |                |
| 1                                                                                                  | Panel Beating                |      |            | \$ 500.00      |
| 1                                                                                                  | Spray Painting Charge        |      |            | \$ 500.00      |
| 1                                                                                                  | Wiring Charge                |      |            | \$ 50.00 X     |
| 1                                                                                                  | R/Refix Reverse Sensor       |      |            | \$ 120.00 X    |
| 1                                                                                                  | Tuff Kote                    |      |            | \$ 80.00 X     |
| TOTAL LABOUR                                                                                       |                              |      |            | \$ 1170.00     |
| ESTIMATE TOTAL                                                                                     |                              |      |            | \$ 3,316.22    |

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No . 305177411  
Date : 21. Jun. 2018

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA4412T

Date of Accident: 19.06.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA SDD818P

2. The finalized amount shall be:

(a) Spare Parts after List discount \$866.18

(b) Labour Charges \$430.00

Total for Part-By-Part Repair Cost \$1,296.18

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

Final Lumpsum Repair cost \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 21/6/18

### For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        |                             |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    |        |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:

Final Amount Subject to Insurance Approval

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 21.06.2018

Time: 08:29:15

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305177411  
REGN NO : SHA4412T  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 13.10.2016  
DATE/TIME IN : 19.06.2018 10:40  
ACCIDENT DATE : 19.06.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                           |      |        |       |        |
|------------------------|---------------------------|------|--------|-------|--------|
| 0001 04-01-0103-0579-G | I40VC COVER ASSY-RR BUMPE | 1    | 603.60 | 20.00 | 482.88 |
| 0002 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 L | 22.00  | 20.00 | 17.60  |
| 0003 04-01-0103-0738-G | I40VC COVER-RR BUMPER LWR | 1    | 225.00 | 20.00 | 180.00 |
| 0004 09-01-9999-0068-A | HYUNDAI REVERSE SENSOR AS | 1    | 135.70 | 0.00  | 135.70 |
| 0005 04-01-0103-1150-A | I40VC PROTECTOR MAT       | 1    | 50.00  | 0.00  | 50.00  |

SUB-TOTAL : 866.18

## JOB NATURE

|             |                             |        |
|-------------|-----------------------------|--------|
| 0000 L      | PANEL BEATING               | 200.00 |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA | 200.00 |
| 0002 L      | REMOVE/REFIX REVERSE SENSOR | 30.00  |

SUB-TOTAL : 430.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 21.06.2018

Time: 08:29:15

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305177411  
REGN NO : SHA4412T  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 13.10.2016  
DATE/TIME IN : 19.06.2018 10:40  
ACCIDENT DATE : 19.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,296.18

\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE:

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE:

AUTHORISED : YES / NO