

(08/11/13) wef  
ASS. REC. BY: MARUJ

REF:

MSI G

CC3/MSH1801119/3/Uqb

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No: 555 5942C

at Workshop n/s PL

of \_\_\_\_\_

Insured:

Policy No. A2894372AUV

Claims No. 562092

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 11500

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 555 5942C

Yr Regn: 18/9, 0P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota 1515 c.c. 1794

Colour: Blu A/C: Insured / Std / NI / NA

Sp. Reading: 27.5075 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 2NM100056907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSH / PIR / SUMI /

TOYO / YOKO or h.fly

Front

Rear

R/Bal: 5 mm

R/Bal: 5 mm

L/Bal: 5 mm

L/Bal: 5 mm

D.O.A: 20/6/18

D.O.I: 20/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear & PL

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3rdh done h.c.f LTA P403 3rdh. 10+31+31+17=892

892 x 60 = Rmb / 5340 net 3097

21/6/18 2:45pm Email GIA report to Jasmine Lok & Margaret Lok.

21/7/18 confirmed L/S @ 3000 with Alvin (Red 88121.41, 73%)

22/7/18 @ 11:13pm revised to Jasmine Lok via Messenger.

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ - R\$ - SI

Photos

Others

TOTAL

200

Report Format:

MER-TP

Lump Sum / I.B.d: (\$ 3000 )

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 23 Jul 2018

**Preliminary Advice**

Insured Vehicle No	: SLE5004M	Accident Date	: 20/06/2018
TP Vehicle No	: SJJ5942C	Assignment Date	: 10/07/2018
Make	: TOYOTA ISIS	Est. Duration of Repair	: 6.00
Date of Inspection	: 20/06/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear &amp; front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,241.41
Revised Amount	:S\$	7,160.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,160.38
Lump Sum Repair	:S\$	3,000.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 21 June 2018 2:48 PM  
**To:** Jasmine Lok Kheng Kwei; Margaret Loh  
**Cc:** KKLau; SUR; Accounts (LKKAuto)  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 20/06/2018, SJJ 5942C (TP VEHICLE), SLE 5004M (OI VEHICLE)  
**Attachments:** SJJ5942C GIA.pdf

Dear Jasmine and Margaret,

Please be informed that we had inspected the vehicle SJJ 5942C at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 20/06/2018.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	3454D
<b>Vehicle Details</b>	
Vehicle No.:	SJJ5942C
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ISIS 1.8LX A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1ZZ3141029
Chassis No.:	ZNM100056907
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,361.00
Original Registration Date:	18 Sep 2008
First Registration Date:	18 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$16,180.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Sep 2018
PARF Rebate Amount:	\$8,090.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Sep 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$9,185.00
COE Rebate Amount:	\$313.00
<b>Total Rebate Amount:</b>	<b>\$8,403.00</b>

The information contained herein is correct as at 20 Jun 2018

OK



## CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find a

### Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

7/14 Chrysler 300C. Agent Maintained. Low KM. 1 Owner



Squarish Overalls With Low Body Profile. High ARF \$71.5K/High Paper Value \$96k.  
Shine Connect StarAd


[Browse by Category](#)
[Sort b](#)

13 vehicles

Toyota ISIS

[Advan](#)

Search Selection

Toyota ISIS

Any

Any

2008

Any



**Toyota ISIS 1.8A LX (COE till 01/2023)**

**\$35,800**

**\$7,850 /yr**

**11-Jan-2008**

**1,794 cc**

Smooth And Quiet Engine, Super Fuel Efficiency, Spacious And Comfortable For Driver And Sliding Doors For Passengers  
Reliable Engine And Superb Handling Don't Miss This One If Y...

Posted: 19-Jun-2018 Tags: 2008 Toyota ISIS, Toyota ISIS, Toyota, ISIS, Used Toyota



**Toyota ISIS 1.8A LX (OPC) (New 5-yr COE)**

**\$33,900**

**\$6,780 /yr**

**04-Jul-2008**

**1,794 cc**

**12**

Hari Raya Special Free 1 Year Warranty! All Our Quality Pre Owned Cars Are Selling At The Most Reasonable Price And V  
STA/VICOM Evaluate Are Welcome. Easy Approval! Down Payment \$2...

Posted: 14-Jun-2018 Tags: 2008 Toyota ISIS, Toyota ISIS, Toyota, ISIS, Used Toyota



**Toyota ISIS 1.8A LX (New 5-yr COE)**

**\$41,800**

**\$8,360 /yr**

**18-Jul-2008**

**1,794 cc**

**10**

One Owner, New Paintwork, Fully Done Up, No Further Repairs Is Needed, Do Drop By For Viewing/Test Drive.

Posted: 11-Jun-2018 Tags: 2008 Toyota ISIS, Toyota ISIS, Toyota, ISIS, Used Toyota



**Toyota ISIS 1.8A LX (New 5-yr COE)**

**\$32,800**

**\$6,560 /yr**

**11-Jun-2008**

**1,794 cc**

Excellent Condition. Well Maintained Car Interior. New Paint For New Owner. Enjoy The Convenient Of Powered Sliding E  
conomy MPV. Spacious And Reliable. Easy Maintenance. View To...

Posted: 09-Jun-2018 Tags: 2008 Toyota ISIS, Toyota ISIS, Toyota, ISIS, Used Toyota

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Compare](#)
[et](#)
[On The Move](#)
[Lifestyle](#)


## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/06/2018 13:10
Date Of Accident	20/06/2018 09:40
Exact Location Of Accident	BRAS BASAH ROAD (AFTER QUEEN STREET)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ5942C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ECHAN STUDIO
Co Reg No	53243454D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93883383

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ISIS 1.8LX A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5079169819-02 TP
Cover Note Number	

### Driver

Name of Driver	HONG LEE HIN (FANG LIXING)
NRIC No	S7343904C
Date Of Birth	02/12/1973
Occupation	OUTDOOR
Date Of Driving Pass	30/07/1991
Driving Experience	26 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96720831
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 763 WOODLANDS AVE 6 #12-66
Postcode	730763
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE5004M
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF 1.2 TSI AT 5G12BZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC458C
Vehicle Make/Model/Colour	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name HONG LEE HIN (FANG LIXING)

Approximate Age

Injuries Sustain CHEST PAIN, NECK ACHE

Injured person in which vehicle? SJJ5942C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address


Postcode

# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

20 JUN 2018

**BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Witnessed by Reporting Centre Personnel

Sketch Plan

A: 5009942C	
B: 51E5004M	
C: 5H458C	

Describe Circumstances of the Accident


On 20/06/2018 at about 9:40am, I was traveling along Bras Basah Rd after Queen St towards Victoria St. I was stationary due to the front traffic. Suddenly, vehicle A hit my rear and pushed my vehicle forward to hit the front vehicle C. I was involved in a three vehicle chain collision.

Declaration

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time



  
Driver's Signature (If driver is not the policyholder) / Date & Time

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Witnessed by Reporting Centre Personnel

20 JUN 2018

**FASTECH AUTO PTE LTD**  
**1 Kaki Bukit Ave 6**  
**#01-46/48/50 Autobay**  
**SINGAPORE 417883**

VEHICLE NO: SJJ 5942C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Allowed  
 after  
 2/5 \$3000  
 6 day.*

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE <i>12/0.10</i>	<i>Body</i> \$1,866.10
1 PCS	TAILGATE REAR LOGO	<i>neu</i> \$60.00
1 PCS	TAILGATE WEATHERSTRIP	<i>neu</i> \$266.20
1 PCS	TAILGATE REAR WINDSCREEN MOULDING <i>66.50</i>	<i>neu</i> \$115.30
1 PCS	REAR BUMPER	<i>DI</i> \$875.11
1 PCS	REAR BUMPER TOWING COVER	<i>TO-1</i> \$30.00
1 PCS	REAR BUMPER RETAINERS <i>45.80</i>	<i>Set</i> \$66.50
1 PCS	REAR BUMPER LAMP N/S <i>155.20</i>	<i>CR</i> \$215.30
1 PCS	REAR END PANEL	<i>Body</i> \$665.20
1 PCS	FRONT BUMPER	<i>DI/TO-1</i> \$861.10
1 PCS	FRONT BUMPER SPONGE	<i>NZ</i> \$160.00 X
1 PCS	FRONT BUMPER REINFORCEMENT	<i>DS</i> \$295.30 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.10	<i>Body</i> \$130.20
1 PCS	FRONT BRACE PANEL	<i>neu</i> \$68.50
1 PCS	FRONT SUPPORT PANEL	<i>neu</i> \$685.30 X
1 PCS	FRONT GRILLE	<i>CR</i> \$351.30
		\$6,711.41
	S.NETT	
1 SET	REAR BUMPER REVERSE SENSOR	<i>short</i> \$280.00 <i>200</i>
1 PCS	REAR WINDSCREEN SEALANT	<i>neu</i> \$50.00 <i>40</i>
1 PCS	REAR END PANEL SEALANT	<i>neu</i> \$50.00 ✓
1 PCS	FRONT LICENCE PLATE W/HOLDER	<i>Set</i> \$50.00 <i>40</i>
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00 <i>30</i>
	TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00 <i>50</i>
	TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00 <i>120</i>
	TO TRANSFER TAILGATE MECHANISM	\$100.00 <i>60</i>
	TO DISMENTLE & REFIX SEAT CUSHION UPHOLSTERY	\$150.00 <i>80</i>
	TO SPRAY RUST PROOFING	\$120.00 <i>80</i>
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS	\$1,500.00 <i>1000</i>
	TO PUTTY & SPRAY PAINTING	\$1,800.00 <i>1600</i>
	TOTAL	\$11,121.41

*(257)  
 5080.51*

*700*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2018		10 Jul 2018 10:16 <a href="#">Edit Adj Rpt</a>	<b>S\$3,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	GAN LEONG HIN, ID: S2717111G, Tel: +6590949812								
Main Claimant:	ECHAN STUDIO, Co. Reg. No.: 53243454D								
Vehicle Reg. No.:	SJJ5942C	Date of Loss:	20/06/2018 09:00 - :59 [117 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 562092	Policy/Cover Note No.:	A28797372AVW (Comprehensive) Coverage: 25/07/2017 - 24/07/2018						
Vehicle Reg. No. (Insured):	SLE5004M	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/08/2018]								
Driver/Custodian (Insured):	DRAGONA GAN IOANNA (), NRIC: S2717112E, Tel: +6590949812								
Adj Asg. Remarks:	ON WP								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJJ5942C (562092)  
[SLE5004M]  
TP  
ECHAN STUDIO  
Jun 20 2018 9:00AM  
[GAN LEONG HIN]  
Fastech Auto Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	10/07/18 10:12	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: OD - Reg. No: SLE5004M, Claimant: GAN LEONG HIN</small>	 Load HTM	
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	23/07/18 13:13	<b>Adjuster Immediate Advice</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
		<b>LKK Auto Consultants Pte Ltd (HQ)</b>		
1	23/07/18 13:20	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 13:20	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/18 13:20	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/18 13:20	<b>General View</b>	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
64	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
65	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
66	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
67	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
68	23/07/18 13:20	General View	 Load JPG	<input checked="" type="checkbox"/>
69	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	23/07/18 13:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 10:11	LKK EMAIL INFORMING TP VEHICLE SURVEYED AT M/S FASTECH AUTO	Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
2	10/07/18 10:12	TP REPORT SJJ5942C From:OD - Reg. No: 5LE5004M, Claimant: GAN LEONG HIN		Load PDF
3	10/07/18 10:12	TP REPORT SHC458C From:OD - Reg. No: 5LE5004M, Claimant: GAN LEONG HIN		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18011193/UQBQ2

Date: 26/07/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28797372AVW  
**Claimant Vehicle No :** SJJ5942C **Insured Vehicle No :** SLE5004M  
 Date of Loss: 20/06/2018 Nature of Claim: TP Claim No: 562092

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ5942C**  
 Make & Model: TOYOTA ISIS, 1.8 LXA (A) Engine No: 1ZZ3141029  
 Reg. Date: 18/09/2008 (Man. Year: 2008) Chassis No: ZNM100056907  
 Colour: Blue Odometer: 275075 km  
 Engine Capacity: 1794 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: HIFLY 5 mm Rear Left Side: HIFLY 5 mm  
 Front Right Side: HIFLY 5 mm Rear Right Side: HIFLY 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,141.41	4,140.38	3,001.03	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	3,020.00	960.00	24.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,121.41</b>	<b>7,160.38</b>	<b>3,961.03</b>	<b>35.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>(S\$)</b>	11,121.41	3,000.00	8,121.41	73.03
<b>+ GST 7.00/7.00% (S\$)</b>	778.50	210.00	568.50	73.03
<b>Nett Amount (S\$)</b>	<b>11,899.91</b>	<b>3,210.00</b>	<b>8,689.91</b>	<b>73.03</b>

### INSPECTION

Date of Assignment: 10/07/2018  
 Date Inspected: 20/06/2018 Inspected At: Fastech Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
 Singapore 417883  
 Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2018)
<b>Parts:</b> 144	TOYOTA ISIS 1.8 LXA (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJJ5942C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,866.10 F	*1,210.10 FL
2	1		*TAILGATE REAR LOGO	Necessary	60.00 F	*60.00 FL
3	1		*TAILGATE WEATHERSTRIP	Twisted	266.20 F	*266.20 FL
4	1		*TAILGATE REAR WINDSCREEN MOULDING	Necessary	115.30 F	*66.50 FL
5	1		*REAR BUMPER	Distorted	875.11 F	*875.11 FL
6	1		*REAR BUMPER TOWING COVER	Torn	30.00 F	*30.00 FL
7	1		*REAR BUMPER RETAINER N/S	Bent	66.50 F	*45.80 FL
8	1		*REAR BUMPER LAMP N/S	Cracked	215.30 F	*155.20 FL
9	1		*REAR END PANEL	Badly Dented	665.20 F	*665.20 FL
10	1		*FRONT BUMPER	Dented / Torn	861.10 F	*861.10 FL
11	1		*FRONT BUMPER SPONGE	Not fitted	160.00 F	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Dented	295.30 F	*295.30 FL
13	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.20 F	*130.20 FL
14	1		*FRONT BRACE PANEL	Twisted	68.50 F	*68.50 FL
15	1		*FRONT SUPPORT PANEL	Repair	685.30 F	*- FL
16	1		*FRONT GRILLE	Cracked	351.30 F	*351.30 FL
17	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
19	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,141.41</b>	<b>5,410.51</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>1,270.13</b>
<b>Total Parts (\$\$)</b>	<b>7,141.41</b>	<b>4,140.38</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	120.00	80.00
7	LABOUR FOR PANEL BEATING ,CUT ,WELD,STRAIGHTEN & REPLACING PARTS	New	1,500.00	1,000.00
8	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,600.00
<b>Gross Labour Cost (S\$)</b>			<b>3,980.00</b>	<b>3,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >