

22/03/2007

ASS. REC. BY:

REF: CS/FCI18011210/ Ksd3<sup>n2</sup>

Special Instruction:

Surveyor

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

20/6/18 @ 12:18pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGJ 7475G

Insured:

SHB 47722

at Workshop m/s

Chew Goon Motor

Tel:

6484 1626

of

Blk 10, AMK Ind. park 24 Ave 5 # 01-15

Policy No:

Claim No:

D1800 4755 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/06/2018

CA / REV / REP. / REV 24 HRS

(up)

21/06/2018

H.O.D. Endorsement:

Date/Time:

12:41pm @ 20/6/18

Person Contacted:

Gmlee

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGJ 7475G - X

SHB 47722 - CS/FCI17008225/H/vbn2

DOT: 25/04/2017

22/06/18

@ 16:38 p.m. revised PA to Sithara via email..

3/1 @ 2252 email &amp; confirm

REF: PC1

## ASSIGNMENT

From

Date: 21/06/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGJ 7475G

at Workshop m/s Chew Goon Motor

of Blk 10 AMK Ind. park 2A Ave S# 01-15

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 829k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lump Sum: 1-B.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SGJ 7475G Yr Regn: 05 10

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volks wagen <sup>A</sup> Scirocco <sup>75i</sup> 1390

Colour:

m. Green

A/C: Insured / Std / NI / NA

Sp. Reading:

93867

T/Radio: Insured / Std / NI / NA

Eng/No:

WVW ZZZ 137 AV 434960

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 40 R 18

R:

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/6/18

D.O.I.

21/6/18

Survey held at

☒Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/6 File sent to Catherine

RECEIVED 03 JUL 2018

Date/Time File Pass to?

03/07/18

1) Typist

Date/Time File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$) 2,252.00 p/p

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

1) S + R.S. \$1

1) Photos

1) Others

TOTAL

130

50

50

22

252

**MOTOR SURVEY ASSIGNMENT**

Date 14-06-2018 Our Ref No. D18004755MFSH

Accident Date 13-06-2018 Claim Type. Third Party

Insured Vehicle SHB4772Z Third Party Vehicle. SGJ7475G

Survey Location BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT

Contact Person. GRACE

Contact No. 64841626/ 0 Fax No. 64840465

Survey Type WITHOUT PREJUDICE:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop CHEW GOON MOTOR Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge SITHARA

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241473)



PRI Documents



Close



## PRI Header Details

Claim No	D18004755MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHEW GO
Workshop Name	CHEW GOON MOTOR (Contact Person : GRACE)	Survey Location & Contact Details	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-AUTOPOINT Mobile: 0 , Phone: 64841626 , Fax: 64840465 EmailId: AD3@CHEWGOONMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB4772Z	TP Vehicle No	SGJ7475G
PRI Recieved Date	19-06-2018 09:59:10 PM	Surveyor Appointed Date	20-06-2018 12:17:37 PM	Surveyor Accept Date	20-06-2018 1

## Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	20-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

## Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011210/Ksd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 20-06-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4772Z	Veh. Inspected	SGJ 7475G
Policy No.		Coverage (\$)	0.00
Claim No.	D18004755MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	20/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	13/06/2018	Inspection Date
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047	

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5700B

**Vehicle Details**

Vehicle No.:	SGJ7475G
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Jun 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	Green
Manufacturing Year:	2010
Engine No.:	CAV169158
Chassis No.:	WVWZZZ13ZAV434960
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$24,389.00
Original Registration Date:	14 May 2010
First Registration Date:	14 May 2010
Transfer Count:	0
Actual ARF Paid:	\$24,389.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2020
PARF Rebate Amount:	\$13,413.00

**Intended COE Rebate Details**

COE Expiry Date:	13 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$3,546.00
<b>Total Rebate Amount:</b>	<b>\$16,959.00</b>

The information contained herein is correct as at 13 Jun 2018

OK

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 22 June 2018 4:38 PM  
**To:** 'Nivitha (LKK Auto)'; 'Claim Workflow System'; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; "SUR"  
**Subject:** RE: SURVEY ASSESSMENT - D18004755MFSH/1  
**Attachments:** SGJ 7475G - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised for SGJ 7475G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 20 June 2018 4:17 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; "SUR" <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004755MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 20 June 2018 12:17 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004755MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004755MFSH

Date: 22 June 2018

Our Ref: CS/FCI18011210/Ksd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SGJ 7475G .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/06/2018 at the premises of M/s Chew Goon Motor and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,527.00</u> .
Revised Estimate Amount	: S\$ <u>1,660.00</u> .
"Check" Items Amount	: S\$ <u>1,187.00</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 2 Days

Yours faithfully,

Kenneth Kong

Automotive Assessor

4408902



NRIC No. S7905700B



Date of issue  
27-05-2009

APT BLK 199A PUNGGOL FIELD #15-405  
SINGAPORE 621199

NRIC No: S7905700B Date: 16/01/2016


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE 11 Feb 1999

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

NP 428A

Licence No: S7905700B



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7905700B



Name  
CHAN CHONG WAI  
(CHEN ZONGWEI)  
陈宗伟

Race  
CHINESE

Date of birth  
07-03-1979

Sex  
M

Country of birth  
SINGAPORE

S7905700B

REPUBLIC OF SINGAPORE DRIVING LICENCE

Chan Chong Wai S7905700B



CHAN CHONG WAI (CHEN ZONGWEI)

Birth Date: 07 Mar 1979

Issue Date: 25 Jan 2003



10061508738

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5100102604

**Cover :** drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SGJ7475G**  
Chassis Number : WVWZZZ13ZAV434960
2. Name of Policyholder : CHAN CHONG WAI
3. Effective Date of Insurance : 14 May 2018
4. Expiry Date of Insurance : 13 May 2019
5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

**This Policy does not cover**

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: YES
PRIMARY DRIVER	: CHAN CHONG WAI
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: DBS BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : B.A.S. INSURANCE AGENCY (00000573236)  
Date of Issue : 20 Apr 2018 16:14 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Policy No: Third Party

Date: 19.06.2018

Accident Date : 13.06.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Volkswagen Scirocco" Reg. No. SGJ7475G Claiming Against Your Insured Veh. No. SHB4772Z			
1pc	Rear Number Plate Lamp RH	5.00	165.00 ✓
1pc	Rear Bumper		870.00 ✓
10pcs	Rear Bumper Clips		50.00 ✓
1pc	Rear Bumper Bracket RH		60.00 ✓
1pc	Rear Bumper Core		102.00 ✓
1pc	Rear Bumper Sponge		80.00 ✓
1pc	Rear Bumper Reinforcement		455.00 ✓
1pc	Rear Bumper Tow Cover		30.00 ✓
1pc	Rear Bumper Reflector RH		60.00 ✓
1pc	Rear Bumper Lower Cover (Alum)		230.00 ✓
			2,082.00
1pc	Rear Number Plate		45.00 SN ✓
1pc	Rear Bumper Reverse Sensor		280.00 SN 200 ✓
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00 50 ✓
	Labour Charge - Panel Beating, Repairing Of End Panel and Parts Replacement		400.00 200 ✓
	To Respray Affected Areas		600.00 250 ✓
		Total :	3,527.00

*Not Authorised*  
*Repairing B4 parts*  
*2 days*  
*2252.00*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011210/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-07-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHB 4772Z	Veh. Inspected	SGJ 7475G
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18004755MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	20/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	VOLKSWAGEN SCIROCCO TSI (A)	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WWWZZZ13ZAV434960	Colour	METALLIC GREEN
Odometer	93867	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	7 mm
L/H Front Tyre	225/40 R18	GOODYEAR	7 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	7 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	13/06/2018	Inspection Date	21/06/2018
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 7475G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR NUMBER PLATE LAMP RH	MISSING	165.00	165.00
1	REAR BUMPER	BUCKLED	870.00	870.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	60.00	-
1	REAR BUMPER CORE	CRACKED	102.00	102.00
1	REAR BUMPER SPONGE	CRACKED	60.00	60.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	455.00	-
1	REAR BUMPER TOW COVER	MTG CRACKED	30.00	30.00
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	60.00	-
1	REAR BUMPER LOWER COVER (ALUM)	BENT	230.00	230.00
			2,082.00	1,507.00
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	DENTED	45.00	45.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			325.00	245.00
<b>LABOUR</b>				
	TO CONDUCT ELECTRICAL CHECK, REPLACE REVERSE SENSORS, MODULE, REWIRING ETC.		120.00	50.00
	LABOUR CHARGE-PANEL BEATING, REPAIRING OF END PANEL AND PARTS REPLACEMENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET RH AND REAR BUMPER REINFORCEMENT.		400.00	200.00
	TO RESPRAY AFFECTED AREAS.		600.00	250.00
-			-	-
-			-	-
-			-	-
			1,120.00	500.00
<b>GRAND TOTAL</b>			<b>3,527.00</b>	<b>2,252.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,252.00</b>

Report Ref No. CS/FCI18011210/Ksd3n2



Report Ref No. CS/FCI18011210/Ksd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.