

Kalin

REF: NS/INC18011220/Klqbnz

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured **OKR 523R**  
 Policy No **5083569103-01 010917**  
 Claims No **MM/0999476-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **SHC 276K** Yr Regn: **30 Jun 2013**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /  
 Truck / Trailer or  
 Make: **Hyan Jr Sorento** c.c **194**  
 Colour **Yellow** A/C: Insured / Std / NI / NA  
 Sp.Reading **646063** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **KMHET4IVMCA831409**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inord~~r~~ / Jammed / Leaked / Burnt or  
 Brake: Inord~~r~~ / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD / Rim or  
 Tyre Size: F: **215/60R16**  
 R: \_\_\_\_\_

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Westlake**

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: **2** days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front **7** mm Rear **7** mm  
 R/Bal. **7** mm L/Bal. **7** mm  
 D.O.A. **19/6/08** D.O.I. **20/6/08**

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Survey held at **CDHE (Loyang)**  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**O/S Body.**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 276K - X
	OKR 523R - X
<b>22/6/08</b>	<b>Checked 4s &amp; roof 20gys.</b> <b>(Weld @ 1486.60, 5I%)</b>

**IME**  
**4s**

RECEIVED 26 JUN 2010

Date/Time. File Pass to?  : Preli. Report  
 : Final Report  
 1) **7/6/08** **transfer**  
 Date/Time. File Return to?  
 2) \_\_\_\_\_

Days Of Repair: **2**  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)

Survey Fee:  
 Transportation  
 ) \$ + RS, SI  
 ) Photos  
 ) Others

Report Format: **TP**



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18011220/K1qb			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 20-06-2018	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKR 5223R	Veh. Inspected	SHC 276K
Policy No.	5083569103-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	19/06/2018	Inspection Date	20/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0999285-002	COMFORT TRANSPORTATION PTE LTD	SHD 4182R	SLP 4094B	18/06/2018	\$ 3,738.64	\$ 900.00
2	MT/0999426-002	CITYCAB PTE LTD	SHC 276K	SKR 5223R	19/06/2018	\$ 2,686.00	\$ 1,200.00
3	MT/0999510-003	COMFORT TRANSPORTATION PTE LTD	SH 8839C	SHB 8865M	20/6/2018	\$ 1,603.13	\$ 400.00
4	MT/0999812-001	COMFORT TRANSPORTATION PTE LTD	SHC 2368R	GBE 2572C	18/6/2018	\$ 2,420.52	\$ 1,550.00
5	MT/0998569-002	COMFORT TRANSPORTATION PTE LTD	SHD 3594S	SLU 6879P	13/6/2018	\$ 7,568.23	\$ 5,702.63

Claim received from LKK Auto

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

My Desktop  
Notice of Loss

Policy Query

Policy No.  Date of Accident

Vehicle No. (For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5083569103-01	HAWK ASIA PACIFIC PTE LTD	200306748G	GFT	Third Party, Fire & Theft	SKR5223R	SKR5223R	01/09/2017	

Continue

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/06/2018 09:46
Date Of Accident	19/06/2018 17:30
Exact Location Of Accident	SENTOSA GATEWAY TWDS SENTOSA
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC276K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

### Driver

Name of Driver	CHUA HOCK SENG
NRIC No	S0707867F
Date Of Birth	12/04/1945
Occupation	OUTDOOR
Date Of Driving Pass	26/02/1972
Driving Experience	46 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83553661
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 171 ANG MO KIO AVENUE 4 #08-513
Postcode	560171
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE
Passenger 3	NAME: : - GENDER: : FEMALE
Passenger 4	NAME: : - GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR5223R
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

LH FRONT

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD  
CO. REG. NO. 199502839G

Loke Wei Yieng

Policyholder's Signature  
Date & Time:


Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/6/18. at about 17:50 hrs, I was driving along Sentosa Gateway at speed of 40 km/h.

Out of sudden, a car SKR 5223R cut into my lane in speedy manner. Due to this cause, the car left front portion hit & grazed onto the right front portion of my taxi.

04 passengers on board my taxi. No injury at the point of accident. Passenger contact

no: +62 81243413505, she claims to be my witness

DECLARATION




I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD  
CO. REG. NO. 199502839G

Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



A member of COMFORTDELGRO

Date/Time: 20.06.2018 12:56 Page : 1

Team: ARC Repair TP(CFSO)1

**JOB CARD** Sales Order: JC NO: 305177765

STOMER  
 CITYCAB PTE LTD  
 VMS 7010070  
 STOMER NO. 383 SIN MING DRIVE  
 DRESS Singapore SINGAPORE 575717  
 65551188 (O)  
 L (R) (F)  
 COUNT CARD NO.

VA21

REGN NO: SHC 276K	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: SONATA	DATE/TIME IN 20.06.2018 08:40
YR OF MANU. 30.01.2013	TARGET DATE
CHASSIS CODE KMHE141VMCA831409	COMPLETION DATE/TIME:

(C)

JOB DESCRIPTION

Accident Date: 19.06.2018  
 NATURE: 3P 19.06.2018

S/NO	LABOR CODE	DESCRIPTION
	NTUC - Taxi	Right Front damage
	LKK/Kadmi -	

HECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Name: \_\_\_\_\_  
 No.: SHC 276K LARRY  
 Vehicle No.: \_\_\_\_\_

Vehicle No.: SHC 276K

Larry NG

Signature/Date

Name of Service Advisor Date

to be returned to Service Reception upon collection

To be kept by Security Guard

**CITY CAB PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 276K

DATE 20/6/2018 10:06

MAKE :

DOA: 19.06.18

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 538.80
	Front Bumper Bracket Top (RH) <i>X su</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>X su</i>			\$ 20.10
	Front Fender (RH) <i>— part</i>			\$ 593.00
	Front Fender Shield (RH) <i>X su</i>			\$ 86.00
	Front Fender Retainer <i>X su</i>			\$ 9.20
	Front Wheel Hub Cap (RH) <i>— brand</i>			\$ 145.00
	<i>Front RH Door X repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 1,414.50</b>
	<b>LESS 20%</b>			<b>\$ 282.90</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,131.60</b>
	Front Door City Cab Logo (RH) <i>— all</i>			\$ 75.00 <b>Nett</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>560.00</del>
	Spray Painting Charge			\$ <del>750.00</del> <b>600</b>
	Tuff Kote			\$ <del>50.00</del> <b>20</b>
	FRT Wheel Alignment			\$ <del>120.00</del> <b>X 2</b>
	<b>TOTAL LABOUR</b>			<b>\$ 1,480.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,686.60</b>

*Kaluh (LKK)*  
*20/6/18 15/10 hrs.*  
*2 Rps*  
*L/S*  
*After Repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305177765  
Date : 22. Jun. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : KALVIN  
Vehicle Reg No. : SHC 276K Date of Accident: 19.06.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SKR5223R
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_
  - Final Lumpsum Repair cost** \$1,200.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : Larry Ng  
Tel : 6214 8316  
Fax : 6546 8156

Signature :   
Name : Calvin  
Date : 22/6/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18011220/K1qbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 27-06-2018
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 5223R	Veh. Inspected	SHC 276K
Policy No.	5083569103-01	Coverage (\$)	0.00
Claim No.	MT/0999426-002	Excess (\$)	0.00
Assign From		Assign Date	20/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KMHET41VMCA831409	Colour	YELLOW
Odometer	646063	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/06/2018	Inspection Date	20/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 276K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	538.80	-
1	FRONT BUMPER BRACKET TOP (RH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (RH)	SERVICEABLE	20.10	-
1	FRONT FENDER (RH)	DENTED	593.00	593.00
1	FRONT FENDER SHIELD (RH)	SERVICEABLE	86.00	-
1	FRONT FENDER RETAINER	SERVICEABLE	9.20	-
1	FRONT WHEEL HUB CAP (RH)	GRAZED	145.00	145.00
1	FRONT RH DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-282.90	-147.60
			1,131.60	590.40
<b>SPECIAL NETT ITEMS</b>				
1	FRONT DOOR CITY CAB LOGO (RH)(SN)	NECESSARY	75.00	75.00
			75.00	75.00
<b>LABOUR</b>				
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER AND FRONT RH DOOR.		560.00	200.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	TUFF KOTE.		50.00	20.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,480.00	820.00
<b>GRAND TOTAL</b>			<b>2,686.60</b>	<b>1,485.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,200.00</b>

Report Ref No. NS/INC18011220/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.