

ASS. REC. BY:

REF:

CS/E6118011252/Usber

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

E61

Date/Time:

22062018 1043am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 7115L

Insured:

SJS 2539G

at Workshop m/s

Fastech Auto

Tel:

6746 5445

of

Bik 1 Kaki Bukit Ave 6 # 01-46

Policy No:

Claim No:

SJS 2539G / SA/pl

Sum Insured:

Excess:

Make of Veh.

D.O.A.

15062018

(Client's Record)

CA / REV / REP. / REV 24 HRS. 10/18

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 7115L - X

SJS 2539G - X

22/06/18

@ 16:37 pm. revert policy Estimate from repairer to Pei Li via email

(08/11/13) waf

ASS. REQ. BY: 310-165

REF:

ER1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SJX7115Lat Workshop mis HP.

of _____

Insured: SJS25396

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 29800

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJX7115L Yr Regn: 7 10Type: CA / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FIAT Bravo c.c. 1368Colour: white A/C: Insured / Std / NI / NASp. Reading: 182600 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA19800004289853Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45R17 55ES / LUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 Rear: 6

R/Bal: _____ mm R/Bal: _____ mm

L/Bal: 6 mm L/Bal: 6 mmD.O.A. 20/6/18 D.O.I. 21/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

near L.H.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 16750 2hrs rep 10500net 1305020/7/18 confirmed L/S of 13,000 with Alu.(\$38,854.10 Red - 75%)

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

23/07/181) Typt

Date/Time, File Return to?

2) _____

☐ : Prell. Report☒ : Final ReportDays Of Repair: 10Resurvey No. of Trip: 3Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 350

Transportation: _____

\$ - RS. \$

Photos

Others

TOTAL

350

Report Format: _____

Lump Sum / I.B.I. (\$) 13,000.00 L/S

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 22 June 2018 10:43 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : SJS2539G / TP : SJX7115L/LKK / DOA : 15/06/2018
Attachments: OI - 4TH VEH SJS2539G - SAS.pdf; 3RD VEH SJX7115L - SAS.pdf; 2ND VEH SFP5088J - SAS.pdf; SJX7115L - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 22.06.2018
Our Reference: SJS 2539G/SA/pl
Your Reference: SJX 7115L

To: FASTECH AUTO PTE LTD

Sent via Fax
or
Email nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJX 7115L
Insured's Vehicle: SJS 2539G
Date Of Accident: 20.06.2018


We acknowledge receipt of your request for PRS on: 21.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us today.
☒ Others: OFFICER-IN-CHARGE - SITI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9618E

Vehicle Details

Vehicle No.: SJX7115L

Vehicle to be Exported: No

Intended De-registration Date: 21 Jun 2018

Vehicle Make: FIAT

Vehicle Model: BRAVO 1.4L 150HP MANUAL TURBO
ABS AIRBAG

Primary Colour: White

Manufacturing Year: 2010

Engine No.: 198A10001536374

Chassis No.: ZFA19800004289853

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$17,776.00

Original Registration Date: 01 Jul 2010

First Registration Date: 01 Jul 2010

Transfer Count: 1

Actual ARF Paid: \$17,776.00 *fff***Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Jun 2020

PARF Rebate Amount: \$10,665.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$30,051.00

COE Rebate Amount: \$6,085.00

Total Rebate Amount: \$16,750.00

The information contained herein is correct as at 21 Jun 2018

OK

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.
You can read customers' reviews & ratings on their services too.

Fiat Bravo Price Range Depreciation 2010 Vehicle Type Submit Advanced Search

Home » Used Cars » SG Car Consign Pte Ltd » Fiat Bravo 1.4A T-Jet

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Rental

For Private & Commercial Vehicles
Rental From \$50/Day

2ent



Singtel

MOST AFFORDABLE data plan at Singtel!

Compare

Fiat Bravo 1.4A T-Jet

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$27,000	
Depreciation	\$10,600 /yr	?
	View models with similar depreciation	
Reg Date	11-Jan-2010	
	(1yr 6mths 20days COE left)	
Manufactured	2009	?
Mileage	82,000 km (9.7k /yr)	
Transmission	Auto	
Engine Cap	1,368 cc	
Road Tax	\$608 /yr	?
Power	88.0 kW (118 bhp)	
	View specs of the Fiat Bravo (2007-2016)	
Curb Weight	1,335 kg	?
Features	-	
Accessories	-	
Description	Ideal For Short Term Usage! Reliable Fiat Bravo 1.4A T-Jet, Always Serviced And Maintained Regularly, That's Why Till Now It Has Got No Repairs Needed. Beautiful Paintwork And Healthy Engine Condition Easily Able To Last Till Scrap Without Worry. Selling On Behalf Of Owner, Please Call To Arrange Before Viewing.	
COE	\$18,502	?
OMV	\$20,998	?
ARF	\$20,998	?
Dereg Value	\$14,428 as of today (change)	?
No. of Owners	3	?
Type of Veh	Hatchback	
Category	PAFF Car, Consignment Car, Low Mileage Car	
Availability	Available	Consignment

Add to Shortlist Add to Compare Add a Note

Posted on: 14-Apr-2018 | Last Updated on: 18-Jun-2018

Tags: Fiat Bravo, 2010 Fiat Bravo, Fiat, Bravo, Used Fiat

Upfront Payment = more Financial Info

Transfer Fee	\$25	?
Down Payment	\$8,100 (change)	Maximum 70% Loan ?

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- List of owner consignment cars
- List of consignment agents



Seller Information

Company	SG Car Consign Pte Ltd <ul style="list-style-type: none">dealer's priority72 cars sold 114 cars available	
Address	170 Upper Bukit Timah Road #01-28	
	Search cars nearby this location	
Location	Bukit Timah Shopping Centre	
Office No	61000200	
Contact Person(s)	Bryan Tan	91795745

Useful Services


STA

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 June 2018 4:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: ASSIGNMENTS@LKKAUTO.COM; "SUR"; 'Catherine Chong (LKK Auto)'
Subject: RE: SJS2539G / TP : SJX7115L/LKK / DOA : 15/06/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SJX 7115L on 21/06/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 22 June 2018 10:57 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: ASSIGNMENTS@LKKAUTO.COM; "SUR" <sur@lkkauto.com>
Subject: RE: SJS2539G / TP : SJX7115L/LKK / DOA : 15/06/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Friday, 22 June, 2018 10:43 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : SJS2539G / TP : SJX7115L/LKK / DOA : 15/06/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD**.

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2018 15:11
Date Of Accident	20/06/2018 17:55
Exact Location Of Accident	ALONG AYE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX7115L
Insured/Policyholder	
Name Of Registered Owner	LOH YEOW TECK (LU YAODE)
NRIC No	S8809618E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90055469
Alternative Phone No	OFFICE-60000000

Vehicle Particulars

Manufacturer	FIAT
Model	BRAVO-1.4 (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA111149/1
Cover Note Number	

Driver

Name of Driver	LOH YEOW TECK (LU YAODE)
NRIC No	S8809618E
Date Of Birth	22/03/1988
Occupation	INDOOR
Date Of Driving Pass	25/10/2007
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90055469
Fax Number	
Contact Number	OFFICE-60000000
Email Address	NOEMAIL

Address	183C BOON LAY AVE #05-740
Postcode	643183
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : WIU PEI WEN GENDER: : FEMALE
Passenger 2	NAME: : LOH YU XIANG XAVIER GENDER: : MALE
Passenger 3	NAME: : LOH YI JUN XANDRA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T/20180620/2168
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report please refer to Police Report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	GET FROM WORKSHOP
Was there any audio recorded?	NO

1755
245
245

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS2539G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name UNITED OVERSEAS INSURANCE LTD
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SCQ5818A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SFP5088J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLR7977Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOH YEOW TECK (LU YAODE)
Approximate Age 30

Injuries Sustain	BODY PAIN
Injured person in which vehicle?	SJX7115L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	WIU PEI WEN
Approximate Age	30
Injuries Sustain	BODY PAIN
Injured person in which vehicle?	SJX7115L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	LOH YU XIANG XAVIER
Approximate Age	9
Injuries Sustain	BODY PAIN
Injured person in which vehicle?	SJX7115L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 4

Name	LOH YI JUN XANDRA
Approximate Age	1
Injuries Sustain	BODY PAIN
Injured person in which vehicle?	SJX7115L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: *Ramon C.*
NRIC/TIN No.: *57131809E*

Sketch Plan #2

SKETCH PLAN



E-SLR 7977Z
P-SFP 5088J
A-SJX 7115L
B-SJS 2539H
C-SLR 5818A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report T/20180620/2168

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: R. ...
NRIC/FIN No.: ST318090

Police Report



**SINGAPORE
POLICE FORCE**



T/20180620/2168

1 of 5

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

Report No. T/20180620/2168

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/06/2018 20:34		Vide Report No.:		Station Diary No.: 76	
Informant's Particulars					
Name of Informant: LOH YEOW TECK			Address: APT BLK 183C BOON LAY AVENUE #05-740 SINGAPORE 643183		
ID Type / ID No.: NRIC NO / S8809618E			Contact No.: Home/Office: Mobile: 90055469		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 22/03/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Interior designer			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/06/2018 17:55	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY Along AYE towards TUAS, after Buona Vista exit				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: chain collision				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SCQ5818A	Car					0
SFP5088J	Car					0
SJS2539G	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Police Report



**SINGAPORE
POLICE FORCE**



T/20180020/2160

2 of 5

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759990

Report No. T/20180020/2160

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJX7115L	Car	FIAT	BRAVO 1.4L 150HP MANUAL TURBO ABS AIRBAG	White	Seriously Damaged	4
SLR7977Z	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJX7115L	AXA INSURANCE SINGAPORE PTE LTD	GA111149	01/07/2017	30/06/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	ABDUL KADER S/O SHAHUL HAMEED		ID No.	S15271600
Related Vehicle	SCQ5818A (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	YEO LAI CHOON		ID No.	S11599241
Related Vehicle	SFP5088J (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Police Report



**SINGAPORE
POLICE FORCE**



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

3 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

Driver			
Name	KOH CHIN MING EUGENE		ID No. S9350326J
Related Vehicle	SJS2539G (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	LOH YEOW TECK		ID No. S8809818E
Related Vehicle	SJX7115L (Car)		Contact No. 90055469
Hospital/Clinic	THE CHONG FAMILY CLINIC		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	20/06/2018		Date Discharge 20/06/2018
No. of Days granted Medical Leave	03		Degree of Injury NIL
Driver			
Name	SAMSON LIM CHOON NGEE		ID No. S7728074Z
Related Vehicle	SLR7977Z (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 20/06/2018 at about 1850hrs, I was driving my vehicle bearing the registration number SJX7115L along AYE towards Tuas. At that point of time, I had my son (9 years old) seated at the front passenger seat whereas my wife and my daughter (1 year old) were at the rear passenger seat with my daughter in the baby chair. I was driving in the extreme first lane with a speed of about 80km/h. At that point of time, the road was wet as the rain had just stop.

After the exit of Buona Vista, I saw the vehicle in front of me (SFP5088J) stepping on his brake and eventually come to a stop. I did the same and stopped my vehicle completely behind his. After which, my wife told me that she noticed the car behind me (SJS2539G) was approaching towards my vehicle in a fast manner. After hearing what my wife said, I immediately felt a huge impact on my rear. The impact had caused my vehicle to inched forward and hit onto the vehicle in front of me. After the impact, I went

Police Report



**SINGAPORE
POLICE FORCE**



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

4 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

down from my vehicle and made a check and discovered that there were a total of five vehicles involved in a chain collision.

The sequence of the vehicle involve is as follows;
SLR7977Z (1st vehicle)
SFP5088J (2nd vehicle)
SJX7115L (3rd vehicle) - my vehicle
SJS2539G (4th vehicle)
SCQ5818A (5th vehicle)

I wish to state that the fourth vehicle had hit onto my rear before the fifth vehicle hit onto his. The impact of my car hit onto the second car had caused the second car to hit onto the first car. No car was towed away as all were still able to move. No police or ambulance were at scene. My car suffered dent on the front bonnet and my left side of the head light was broken. My rear bumper also suffered deep dent and my left tail light and both the reverse light was broken.

I wish to add on that after we drove off from the scene, I, my wife and my son felt some pain and as we are concerned on our daughter's condition, we went to seek medical treatment at The Chong Family Clinic. All of us were treated and both I and my wife were given 3 days of medical leave whereas my son was given 5 days of medical leave. As for my daughter, the doctor made checks on her and as of now she was fine. I have an in-build camera installed in my car however I have yet to check if it captured anything. I am unsure if there is any CCTV installed at the vicinity.

The particular of my family members are as follows;
Wife: Wu Pei Wen, S8813485J
Son: Loh Yu Xiang Xavier, T0912702F
Daughter: Loh Yi Jun Xandra, T1718287G

Police Report



**SINGAPORE
POLICE FORCE**



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-458
SINGAPORE 120427
Tel No: 1800-7759999

5 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 3 MUHAMMAD RAFIQ KHAN BIN DAUD

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

SN 40

Signature Of Informant:

Date/Time:
20/06/2018 20:34

Classification Of Case:

Driving License

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man

License Number: S8809618E

Name: LOH YEDW TECK (LU YAOKE)

Birth Date: 22 Mar 1988

Issue Date: 25 Oct 2007

Barcode: S8809618E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES):

Class 2 Motor Cars - 3000kg with ≤ 7 passengers, exclusive of the driver, and other motor vehicles $\leq 2000kg$

VALID DATE: 25 Oct 2017

NP 4284



Insurance Cert



redefining / insurance

AXA Insurance Pte Ltd
 1800 888 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

account number
 05186

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 188) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third-Party Risks) Rules, 1989 (Malaysia)

Policy details

Policyholder name	LOH YEDWTECK	Certificate number	6A111149 / 1
Cover	Comprehensive	Chassis number	ZFA15800004289853
Plan name	Essential	Engine number	108A10001536374
NCD applicable	90%		
Vehicle registration number	SIXT115L		
Period of Insurance	from 01/07/2017 to 30/06/2018 (both dates inclusive)		
Finance loan company	MAYBANK		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be induced under these headings.

EXCESS Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed Authorised Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

[We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 188) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 188).

The Premium Warranty Clause requires the premium to be paid in full within a specific period fixing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068611
 Customer Centre, #B1-01

1 of 3

Date of Accident : 20/6/18 Accident Time: 5:55pm (24-HR-Format)
 Accident Place : Along AYE towards Tuas
 Vehicle No. (Car Plate No.) : SJX 7115L Make/Model: Fiat Bravo 1.4
 Insurance Company : AXA Policy No: GA111149/1
 Owner or Company Name /IC No. : Loh Yeeow Teck /58809618E
 Owner or Company Contact No. : _____ Owner's Hp 96055469 Company Tel _____
 DRIVER'S Name / IC No. : as above
 DRIVER'S Date Of Birth : 22/3/1988 DRIVER'S License Pass Date 25/10/2007
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner
 DRIVER'S Address : Blk 183C Boon Lay Ave #05-740 643183
 DRIVER'S Contact No / Alt No. : 1) _____ 2) _____
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address : kennyloh_yt@hotmail.com
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): 4
 Was there any video Captured by car camera: YES \ NO
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: <u>SS 525396 (Ergo)</u>	Vehicle No: <u>SCQ 5818A</u>
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**

Wu Pei Wen (F)
 Loh Yu Xiang Xavier (M)
 Loh Yi Jun Xianchen (F)

vehicle D - SFP 5088S
 vehicle E - SLR 7977Z



SINGAPORE POLICE FORCE



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

1 of 5

Report No. T/20180620/2168

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/06/2018 20:34		Vide Report No.:		Station Diary No.: 76	
Informant's Particulars					
Name of Informant: LOH YEOW TECK			Address: APT BLK 183C BOON LAY AVENUE #05-740 SINGAPORE 643183		
ID Type / ID No.: NRIC NO / S8809618E			Contact No.: Home/Office: Mobile: 90055469		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 22/03/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Interior designer			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/06/2018 17:55	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY Along AYE towards TUAS, after Buona Vista exit				
Weather: Clear		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: chain collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SCQ5818A	Car					0
SFP5088J	Car					0
SJS2539G	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



SINGAPORE POLICE FORCE



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

2 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJX7115L	Car	FIAT	BRAVO 1.4L 150HP MANUAL TURBO ABS AIRBAG	White	Seriously Damaged	4
SLR7977Z	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJX7115L	AXA INSURANCE SINGAPORE PTE LTD	GA111149	01/07/2017	30/06/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	ABDUL KADER S/O SHAHUL HAMEED		ID No.	S1527160D
Related Vehicle	SCQ5818A (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	YEO LAI CHOON		ID No.	S1159924I
Related Vehicle	SFP5088J (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



SINGAPORE POLICE FORCE



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

3 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

Driver			
Name	KOH CHIN MING EUGENE	ID No.	S9350326J
Related Vehicle	SJS2539G (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LOH YEOW TECK	ID No.	S8809618E
Related Vehicle	SJX7115L (Car)	Contact No.	90055469
Hospital/Clinic	THE CHONG FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	20/06/2018	Date Discharge	20/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	SAMSON LIM CHOON NGEE	ID No.	S7728074Z
Related Vehicle	SLR7977Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/06/2018 at about 1850hrs, I was driving my vehicle bearing the registration number SJX7115L along AYE towards Tuas. At that point of time, I had my son (9 years old) seated at the front passenger seat whereas my wife and my daughter (1 year old) were at the rear passenger seat with my daughter in the baby chair. I was driving in the extreme first lane with a speed of about 80km/h. At that point of time, the road was wet as the rain had just stop.

After the exit of Buona Vista, I saw the vehicle in front of me (SFP5088J) stepping on his brake and eventually come to a stop. I did the same and stopped my vehicle completely behind his. After which, my wife told me that she noticed the car behind me (SJS2539G) was approaching towards my vehicle in a fast manner. After hearing what my wife said, I immediately felt a huge impact on my rear. The impact had caused my vehicle to inched forward and hit onto the vehicle in front of me. After the impact, I went



**SINGAPORE
POLICE FORCE**



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

4 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

down from my vehicle and made a check and discovered that there were a total of five vehicles involved in a chain collision.

The sequence of the vehicle involve is as follows;

SLR7977Z (1st vehicle)
SFP5088J (2nd vehicle)
SJX7115L (3rd vehicle) - my vehicle
SJS2539G (4th vehicle)
SCQ5818A (5th vehicle)

I wish to state that the fourth vehicle had hit onto my rear before the fifth vehicle hit onto his. The impact of my car hit onto the second car had caused the second car to hit onto the first car. No car was towed away as all were still able to move. No police or ambulance were at scene. My car suffered dent on the front bonnet and my left side of the head light was broken. My rear bumper also suffered deep dent and my left tail light and both the reverse light was broken.

I wish to add on that after we drove off from the scene, I, my wife and my son felt some pain and as we are concerned on our daughter's condition, we went to seek medical treatment at The Chong Family Clinic. All of us were treated and both I and my wife were given 3 days of medical leave whereas my son was given 5 days of medical leave. As for my daughter, the doctor made checks on her and as of now she was fine. I have an in-build camera installed in my car however I have yet to check if it captured anything. I am unsure if there is any CCTV installed at the vicinity.

The particular of my family members are as follows;

Wife: Wiu Pei Wen, S8813485J
Son: Loh Yu Xiang Xavier, T0912702F
Daughter: Loh Yi Jun Xandra, T1718287G



**SINGAPORE
POLICE FORCE**



T/20180620/2168

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

5 of 5

Report No. T/20180620/2168

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 3 MUHAMMAD RAFIQ KHAN BIN DAUD

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

SN 40

Signature Of Informant:

Date/Time:
20/06/2018 20:34

Classification Of Case:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

	E	D	A	B	C	
						E-SLR7977Z
						D-SFP5088J
						A-SJX7115L
						B-SJS25394
						C-SCQ5818A

Refer to the police report T/20180620/2168

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Not Allowed
 1/5 #13.000
 21/6/18
 10 by.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6
 #01-46,48,50 Autobay
 SINGAPORE 417883
 VEHICLE NO: SJX 7115L

QTY	PARTICULAR	AMOUNT
1 PCS	REAR WINDSCREEN MOULDING	125.10
1 PCS	TAILGATE 2110.00	2,650.00
1 PCS	TAILGATE REAR LOGO	100.00
1 PCS	TAILGATE INNER LOCK 195	399.00
1 PCS	TAILGATE WEATHERSTRIP 215	298.00
1 PCS	TAILGATE INNER TRIM BOARD 480	650.00
2 PCS	TAILLAMPS @ \$750.00 480 x 2 = 960	1,500.00
2 PCS	TAILLAMP HOUSING PANELS @ \$345.00	690.00 X
1 PCS	REAR BUMPER 1050	1,880.00
1 PCS	REAR BUMPER LOWER 650	1,250.00
2 PCS	REAR BUMPER LAMPS @ \$390.00 110	780.00
2 PCS	REAR BUMPER SIDE RETAINERS @ \$105.00 65 x 2 = 130	210.00
1 PCS	REAR BUMPER REINFORCEMENT 605	645.00
1 SET	REAR BUMPER CLIPS	50.00
1 PCS	REAR END PANEL 725	1,018.00
1 PCS	REAR END PANEL TOP GARNISH 300	425.00
1 PCS	REAR FLOOR PANEL	1,480.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD 466	620.00
2 PCS	REAR FENDERS @ \$1125.00	2,250.00 X
2 PCS	REAR FENDER INNER TRIMS @ \$405.00 290	810.00
1 PCS	REAR EXHAUST 725	820.00
2 PCS	REAR EXHAUST MOUNTINGS @ \$60.00	120.00 X
1 PCS	BONNET 1650	2,150.00
2 PCS	BONNET HINGES @ \$118.00	236.00 X
1 PCS	BONNET INSULATOR	320.00 X
1 SET	BONNET INSULATOR CLIPS	50.00 X
1 PCS	FRONT BUMPER 1080	1,850.00
1 PCS	FRONT BUMPER REINFORCEMENT 620	695.00
1 PCS	FRONT BUMPER SPONGE 211	300.00
2 PCS	FRONT BUMPER SIDE RETAINERS @ \$85.00 65 x 2 = 130	170.00
1 PCS	FRONT BUMPER TOP CENTRE GRILLE 188	302.00
1 PCS	FRONT BUMPER BOTTOM CENTRE GRILLE 180	295.00
2 PCS	FRONT BUMPER FOG LAMPS @ \$433.00	866.00 X
1 PCS	FRONT BUMPER LOGO 100	105.00
1 PCS	FRONT BUMPER CLIPS	50.00

10%

1 PCS	BONNET LOCK
1 PCS	FRONT SUPPORT PANEL 820
1 PCS	FRONT SUPPORT GARNISH 105
2 PCS	HEADLAMPS @\$1850.00 880 X 2 = 1960
1 PCS	AIR CON CONDENSER 1020
1 PCS	AIR CON CONDENSER OUTER GARNISH 245
1 PCS	RADIATOR 1305
1 PCS	RADIATOR FAN MOTOR ASSY 1100
1 PCS	INTER COOLER ASSY
1 PCS	WIPER WASHER TANK
2 PCS	FRONT FENDERS @\$675.00
2 PCS	FRONT FENDER INNER SHIELDS @\$180.00
1 PCS	ALTERNATOR
1 PCS	AIRCON COMPRESSOR

Top	\$109.00 ✓
Seat/Buc	\$1,220.00 ✓
Top	\$188.00 ✓
CAR	\$3,700.00 ✓
Seat/Pan	\$1,288.00 ✓
7.5	\$366.00 ✓
Seat/Cr	\$1,822.00 ✓
Cnc/Jan	\$1,415.00 ✓
11	\$990.00 X
11	\$225.00 X
11	\$1,350.00 X
11	\$360.00 X
11	\$2,122.00 X
11	\$1,800.00 X
	\$43,114.10

(102)

	S.NETT
1 SET	REAR BUMPER REVERSE SENSOR
1 SET	REAR BUMPER REVERSE CARMERA
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR LICENCE PLATE W/HOLDER
1 SET	REAR EXHAUST CHROME
1 PCS	FRONT LICENCE PLATE W/HOLDER
1 BOT	RADIATOR COOLANT
1 PCS	AIRCON COMPRESSOR

shold	\$300.00 200
11	\$500.00 X
ru	\$50.00 ✓
ru	\$50.00 40
3w	\$50.00 ✓
Set	\$200.00 100
3w	\$50.00 40
ru	\$50.00 30
11	\$280.00 X

LABOUR CHARGES:

TOWING CHARGE	\$150.00 50
TO CHECK WIRING	\$100.00 30
TO DISMENTLE & REPLACING REVERSE SENSOR	\$100.00 50
TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00 120
TO DISMENTLE & REFIX REAR EXHAUST	\$100.00 60
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY	\$180.00 80
TO DISMENTLE & REFIX PETROL TANK	\$100.00 X
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00 X
TO REFILL AIR CON GAS	\$150.00 100
TO SPRAY RUST PROOFING	\$300.00 100
LABOUR FOR PANEL BEATING,CUT,WELD STRAIGHTENED & REPLACING PARTS	\$3,000.00 1400
TO PUTTY & SPRAY PAINTING	\$2,500.00 1800

TOTAL	\$51,854.10
-------	-------------

7-20099-1
18081-19

4300
22881-18
17911



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18011252/Usbe2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 02-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 2539G	Veh. Inspected	SJX 7115L
Policy No.		Coverage (\$)	0.00
Claim No.	SJS2539G/SA/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	22/06/2018

2. Vehicle Particulars & Condition

Make & Model	FIAT BRAVO (A)	c.c	1368
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	ZFA19800004289853	Colour	WHITE
Odometer	182600	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/06/2018	Inspection Date	21/06/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7115L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	125.10	125.10
1	TAILGATE	DENTED / BENT	2,650.00	2,110.00
1	TAILGATE REAR LOGO	NECESSARY	100.00	100.00
1	TAILGATE INNER LOCK	TWISTED	399.00	195.00
1	TAILGATE WEATHERSTRIP	TWISTED	298.00	215.00
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	650.00	480.00
2	TAILLAMPS @\$750.00	CRACKED	1,500.00	900.00
2	TAILLAMP HOUSNG PANELS @\$345.00	TO REPAIR SEE LABOUR	690.00	-
1	REAR BUMPER	DISTORTED	1,880.00	1,050.00
1	REAR BUMPER LOWER	DISTORTED	1,250.00	650.00
2	REAR BUMPER LAMPS @\$390.00	N/S BROKEN	780.00	110.00
2	REAR BUMPER SIDE RETAINERS @\$105.00	BENT	210.00	130.00
1	REAR BUMPER REINFORCEMENT	DISTORTED	645.00	605.00
1	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	1,018.00	725.00
1	REAR END PANEL TOP GARNISH	TWISTED / CRACKED	425.00	300.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,480.00	-
1	REAR FLOOR PANEL TOP BOARD	WARPED	620.00	466.00
2	REAR FENDERS @\$1125.00	TO REPAIR SEE LABOUR	2,250.00	-
2	REAR FENDER INNER TRIMS @\$405.00	N/S DEFORMED / TORN	810.00	290.00
1	REAR EXHAUST	BENT / TWISTED	820.00	725.00
2	REAR EXHAUST MOUNTING @\$60.00	NOT NECESSARY	120.00	-
1	BONNET	BUCKLED	2,150.00	1,650.00
2	BONNET HINGES @\$118.00	TO REPAIR SEE LABOUR	236.00	-
1	BONNET INSULATOR	NOT NECESSARY	320.00	-
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	50.00	-

Report Ref No. CS/EGI18011252/Usbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DISTORTED	1,850.00	1,080.00
1	FRONT BUMPER REINFORCEMENT	BENT	695.00	620.00
1	FRONT BUMPER SPONGE	TORN	300.00	211.00
2	FRONT BUMPER SIDE RETAINERS @\$85.00	BENT	170.00	130.00
1	FRONT BUMPER TOP CENTRE GRILLE	CRACKED	302.00	188.00
1	FRONT BUMPER BOTTOM CENTRE GRILLE	CRACKED	295.00	180.00
2	FRONT BUMPER FOG LAMPS @\$433.00	NOT NECESSARY	866.00	-
1	FRONT BUMPER LOGO	NECESSARY	105.00	100.00
1	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	BONNET LOCK	TWISTED	109.00	109.00
1	FRONT SUPPORT PANEL	BENT / BUCKLED	1,220.00	820.00
1	FRONT SUPPORT GARNISH	TORN	188.00	105.00
2	HEADLAMPS @\$1850.00	CRACKED	3,700.00	1,960.00
1	AIR CON CONDENSER	BENT / PUNCTURE	1,288.00	1,020.00
1	AIR CON CONDENSER OUTER GARNISH	DISTORTED	366.00	245.00
1	RADIATOR	BENT / CRACKED	1,822.00	1,305.00
1	RADIATOR FAN MOTOR ASSY	CRACKED / JAMMED	1,415.00	1,100.00
1	INTER COOLER ASSY	NOT NECESSARY	990.00	-
1	WIPER WASHER TANK	NOT NECESSARY	225.00	-
2	FRONT FENDERS @\$675.00	TO REPAIR SEE LABOUR	1,350.00	-
2	FRONT FENDER INNER SHIELDS @\$180.00	NOT NECESSARY	360.00	-
1	ALTERNATOR	NOT NECESSARY	2,122.00	-
1	AIRCON COMPRESSOR	NOT NECESSARY	1,800.00	-
	LESS 10% DISCOUNT		-	-2,009.91
			43,114.10	18,089.19
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	SET REAR BUMPER REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	50.00

Report Ref No. CS/EGI18011252/Usbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR EXHAUST CHROME (SN)	BENT	200.00	100.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
1	AIRCON COMPRESSOR (SN)	NOT NECESSARY	280.00	-
			1,530.00	510.00
	LABOUR			
	TOWING CHARGE		150.00	50.00
	TO CHECK WIRING		100.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR		100.00	50.00
	TO DISMENTLE & REFIX REAR WINDSCREEN		150.00	120.00
	TO DISMENTLE & REFIX REAR EXHAUST		100.00	60.00
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY		180.00	80.00
	TO DISMENTLE & REFIX PETROL TANK	NOT NECESSARY	100.00	-
	TO MOUNT VEHICLE ON CAR O-LINER	NOT NECESSARY	380.00	-
	TO REFILL AIR CON GAS		150.00	100.00
	TO SPRAY RUST PROOFING		300.00	100.00
	LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTENED & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSNG PANELS, REAR FLOOR PANEL, REAR FENDERS, BONNET HINGES AND FRONT FENDERS.		3,000.00	1,400.00
	TO PUTTY & SPRAY PAINTING		2,500.00	1,800.00
			7,210.00	3,790.00
GRAND TOTAL			51,854.10	22,389.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/EGI18011252/Usbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.