

22/03/2002

ASS. REC. BY:

REF: CS3/AIG18011259/T124d30

Special Instruction:

Surveyor: Tau fikh
MeimenASSIGNMENT (Office)From (Person): Chin Lee Ying

of

AIGDate/Time: 21/6/18 @ 9:44am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 3622H

Insured:

SLZ 2780P

at Workshop m/s

Topmax Auto Bodyshop

Tel:

6744 2653

of

Blk 3007 Ubi Road 1 # 01-410

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/06/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time: 12:21pm @ 21/6/18

Person Contacted:

Carmen

Vehicle

IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJP 3622H - x</u>
	<u>SLZ 2780P - x.</u>
<u>25/6/18</u>	<u>Disman/led.</u>

REF: **AIG****ASSIGNMENT****LoE 2019 March**From: Date: **21/06/18**

Estimated Cost:

OD: **(TP)** WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJP 3622H

at Workshop n/s

Topmax Autoof **Blk 3007 ubi Road 1 # 01-410**

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Carmen@ 67442653

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **7** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **(up)**

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

25 P/18 Submit DAR Report.Veh No: **SJP 3622 H**Yr Regn: **209, March**Type: **(M)** Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520I

C.G

1995

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

196810

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBANT/2060GX 29924Gen. Cond: **(Good)** / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/35R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21/6/18

Survey held at

TopmaxDes. of Damages: Frt / Rear / O/S **(N/S)** / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?

☐

: Prel. Report

ti)

☐

: Final Report

Date/Time File Return to?

ti)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

180**20****200**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18011259/T1z4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 21-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLZ 2780P	Veh. Inspected	SJP 3622H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	21/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/06/2018	Inspection Date	21/06/2018
Survey held at	TOPMAX AUTO BODYSHOP BLK 3007 UBI ROAD 1 #01-410 SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLZ2780P AND SJP3622H ON 19/06/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 21/6/2018 9:44:14 AM

Attachments:  FaxB3EE.TIF  Notice to AIG to conduct PRI (Topmax)SJP3622H.PDF

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

YOGARAJAH LLC

ADVOCATES & SOLICITORS

663 North Bridge Road
#19-05 Southbank
Singapore 196785
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No: 201333127N)

Our Ref : CY(Topmax)SJP3622H(AC)hh
Please email to: helen@yoga-legal.com
Your Ref : Your insured vehicle SLZ2780P

20th June 2018

Ong Hwee Nai
c/o The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SJP3622H & SLZ2780P ON 19/06/2018 @ 13:00 HRS
ALONG BLK 453 ANG MO KIO AVE 10 CAR PARK

We are instructed by M/s. Seng Huat Bean Curd Pte Ltd to notify you of a road traffic accident on 19th June 2018 at about 13:00 hours along Blk 453 Ang Mo Kio Ave 10 car park involving our client's vehicle SJP3622H and vehicle number SLZ2780P driven by you /your insured's driver at the material time. A copy of our client's accident statement is attached.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

C. Yogarajah LLC

Enc

c.c. client
M/s. Seng Huat Bean Curd Pte Ltd
c/o M/s. Topmax Auto BodyShop
By email
(Attention: Carmen Chang)

For Surveyor
Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Disclaimers: Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been transmitted securely, the sender does not warrant the confidentiality of the content of this message or the accuracy of the information contained therein. If you wish to receive a hard copy of this communication for comparison or should you require any other form of verification of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

Our Ref : CY(Topmax)SJP3622H(AC)hh
Please email to: helen@yoga-legal.com
Your Ref : 2282746869SG003

20th June 2018

The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

By Email

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SJP3622H & SLZ2780P ON 19/06/2018 @ 13:00 HRS
ALONG BLK 453 ANG MO KIO AVE 10 CAR PARK

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose M/r. Alan Cheong K.H of M/s. C L Appraiser Pte Ltd to conduct a Pre-Repair inspection.


Please be informed that the said vehicle can be inspected at:

Name of workshop : M/s. TopMax Auto BodyShop
Address : Block 3007 Ubi Road 1 #01-410
Singapore 408701
Contact person : Miss Carmen Chang
Telephone number : 67442653
Fax : 67441153

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a "single joint expert".

If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.

Yours faithfully,


C. Yogarajah LLC

c.c. client
M/s. Seng Huat Bean Curd Pte Ltd
M/s. Topmax Auto BodyShop (By email)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection:

/

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6477M
Vehicle Details	
Vehicle No.:	SJP3622H
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jun 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	B303I350N46B20BE
Chassis No.:	WBANT12060CX29924
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$44,437.00
Original Registration Date:	20 Mar 2009
First Registration Date:	20 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$44,437.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Mar 2019
PARF Rebate Amount:	\$22,218.00
Intended COE Rebate Details	
COE Expiry Date:	19 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$5,001.00
COE Rebate Amount:	\$363.00
Total Rebate Amount:	\$22,581.00

The information contained herein is correct as at 25 Jun 2018

OK

8 panels

27 - 28k

9 mth 1 day left

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2018 16:17
Date Of Accident	19/06/2018 13:00
Exact Location Of Accident	BLK 453 ANG MO KIO AVE 10 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP3622H
Insured/Policyholder	
Name Of Registered Owner	SENG HUAT BEAN CURD PTE LTD
Co Reg No	201326477M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96991769

Vehicle Particulars

Manufacturer	BMW
Model	520I-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA266761/1
Cover Note Number	

Driver

Name of Driver	NG TIEN CHYE ALAN
NRIC No	S7632303H
Date Of Birth	15/09/1976
Occupation	INDOOR
Date Of Driving Pass	28/04/2004
Driving Experience	14 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96991769
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 116A RIVERVALE DRIVE #13-02
SINGAPORE

Postcode 541116

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLZ2780P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if so said.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the sending of correspondence, statements, invoices, reports or notices to me, which could involve disclosures of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be acted outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Person's Signature
Name:
NRIC/PR No. 

Sketch Plan #2

SKETCH PLAN

Vehicle No	
A	SLP3622 H
B	SL72780 P

Legend	
Vehicle	Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19th June 2018 at about 1pm, when I was leaving the carpark of B14 453 Ang Mo Kio Ave 10, just metres away from the exit gantry I was hit by another car on my left side of the passenger area. The other car was supposed to stop and waited for me to drive towards the gantry, but from the driver I told me, she wanted to press on the brake but instead she pressed on the accelerator. And therefore my side of my left car was hit. I wasn't injured and I was alone at the incident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a 14-day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Person's Signature

Name:

NRIC/FIN No.:

Guidance Sheet - Motor Insurance

MOTOR CAR (TT)

Front Portion

Vehicle No: SJP 36224

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender		DD	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp		MIS	
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield		DIV	
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim		CUT	
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper	SCR ✓		
1143	993017	Rear Bumper Lower	SCR ✓		
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	DIS ✓		
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	DIS ✓		
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim	CUT ✓		
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

[Signature]
25/7/2018

(01)Bent (2)Bent (3)Bent (4)Cracked (5)Cur (6)Scratched
(07)Deformed (08)Glued (09)Hatched (10)Broken (11)Necessary (12)Missing
(13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (LFD)

(1) Replace (γ^2) (2) Repair (γ^2) (3) Check (γ^2)
(4) Not Consistent (If C)

Vehicle No:

SIP1622 H

[illegible]

Assessor: Tau Likh

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

MOTOR CAR (UC)

Vehicle No: SJP 3622 H

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	DA	✓	
1376	995199	Frt LH Knuckle Arm Bearing	DM	✓	
1377	995178	Frt LH Lower Arm	DM	✓	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm	DA	✓	
1409	993551	Rear LH Knuckle Arm Bearing	NEC	✓	
1410	993597	Rear LH Lower Arm	BT	✓	
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

Assessor: Toufik

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2018 Edit Reg		21 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ONG HWEE NAI , ID: S0062513B									
Main Claimant: SENG HUAT BEAN CURD PTE LTD , Co. Reg. No.: 201326477M									
Vehicle Reg. No.: SJP3622H		Date of Loss: 19/06/2018 13:00 - :59 [110 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2282746869SG		Policy/Cover Note No.: 1800043429 (Comprehensive) Coverage: 27/04/2018 - 26/04/2020							
Vehicle Reg. No. (Insured): SLZ2780P		Policy No. (Claimant):							
		Excess:							
Repairer: Topmax Auto Bodyshop (HQ) BLK 3007 UBI ROAD 1, #01-410 Kampong Ubi Industrial Estate, 408701 Ubi - Tel: 67442653									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/07/2018]									
Claimant's Solicitor: C YOGARAJAH LLC - Tel: 62925838									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (25/06/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJP3622H (2282746869SG)
[SLZ2780P]**

TP

SENG HUAT BEAN CURD PTE LTD

Jun 19 2018 1:00PM

[ONG HWEE NAI]

Topmax Auto Bodyshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print	
1	23/06/18 11:03	General View														Load JPG	☒	
2	23/06/18 11:03	General View														Load JPG	☒	
3	23/06/18 11:03	General View														Load JPG	☒	
4	23/06/18 11:03	General View														Load JPG	☒	
5	23/06/18 11:03	General View														Load JPG	☒	
6	23/06/18 11:03	General View														Load JPG	☒	
7	23/06/18 11:03	General View														Load JPG	☒	
8	23/06/18 11:03	General View														Load JPG	☒	
9	23/06/18 11:03	General View														Load JPG	☒	
10	23/06/18 11:03	General View														Load JPG	☒	
11	23/06/18 11:03	General View														Load JPG	☒	
12	23/06/18 11:03	General View														Load JPG	☒	
13	23/06/18 11:03	General View														Load JPG	☒	
14	23/06/18 11:03	General View														Load JPG	☒	
15	23/06/18 11:03	General View														Load JPG	☒	
16	23/06/18 11:03	General View														Load JPG	☒	
17	23/06/18 11:03	General View														Load JPG	☒	
18	23/06/18 11:03	General View														Load JPG	☒	
19	23/06/18 11:03	General View														Load JPG	☒	
20	23/06/18 11:03	General View														Load JPG	☒	
21	23/06/18 11:03	General View														Load JPG	☒	
22	23/06/18 11:03	General View														Load JPG	☒	
23	23/06/18 11:03	General View														Load JPG	☒	
24	23/06/18 11:03	General View														Load JPG	☒	
25	23/06/18 11:03	General View														Load JPG	☒	
26	23/06/18 11:03	General View														Load JPG	☒	
27	23/06/18 11:03	General View														Load JPG	☒	
28	23/06/18 11:03	General View														Load JPG	☒	
29	23/06/18 11:03	General View														Load JPG	☒	
30	23/06/18 11:03	General View														Load JPG	☒	
31	23/06/18 11:03	General View														Load JPG	☒	
32	23/06/18 11:03	General View														Load JPG	☒	
33	23/06/18 11:03	General View														Load JPG	☒	
34	23/06/18 11:03	General View														Load JPG	☒	
35	23/06/18 11:03	General View														Load JPG	☒	
36	23/06/18 11:03	General View														Load JPG	☒	
37	23/06/18 11:03	General View														Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/06/18 11:03	General View	 Load JPG	☒
39	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
40	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
41	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
42	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
43	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
44	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
45	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
46	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
47	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
48	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
49	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
50	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
51	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
52	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
53	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
54	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
55	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
56	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
57	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
58	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
59	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
60	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
61	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
62	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
63	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
64	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
65	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
66	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
67	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
68	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
69	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
70	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
71	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
72	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
73	25/07/18 10:11	Dismantled Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/06/18 13:39	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011259/T1Z4D3E2

Date: 25/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800043429
Claimant Vehicle No : SJP3622H **Insured Vehicle No :** SLZ2780P
 Date of Loss: 19/06/2018 Nature of Claim: TP Claim No: 2282746869SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP3622H**
 Make & Model: BMW 520I, 2.0 (A) Engine No: B303I350N46B20BE
 Reg. Date: 20/03/2009 (Man. Year: 2008) Chassis No: WBANT12060CX29924
 Colour: White Odometer: 196810 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/06/2018
 Date Inspected: 21/06/2018 Inspected At: Topmax Auto Bodyshop (HQ)
 BLK 3007 UBI ROAD 1, #01-410 Kampong
 Ubi Industrial Estate
 Singapore 408701
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Dented	0.00 F	*- F
2	1		*FRT LH FENDER LAMP	Missing	0.00 F	*- F
3	1		*FRT LH FENDER INNER SHIELD	Distorted	0.00 F	*- F
4	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
5	1		*REAR BUMPER UPPER	Scratched	0.00 F	*- F
6	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F
7	1		*REAR LH FENDER	Distorted	0.00 F	*- F
8	1		*REAR LH FENDER INNER SHIELD	Distorted	0.00 F	*- F
9	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
10	1		*FRT LH DOOR	Dented	0.00 F	*- F
11	1		*FRT LH DOOR HINGE (LOWER)	Bent	0.00 F	*- F
12	1		*FRT LH DOOR WING MIRROR	Repair	0.00 F	*- F
13	1		*FRT LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
14	1		*FRT LH DOOR GLASS REGULATOR MOTOR	Damaged	0.00 F	*- F
15	1		*FRT LH DOOR RUBBER	Cut	0.00 F	*- F
16	1		*FRT LH DOOR CHECKER	Cut	0.00 F	*- F
17	1		*FRT LH DOOR OUTER PILLAR	Repair	0.00 F	*- F
18	1		*ROCKER PANEL GARNISH LH	Cut	0.00 F	*- F
19	1		*REAR LH DOOR	Dented	0.00 F	*- F
20	1		*REAR LH DOOR RUBBER	Cut	0.00 F	*- F
21	1		*FRT LH KNUCKLE ARM	Damaged	0.00 F	*- F
22	1		*FRT LH KNUCKLE ARM BEARING	Damaged	0.00 F	*- F
23	1		*FRT LH LOWER ARM	Damaged	0.00 F	*- F
24	1		*REAR LH KNUCKLE ARM	Distorted	0.00 F	*- F
25	1		*REAR LH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
26	1		*REAR LH LOWER ARM	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >