

INSDM

INS. CASE OWNER:

Maricel

CC 6 LRP  
ATG1801

12/6/18, 12/6/18

LKK:

IDAC:

Surveyor:

Tautik

DOI:

ASSIGNMENT

20/6/18

Date / Time:

20/6/18

Registered in Merit:

21/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLL 1170E

Name of Insured:

LRP

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

18/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Hui (Hoon) Yuen

Driver Tel No.:

(V/L/YES / NO)

Claim No.:

70497481255

Policy No.:

44444416

Make / Model:

Honda

Place of Accident:

CENTRAL BUSINESS

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final? Yes / No

SLV 6971A



INSRS:

WSP:

Tel:

Liability:

RMKS:

PENGAS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

25/6/18

SLV 6971A - 2

SLL 1170E - 2

4/7/18

6/7/18

6/21/18

Unclear.

Email to TP. Request for video.

Sent letter to OI via email (5/5/18).

- VIDEO IN. STAMP IN V/UC/SLV 6971A

- UPLOADED IN WIKIMEDIA

19/06/19

- SEND 2ND OFFER TO TP.

20/07/19

- MB INTERVIEWED MAINTAIN OFFER.

- MAINTAIN OFFER TO TP.

26/07/2020

- TP ACCEPTED OFFER

- ALL DOCS IN ORDER

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

25/6/18

By (MATTI)

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI (MATTI)

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA/GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

\$5,379.92

6 days

Reduction:

63 %

FINAL SETTLEMENT

Date/Time:

26/07/2020

Confirm with:

ALOX

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL

Repair Cost:

(w/GR)

\$5,756.09

Loss of Rental (LOR):

\$5

560.00

(7 days)

x 480

(GRAB RATES)

Loss of Use (LOU):

\$5

-

(5 x days)

Loss of Income (LOI):

\$5

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

7.49

Medical:

\$5

-

Disbursement:

\$5

-

(e.g. Tow / Independent)

Legal Cost:

\$5

-

Total:

\$5

6,323.58

Global Sum \$5:

6,320.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

\$5

6,320.00

Name 1:

PENGAS ENGINEERING &amp; TRADING PTE LTD

Payee 2: (Strike if N.A.)

\$5

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$5

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4820.00

COPY SENT  
21/7/2020

Tanfer

REF: ALH

# ASSIGNMENT

From: Date: 20062018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 6971A

at Workshop mis:

Pegasus

74 Kian Teck Rd

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res. : Yes or No

Lum Sum:

%

3 Val. : Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 6971A

Yr Regn:

2018 Jan.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer nr

Make:

Max 43

cc 1496

Colour:

Silver

A/C: Insured / Std / Nil / NA

Sp Reading:

-

T/Radio: Insured / Std / Nil / NA

Eng No:

C No:

5M63N2248H0160215

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Bim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

2

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

20/6/18 @ 4pm

Survey held at:

Pegasus

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt N/S, U/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SLM 7873R

No Key

PIP \$ 5379.52 Red \$ 8751.28 / 62%  
(Red: 49,163.36 / 60%)

CaseTime, File Pass to?

☐

: Preli. Report

File

☐

: Final Report

CaseTime, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. S + RT. 2.

3. Other

4. Other

5. Other

6. Other

TOTAL

Report Format:

Lump Sum / I.B. / IS

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                             |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                     |                                                                              | Ref : CC6/LCR18011262/T1pb3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDINGSINGAPORE 079120                                                                              |                                                                              | Date : 21-06-2018           |            |  |
|                                                                                                                                        |                                                                              | Code : LCR                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                             |            |                                                                                     |
| Insured Veh.                                                                                                                           | SLL 1170E                                                                    | Veh. Inspected              | SLV 6971A  |                                                                                     |
| Policy No.                                                                                                                             |                                                                              | Coverage (\$)               | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                              | Excess (\$)                 | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                              | Assign Date                 | 21/06/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                             |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                              | c.c                         | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.                |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                              | Colour                      |            |                                                                                     |
| Odometer                                                                                                                               | -                                                                            | Steering                    |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                              | Modification                |            |                                                                                     |
| General                                                                                                                                |                                                                              |                             |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                             |            |                                                                                     |
|                                                                                                                                        | Size                                                                         | Make                        | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                              |                             | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                              |                             | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                              |                             | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                              |                             | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                             |            |                                                                                     |
|                                                                                                                                        |                                                                              |                             |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                              |                             |            |                                                                                     |
| Accident Date                                                                                                                          | 18/06/2018                                                                   | Inspection Date             | 20/06/2018 |                                                                                     |
| Survey held at                                                                                                                         | PEGASUS ENGINEERING & TRADING PTE LTD<br>51 DEFU LANE 10<br>SINGAPORE 539216 |                             |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                             |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                             |            |                                                                                     |

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                           |                                                                                                                                                          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>74 KIAN TECK ROAD<br>SINGAPORE 628800<br><br>Officer in Charge : WEE TZE FAH<br>Tel :<br>Email : | <b>Customer :</b><br><br><b>GRAB RENTALS 2 PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax No : |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                            |                                        |                              |
|--------------------------------------------------------------------------------------------|----------------------------------------|------------------------------|
| <b>Quotation No. :</b> QO18/06-1176                                                        | <b>Quotation Date :</b> 18/06/2018     | <b>Terms :</b> 30 DAYS       |
| <b>Vehicle No. :</b> SLV6971A                                                              | <b>Chassis No. :</b> JM6BN22A8H0160215 | <b>Third Party Insurer :</b> |
| <b>Model :</b> MAZDA 3                                                                     | <b>Date of Accident :</b>              |                              |
| <b>Remarks :</b> TP INSURER: AIG, INSURED'S VEH NO: SLL1170E, DATE OF ACCIDENT: 18.06.2018 |                                        |                              |

| ITEM | DESCRIPTION                                         | Qty | UNIT PRICE | AMOUNT (SGD) |
|------|-----------------------------------------------------|-----|------------|--------------|
| 1    | LHS FRONT FENDER                                    | 1   | 334.0000   | bt 334.00    |
| 2    | LHS FRONT FENDER INNER COWLING                      | 1   | 130.0000   | de 130.00    |
| 3    | LHS FRONT FENDER INNER COWLING CLIPS                | 6   | 5.0000     | ne 30.00     |
| 4    | LHS FRONT FENDER INSULATION FOAM                    | 1   | 36.0000    | neq 36.00    |
| 5    | LHS FRONT FENDER TOP GARNISH                        | 1   | 46.0000    | ny x 46.00   |
| 6    | LHS FRONT FENDER TOP GARNISH CLIPS                  | 3   | 5.0000     | ny x 15.00   |
| 7    | LHS FRONT FENDER STAY BRACKET                       | 1   | 40.0000    | ny x 40.00   |
| 8    | LHS HEAD LAMP                                       | 1   | 1,020.0000 | ny 1,020.00  |
| 9    | LHS HEAD LAMP CLIP HOLDER                           | 1   | 10.5000    | ne 10.50     |
| 10   | <del>LHS</del> FRONT BUMPER                         | 1   | 825.0000   | ny 825.00    |
| 11   | LHS FRONT BUMPER INDICATION LIGHT                   | 1   | 140.0000   | ny 140.00    |
| 12   | LHS FRONT BUMPER INDICATION LIGHT GARNISH           | 1   | 38.0000    | de 38.00     |
| 13   | LHS FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION | 1   | 20.0000    | mis 20.00    |
| 14   | FRONT BUMPER CLIPS                                  | 10  | 5.0000     | ny 50.00     |
| 15   | LHS FRONT BUMPER TOW COVER                          | 1   | 14.0000    | x 14.00      |
| 16   | LHS FRONT BUMPER REINFORCEMENT                      | 1   | 480.0000   | x 480.00     |
| 17   | LHS FRONT BUMPER REINFORCEMENT COVER                | 1   | 67.0000    | x 67.00      |
| 18   | FRONT BUMPER REINFORCEMENT COVER CLIPS              | 4   | 5.0000     | x 20.00      |
| 19   | LHS FRONT BUMPER LOWER SUPPORT GARNISH              | 1   | 96.0000    | ? 96.00      |
| 20   | LHS FRONT BUMPER LOWER SPLASHIELD COVER             | 1   | 95.0000    | ? 95.00      |
| 21   | FRONT SUPPORT PANEL - METAL                         | 1   | 140.0000   | ? 140.00     |
| 22   | FRONT SUPPORT PANEL - FIBRE                         | 1   | 470.0000   | ? 470.00     |
| 23   | FRONT SUPPORT PANEL TOP COVER                       | 1   | 91.0000    | ? 91.00      |

C/F 0.00



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                           |                                                                                              |
|-------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|
| <b>From :</b>                                                                             | <b>Customer :</b>                                                                            |
| <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>74 KIAN TECK ROAD<br>SINGAPORE 628800 | <b>GRAB RENTALS 2 PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960 |
| Officer in Charge : WEE TZE FAH<br>Tel :<br>Email :                                       | Attn :<br>Tel :<br>Fax No. :                                                                 |

|                                                                                     |                                 |                       |
|-------------------------------------------------------------------------------------|---------------------------------|-----------------------|
| Quotation No. : QO18/06-1176                                                        | Quotation Date : 18/06/2018     | Terms : 30 DAYS       |
| Vehicle No. : SLV6971A                                                              | Chassis No. : JM6BN22A8H0160215 | Third Party Insurer : |
| Model : MAZDA 3                                                                     | Date of Accident :              |                       |
| Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLL1170E, DATE OF ACCIDENT: 18.06.2018 |                                 |                       |

| ITEM | DESCRIPTION                                 | Qty | UNIT PRICE | AMOUNT (SGD) |
|------|---------------------------------------------|-----|------------|--------------|
|      |                                             |     | B/F        | 0.00         |
| 24   | RADIATOR GRILLE                             | 1   | 150.0000   | 150.00       |
| 25   | RADIATOR GRILLE CHROME GARNISH              | 1   | 183.0000   | 183.00       |
| 26   | RADIATOR GRILLE CHROME GARNISH BASE         | 1   | 20.0000    | 20.00        |
| 27   | RADIATOR GRILLE OUTER GARNISH               | 4   | 339.0000   | 1,356.00     |
| 28   | RADIATOR GRILLE OUTER GARNISH RIVETS        | 1   | 36.0000    | 36.00        |
| 29   | RADIATOR GRILLE EMBLEM BADGE                | 1   | 59.0000    | 59.00        |
| 30   | RADIATOR GRILLE OUTER GARNISH SUPPORT       | 1   | 185.0000   | 185.00       |
| 31   | RADIATOR GRILLE OUTER GARNISH SUPPORT CLIPS | 3   | 5.0000     | 15.00        |
| 32   | FRONT WHEEL HUB CAP                         | 1   | 120.0000   | 120.00       |
| 33   | LHS FRONT SHOCK ABSORBER                    | 1   | 287.0000   | 287.00       |
| 34   | LHS FRONT SHOCK ABSORBER TOP MOUNT          | 1   | 92.0000    | 92.00        |
| 35   | LHS FRONT LOWER ARM                         | 1   | 485.0000   | 485.00       |
| 36   | LHS FRONT WHEEL KNUCKLE                     | 1   | 384.0000   | 384.00       |
| 37   | LHS FRONT WHEEL BEARING WITH HUB            | 1   | 542.0000   | 542.00       |
| 38   | LHS FRONT WHEEL ABS SENSOR                  | 1   | 133.0000   | 133.00       |
| 39   | STEERING ROCK AND PINION ASSY               | 1   | 193.0000   | 193.00       |
| 40   | LHS ENGINE SUSPENSION CROSS MEMBER BRACKET  | 1   | 59.0000    | 59.00        |
| 41   | BONNET                                      | 1   | 1,068.0000 | 1,068.00     |
| 42   | BONNET HINGE                                | 2   | 82.0000    | 164.00       |
| 43   | BONNET OUTER WEATHERSTRIP SEAL              | 1   | 64.0000    | 64.00        |
| 44   | BONNET INNER WEATHERSTRIP SEAL              | 1   | 26.0000    | 26.00        |
| 45   | LHS DRIVESHAFT                              | 1   | 1,336.0000 | 1,336.00     |

C/F 0.00

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                           |                                                                                                                                                           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>74 KIAN TECK ROAD<br>SINGAPORE 628800<br><br>Officer in Charge : WEE TZE FAH<br>Tel :<br>Email : | <b>Customer :</b><br><br><b>GRAB RENTALS 2 PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax No. : |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                            |                                        |                              |
|--------------------------------------------------------------------------------------------|----------------------------------------|------------------------------|
| <b>Quotation No. :</b> QO18/06-1176                                                        | <b>Quotation Date :</b> 18/06/2018     | <b>Terms :</b> 30 DAYS       |
| <b>Vehicle No. :</b> SLV6971A                                                              | <b>Chassis No. :</b> JM6BN22A8H0160215 | <b>Third Party Insurer :</b> |
| <b>Model :</b> MAZDA 3                                                                     | <b>Date of Accident :</b>              |                              |
| <b>Remarks :</b> TP INSURER: AIG, INSURED'S VEH NO: SLL1170E, DATE OF ACCIDENT: 18.06.2018 |                                        |                              |

| ITEM | DESCRIPTION                                                                                                                    | Qty | UNIT PRICE  | AMOUNT (SGD)         |
|------|--------------------------------------------------------------------------------------------------------------------------------|-----|-------------|----------------------|
|      |                                                                                                                                |     | B/F         | / 0.00               |
| 46   | LHS DRIVESHAFT OIL SEAL                                                                                                        | 1   | 24.0000     | MX 24.00             |
| 47   | LESS 20% ON ITEM 1 - 46                                                                                                        | 1   | -2,237.7000 | -2,237.70            |
| 48   | FRONT WHEEL RIM                                                                                                                | 1   | 600.0000    | MX 300 600.00        |
| 49   | FRONT WHEEL TYRE                                                                                                               | 1   | 250.0000    | ph 250.00            |
| 50   | TO CHECK ELECTRICAL LIGHTING CONCERNED                                                                                         | 1   | 80.0000     | 30 80.00             |
| 51   | TO RUST-PROOFING OF THE AFFECTED AREAS                                                                                         | 1   | 150.0000    | 30 150.00            |
| 52   | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT                                                                        | 1   | 120.0000    | 80 120.00            |
| 53   | TO TRANSFER OF LHS WHEEL TYRE, RIM AND ON WHEEL BALANCING                                                                      | 1   | 80.0000     | nn X 30? 80.00       |
| 54   | TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING | 1   | 350.0000    | nn 150? photo 350.00 |
| 55   | USING ONBOARD SCAN TOOL PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT                  | 1   | 550.0000    | 150 550.00           |
| 56   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME         | 1   | 1,400.0000  | 700 1,400.00         |
| 57   | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                               | 1   | 1,600.0000  | 700 1,600.00         |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Signature:

Date:

**Sub Total** 14,130.80  
**GST(7.00%)** 989.16  
**Total (SGD)** 15,119.96

Tan Lim 97445749  
 WP  
 20/6/18 @ 1600  
 Resurvey before paint  
 6 days  
 Sun@1hlaunto.com



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                |
|--------------------------------------------------------------------------------|
| <b>From :</b>                                                                  |
| PEGASUS ENGINEERING & TRADING PTE LTD<br>74 KIAN TECK ROAD<br>SINGAPORE 628800 |
| Officer in Charge : WEE TZE FAH<br>Tel :<br>Email :                            |

|                                                                                       |
|---------------------------------------------------------------------------------------|
| <b>Customer :</b>                                                                     |
| GRAB RENTALS 2 PTE LTD<br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960 |
| Attn :<br>Tel :<br>Fax No. :                                                          |

|                                           |                                 |                           |
|-------------------------------------------|---------------------------------|---------------------------|
| Quotation No. : QO18/06-1389              | Quotation Date : 22/06/2018     | Terms : 30 DAYS           |
| Vehicle No. : SLV6971A                    | Chassis No. : JM6BN22A8H0160215 | Third Party Insurer : AIG |
| Model : MAZDA 3                           | Date of Accident : 18/06/2018   |                           |
| Remarks : SUPPLEMENTARY ITEM FOR SLV6971A |                                 |                           |

| ITEM | DESCRIPTION        | Qty | UNIT PRICE | AMOUNT (SGD) |
|------|--------------------|-----|------------|--------------|
| 1    | DC CONVERTER       | 1   | 481.4000   | 481.40       |
| 2    | LESS 20% ON ITEM 1 | 1   | -96.2800   | -96.28       |

|             |        |
|-------------|--------|
| Sub Total   | 385.12 |
| GST(7.00%)  | 26.96  |
| Total (SGD) | 412.08 |

Please conduct the survey at  
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                   |                                                                                                                                                  |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>74 KIAN TECK ROAD<br>SINGAPORE 628800<br>Officer in Charge : WEE TZE FAH<br>Tel :<br>Email : | <b>Customer :</b><br><b>GRAB RENTALS 2 PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br>Attn :<br>Tel :<br>Fax No : |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                     |                                 |                      |
|-------------------------------------------------------------------------------------|---------------------------------|----------------------|
| Quotation No. : QO18/08-1176                                                        | Quotation Date : 18/06/2018     | Terms : 30 DAYS      |
| Vehicle No. : SLV6971A                                                              | Chassis No. : JM5BN22A8H0160215 | Thrd Party Insurer : |
| Model : MAZDA 3                                                                     | Date of Accident :              |                      |
| Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLL1170E, DATE OF ACCIDENT: 18.06.2018 |                                 |                      |

| ITEM | DESCRIPTION                                         | Qty | UNIT PRICE | AMOUNT (SGD) |
|------|-----------------------------------------------------|-----|------------|--------------|
| 1    | LHS FRONT FENDER                                    | 1   | 334.0000   | bf 334.00    |
| 2    | LHS FRONT FENDER INNER COWLING                      | 1   | 130.0000   | de 130.00    |
| 3    | LHS FRONT FENDER INNER COWLING CLIPS                | 8   | 5.0000     | ne 30.00     |
| 4    | LHS FRONT FENDER INSULATION FOAM                    | 1   | 36.0000    | ne 36.00     |
| 5    | LHS FRONT FENDER TOP GARNISH                        | 1   | 46.0000    | X 46.00      |
| 6    | LHS FRONT FENDER TOP GARNISH CLIPS                  | 3   | 5.0000     | X 15.00      |
| 7    | LHS FRONT FENDER STAY BRACKET                       | 1   | 40.0000    | ? 40.00      |
| 8    | LHS HEAD LAMP                                       | 1   | 1,020.0000 | ora 1,020.00 |
| 9    | LHS HEAD LAMP CLIP HOLDER                           | 1   | 10.5000    | de 10.50     |
| 10   | LHS FRONT BUMPER                                    | 1   | 825.0000   | ora 825.00   |
| 11   | LHS FRONT BUMPER INDICATION LIGHT                   | 1   | 140.0000   | ora 140.00   |
| 12   | LHS FRONT BUMPER INDICATION LIGHT GARNISH           | 1   | 38.0000    | de 38.00     |
| 13   | LHS FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION | 1   | 20.0000    | mis 20.00    |
| 14   | FRONT BUMPER CLIPS                                  | 10  | 5.0000     | ora 50.00    |
| 15   | LHS FRONT BUMPER TOW COVER                          | 1   | 14.0000    | X 14.00      |
| 16   | LHS FRONT BUMPER REINFORCEMENT                      | 1   | 480.0000   | X 480.00     |
| 17   | LHS FRONT BUMPER REINFORCEMENT COVER                | 1   | 67.0000    | X 67.00      |
| 18   | FRONT BUMPER REINFORCEMENT COVER CLIPS              | 4   | 5.0000     | X 20.00      |
| 19   | LHS FRONT BUMPER LOWER SUPPORT GARNISH              | 1   | 98.0000    | ? 98.00      |
| 20   | LHS FRONT BUMPER LOWER SPLASHIELD COVER             | 1   | 95.0000    | ? 95.00      |
| 21   | FRONT SUPPORT PANEL - METAL                         | 1   | 140.0000   | ? 140.00     |
| 22   | FRONT SUPPORT PANEL - FIBRE                         | 1   | 470.0000   | ? 470.00     |
| 23   | FRONT SUPPORT PANEL TOP COVER                       | 1   | 91.0000    | X 91.00      |

### Supplement Parts

\* Converter, DC/AC 15481.40 ora  
 Wheel housing - repair fur

2633.50 CIF 0.00

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                           |                                                                                                                                                          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>74 KIAN TECK ROAD<br>SINGAPORE 628800<br><br>Officer in Charge : WEE TZE FAH<br>Tel :<br>Email : | <b>Customer :</b><br><br><b>GRAB RENTALS 2 PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax No : |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                     |                                 |                       |
|-------------------------------------------------------------------------------------|---------------------------------|-----------------------|
| Quotation No. : QO18/06-1176                                                        | Quotation Date : 18/06/2018     | Terms : 30 DAYS       |
| Vehicle No. : SLV6971A                                                              | Chassis No. : JM6BN22A8H0160215 | Third Party Insurer : |
| Model : MAZDA 3                                                                     | Date of Accident :              |                       |
| Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLL1170E, DATE OF ACCIDENT: 18.06.2018 |                                 |                       |

| ITEM | DESCRIPTION                                                                                                                    | Qty | UNIT PRICE  | AMOUNT (SGD)      |
|------|--------------------------------------------------------------------------------------------------------------------------------|-----|-------------|-------------------|
|      |                                                                                                                                |     |             | B/F    /    0.00  |
| 46   | LHS DRIVESHAFT OIL SEAL                                                                                                        | 1   | 24.0000     | <del>24.00</del>  |
| 47   | LESS 20% ON ITEM 1 - 46                                                                                                        | 1   | -2,237.7000 | -2,237.70         |
| 48   | FRONT WHEEL RIM                                                                                                                | 1   | 600.0000    | 800.00            |
| 49   | FRONT WHEEL TYRE                                                                                                               | 1   | 250.0000    | <del>250.00</del> |
| 50   | TO CHECK ELECTRICAL LIGHTING CONCERNED                                                                                         | 1   | 80.0000     | 80.00             |
| 51   | TO RUST-PROOFING OF THE AFFECTED AREAS                                                                                         | 1   | 150.0000    | 150.00            |
| 52   | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT                                                                        | 1   | 120.0000    | 120.00            |
| 53   | TO TRANSFER OF LHS WHEEL TYRE, RIM AND ON WHEEL BALANCING                                                                      | 1   | 80.0000     | 80.00             |
| 54   | TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING | 1   | 350.0000    | 350.00            |
| 55   | USING ONBOARD SCAN TOOL PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT                  | 1   | 550.0000    | 550.00            |
| 56   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME         | 1   | 1,400.0000  | 1,400.00          |
| 57   | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                               | 1   | 1,600.0000  | 1,600.00          |

Parts 34,644.90  
 Less 20% : ( 922.38 )  
 3,689.52  
 Labour 1,690.00  
 PBP 5,379.52 #

Tan Kah 97495749  
 -wp-  
 20/6/18 @ 1600  
 Resing before paint  
 6 days  
 sur@1h.com.sg

PBP \$5,379.52

|                    |                  |
|--------------------|------------------|
| Sub Total          | 14,130.80        |
| GST(7.00%)         | 989.16           |
| <b>Total (SGD)</b> | <b>15,119.96</b> |

Please conduct the survey at  
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

## Hsiao Tong (LKKAuto)

---

**From:** Shu Pei (LKKAuto)  
**Sent:** Thursday, 16 August 2018 5:00 PM  
**To:** ar\_claims@pegasusengrg.com.sg; Taufikh (LKKAuto); Hsiao Tong (LKKAuto)  
**Cc:** Lionel Chua; Admin A  
**Subject:** FW: SLV6971A TP-AIG (DOA-18/06/2018) Finalised on a Without Prejudice basis  
**Attachments:** 20180816123831560.pdf

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

| LKK ref               | Officer in charge    |
|-----------------------|----------------------|
| CC6/LCR18011262/T1pb3 | Taufikh / Hsiao Tong |

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering <ar\_claims@pegasusengrg.com.sg>

**Sent:** Thursday, 16 August 2018 12:55 PM

**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Cc:** Lionel Chua <lionelchua@pegasusengrg.com.sg> <lionelchua@pegasusengrg.com.sg>

**Subject:** SLV6971A TP-AIG (DOA-18/06/2018) Finalised on a Without Prejudice basis

**Dear Taufikh,**

**Please find the calculation for your confirmation.**

**Part by Part repair \$5,379.52 and 6 days repair.**

**The attached copies of the documents for your attention.**

Thank You

Best Regards,

Wee

Pegasus Engineering & Trading Pte Ltd

Office: 65137748

Fax: 62513161

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 1345N   |

### Vehicle Details

|                                |                         |
|--------------------------------|-------------------------|
| Vehicle No.:                   | SLV6971A                |
| Vehicle to be Exported:        | Yes                     |
| Intended De-registration Date: | 18 Jun 2018             |
| Vehicle Make:                  | MAZDA                   |
| Vehicle Model:                 | MAZDA3 SEDAN 1.5 AT EU6 |
| Primary Colour:                | Silver                  |
| Manufacturing Year:            | 2017                    |
| Engine No.:                    | P520452672              |
| Chassis No.:                   | JM6BN22A8H0160215       |
| Maximum Power Output:          | 88.0 kW (118 bhp)       |
| Open Market Value:             | \$14,938.00             |
| Original Registration Date:    | 11 Jan 2018             |
| First Registration Date:       | 11 Jan 2018             |
| Transfer Count:                | 0                       |
| Actual ARF Paid:               | \$14,938.00             |

### Intended PARF Rebate Details

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 10 Jan 2028 |
| PARF Rebate Amount:           | \$11,203.00 |

### Intended COE Rebate Details

|                             |                                      |
|-----------------------------|--------------------------------------|
| COE Expiry Date:            | 10 Jan 2028                          |
| COE Category:               | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):          | 10                                   |
| QP Paid:                    | \$42,900.00                          |
| COE Rebate Amount:          | \$34,320.00                          |
| <b>Total Rebate Amount:</b> | <b>\$45,523.00</b>                   |

The information contained herein is correct as at 18 Jun 2018

OK

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Friday, 6 July 2018 8:32 AM  
**To:** 'Pegasus Engineering'  
**Subject:** Your Ref: SLV 6971A \*Our Ref: CC6/LCR18011262/T1pb3 [ACCIDENT INVOLVING SLL 1170E(AIG) & SLV 6971A ON 18/06/2018]  
**Attachments:** Statement of SLL 1170E.pdf

Your Ref: **SLV 6971A** Without Prejudice  
Our Ref: CC6/LCR18011262/T1pb3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLL 1170E(AIG) & SLV 6971A ON 18/06/2018**

We refer to the above matter.

Please be informed that liability is unclear. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAUTO)

---

**From:** Pegasus Engineering <ar\_claims@pegasusengrg.com.sg>  
**Sent:** Monday, 29 October 2018 4:24 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Lionel Chua <lionelchua@pegasusengrg.com.sg>; Pegasus Engineering; Taufikh (LKKAUTO)  
**Subject:** LOD - Third party claim - SLV6971A Your ref :CC6/LCR18011262/T1pb3-SLL1170E on 18.06.2018  
**Attachments:** 20181029161456746.pdf

Without Prejudice

Dear Hsiao Tong,

Refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf.

Thanks & Regards,  
Lionel Chua  
Pegasus Engineering & Trading Pte Ltd  
74 Kian Teck Road S628800  
Office: 65137748  
Fax: 62513161



MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807  
Tel: +65 6827 7888, Fax: +65 6827 7800  
Co. Reg. No. 200412212G GGT Reg. No. 20-041221G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.S.400  
Cars for Hire

COMMERCIAL VEHICLE - FLEET  
Comprehensive

Certificate No. A 29069774 MKE

Excess : SGD2,000

1. Index Mark and Registration Number of Vehicle

SLV5971A

2. Name of Policyholder

Grab Rentals 2 Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/02/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive\*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.  
Approved Insurers

Chief Executive Officer

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                      |                                                |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 22 Jun 2018<br><a href="#">Edit Reg</a> |               | 20 Jun 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>\$45,379.52</b><br><a href="#">Edit Estimates</a> | <b>\$45,379.52</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

|                             |                                                                                                                           |                        |                                                                            |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------------------------|
| Insured:                    | LCRF PTE LTD, Co. Reg. No.: 201624597K                                                                                    |                        |                                                                            |
| Main Claimant:              | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G                                                                            |                        |                                                                            |
| Vehicle Reg. No.:           | SLV6971A                                                                                                                  | Date of Loss:          | 18/06/2018 12:00 - :59<br>[5 Months and 7 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 7049748327SG                                                                                                         | Policy/Cover Note No.: | 0999994808 (Comprehensive)                                                 |
| Vehicle Reg. No. (Insured): | SLL1170E                                                                                                                  | Policy No. (Claimant): |                                                                            |
|                             |                                                                                                                           | Excess:                |                                                                            |
| Repairer:                   | Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751                       |                        |                                                                            |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Olea, Maricel] Maricel.Olea@aig.com    |                        |                                                                            |
| Claimant's Insurer:         | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888                                                            |                        |                                                                            |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/07/2018] |                        |                                                                            |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

\*SLV6971A (7049748327SG)  
[SLL1170E]  
TP  
GRAB RENTALS PTE LTD  
Jun 18 2018 12:00PM  
[LCRF PTE LTD]  
Pegasus Engineering & Trading Pte Ltd

|                                |                 |                                                    |  |                    |  |              |  |              |          |                                                         |                                     |
|--------------------------------|-----------------|----------------------------------------------------|--|--------------------|--|--------------|--|--------------|----------|---------------------------------------------------------|-------------------------------------|
| Upload Documents               |                 | Upload Photos                                      |  | Compose New Letter |  | Upload Video |  | Upload Audio |          | View <span style="float: right;">View in Browser</span> |                                     |
| <b>Video</b>                   |                 |                                                    |  |                    |  |              |  |              |          | 1 per page                                              | <input checked="" type="checkbox"/> |
| No                             | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |  |                    |  |              |  | Thumbnail    | Print    |                                                         |                                     |
| 1                              | 19/06/19 13:29  | Video - Accident<br>TP VIDEO FOOTAGE               |  |                    |  |              |  |              | Load MP4 |                                                         |                                     |
| <b>Letters/Correspondences</b> |                 |                                                    |  |                    |  |              |  |              |          | 1 per page                                              | <input checked="" type="checkbox"/> |
| No                             | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |  |                    |  |              |  | Thumbnail    | Print    |                                                         |                                     |
| 1                              | (Draft)         | Third Party Express Settlement - Payment Breakdown |  |                    |  |              |  |              | Edit     |                                                         |                                     |
| <b>Photos/Images</b>           |                 |                                                    |  |                    |  |              |  |              |          | 3 per page                                              | <input checked="" type="checkbox"/> |
| No                             | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  |  |                    |  |              |  | Thumbnail    | Print    |                                                         |                                     |
| 1                              | 06/07/18 08:11  | Chassis Number                                     |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 2                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 3                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 4                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 5                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 6                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 7                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 8                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 9                              | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 10                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 11                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 12                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 13                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 14                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 15                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 16                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 17                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 18                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 19                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 20                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 21                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 22                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 23                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 24                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 25                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 26                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 27                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 28                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 29                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 30                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 31                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 32                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 33                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 34                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 35                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 36                             | 06/07/18 08:11  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |

| Video         |                 |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|---------------|-----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                      | Print                               |
|               |                 |                                           |                                                                                                | <input checked="" type="checkbox"/> |
| 37            | 06/07/18 08:11  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 38            | 06/07/18 08:11  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 06/07/18 08:11  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 06/07/18 08:11  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 27/10/18 12:55  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| Documentation |                 |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                      | Print                               |
| 1             | 21/06/18 19:40  | TP ESTIMATE- MARKED                       |  Load PDF   |                                     |
| 2             | 21/06/18 19:40  | TP GIA REPORT                             |  Load PDF   |                                     |
| 3             | 30/07/19 12:08  | EMAIL TO TP                               |  Load PDF   |                                     |
| 4             | 30/07/19 13:12  | TP LOD                                    |  Load PDF   |                                     |
| 5             | 26/02/20 19:47  | EMAIL FROM TP                             |  Load PDF |                                     |
| 6             | 03/03/20 14:25  | WORKSHOP INVOICE                          |  Load PDF |                                     |
| 7             | 03/03/20 14:25  | AUTHORISATION TO ACT FORM                 |  Load PDF |                                     |
| 8             | 03/03/20 14:25  | Release Voucher                           |  Load PDF |                                     |
| 9             | 03/03/20 14:25  | RENTAL RECEIPT                            |  Load PDF |                                     |
| 10            | 03/03/20 14:25  | LTA SEARCH                                |  Load PDF |                                     |
| 11            | 03/03/20 14:25  | LOD                                       |  Load PDF |                                     |
| 12            | 03/03/20 14:25  | LETTER TO OI                              |  Load PDF |                                     |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                      | Print                               |
| 1             | 22/06/18 11:51  | OI GIA REPORT                             |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                          | Reset | Save | Print |
|------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                 |       |      |       |
| <div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div></div> </div>                                           |       |      |       |
| Show Remarks To: <input type="checkbox"/> Handling Insurer<br>Note: Remarks are private unless you show it to other parties. |       |      |       |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                 |
|-------------------|---------------------|--------|-----------------|
| Vehicle No:       | SLL1170E (Insd veh) | Model: | MAZDA 3 1.5 (A) |
|                   | SLV6971A (TP veh)   |        |                 |
| Date of Accident: | 18/06/2018          |        |                 |

|                                                                                                                                               |   |                                                 |                                 |
|-----------------------------------------------------------------------------------------------------------------------------------------------|---|-------------------------------------------------|---------------------------------|
| Global Sum Settlement                                                                                                                         | : | <input checked="" type="checkbox"/> [ X ] Yes   | <input type="checkbox"/> [ ] No |
| Repair Estimate                                                                                                                               | : | \$                                              | 15,532.03                       |
| Final Repair Cost                                                                                                                             | : | \$                                              | 6,320.00                        |
| Loss of Use                                                                                                                                   | : | \$                                              | days at \$0.00 per day          |
| Rental (if any)                                                                                                                               | : | \$                                              | 7 days                          |
| LTA / GIA Search Fee                                                                                                                          | : | \$                                              |                                 |
| Others:                                                                                                                                       | : | \$                                              |                                 |
|                                                                                                                                               | : | \$                                              |                                 |
| Final Settlement Sum (Global Sum)                                                                                                             | : | \$                                              | 6,320.00                        |
| Is Third Party Workshop GIA Registered? <input type="checkbox"/> [ ] YES <input checked="" type="checkbox"/> [ X ] NO (Kindly indicate below) |   |                                                 |                                 |
| A) For <b>Non GIA Registered Workshop:</b>                                                                                                    |   | Agreed Liability ____ 100 ____ (%)              |                                 |
| B) For <b>GIA Registered Workshop:</b>                                                                                                        |   | BOLA Applicable: Yes/ No BOLA Scenario No: ____ |                                 |
| BOLA Liability: ____ (%)                                                                                                                      |   | Assessed Liability (*): ____ (%)                |                                 |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.                                          |   |                                                 |                                 |
| Remarks _____                                                                                                                                 |   |                                                 |                                 |

| Payment Instruction: Payee's Breakdown |                                       |   |             |
|----------------------------------------|---------------------------------------|---|-------------|
| 1)                                     | Pegasus Engineering & Trading Pte Ltd | : | \$ 6,320.00 |
| 2)                                     |                                       | : | \$          |
| 3)                                     |                                       | : | \$          |
| 4)                                     |                                       | : | \$          |

JOANNE LEE KHANG MIN

03 Mar  
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18011262/T1HS3Q2

Date: 03/03/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994808  
**Claimant**  
**Vehicle No :** SLV6971A **Insured Vehicle No :** SLL1170E  
**Date of Loss:** 18/06/2018 **Nature of Claim:** TP **Claim No:** 7049748327SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLV6971A**  
 Make & Model: MAZDA 3, 1.5 (A) Engine No: P520452672  
 Reg. Date: 11/01/2018 (Man. Year: 2017) Chassis No: JM6BN22A8H0160215  
 Colour: Silver Odometer: 0 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                           | 10,185.92        | 3,689.52        | 6,496.40        | 63.78        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00            |              |
| Labour                                          | 4,330.00         | 1,690.00        | 2,640.00        | 60.97        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00            |              |
| Towing                                          | 0.00             | 0.00            | 0.00            |              |
| <b>Gross Total (\$\$)</b>                       | <b>14,515.92</b> | <b>5,379.52</b> | <b>9,136.40</b> | <b>62.94</b> |
| <b>+ GST 7.00/7.00% (\$\$)</b>                  | <b>1,016.11</b>  | <b>376.57</b>   | <b>639.54</b>   | <b>62.94</b> |
| <b>Nett Amount (\$\$)</b>                       | <b>15,532.03</b> | <b>5,756.09</b> | <b>9,775.94</b> | <b>62.94</b> |
| <b>+ Car Rental (7.0 x S\$80.00/day) (\$\$)</b> |                  | <b>560.00</b>   |                 |              |
| <b>+ Doc/Search Fee (\$\$)</b>                  |                  | <b>7.49</b>     |                 |              |
| <b>Nett Liability (\$\$)</b>                    |                  | <b>6,323.58</b> |                 |              |
| <b>Global Sum Settlement (\$\$)</b>             |                  | <b>6,320.00</b> |                 |              |

## INSPECTION

Date of Assignment: 20/06/2018  
 Date Inspected: 20/06/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck)  
 74 Kian Teck Road  
 Singapore 628800  
 Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                             | Condition        | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------------------------|------------------|-------------|--------------|
| 1   | 1   |          | *LHS FRONT FENDER                                       | Bent             | 334.00 FL   | *334.00 FL   |
| 2   | 1   |          | *LHS FRONT FENDER INNER COWLING                         | Deformed         | 130.00 FL   | *130.00 FL   |
| 3   | 6   |          | *LHS FRONT FENDER INNER COWLING CLIPS                   | Necessary        | 30.00 FL    | *30.00 FL    |
| 4   | 1   |          | *LHS FRONT FENDER INSULATION FOAM                       | Necessary        | 36.00 FL    | *36.00 FL    |
| 5   | 1   |          | *LHS FRONT FENDER TOP GARNISH                           | Not<br>Necessary | 46.00 FL    | *- FL        |
| 6   | 3   |          | *LHS FRONT FENDER TOP GARNISH CLIPS                     | Not<br>Necessary | 15.00 FL    | *- FL        |
| 7   | 1   |          | *LHS FRONT FENDER STAY BRACKET                          | Not<br>Necessary | 40.00 FL    | *- FL        |
| 8   | 1   |          | *LHS HEAD LAMP                                          | Cracked          | 1,020.00 FL | *1,020.00 FL |
| 9   | 1   |          | *LHS HEAD LAMP CLIP HOLDER                              | Necessary        | 10.50 FL    | *10.50 FL    |
| 10  | 1   |          | *FRONT BUMPER                                           | Cracked          | 825.00 FL   | *825.00 FL   |
| 11  | 1   |          | *LHS FRONT BUMPER INDICATION LIGHT                      | Cracked          | 140.00 FL   | *140.00 FL   |
| 12  | 1   |          | *LHS FRONT BUMPER INDICATION LIGHT GARNISH              | Deformed         | 38.00 FL    | *38.00 FL    |
| 13  | 1   |          | *LHS FRONT BUMPER INDICATION LIGHT GARNISH<br>EXTENSION | Missing          | 20.00 FL    | *20.00 FL    |
| 14  | 10  |          | *FRONT BUMPER CLIPS                                     | Necessary        | 50.00 FL    | *50.00 FL    |
| 15  | 1   |          | *LHS FRONT BUMPER TOW COVER                             | Not<br>Necessary | 14.00 FL    | *- FL        |
| 16  | 1   |          | *LHS FRONT BUMPER REINFORCEMENT                         | Not<br>Necessary | 480.00 FL   | *- FL        |
| 17  | 1   |          | *LHS FRONT BUMPER REINFORCEMENT COVER                   | Not<br>Necessary | 67.00 FL    | *- FL        |
| 18  | 4   |          | *FRONT BUMPER REINFORCEMENT COVER CLIPS                 | Not<br>Necessary | 20.00 FL    | *- FL        |
| 19  | 1   |          | *LHS FRONT BUMPER LOWER SUPPORT GARNISH                 | Not<br>Necessary | 96.00 FL    | *- FL        |
| 20  | 1   |          | *LHS FRONT BUMPER LOWER SPLASHIELD COVER                | Not<br>Necessary | 95.00 FL    | *- FL        |
| 21  | 1   |          | *FRONT SUPPORT PANEL -METAL                             | Not<br>Necessary | 140.00 FL   | *- FL        |
| 22  | 1   |          | *FRONT SUPPORT PANEL -FIBRE                             | Not<br>Necessary | 470.00 FL   | *- FL        |
| 23  | 1   |          | *FRONT SUPPORT PANEL TOP COVER                          | Not<br>Necessary | 91.00 FL    | *- FL        |
| 24  | 1   |          | *RADIATOR GRILLE                                        | Not<br>Necessary | 150.00 FL   | *- FL        |
| 25  | 1   |          | *RADIATOR GRILLE CHROME GARNISH                         | Cracked          | 183.00 FL   | *183.00 FL   |
| 26  | 1   |          | *RADIATOR GRILLE CHROME GARNISH BASE                    | Not<br>Necessary | 20.00 FL    | *- FL        |
| 27  | 4   |          | *RADIATOR GRILLE OUTER GARNISH                          | Not<br>Necessary | 1,356.00 FL | *- FL        |
| 28  | 1   |          | *RADIATOR GRILLE OUTER GARNISH RIVETS                   | Necessary        | 36.00 FL    | *36.00 FL    |
| 29  | 1   |          | *RADIATOR GRILLE EMBLEM BADGE                           | Not<br>Necessary | 59.00 FL    | *- FL        |
| 30  | 1   |          | *RADIATOR GRILLE OUTER GARNISH SUPPORT                  | Not<br>Necessary | 185.00 FL   | *- FL        |
| 31  | 3   |          | *RADIATOR GRILLE OUTER GARNISH SUPPORT<br>CLIPS         | Not<br>Necessary | 15.00 FL    | *- FL        |
| 32  | 1   |          | *FRONT WHEEL HUB CAP                                    | Cut              | 120.00 FL   | *120.00 FL   |
| 33  | 1   |          | *LHS FRONT SHOCK ABSORBER                               | Not<br>Necessary | 287.00 FL   | *- FL        |
| 34  | 1   |          | *LHS FRONT SHOCK ABSORBER TOP MOUNT                     | Not<br>Necessary | 92.00 FL    | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------------|---------------|-------------|--------------|
| 35  | 1   |          | *LHS FRONT LOWER ARM                        | Not Necessary | 485.00 FL   | *- FL        |
| 36  | 1   |          | *LHS FRONT WHEEL KNUCKLE                    | Not Necessary | 384.00 FL   | *- FL        |
| 37  | 1   |          | *LHS FRONT WHEEL BEARING WITH HUB           | Not Necessary | 542.00 FL   | *- FL        |
| 38  | 1   |          | *LHS FRONT WHEEL ABS SENSOR                 | Not Necessary | 133.00 FL   | *- FL        |
| 39  | 1   |          | *STEERING RACK AND PINION ASSY              | Not Necessary | 193.00 FL   | *- FL        |
| 40  | 1   |          | *LHS ENGINE SUSPENSION CROSS MEMBER BRACKET | Not Necessary | 59.00 FL    | *- FL        |
| 41  | 1   |          | *BONNET                                     | Bent          | 1,068.00 FL | *1,068.00 FL |
| 42  | 2   |          | *BONNET HINGE                               | Repair        | 164.00 FL   | *- FL        |
| 43  | 1   |          | *BONNET OUTER WEATHERSTRIP SEAL             | Necessary     | 64.00 FL    | *64.00 FL    |
| 44  | 1   |          | *BONNET INNER WEATHERSTRIP SEAL             | Necessary     | 26.00 FL    | *26.00 FL    |
| 45  | 1   |          | *LHS DRIVESHAFT                             | Not Necessary | 1,336.00 FL | *- FL        |
| 46  | 1   |          | *LHS DRIVESHAFT OIL SEAL                    | Not Necessary | 24.00 FL    | *- FL        |
| 47  | 1   |          | *FRONT WHEEL RIM                            | Not Necessary | 600.00 FS   | *- FS        |
| 48  | 1   |          | *FRONT WHEEL TYRE                           | Not Necessary | 250.00 FS   | *- FS        |
| 49  | 1   |          | *DC CONVERTER                               | Cracked       | 481.40 FL   | *481.40 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,519.90**    **4,611.90**  
 - List Item Discount on L Items 20.00/20.00% (\$\$)    2,333.98    922.38

Total Parts (\$\$) **10,185.92**    **3,689.52**

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                               |          |                 |                 |
| 1                               | TO CHECK ELECTRICAL LIGHTING CONCERNED                                                                                        | New      | 80.00           | 30.00           |
| 2                               | TO RUST-PROOFING OF THE AFFECTED AREAS                                                                                        | New      | 150.00          | 30.00           |
| 3                               | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT                                                                       | New      | 120.00          | 80.00           |
| 4                               | TO TRANSFER OF LHS WHEEL TYRE ,RIM AND ON WHEEL BALANCING                                                                     | New      | 80.00           | 0.00            |
| 5                               | TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS,REMOVE AND RENEWAL OF THE NECESSARY PARTS ,TO PERFORM FINAL CHECKING AND TESTING | New      | 350.00          | 0.00            |
| 6                               | USING ONBOARD SCAN TOOL PERFORM FULL ENGINE DIAGNOSTIC CHECK ,TO CONFIGURE AND CLEAR ,RESET SRS SERVICE LIGHT                 | New      | 550.00          | 150.00          |
| 7                               | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME        | New      | 1,400.00        | 700.00          |
| 8                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                              | New      | 1,600.00        | 700.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                               |          | <b>4,330.00</b> | <b>1,690.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >